Menmen Distributed Co		ASSIGNMENT (Office) FGI	Date/Time	02/07/2018@2.21pr
To Inspect V at Workshop of	phick No XI	= 99 E uan Hwa ai Kadut street #	Tel 626	9 9 192 9028 87
Sum Insured Make of Veli (Client's Record CA / (RE)) REP. / REV 24 HRS	Excess	03/07/2018	7/06/2018 Be Morning
Date/Time	Action/Instruction (VE 49F - NA G		Vehicle IN (DUA: 25/02/2017
05/1/18		ino My Blos	k- stask	
6 7 18	Ko-saek manda Lee Kuan Hwa-	te with mv		-1.11s (Colution)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inte	rnationale Des Experts En Autom	
RG	O INSURANCE PTI	ELTD	Ref : CS/EGI180119	65/VVd3
104-0	MASEK BOULEVAR 01 SUNTEC TOWE SAPORE 038985	RD R FIVE	Date: 02-07-2018	
		Policy Pa	rticulars :- OWN DAMAGE	1
	Insured Veh.		Veh. Inspected	XE 99E
_	Policy No.	DMCV17S017843	Coverage (\$)	0.00
	Claim No.	HIMMES NO CONTRIBUTION OF THE PROPERTY OF THE	Excess (\$)	0.00
	Assign From	SITI ATIKAH	Assign Date	02/07/2018
2.		Vehicle	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3.		C	onditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	Server all	De	scription of Damages	1.500
			Seneral Information	
5.	Little Line Age 1		Inspection Date	
	Accident Date	27/06/2018 LEE KUAN HWA MOTO		
	Survey held at	24 SUNGEI KADUT ST. SINGAPORE 729050		
5a.			Remarks	
	TAXTUE MADVETA	ALUE IS S\$(ES CE TO YOUR INSTRUCTI	T. AVERAGE) ONS, WE HAVE AUTHORISED	REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

Core	Notified	Est Submitted	Adj Assigned	Adl Rot		d) Submitted	Ins Authled	Status		
Main	02 Jul 2018 10:47 Sendback Est	02 Jul 2018 12:21 \$\$29,264.15	02 Jul 2018 14:21 Assign	PNQ DIR	0	d) Soprimited	Ins. Auch ed		ssignment Case	
	Main	Refere	nce	CI	aim Details		Documents		Show All	
CLAIM SU	BFOLDER DETAIL	.s								
Insured:	SING LIAN CR	ANES PTE.LTD,	Co. Reg. No.: 20	01129107	rc .					
Vehicle Reg No.:					Date of Loss	27/06/2018 04:00 - :59 [45 Months and 18 Days From LTA Reg Date (Man Yr			ate (Man Yr)]	
Claim Type	OD	OD			Policy/Cover Note No.:	DMCV17S017843 (Comprehensive)				
4000000000					Excess:	\$\$1,500,00				
Repairer:	Lee Kuan Hwa	Motor Service (Sungel Kadut)	24 Sunge	Kadut Stree	t 4, 729050 Su	ngei Kadut - Tel: 62	2699192		
Handling Insurer:		ce Pte. Ltd. (HQ					10.0000			
Adjuster:	LKK Auto Cons	ultants Pte Ltd	(HQ) - Tel: 6256	-3561	[Final Rpt	due 11/07/2	2018]			
Adj Asg. Remarks:	1. Pls conduct O	D survey on WP b rts not to be relea	asis 2. Pls assist	to advise	the consiste	ncy of the dam	ages too. 3. Attache	ed are inst	ured and TP's	
ASSOCIAT	ED MAIL RECEIV	ED					View A	All I Com	pose Case Mail	
There are n	o mail for this case.									
ALL ASSO	CIATED TASKS					View All	Search Tasks Cres	ate New Ta	et II Complete	
Due Date	Priority Ty	pe Task Grou	p Subject		er Assim	ALCOH WILL	Search lasks Crea	are usem 19	sk Complete	

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 9 July 2018 12:51 PM

To:

kuanhwa@singnet.com.sg

Cc:

SUR

Subject:

XE 99E-DOA: 27/6/2018

Dear Adeline,

As instructed by our client, please proceed to repair the insured vehicle XE 99E on Lump Sum Repair (Excess \$1500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

YEGGE

				Jun 27 2 [SING LIAN C	OD OD: 4:00AM PRANES PTE.LTD) wa Motor Service		
Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward		
rom o Subject	LKK HO	1			/07/2018 10:07 AM. Claim Handler: Siti Atika	h	
Approved	:27373.15						
DOCUM	ENTS SU	MMARY					
There ar	e no docur	ments.					

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Siti Atikah Attn:

Date: 06 Jul 2018

Preliminary Advice

Vehicle No. : XE99E

: 27/06/2018 Accident Date

Make : ISUZU CYH52T Assignment Date : 02/07/2018

: DMCV17S017843 Policy No. Excess

Date of Inspection: 03/07/2018

Est. Duration of Repair : 8.00

: \$\$1,500.00

Inspection At

: LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT)

24 SUNGEI KADUT STREET 4

SINGAPORE 729050

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,264.15
Revised Amount	:S\$	9,486.15
Check Items (Estimated)	:S\$	17,887.00
Total	:S\$	27,373.15

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	33,350.00
Salvage Value	:S\$	
Margin for Repair	:SS	71,650.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Siti Atikah Date: 06 Jul 2018

Preliminary Advice

: 27/06/2018 Accident Date Vehicle No : XE99E : DMCV17S017843 Policy No. Make : ISUZU CYH52T : \$\$1,500.00 Excess Assignment Date : 02/07/2018 Est. Duration of Repair : 8.00 Date of Inspection: 03/07/2018

Inspection At

: LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT)

24 SUNGEI KADUT STREET 4

SINGAPORE 729050

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,264.15
Revised Amount	:S\$	9,486.15
Check Items (Estimated)	:S\$	17,687.00
Total	:S\$	27,173.15

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	33,350,00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,650.00

Remarks

(x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Siti Atikah

Date: 04 Jul 2018

Preliminary Advice

Vehicle No

: XE99E

Accident Date

: 27/06/2018

Make

: ISUZU CYH52T

Policy No.

: DMCV17S017843

Assignment Date : 02/07/2018

Excess

: S\$1,500.00

Date of Inspection : 03/07/2018

Est. Duration of Repair

: 8.00

Inspection At

: LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT)

24 SUNGEI KADUT STREET 4

SINGAPORE 729050

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,264.15
Revised Amount	:S\$	9,486.15
Check Items (Estimated)	:S\$	17,687.00
Total	:S\$	27,173.15

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	TBA
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

)	The vehicle is repairable at our adjusted amount.	We have als	so confirmed	excess	and police	cy coverage.
	Kindly let us have your authorisation.					

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Pending market value.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	9107C	
Vehicle No.:	XE99E	
Vehicle to be Exported:	No	
Intended De-registration Date:	05 Jul 2018	
Vehicle Make:	ISUZU	
Vehicle Model:	CYH52T	
Primary Colour:	White	
Manufacturing Year:	2014	
Engine No.:	6WG1421157	
Chassis No.:	JALCYH52TE7000112	
Maximum Power Output:		
Open Market Value:	\$94,172.00	
Original Registration Date:	09 Sep 2014	
First Registration Date:	09 Sep 2014	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$4,709.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	08 Sep 2024	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	10	
QP Paid:	\$54,009.00	
COE Rebate Amount:	\$33,350.00	
Total Rebate Amount:	\$33,350.00	

The information contained herein is correct as at 05 Jul 2018

Annex A

Transaction ref 20150930151233705508

The owner and vehicle particulars for Vehicle No. XE99E as at 30 Sep 2015 are as follows:

1.	Name	: SING LIAN CRANES PTE, LTD.
2.	Identification No. Type	: Company
3.	Identification No.	: 201129107C
4.	Place Of Passport Issue	:-
5.	Vehicle No.	: XE99E
6.	Previous Vehicle No.	;-
7.	Effective Date of Ownership	: 30 Sep 2015
8.	Original Registration Date	; 09 Sep 2014
9.	First Registration Date	: 09 Sep 2014
10.	Vehicle Type	: B30 - Goods (Open) Lorry (Wooden Body)
11.	Vehicle Scheme	: Normal
12.	Attachment 1	; With Crane
13.	Attachment 2	1(2)
14.	Attachment 3	1-
15.	Vehicle Make	: ISUZU
16.	Vehicle Model	: CYH52T
17.	Year of Manufacture	: 2014
18.	Primary Colour	: White
19.	Secondary Colour	: •
20.	Passenger Capacity	; 2
21.	Chassis/Trailer Chassis No.	: JALCYH52TE7000112/-
22.	Propellant	: Diesel
23.	Engine No./Motor No.	: 6WG1421157 / -
24.	Engine Capacity(cc)/Power Rating(kW)	: 15681 / -
25.	Maximum Power Output(kW/bhp)	:-/-
26.	Unladen Weight(kg)	: 19060





S PASS

Employment of Foreign Manpower Act (Chapter 91A) Republic of Singapore

ENDINE COMPORATION PTE. LTD.

Sealer CONSTRUCTION Name



YAN ZHENHUI DRIVER, TRAILER TRUCK



Date of Approx 25-07-2017

Date of leave 10-08-2017 Date of Expery 14-08-2019



L8203618

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)


Class 3 Motor Cars = 3000kg with = 7 passangers, exclusive at the driver; and ather motor vehicles = 2500kg at the driver; and ather motor vehicles = 500kg at the driver; and ather motor which = 2500kg load or passangers and the onlacten weight > 2500kg load or passangers and the onlacten weight > 2500kg load or passangers and the onlacten weight > 2500kg load and the unlacten weight > 1250kg to Jun 2011 load and the unlacten weight > 1250kg load and the unlacten weight > 1250kg

13 Jun 2011

Licence No. GR238742P

VISIT PASS immgration Regulations

YAN THENHUL



Date of Sixth Sex 23-01-1970 M Date of Sesse Date of Explry

D8238242P 10-08-2017 14-09-2019

CHINESE

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SUMMENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, ON WHEN A NEW CARD IS ISSUED TO YOU.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver. 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. repudiate policy ability.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for Any false reporting may be referred to the Police for Investigation. archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

sforesaid.	ACCIDENT STATEMENT	
D. L. Of Brendt	28/06/2018 10:28	
Date Of Report	27/06/2018 04:10	
Date Of Accident	ALONG LORNIE ROAD	
Exact Location Of Accident	SINGAPORE	
Country/State of Loss	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XE99E	
Ingured/Policyholder		

Vehicle Registration Number	
Insured/Policyholder	
Name Of Registered Owner	SING LIAN CRANES PTE.LTD
Name Of Registered Office	201129107C
Co Boo No	20112717

Co Reg No NOEMAIL Email Address

Mobile Phone No OFFICE-65091669 Alternative Phone No

Vehicle Particulars ISUZU Manufacturer CYH52T-15.7 D (M)

Model Exact Purpose for which vehicle was being used at

time of accident Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken COMMERCIAL VEHICLE Vehicle Category

Insurance Company ERGO INSURANCE PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

Policy Number Cover Note Number

Driver YAN ZHEN HUI Name of Driver G8238242P NRIC No 23/01/1970 Date Of Birth OUTDOOR Occupation 18/02/2009

Date Of Driving Pass 9 YEARS AND 4 MONTHS Driving Experience

MALE

Gender (LOCAL) +65-82093327 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

Address

3A/5A ALIWAL STREET, CHENN LOONN BUILDING SINGAPORE 199896

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

NO

NO

NO

YES

NO NO

SLX9115A

PRIVATE CAR

Weather Conditions RAINING Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by NO

ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFERS TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 13

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

t the date 27/06/2018 at about	1 0410	hrs - I	5	opped
y Vehicle A (XE 99 E) within 1		along	Lornia	
uddenly, the vehicle B (SLX 9115 A the rear of my vehicle.	from		COMP 0	and hit

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (if driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

飞瓶鳞



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours : Monday to Friday, 09:00 – 17:00 UEN: 566550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

	A	DDENDUM		
PARTICULARS OF PER	SONMAKINGTHEAMI 38/06/18 YAN ZHEN	ENDMENTS:	Registration No:	XE 99 E
Original Report No :	YAN TIKA	venicio	negistration (98238242 P
Name(as shown in NRIC):	(FII ZHHO	NRIC/FI	N/Passport No :	
(*Vehicle Driver/Veh	nicle Owner) (*) Please			
Address :				
Contact (Tel) :		Mobile	No.:	
Email Address :				
Date of Accident :	27 106/18	Time o	f Accident :	0410 hrs
Place of Accident :	LORNIE ROA	D		
Company.	SING HAN C	RANES PTE-LTD		
	party vehicle			
·				
			N)
Policyholder / Driv	er's Signature		Reporting Centre I	Personnel's Signature
Date:			VRIC/FIN No.:	

Date:



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours: Monday to Friday, 09:00 – 17:00 UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

		ADD	ENDUM	
A)	PARTICULARS OF PERS	SON MAKING THE AMEND	MENTS:	40.5
	Original Report No :_	28/06/2018	Vehicle Registration	No: XE 99E
	Name of the same to tipic !	YAN ZHEN HUI	NRIC/FIN/Passport	No: 48238242P
	(*Vehicle Driver / Vehi	icle Owner) (*) Please dele	te as appropriate	
				Singapore(
	Address :.			8 20933A
	Contact (Tel) :	1	Mobile No.:	
	Email Address :			211
	Date of Accident :	27/06/2018	Time of Accident :	0 1410 Hrs
	Place of Accident :	LORNIE ROAD		
		SING LIAN CRAN	ES PTE LTD	
	Insurance Company:	0.11		
	7)			
			/	ly.
	Policyholder / Drive	er's Signature	Reporting Cen	itre Personnel's Signature
	Date:	1 2 aiBillacar a	Name: NRIC/FIN No.:	

GIARRIC inidendumform_V3

Date:

Lee Kuan Hwa Motor Service (Co. Reg. No. 36463500B)

24 Sungei Kadut Street 4 Singapore 729050

Tel: 62699192 Fax: 62692239 Email: kuanhwa@singnet.com.sg

INSURER:

ERGO Insurance Pte. Ltd. (HQ)

SING LIAN CRANES PTE.LTD

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

DMCV17S017843

Policy No:

Vehicle Reg. No.:

Driver Age/Info:

TP Injury Involved?

NO

XE99E

Party At Fault: Third Party

Involved?

Chassis No:

Ref. No:

Date of Loss:

Driveable?

27/06/2018

UNKNOWN

JALCYH52TE7000112

YES

Vehicle Reg. Date: 09/09/2014

Insured/Claimant:

Make/Model:

ISUZU CYH52T, 15.7 D (M)

Vehicle Colour:

Engine No:

Odometer:

WHITE

6WG1421157

0 KM

Paint Type:

Total Loss?

YES Est. Duration of Repair 10

(day)

Present Location:

LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT)

	Amount
	24,613.45
	10.70
	4,640.00
	0.00
	29, 666.65 0.00
Gross Total (S\$)	29,264.15
+ GST 7.00% (S\$)	2,048.49
Nett Amount (S\$)	31,312.64
	+ GST 7.00% (S\$)

This claim is handled by: ADELINE LEE SU FANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 02 Jul 2018)

Parts:

N/A

ISUZU CYH52T 15.7 D (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Lee Kuan Hwa Motor Service/XE99E/02/07/2018 12:21

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No. Qty Part No.	Particulars	%Disc	%Depr	Amount
1 1	*Rear tail gate VBR	0.00	0.00	480.00 F
2 1 7	*Rear side gate RH ?V CPK	0.00	0.00	*480.00 F
3 (5)	*Rear side gate hinges Jacform	0.00	0.00	1 *200.00 F
4 1	*Rear bumper VBB	0.00	0.00	(*800.00F)
5 2	*Rear bumper bracket VORFORM	0.00	0.00	*600:00 F
6 1	*Rear number plate V07	0.00	0.00	*15.00 F
7 2	*Rear number plate lamp / CRK	0.00	0.00	*60.00 F
8 1	*Rear lamp / B#	0.00	0.00	*285.00 F
9 1	*Rear lamp bracket Volleren	0.00	0.00	*250.00 F
10 1	*Rear mudguard /DT	0.00	0.00	*260.00 F
11 1	*Rear mudflat V GR	0.00	0.00	*45.00 F
12 1	*Rear mudflat bar VNEC	0.00	0.00	*30.00F
13 1	*Rear tyre / wt	0.00	0.00	600.00F
14 1	*Rear gear box housing of 1000 600 5500	0.00	0.00	1. *9,300.00F
15 2	*Rear gear box housing arm mounting 10T	0.00	0.00	*600.00 F
16 1	*Rear body lower chassis bar	0.00	0.00	*280.00 F
17 1	*Rear hydrawlic cyL chassis VCR k	0.00	0.00	3,600.00 F
18 4	*Rear hydrawlic pipe VOT	0.00	0.00	*360.00 F
19 2	*Rear hydrawlic hose Vockerm	0.00	0.00	*280.00 F
20 1	*Rear hydrawlic cyL VBR	0.00	0.00	*1,800.00F
21 1	*Rear valve Po check VNSC	0.00	0.00	*290.00 F
22 4	*Rear hose guide I coform	0.00	0.00	*260.00 F
23 18	*Rear hydraulic oil VINEC	0.00	0.00	*108.00 F
24 8	*Rear bolt & nut INEL	0.00	0.00	*96.00 F
25 18	*Rear gear box oil JNEC	0.00	0.00	*144.00 F
26 1	*Rear safety lamp / CRK	0.00	0.00	*180.00 F
=Franchise part.	AND ADDRESS OF THE PROPERTY OF			N STANSSESSES
	Sub Total (S\$)			21,403.00
	+ Margin on L,N Items 15.00% (S\$)			3,210.45
	Total Parts (S\$)			24,613.45

Lee Kuan Hwa Motor Service/XE99E/02/07/2018 12:21. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
Mis 1	cellar 1	OD/TP Case (Insurer)		10.70
			Sub Total (S\$)	10.70

Estima	toe on	abour
	tes on	Laboui

No	Particulars	Lab.Type	Amount
Lab	our Items	ONCY	
1	To towing	New	× 200.00 ✓ * n
2	To wiring	New	80.00 50
3	To repair rear body labour	New	680,00 400
4	To repair & repair labour	New	600.00 500
5	To repair & replace hydraulic , pipe, pump, etc.labour	New	1,200.00 1000
6	To replace gear box housing labour	New	1,200.00 420
7	To spray putty	New	680.00-500
		Gross Labour Cost (S\$)	4,640.00

Lee Kuan Hwa Motor Service/XE99E/02/07/2018 12:21. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- Lump Sum Repair

- Photo after paint

16463

20% 17841.96 LICK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

L/S: \$ 17850@8 days

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_vi... 2/7/2018



REPAIR DETAILS

Reference

Part Source:

(Last Synchronised 02 Jul 2018)

Parts:

ISUZU CYH52T 15.7 D (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Lee Kuan Hwa Motor Service/XE99E/02/07/2018 12:21

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages; running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No. Qty Pari No.	Particulars	%Disc	%Depr	Amount
1 1	*Rear tail gate < BR	0.00	0.00	480.00 F
2 1 7	*Rear şide gate RH ?	0.00	0.00	*480.00 F
3 5	*Rear side gate hinges / 0 a form	0.00	0.00	*200,00 F
4 1	*Rear bumper VRR	0.00	0.00	(*800.00F)
5 -2	*Rear bumper bracket Victoria	0.00	0.00	:600.00F 30
5 1	*Rear number plate VOT	0.00	0.00	*15.00 F
7 2	*Rear number plate lamp	0.00	0.00	*60.00 F
8 1	*Rear lamp V 64	0.00	0.00	*285.00 F
9 1	*Rear lamp bracket Volleger	0.00	0.00	*250.00
10 1	*Rear mudguard - DT	0.00	0.00	*260.00 F
11 .1	*Rear mudflat VBR	0.00	0.00	*45.00 F
12 1	*Rear mudflat bar VNEC	0.00	0.00	*30.00F / 6
13 1	*Rear tyre	0.00	0:00	*600:00 F
14 1	*Rear gear box housing of Physics	0.00	0.00	19,300.00 F 50
15 2	*Rear gear box housing arm mounting IT	0.00	0.00	*600.00 F
16 1	*Rear body lower chassis bar PT	0.00	0.00	*280.00 F
17 1	*Rear hydrawlic cyL chassis JORIA	0.00	0.00	*3,600.00 F
18 4	*Rear hydrawlic pipe VOT	0.00	0.00	*360.00 F
19 2	*Rear hydrawlic hose / Dokerm	0.00	0.00	*280.00 F
20 1	*Rear hydrawlic cyL	0.00	0.00	*1,800.00 F
21 1	*Rear valve Po check V NEC	0.00	0.00	*290.00 F
22 4	*Rear hose guide - Calores	0.00	0.00	*260.00 F
23 18	*Rear hydraulic oil V IVEC	0:00	0.00	*108.00 F
24 B	*Rear bolt & nut of NEC	0.00	0.00	*96.00 F
25 18	*Rear gear box oil _ NEL	0.00	0.00	*144.00 F
26 1	*Rear safety lamp	0.00	0.00	*180.00 F
FoFranchise part	Advisor Control of the Control of th	1107.31.1	120.001	110.01.00
	Sub Total			21,403.00
	+ Margin on L,N Items 15.00%	(S\$)		3,210.45
	Total Parts	(S\$)		24,613.45

Lee Kuan Hwa Motor Service/XE99E/02/07/2018 12:21. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Lee Kuan Hwa Motor Service (Co.Reg.No:36463500B)

24 Sungei Kadut Street 4 Singapore 729050

Tel: 62699192 Fax: 62692239 Email: kuanhwa@singnet.com.sg

(SUPPLEMENTARY)

INSURER:

Present Location:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CL	AIM		
Claim Type:	OD (OWN DAMAGE)	Ref. No:	BENEZIIO PTIA
Policy No:	DMCV17S017843	Date of Loss:	27/06/2018
Vehicle Reg. No.:	XE99E	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SING LIAN CRANES PTE.LTD		
Make/Model:	ISUZU CYH52T, 15.7 D (M)	Vehicle Reg. Date:	09/09/2014
Vehicle Colour:	WHITE		
Engine No:	6WG1421157	Chassis No:	JALCYH52TE7000112
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

	Amount
	402.50
	0.00
	0.00
	0.00
	0.00
Gross Total (S\$)	402.50
+ GST 7.00% (S\$)	28.18
Nett Amount (S\$)	430.68
+ Previous Estimates (S\$)	31,312.64
Claim Total (S\$)	31,743.32
	+ GST 7.00% (S\$) Nett Amount (S\$) + Previous Estimates (S\$)

LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT)

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS Reference Part Source: (Last Synchronised: 03 Sep 2018) ISUZU CYH52T 15.7 D (M) (Model not available in database) Parts: N/A Labour: Repairer's (Price-denominated Standard List) Lee Kuan Hwa Motor Service/XE99E/03/09/2018 11:54 Print Code: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers Validity:

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

	17		Parts
-0	m a	nn sai	Parie

No. Qty Part No.	Particulars		%Disc	%Depr		Amount
1 1	*Rear Tool Box	pm	0.00	0.00	150	*350.00 F
F=Franchise part.		Sub Total (S\$)				350.00
	+ Margi	n on L,N Items 15.00% (S\$)				52.50
		Total Parts (S\$)				402.50
		iotal Parts (5\$)				402.5

Lee Kuan Hwa Motor Service/XE99E/03/09/2018 11:54. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lee Kuan Hwa Motor Service/XE99E/03/09/2018 11:54. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 12 September 2018 2:57 PM

To:

kuanhwa@singnet.com.sg

Cc:

SUR

Subject:

RE: XE 99E-DOA: 27/6/2018

Dear Adeline,

Noted with thanks.

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kuanhwa@singnet.com.sg <kuanhwa@singnet.com.sg>

Sent: Tuesday, 11 September 2018 4:45 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: XE 99E-DOA: 27/6/2018

Dear Veron,

Ok confirm cost of repair @ \$18,300.00.

Kindly make the offer in the merimen so that we could submit our repair bill.

Thank you.

Regards, Adeline Lee

Lee Kuan Hwa Motor Service Tel: 6269 9192 Fax: 6269 2239

H/P: 9028 8798

From: Veron Chen (LKKAuto)

Sent: Tuesday, September 11, 2018 3:42 PM

To: kuanhwa@singnet.com.sg

Subject: RE: XE 99E-DOA: 27/6/2018

Dear Adeline,

We close at Lump Sum \$18,300 before excess \$1500 @ 8 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 10 September 2018 2:25 PM

To: 'kuanhwa@singnet.com.sg' <kuanhwa@singnet.com.sg>

Subject: RE: XE 99E-DOA: 27/6/2018

Dear Adeline,

Re-offer Lump Sum \$18,200 before excess \$1500 @ 8 working days.

Kindly check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kuanhwa@singnet.com.sg <kuanhwa@singnet.com.sg>

Sent: Friday, 24 August 2018 2:00 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: Re: XE 99E-DOA: 27/6/2018

Dear Veron,

As spoken, please refer to the after repair photos as we have replaced the gatetail and the sidegate.

Regards,

Adeline Lee

Lee Kuan Hwa Motor Service

Tel: 6269 9192 Fax: 6269 2239

H/P: 9028 8798

From: Veron Chen (LKKAuto)

Sent: Thursday, August 23, 2018 9:04 AM

To: kuanhwa@singnet.com.sg

Subject: RE: XE 99E-DOA: 27/6/2018

Dear Adeline,

Offer Lump Sum \$17,400 before excess \$1500 @ 8 working days.

Kindly check and confirm.

Please provides us towing receipt.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 23 July 2018 9:46 AM

To: Sathya Sai (LKK Auto) < Sathya Sai@lkkauto.com>

Subject: FW: XE 99E-DOA: 27/6/2018

Dear Sathya,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kuanhwa@singnet.com.sg <kuanhwa@singnet.com.sg>

Sent: Friday, 20 July 2018 2:31 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: Re: XE 99E-DOA: 27/6/2018

Dear Veron,

As spoken, my calculation is of lump repair is \$22,200.00 before excess.

Kindly please confirm.

Thank you.

Regards, Adeline Lee Lee Kuan Hwa Motor Service Tel: 6269 9192 Fax: 6269 2239

H/P: 9028 8798

From: Veron Chen (LKKAuto)

Sent: Monday, July 09, 2018 12:51 PM

To: kuanhwa@singnet.com.sg

Cc: SUR

Subject: XE 99E-DOA: 27/6/2018

Dear Adeline,

As instructed by our client, please proceed to repair the insured vehicle XE 99E on Lump Sum Repair (Excess \$1500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adi Assigned	Adl Rot	At	di Submitted	Ins Auth'ed	Status
Main	02 Jul 2018 10:47 Sendback Est	02 Jul 2018 12:21 \$\$29,264.15	02 Jul 2018 14:21 Edit Adj Rpt	S\$18,300 Edit Estim	.00 S	\$18,300.00 View Rpt		Pending for Survey Report Cancel Case
5upp ≇1	03 Sep 2018 11:50	03 Sep 2018 11:54 \$\$402.50	03 Sep 2018 11:54				(Combined)	Combined with Main Uncombine Suppl.
	Main	Refer	ence	Ciaim	Details		Documents	Show All
CLATM S	UBFOLDER DETA	TLS						
Insured:	and the second s	RANES PTE.LTD.	Co. Reg. No.: 20	01129107C				
Vehicle Re No.:	XE99E			Dat	e of Loss:	27/06/2018 ([45 Months a		A Reg Date (Man Yr)]
Claim Typ	e: OD				cy/Cover e No.:	DMCV17S017	843 (Camprehensive	e)
					ess:	S\$1,500.00	1100-11-02-11-02-2	-witte
Repairer:	Lee Kuan Hy	va Motor Service	(Sungei Kadut)	24 Sungei Ka	dut Street	4, 729050 Sun	gei Kadut - Tel: 626	99192
Handling Insurer:		ince Pte. Ltd. (HC			-			
Adjuster:	11/07/2018		(HQ) - Tel: 6256	-3561 [Ha	ndled by M	tuhammad Na	zril Bin Abdullah)	[Final Rpt due
Adj Asg. Remarks:		OD survey on WP ports not to be rele			consisten	cy of the dama	ges too. 3. Attached	are insured and TP's
ASSOCIA	TED MAIL RECE	IVED					View All	Compose Case Mail
• ERGO_	SG (09/07/2018):	Alert - Adj Manda	ate Approved (S	\$27373.15)	XE99E -	Claim Handle	r: Siti Atikah	
A11 ACC	OCIATED TASKS	a				ormoo T en		constants of prevention
ALL ASS	OCIATED TASKS				-1			New Task Complete
Due Da	te Priority	Type Task Gro	oup Subject	Handler	Assign	ned By C	ompleted On	Created On Done

Page 1 of 3 Merimen e-Claims

Claim Documents

XE99E OD Jun 27 2018 4:00AM [SING LIAN CRANES PTE.LTD] Lee Kuan Hwa Motor Service

Ass	essment Reports		1 per	page V	V
No	Finalized On	Les Kunn Hura Motor Service (Sunnai Vadut)	4 per	Thumbnail	-
1	02/07/16 12:21	Lee Kuan Hwa Motor Service (Sungei Kadut) Repairer Estimates	0	Load HTM	-110
2	03/09/18 11:54	Repairer Estimates Suppl. #1	ŏ	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Prin
1	04/07/18 19:06	Adjuster Immediate Advice	0	Load HTM	
2	06/07/18 09:54	Adjuster Immediate Advice	0	Load HTM	
3	06/07/18 10:39	Adjuster Immediate Advice	0	Load HTM	_
Pho	otos/Images		3 per	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/07/18 10:10	General View	0	Load JPG	V
2	04/07/18 10:10	General View	0	Load JPG	V
3	04/07/18 10:10	General View	0	Load JPG	50
4	04/07/18 10:10	General View	0	Load 3PG	V
5	04/07/18 10:10	General View	0	Load JPG	N.
6	04/07/18 10:10	General View	0	Load JPG	8
7.	04/07/18 10:10	General View	0	Load JPG	V
8	04/07/18 10:10	General View	0	Load 3PG	2
9	04/07/18 10:10	General View	0	Load JPG	W
10:	04/07/18 10:10	General View	0	Load JPG	V
11	04/07/18 10:10	General View	0	Load 3PG	V
12	04/07/18 10:10	General View	0	Load JPG	V
13	04/07/18 10:10	General View	0	Load 3PG	V
14	04/07/18 10:10	General View	0	Load JPG	1
15	04/07/18 10:10	General View	0	Load JPG	V
16	04/07/18 10:10	General View	0	Load JPG	V
17	04/07/18 10:10	General View	0	Load JPG	V
18	04/07/18 10:10	General View	0	Load JPG	V
19	04/07/18 10:10	General View	0	Load 3PG	V
20	04/07/18 10:10	General View	0	Load JPG	V
21	04/07/18 10:10	General View	0	Load JPG	100
22	04/07/18 10:10	General View	0	Load JPG	N.
23	04/07/18 10:10	General View	0	Load JPG	3
24	04/07/18 10:10	General View	0	Load JPG	[A]
		Annaca (Annaca)	8	Load JPG	₩.
25	04/07/18 10:10	General View			_
26	04/07/18 10:10	General View	0	Load JPG	Z
27	04/07/18 10:10	General View	0	Load JPG	V
28	04/07/18 10:10	General View	0	Load JPG	V
29	04/07/18 10:10	General View	0	Load JPG	V
30	04/07/18 10:10	General View	0	Load JPG	N
31	04/07/18 10:10	General View	0	Load JPG	M

Merimen e-Claims Page 2 of 3

Ass	essment Reports		1 per	page V	8
Na	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)	- Indiana	Thumbnail	_
32	04/07/18 10:10	General View	0	Load JPG	
33	04/07/18 10:10	General View	0	Load JPG	N.
34	04/07/18 10:10	General View	0	Load 3PG	V
35	04/07/18 10:10	General View	0	Load JPG	V
36	04/07/18 10:10	General View	0	Load JPG	V
37	04/07/18 10:10	General View	0	Load JPG	V
38	04/07/18 10:10	General View	0	Load JPG	V
39	04/07/18 10:10	General View	0	Load JPG	2
40	04/07/18 10:10	General View	0	Load JPG	Z)
41	04/07/18 10:10	General View	0	Load JPG	3
	GICALVALE SECTION OF	(CLEANING TABLE)	0	in a second con-	(A)
42	04/07/18 10:10	General View		Load JPG	-
43	04/07/18 10:10	General View	0	Load JPG	3
44	04/07/18 10:10	General View	0	Load JPG	V
45	04/07/18 10:10	General View	0	Load JPG	8
46	04/07/18 10:10	General View	0	Load JPG	4
47	04/07/18 10:10	General View	0	Load 3PG	V
48	04/07/18 10:10	General View	0	Load JPG	V
49	04/07/18 10:10	General View	0	Load JPG	V
50	04/07/18 10:10	General View	0	Load JPG	V
51	04/07/18 10:10	General View	0	Load 3PG	V
52	04/07/18 10:10	Chassis Number	0	Load JPG	100
53	04/07/18 10:10	Odometer Reading	0	Load JPG	V
54	24/07/18 10:11	Reinspection Photo	0	Load 3PG	V
55	24/07/18 10:11	Reinspection Photo	0	Load JPG	V
56	24/07/18 10:11	Reinspection Photo	0	Load JPG	V
57	24/07/18 10:11	Reinspection Photo	0	Load JPG	W
58	24/07/18 10:11	Reinspection Photo	0	Load JPG	W
59	24/07/18 10:11	Reinspection Photo	0	Load JPG	V
50	24/07/18 10:11	Reinspection Photo	0	Load JPG	V
61	24/07/18 10:11	Reinspection Photo	0	Load JPG	V
62	24/07/18 10:11	Reinspection Photo	0	Load JPG	3
63	24/07/18:10:11	Reinspection Photo	0	Load JPG	V
64	24/07/18 10:11	Reinspection Photo	0	Load JPG	V
55	12/09/18 15:37	Reinspection Photo	0	Load JPG	3
66	12/09/18 15:37	Reinspection Photo	0	Load 3PG	V
	11	Reinspection Photo	0	Load JPG	₩.
57	12/09/18 15:37	Reinspection Photo		Load JPG	(V)
68	12/09/18 15:37	Keinspection Photo	0	LDag JPG	(A)
Doc	umentation		1 per	page 🔽	V
No	Finalized On	Lee Kuan Hwa Motor Service (Sungei Kadut)		Thumbnall	
1	02/07/18 12:19	ACCIDENT REPORT	0	Load PDF	
Vo	Finalized On	ERGO Insurance Pte. Ltd. (HQ)		Thumbnail	Prin
1	02/07/18 14:05	OI - Singapore Accident Statement	0	Load PDF	
2	02/07/18 14:05	TP - Singapore Accident Statement	0	Load PDF	
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	19/09/18 09:34	Supplementary	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Merimen e-Claims Page 3 of 3

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	V
Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985

Our File No:

CS/EGI18011965/NVD3E2

Date:

19/09/2018

REFERENCE

Date of Loss:

Insured/Claimant:

SING LIAN CRANES PTE.LTD

27/06/2018

Policy No: Nature of Claim: DMCV17S017843

OD

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

XE99E

Make & Model:

ISUZU CYH52T, 15.7 D (M) 09/09/2014 (Man. Year: 2014) Engine No: Chassis No: 6WG1421157

Reg Date:

White

Odometer:

JALCYH52TE7000112 392 km

Colour Engine Capacity:

15681 cc

Market Value/New Car Price: S\$220,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Pre-accident Condition: No

Front Tyre Size: Front Left Side:

295/80 R22.5

Rear Tyre Size:

295/80 R22.5

Front Right Side:

Firenza 5 mm Firenza 5 mm Rear Left Side: Rear Right Side: Linglong 5 mm Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,015.95	19,740.95	5,275.00	21.09
Miscellaneous Items	10.70	10.70	0.00	0.00
Labour	4,640.00	3,170.00	1,470.00	31.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,015.95 19,740.95 10.70 10.70 4,640.00 3,170.00 0.00 0.00 Calculated Gross Total (S\$) 29,666.65 22,921.65	6,745.00	22.74	
Approved Total (Overridden) (S\$)		18,300.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	29,666.65	16,800.00	12,866.65	43.37
+ GST 7.00/7.00% (S\$)	2,076.67	1,176.00	900.67	43,37
Nett Amount (S\$)	31,743.32	17,976.00	13,767.32	43.37

INSPECTION

Date of Assignment:

02/07/2018 Present Location:

Lee Kuan Hwa Motor Service (Sungei

Kadut)

Date Inspected:

03/07/2018 Inspected At:

24 Sungei Kadut Street 4 Singapore 729050

Estimated Period of Repair:

8.0 days

Adjuster Report Page 2 of 4

Adjuster: Muhammad Nazril Bin Abdullah Manager: VERON CHEN

NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Sep 2018)

Parts: N/A ISUZU CYH52T 15.7 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE99E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty F	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear tail gate	Broken	480.00 F	*480.00 F
2	1		*Rear side gate RH	Cracked	480.00 F	*480.00 F
3	5		*Rear side gate hinges	Deformed	200.00 F	*200.00 F
4	1		*Rear bumper	Broken	800.00 F	*800.00 F
5	1		*Rear bumper bracket (2PCS)	Deformed-1pc only	600.00 F	*300.00 F
6	1		*Rear number plate	Dented	15.00 F	*15.00 F
7	2		*Rear number plate lamp	Cracked	60.00 F	*60.00 F
В	1		*Rear lamp	Broken	285.00 F	*285.00 F
9	1		*Rear lamp bracket	Deformed	250.00 F	*250.00 F
10	1		*Rear mudguard	Dented	260.00 F	*260.00 F
11	1		*Rear mudflat	Broken	45.00 F	*45.00 F
12	1		*Rear mudflat bar	Necessary	30.00 F	*30.00 F
13	1		*Rear tyre	Cut	600.00 F	*360.00 FS
14	1		*Rear gear box housing	Dented	9,300.00 F	*5,500.00 F
15	2		*Rear gear box housing arm mounting	Dented	600.00 F	*600.00 F
16	1		*Rear body lower chassis bar	Dented	280.00 F	*280.00 F
17	1		*Rear hydrawlic cyL chassis	Cracked	3,600.00 F	*3,600.00 F
18	4		*Rear hydrawlic pipe	Dented	360.00 F	*360.00 F
19	2		*Rear hydrawlic hose	Deformed	280.00 F	*280.00 F
20	1		*Rear hydrawlic cyL	Broken	1,800.00 F	*1,800.00 F
21	1		*Rear valve Po check	Necessary	290.00 F	*290.00 F
22	4		*Rear hose guide	Deformed	260.00 F	*260.00 F
23	18		*Rear hydraulic oil	Necessary	108.00 F	*108.00 F
24	8		*Rear bolt & nut	Necessary	96.00 F	*96.00 F
25	18		*Rear gear box oil	Necessary	144.00 F	*144.00 F
26	1		*Rear safety lamp	Cracked	180.00 F	*180.00 F
Sup	plemen	tary #1				
27	1		*Rear Tool Box	Damaged	350.00 F	*150.00 F
F=Fm	inchise pe	art. S=Spch	lett.	_		
				Sub Total (S\$)	21,753.00	17,213.00
			+ Margin on L,	N Items 15.00/15.00% (S\$)	3,262.95	2,527.95
				Total Parts (S\$)	25,015.95	19,740.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Misc	cellar	neous Items			
1	1	OD/TP Case (Insurer)		10.70	10.70
			Sub Total (S\$)	10.70	10.70

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	To towing	New	200.00	0.00
2	To wiring	New	80.00	50.00
3	To repair rear body labour	New	680.00	400.00
4	To repair & repair labour	New	600.00	500.00
5	To repair & replace hydraulic , pipe, pump, etc.labour	New	1,200.00	1,000.00
6	To replace gear box housing labour	New	1,200.00	720.00
7	To spray putty	New	680.00	500.00
	Gross Labour Cost (S\$)		4,640.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >