

## Repair Estimate

Date : 26/06/2018

Reference:

Make: CHEVROLET

CRUZE

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SJS 8963A

CHASSIS NO.: KL1JF6961AK518531

ENGINE NO.: F16D34244881

Name of insured .: Liauw Chong Chin

Date of accident.: 19/06/2018

*not attached  
also  
2/6/18  
Sdy.  
2/7/18  
to be paid. Attached -*

We append hereunder the estimated cost of repairs to be carried out to the above vehicle

### Parts

<u>No.</u>	<u>Qty</u>	<u>Part Description</u>	<u>Price (SGD)</u>
<u>1</u>	1	Rear Bumper	20/7/18 1,691.00 ✓
<u>2</u>	1	Rear tow cover	20/7/18 30.00 ✓
<u>3</u>	1	Rear bumper impact beam	850.00 ?
<u>4</u>	4	Reverse sensor	650.00 ?
<u>5</u>	1	Centre Bumper Guide	50.00 ?
<u>6</u>	1	RHRC Bumper Guide	40.00 ✓
<u>7</u>	1	LHRC Bumper Guide	40.00 ✓
<u>8</u>	1	RHR Bumper Guide	30.00 ✓
<u>9</u>	1	LHR Bumper Guide	30.00 ✓
<u>10</u>	1	Rear end panel	750.00 ?
<u>11</u>	1	Rear end panel trim	11 80.00 X
<u>12</u>	1	Rear end panel weather strip	11 190.00 X
<u>13</u>	1	Spare Tyre Panel Board	11 450.00 A
<u>14</u>	1	LHR Tail lamp	11 910.00 X
<u>15</u>	1	RHR Tail lamp	11 910.00 X
<u>16</u>	1	RR Taillamp panel RH	11 300.00 X
<u>17</u>	1	Bootlid	11 1,800.00 X
<u>18</u>	1	Bootlid latch	11 348.00 X
<u>19</u>	1	RH bonnet hinge	11 80.00 X
<u>20</u>	1	Chevrolet lettering	11 65.00 ✓
<u>21</u>	1	Cruze LT lettering	11 65.00 ✓
<u>22</u>	1	Rear Emblem	11 80.00 ✓
<u>23</u>	1	RHR Bootlid Lamp	11 480.00 X
<u>24</u>	1	LHR Bootlid Lamp	11 480.00 X
<u>25</u>	1	Bootlid Garnish	11 180.00 X

Parts Total: \$10,579.00

Less 10%: \$1,057.90

Total : \$9,521.10

## Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair <del>510</del>	2300.00 1650
<u>2</u>	Carry out spray painting on accident affected area. ( Rear Bootlid, Rear bumper, Rear end panel ) <del>450</del>	1200.00 1100
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00 ✓
<u>4</u>	Transfer of parts from old bootlid to new bootlid	11 120.00 X
<u>5</u>	Remove and replace reverse sensor (Labour)	120.00 50
<u>6</u>	To remove and refit cushion upholstery to facilitate repair	100.00 ✓

**Labour Total : \$3,870.00**

## Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>1</u>	Rear Number Plate with holder	11 40.00 X
<b>Other Total :</b>		<b>40.00</b>

Total : \$13,431.10

Gst (7%) : \$940.18

**GRAND TOTAL: \$14,371.28**

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

Ronnie Tan

DID: 6844 1985 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: