

Surveyor

Adnan

ASSIGNMENT (Office)

From (Person)

Yee Pei Li

of

EGI

Date/Time

27/18 @ 2:45pm

Estimated Cost

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 80H

Insured:

GBE 6725C

at Workshop m/s

Green Forest Automobile

Tel:

9271 2214

of

8/kaki Bukit Ave 4 # 05-25 premier

Policy No:

Claim No:

DSMcv1801205/SL/P1

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup>

H.O.D. Endorsement

Date/Time:

2:50pm @ 27/18

Person Contacted:

Chris

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 80H - X

GBE 6725C - X

25/3-

Pending finalize wthn Adnan

lump sum \$3800 Cred: 4090, 51%)

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM80H

Yr Regn:

2012 ^{month}

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mini Cooper

c.c 1598

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

110540

T/Radio: Insured / Std / NI / NA

Eng/No:

WMWSV32000T150808

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/45 R17

R: 205/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 02/07/18

Survey held at

Green forest

Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Ego

RECEIVED 01 APR 2018

Date/Time, File Pass to?



: Preli. Report



: Final Report

1) 114 Typist

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$4

) Photos

) Others

TOTAL

250

Report Format:

Lump Sum / L.B.T (\$

3800/-

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 2 July 2018 2:45 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBE6725C / TP : SLM80H/LKK / DOA : 13/06/2018
Attachments: GBE6725C - SAS.pdf; SLM80H - SAS.pdf; SLM80H - PRS FORM.pdf; Re: SLM 80H & GBE6725C DOA 13/6/18 (DSMCV1801205) (45.5 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **GREEN FOREST AUTOMOBILE PTE LTD**

ADDRESS : 8 KAKI BUKIT AVENUE 4
#05-25 PREMIER @ KAKI BUKIT
SINGAPORE 415875

PERSON TO CONTACT : CHRIS CHAN @ 9271 2214

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Warmest Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247
peili.yee@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 02.07.2018
Our Reference: DSMCV1801205/SL/pl
Your Reference: SLM 80H

Sent via Fax

or

Email

chris_chanbebe@hotmail.com

To: **GREEN FOREST AUTOMOBILE PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: **SLM 80H**
Insured's Vehicle: **GBE 6725C**
Date Of Accident: **13.06.2018**

We acknowledge receipt of your request for PRS on: **29.06.2018**

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☒	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2058H

Vehicle Details

Vehicle No.: SLM80H
Vehicle to be Exported: Yes
Intended De-registration Date: 21 Jun 2018
Vehicle Make: MINI
Vehicle Model: COOPER S 1.6 A
Primary Colour: White
Manufacturing Year: 2011
Engine No.: A419J090N18816A
Chassis No.: WMW5V32000T150808
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$42,496.00
Original Registration Date: 09 Mar 2012
First Registration Date: 09 Mar 2012
Transfer Count: 2
Actual ARF Paid: \$42,496.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Mar 2022
PARF Rebate Amount: \$27,622.00


Intended COE Rebate Details

COE Expiry Date: 08 Mar 2022
COE Category: A - Car (1600cc & below)
COE Period (Years): 10
QP Paid: \$46,889.00
COE Rebate Amount: \$17,391.00
Total Rebate Amount: \$45,013.00

The information contained herein is correct as at 21 Jun 2018.

OK

Handwritten signature and date:
26/6/18
GREGO



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Ee Bee Lay
Period of Insurance : 09 Mar 2018 To 08 Mar 2019
Engine No : A419J030N18B16A
Chassis No : WMW5V32000T150808

Vehicle No. : SLM60H
Policy No. : 1800019767
Endorsement No. : 000000000184933
Issued Date : 07 Mar 2018

NEWTON: GOVER

Make/Model	MINI COOPER S 1.6 [Coupe]				
Engine Capacity/Tonnage	1,538 00 CC	Sum Insured	Market Value	First Year of Registration	2011
Driver Restriction	NA	Off Peak Car	No	Insuring with COE/PAF	Yes

No. and/or Classes of Persons Entitled to Drive:

1. The following are the steps to be followed in the preparation of the final report:

- (a) The first step is to prepare the final report. This is done by the student who has completed the project. The report should be in the form of a paper of 10 pages, double-spaced, with a margin of 1 cm. It should be written in a clear, concise, and logical manner. The report should be written in the first person singular, using the pronoun 'I'.
- (b) The second step is to prepare the final report. This is done by the student who has completed the project. The report should be in the form of a paper of 10 pages, double-spaced, with a margin of 1 cm. It should be written in a clear, concise, and logical manner. The report should be written in the first person singular, using the pronoun 'I'.
- (c) The third step is to prepare the final report. This is done by the student who has completed the project. The report should be in the form of a paper of 10 pages, double-spaced, with a margin of 1 cm. It should be written in a clear, concise, and logical manner. The report should be written in the first person singular, using the pronoun 'I'.

Age Condition	All Age Condition
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

Leontator 'is to use'

Limitation: 35 to 500

15 JUL 1992

and the vehicle was supported by Section 9 of the Motor Vehicle Third-Party Injury and Compensation Act (Cap. 184) and Section 66 of the Road Transport Act 1987 (Amended) in the Eastern District of London (1992/1993).

150355

Section 1
East - 1000 ft. - 1000 ft. - 1000 ft. - 1000 ft.

Section 2
 Copyright Clearance Center 50Wang et al. • *CaMKII α* in the Adult Brain
J. Neurosci., September 24, 2008 • 28(39):9785–9795 • 9795

Named Driver and Excess

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

[illegible]

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan NA

1. In the early 1990s, the rate of policy to which B-5000 (a joint insurance company) is subject is shown in the following table. The table shows the rate of policy to which B-5000 is subject in the early 1990s, the rate of policy to which B-5000 is subject in the early 1990s, and the rate of policy to which B-5000 is subject in the early 1990s.

000161-0000

NORTHSHORE INSURANCE AGENCY

5000141 3/31/89 12 TRADES 21

[illegible]

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

STAFF



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8930197A



TAN KUAN YU
(CHEN GUANYU)
陈冠宇
Race
CHINESE
Date of birth
26-08-1989
Sex
M
Country of birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

S8930197A

TAN KUAN YU
(CHEN GUANYU)

Valid from 25 Aug 1989
Valid until 24 Feb 2012



90613829



NRIC No. S8930197A



Date of issue
27-09-2004


Address
80 LORONG MELAYU
SINGAPORE 416987

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 24 Feb 2012

NP 428A



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

TP Ego

Denise

EE BEE LAY
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

28th June 2018

WMWSV32000T150808

Accident date: 13th June 2018

Estimated repair cost for vehicle no: SLM80H MINI COOPER 1.6 AT '11

S/n	Qty	Items	U/price	Amount
1	1	bonnet <i>Repair</i>		\$1,250.00 x
2	1	Front headlamp-LH <i>cracked</i>		\$950.00 ✓
3	1	Front Grille <i>cracked</i>		\$450.00 ✓ 326.
4	1	Front grille chrome garnish <i>lt</i>		\$240.00 ✓ 163.
5	1	Front bumper fog lamp-LH <i>new</i>		\$481.00 x
6	1	front bumper fog lamp cover -LH <i>new</i>		\$156.00 x
7	1	Front bumper <i>Defend</i>		\$950.00 ✓
8	1	Front bumper reinforcement <i>new</i>		\$550.00 x
9	1	front Bumper lower grille <i>cracked</i>		\$310.00 ✓
10	2	Front bumper side bracket <i>new</i>	\$65.00	\$130.00 x
11	1	Front bumper lower garnish <i>cracked</i>		\$380.00 ✓ 244
12	10	Front bumper clips <i>new</i>	\$5.00	\$50.00 30.

Labour charges
To Check Wiring System

Panel beating

Spray painting

Subtotal :- \$5,867.00

~~\$80.00~~ 30

~~\$600.00~~ 250

~~\$600.00~~ 400

Subtotal :- \$1,280.00

Total:- \$7,147.00

total 3355.70

L/S: 2.6K

04 days

SK

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

TP Ergo
Denise

EE BEE LAY
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

28th JUNE 2018

WMWSV32000T150808

Accident date: 13th JUNE 2018

Estimated repair cost for vehicle no: SLM80H MINI COOPER 1.6 '11

S/n	Qty	Items	U/price	Amount
1	1	head lamp -LH <i>cracked</i>		\$1,150.00 ✓
2	1	front emble logo <i>new</i>		\$60.00 ✓
3	1	Front grille <i>cracked</i>		\$450.00 ✓
4	1	Front grille chrome garnish <i>wt</i>		\$250.00 ✓
5	1	Front Bumper <i>delam</i>		\$1,450.00 1245
6	1	Front Bumper Reinforcement <i>Best</i>		\$850.00 496
7	1	front footwell module <i>new</i>		\$1,250.00 +
8	1	front bumper spoiler (centre) <i>cracked</i>		\$250.00 ✓
9	2	fog lamp with position light <i>cracked</i>	\$460.00	\$920.00 358

Subtotal :- \$6,630.00

Labour charges

To Check Wiring System

~~\$60.00~~ 30

To Panel Beating

780

~~\$600.00~~ 250

To Spray Painting

~~\$600.00~~ 500

Subtotal :- \$1,260.00

Total :- \$7,890.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4826.05

2/S: 3.8K

04 Dup



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18011968/Atd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 02-04-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 6725C	Veh. Inspected	SLM 80H	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1801205/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	02/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WMWSV32000T150808	Colour	WHITE	
Odometer	110540	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	MICHELIN	6 mm	
L/H Front Tyre	205/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	205/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	205/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2018	Inspection Date	02/07/2018	
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 80H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEAD LAMP-LH	CRACKED	1,150.00	1,150.00
1	FRONT EMBLEM LOGO	NECESSARY	60.00	60.00
1	FRONT GRILLE	CRACKED	450.00	450.00
1	FRONT GRILLE CHROME GARNISH	CUT	250.00	250.00
1	FRONT BUMPER	DEFORMED	1,450.00	1,245.00
1	FRONT BUMPER REINFORCEMENT	BENT	850.00	496.00
1	FRONT FOOTWELL MODULE	NOT NECESSARY	1,250.00	-
1	FRONT BUMPER SPOILER (CENTRE)	CRACKED	250.00	250.00
2	FOG LAMP WITH POSITION LIGHT @\$460.00	CRACKED	920.00	358.00
	LESS 5% DISCOUNT		-	-212.95
			6,630.00	4,046.05
	LABOUR			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TO PANEL BEATING.		600.00	250.00
	TO SPRAY PAINTING.		600.00	500.00
			1,260.00	780.00
	GRAND TOTAL		7,890.00	4,826.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS/EGI18011968/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.