

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1052M
Ref. No : TAX/06/18/2125
Reg. Date : 15/11/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : ANDIN NUR SHA BAN
MARJUNI SAMAN
Type of Accident : SIDE SWIPE
Date / Time of Accident : 26/06/2018 03:30:00 PM
Accident Reported Date / Time : 27/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 26/06/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096742
Special Instruction to ARC, if any :
TOWED \$40 / GBH2120H
Prepared Date : 27/06/2018 02:05:42 PM



Sathya Sai
29/6/2018

Sathya Sai @lkkauto.com

- Lump Sum Repair
- Question mark item
- Photo after Paint.

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U50-5706535

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 2,637.86	2,637.86
Other Charges	: 516.00	0.00
TOTAL	: 5,492.86	0.00
Lum Sum Total	: 5,500.00	0.00
No. of Repair Days	: 5.00	0.00 <i>3 days</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 27/06/2018 02:58:33 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/06/2018 02:57:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/27/2018 2:58:45 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	845.00	0.00 600
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 X
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,494.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 40
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	516.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR ✓CRK	1	458.60	25.00	343.95	Replace	Replace	No
52161-16010			BUMPER CLIPS ✓NEC	10	1.61	25.00	12.07	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH X	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR X	1	228.90	25.00	171.67	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR ?	1	205.70	25.00	154.27	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH ?	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE ?	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER ✓NEC	2	60.00	0.00	120.00	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH ?	1	94.80	25.00	71.10	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH X	1	94.80	25.00	71.10	Replace	Replace	No
67005-47241			TAILGATE ASY X	1	1,007.90	25.00	755.92	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) X	1	51.90	25.00	38.92	Replace	Replace	No
58307-47060		6505522	END PANEL ?	1	602.10	25.00	451.57	Replace	Replace	No
52562-47010			TAIL LAMP BRACKET, RH X	1	30.70	25.00	23.02	Replace	Replace	No
61604-47090			FENDER RR/RH R	1	766.80	25.00	575.10	Replace	Replace	No
	COMMON		SMRT LOGO ✓NEC	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 ✓NEC	1	21.60	0.00	21.60	Replace	Replace	No
35637-47021		6505480	FENDER LINER RR/RH X	1	141.30	25.00	105.97	Replace	Replace	No
TOTAL MATERIALS								3,297.38	3,297.33	
TOTAL MATERIALS(Discounted)							2,637.86	2,637.86		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									