



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007253
INV Date 02/11/2020
Reference CC6/CTI18011978/Aea3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLA 1900Z
Insured Veh. GBG 9360R
Claim No. SNM18D03208/C01/0
Policy No. DMCVSN3009161800
Accident Date 26/06/2018
Inspection Date 28/06/2018

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18011978/Aea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-------------------|----------------|------------|
| Insured Veh. | GBG 9360R | Veh. Inspected | SLA 1900Z |
| Policy No. | DMCVSN3009161800 | Coverage (\$) | 0.00 |
| Claim No. | SNM18D03208/C01/0 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 28/06/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | TOYOTA ALTIS | c.c | 1598 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | MR053REH104541111 | Colour | GREY |
| Odometer | 60720 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 205/55 R16 | MICHELIN | 6 mm |
| L/H Front Tyre | 205/55 R16 | MICHELIN | 6 mm |
| R/H Rear Tyre | 205/55 R16 | MICHELIN | 6 mm |
| L/H Rear Tyre | 205/55 R16 | MICHELIN | 6 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 26/06/2018 | Inspection Date | 28/06/2018 |
| Survey held at | MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933 | | |

5a. Remarks

| |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1900Z

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | BONNET | BENT | 1,269.80 | 1,028.10 |
| 1 | FRONT BUMPER | DEFORMED | 594.00 | 594.00 |
| 2 | FRONT BUMPER SIDE RETAINER @\$55.00 | O/S NECESSARY | 110.00 | 55.00 |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | 365.00 | - |
| 1 | FRONT BUMPER REINFORCEMENT SPONGE | NOT NECESSARY | 180.00 | - |
| 1 | FRONT GRILLE | CRACKED | 290.00 | 290.00 |
| 1 | FRONT BUMPER LOWER GRILLE | NOT NECESSARY | 190.00 | - |
| 1 | FRONT GRILLE LOGO | NECESSARY | 45.00 | 45.00 |
| 1 | FRONT BUMPER FOGLAMP | NOT NECESSARY | 380.00 | - |
| 1 | FRONT BUMPER FOGLAMP GARNISH | NOT NECESSARY | 160.20 | - |
| 2 | FRONT HEADLAMP @\$515.00 | CRACKED | 1,030.00 | 1,030.00 |
| 1 | FRONT HEADLAMP LOWER BRACKET | NOT NECESSARY | 52.00 | - |
| 1 | FRONT FENDER | DENTED | 688.90 | 688.90 |
| 1 | FRONT FENDER EMBLEM "VVT-I" | NECESSARY | 63.20 | 63.20 |
| 1 | FRONT WHEEL HOUSE PANEL | NOT NECESSARY | 523.10 | - |
| 1 | FRONT FENDER INNER COWLING | TORN | 230.00 | 182.40 |
| 1 | FRONT SUPPORT PANEL | TO REPAIR SEE LABOUR | 1,733.00 | - |
| 1 | FRONT WIPER WASHER TANK (UPPER) | NOT NECESSARY | 176.00 | - |
| 1 | FRONT WIPER WASHER TANK (LOWER) | NOT NECESSARY | 295.00 | - |
| 1 | FRONT WIPER WASHER TANK MOTOR | NOT NECESSARY | 235.00 | - |
| | LESS 25% DISCOUNT | | -2,152.55 | -994.15 |
| | | | 6,457.65 | 2,982.45 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | REAR NUMBER PLATE (SN) | NOT NECESSARY | 50.00 | - |
| 1 | SETS HEADLAMP CLIP (SN) | NECESSARY | 20.00 | 20.00 |
| 1 | SET FRONT BUMPER CLIPS (SN) | NECESSARY | 20.00 | 20.00 |
| 1 | SET FRONT FENDER COWLING CLIPS (SN) | NECESSARY | 20.00 | 20.00 |
| 1 | FRONT WHEEL TYRE (SN) | NOT NECESSARY | 350.00 | - |

Report Ref No. CC6/CTI18011978/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| 1 | SET FRONT WHEEL RIM (SN) | NOT NECESSARY | 850.00 | - |
| | | | 1,310.00 | 60.00 |
| | LABOUR | | | |
| | TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL. | | 1,400.00 | 600.00 |
| | TO SPRAY PAINT AFFECTED AREA. | | 1,400.00 | 800.00 |
| | TUFF COAT. | NOT NECESSARY | 250.00 | - |
| | WIRING AND BULB CHECKING. | | 120.00 | 30.00 |
| | REMOVE AND REFIX FRONT UNDERCARRIAGE. | NOT NECESSARY | 350.00 | - |
| | FOUR WHEEL ALIGNMENT. | NOT NECESSARY | 100.00 | - |
| | | | 3,620.00 | 1,430.00 |
| GRAND TOTAL | | | 11,387.65 | 4,472.45 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 3,500.00 |

Report Ref No. CC6/CT118011978/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 1900Z

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 1900Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

