



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Lua Sheng Long (Lai Shenglong) Blk 220 Choa Chu Kang Central #06-268 Singapore 680220 Contact No	Cust No/Name	LCV04693/Mr Lua Sheng Long (Lai Shenglong)
	Reg No/Reg Date	SLW5641D / 22/02/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5764446
	Engine No	G4FGJH694993
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV04693	CRDVCH	02/06/2018/ 09:54	TLC	442 / CocoLu	29658		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1375 1650.00
TO RENEW FRT AIRDAM, FRT FENDER LH, REPAIR FRT BUMPER							
E PNT98000							1260 1680.00
TO SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, FRT FENDER LH							
E PNT88000							60 100.00
TO REMOVE & INSTALL FRT AIRDAM							
M SUNDRY							20.00
Sundry							
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M PANEL-FENDER,LH				1.00	396.00	00.00	396.00
M NEW K3 METAL STREAM MST				1.00	1177.00	00.00	1177.00
M GUARD ASSY-FRONT WHEEL,LH				1.00	95.00	00.00	95.00
M LAMP ASSY-HEAD,LH				1.00	2209.00	00.00	2209.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hy 90010068
6 days
03/07/18 @ 1616
Resury by paint

Estimate

Rasul
Hy 90010068
6 days
03/07/18 @ 1616
Repair by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by

	Nett	7,447.00
7% GST on	7447.00	521.29
Total Payable		7,968.29

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.