

HONG NAN MOTOR AGENCY

316 Lavender Street Singapore 338818
Tel : 62998439 / 62995271 Fax : 62993487

EQ Insurance Company Ltd

Attn : Motor Insurance Dept (Third Party Claim)

Dear Sir / Madam ,

Re : Accident involving with GBD1602L (your insured) & AP33J on 12.05.2018

4 Days -
lump sum repair.
After repair photos.
Guo Qiang - 82880282
29/6/18

Repair Cost

Handle bar / BT ?	\$ 457.50
Left brake master pump ?	\$ 285.00
Left brake lever / cut ?	\$ 52.50
Front brake disc - right ?	\$ 390.00
Meter assy complete / CRA	\$ 1,080.00
Instrument group cover / CRA	\$ 195.00
Front fork & under bracket assy ?	\$ 1,598.00
Steering cone upper set ?	\$ 47.50
Lower steering bearing cone ?	\$ 96.00
Front left turn indicator assy / CRA.	\$ 78.00
Front shield - top crowling / cut	\$ 385.00
Front lower shield / cut	\$ 265.00
Top visor lid / CRA	\$ 185.00
Right centre lid / cut	\$ 180.00
Left deflector / mis.	\$ 180.00
Right deflector / mis.	\$ 187.50
Right centre lid cover X NN	\$ 187.50
Left centre lid cover / mis.	\$ 85.00
Upper handle bar cover / re	\$ 85.00
Handle bar centre cover X NN	\$ 195.00
Front mudguard / cut	\$ 120.00
Wheel compartment cover front R - CRA.	\$ 220.00
Front dashboard assy / CRA	\$ 185.00
Left dashboard door / cut	\$ 385.00
Right dashboard door X NN	\$ 58.00
Right dashboard door lid / BR.	\$ 58.00
Left dashboard door lid / BR.	\$ 28.00
Dashboard corner cover right ?	\$ 28.00

Dashboard corner cover left ?	\$	45.00
Dash front left cover / mis	\$	45.00
Dash front right cover / mis	\$	38.00
Dash button panel	\$	38.00
Dash button panel - Re	\$	382.50
Exhaust pipe complete assy ?	\$	980.00
Head lamp stay ?	\$	198.00
Left floor board bracket ?	\$	154.50
Windscreen - CRA	\$	800.00
Front dashboard cover - Cut	\$	128.00
Front meter dash cover - Cut	\$	165.00
Front glove compartment - CRA	\$	280.00
Left central side cover - Cut	\$	180.00
Left step board - Cut	\$	260.00
Centre console lid ?	\$	155.00
Left pillion step board - Cut	\$	45.00
Right rider step board - Cut	\$	85.00
Right pillion step rubber - Cut	\$	35.00
Right pillion step rubber button - MC	\$	5.00
Left spoiler X / Cut	\$	295.00
Right spoiler X / Cut	\$	295.00
Right side cover - CRA	\$	330.00
Right side cover guard - Cut	\$	165.00
Right side cover top cover - CRA	\$	180.00
Right pillion grab bar top - Cut	\$	62.00
Right pillion grab bar bottom - Cut	\$	99.00
Tail light center cover - Re	\$	80.00
Left side cover guard - Cut	\$	165.00
Left side cover top cover - CRA	\$	180.00
Tail right light assy - CRA	\$	384.00
	\$	13,550.50
Less : 10%	\$	(1,355.05)
	\$	12,195.45

Add :

Transport - 2 way	\$	120.00	80
Front number plate	\$	15.00	10
Alignment	\$	150.00	40
Fixing & Removal Labour	\$	850.00	450
Total	\$	13,330.45	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: