

HONG NAN MOTOR AGENCY

316 Lavender Street Singapore 338818
Tel : 62998439 / 62995271 Fax : 62993487

EQ Insurance Company Ltd

Attn : Motor Insurance Dept (Third Party Claim)

Dear Sir / Madam ,

Re : Accident involving with GBD1602L (your insured) & AP33J on 12.05.2018

Repair Cost

Handle bar	\$	457.50
Left brake master pump	\$	285.00
Left brake lever	\$	52.50
Front brake disc - right	\$	390.00
Meter assy complete	\$	1,080.00
Instrument group cover	\$	195.00
Front fork & under bracket assy	\$	1,598.00
Steering come upper set	\$	47.50
Lower steering bearing cone	\$	96.00
Front left turn indicator assy	\$	78.00
Front shield - top crowling	\$	385.00
Front lower shield	\$	265.00
Top visor lid	\$	185.00
Right centre lid	\$	180.00
Left deflector	\$	180.00
Right deflector	\$	187.50
Right centre lid cover	\$	187.50
Left centre lid cover	\$	85.00
Upper handle bar cover	\$	85.00
Handle bar centre cover	\$	195.00
Front mudguard	\$	120.00
Wheel compartment cover front	\$	220.00
Front dashboard assy	\$	185.00
Left dashboard door	\$	385.00
Right dashboard door	\$	58.00
Right dashboard door lid	\$	58.00
Left dashboard door lid	\$	28.00
Dashboard corner cover right	\$	28.00

Dashboard corner cover left	\$	45.00
Dash front left cover	\$	45.00
Dash front right cover	\$	38.00
Dash button panel	\$	38.00
Dash button panel	\$	382.50
Exhaust pipe complete assy	\$	980.00
Head lamp stay	\$	198.00
Left floor board bracket	\$	154.50
Windscreen	\$	800.00
Front dashboard cover	\$	128.00
Front meter dash cover	\$	165.00
Front glove compartment	\$	280.00
Left central side cover	\$	180.00
Left step board	\$	260.00
Centre console lid	\$	155.00
Left pillion step board	\$	45.00
Right rider step board	\$	85.00
Right pillion step rubber	\$	35.00
Right pillion step rubber button	\$	5.00
Left spoiler	\$	295.00
Right spoiler	\$	295.00
Right side cover	\$	330.00
Right side cover guard	\$	165.00
Right side cover top cover	\$	180.00
Right pillion grab bar top	\$	62.00
Right pillion grab bar bottom	\$	99.00
Tail light center cover	\$	80.00
Left side cover guard	\$	165.00
Left side cover top cover	\$	180.00
Tail right light assy	\$	384.00
	\$	<u>13,550.50</u>
Less : 10%	\$	<u>(1,355.05)</u>
	\$	12,195.45
Add :		
Transport - 2 way	\$	120.00
Front number plate	\$	15.00
Alignment	\$	150.00
Fixing & Removal Labour	\$	850.00
Total	\$	<u><u>13,330.45</u></u>

Thx

pauline
22.05.2018

NOTE : Pls kindly send your surveyor to my workshop