

INS. CASE OWNER:

CC 6 /CTI1801

LKK:

IDAC

Surveyor

DOI:

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. _____

Name of Insured

Insured Tel No.

Excess Sec II :S8

Is driver the owner?

If **NO**, Driver Name / Age :

Driver Tel No. :

HP:

DQA:

Nature of Accident :

PLENB.

(V/L: YES / NO)

Claim No.

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES/ NO : TP GIA REPORT: YES / NO

Insured Liability :	%	Final ? Yes / No
---------------------	---	------------------



INRS
WSP:
Tel :
Liability
RMKS



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE/ PIC
7/7/18 JMY	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
13-9-18 FOR MANDATE	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI	☐
	Authorisation To Act	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice	☐
	Towing Invoice	☐
	LTA / GIA :	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: S\$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability: %	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia :
Repair Cost: S\$		
Loss of Rental (LOR): S\$	(days)	
Loss of Use (LOU): S\$	(\$ 200x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search S\$		
Medical: S\$		
Disbursement: S\$	(e.g. Tow/ Independent)	
Legal Cost S\$		
Total: S\$	Global Sum S\$:	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: S\$	Name 1:	
Payee 2: (Strike if N.A.) S\$	Name 2:	
Payee 3: (Strike if N.A.) S\$	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18011986/jb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-07-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKX 6202M	Veh. Inspected	PC 2003Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/04/2018	Inspection Date	
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD #03-01 SINGAPORE 758133		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI18011986/Vjb3

Date: 09.07.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

PC2003Z


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.07.2018 at the premises of M/s SC Auto Industries (S) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,525.00
Revised Estimate Amount	: S\$	2,680.25
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

SATHYA SAI
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 2 July 2018 5:17 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SKX6202M (OI : CTI - SNM18D02357C02) and PC2003Z (TP : LKK REF -CC6/CTI18011986/jb3) on 16.04.2018
Attachments: leeSZ_SNM18D02357C01-SKX6202M-LKKDirectSettlementAccidentLtr_CLCR95.095.pdf; MJAS18060645-01-SKX6202M.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 2 July, 2018 4:23 PM
To: Claims Dept of CTI
Cc: Angie Foo; Sharon Han; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving SKX6202M (OI : CTI - TBA) and PC2003Z (TP : LKK REF - CC6/CTI18011986/jb3) on 16.04.2018

WITHOUT PREJUDICE

Dear Sharon,

We refer to the above matter.

This is a TP direct settlement case from M/s SC Auto Industries (S) Pte Ltd.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair

Please be informed that preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409 .

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02357/C01/2**

Date : **02 JULY 2018**

via Ordinary & Registered Mail

**BLUE STAR CONCIERGE PTE LTD
NO 12 LITTLE ROAD
#05-02 LIAN CHEONG INDUSTRIAL BUILDING
SINGAPORE 536986**

Dear Sir / Madam

**ACCIDENT INVOLVING SKX6202M AND PC2003Z ON 16 APRIL 2018
ALONG PANDAN ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **PC2003Z**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY

Ref : CC6/CTI18011986/JB3

Contact No : 68412409

via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0435A) - YETTA INSURANCE AGENCY PTE LTD

F01/LKKDS-2013



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 750133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S KHIM SEAH ENTERPRISE PTE LTD
NO 71 WOODLANDS IND PARK E9
#06-08 WAVE 9
SINGAPORE 757048
Insured KHIM SEAH ENTERPRISE PTE LTD
Policy VFX/P0902358/00259

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 23/6/2018
Our Case Ref. SC18/06/116/4KS-TP
Accident Date 16/4/2018

Damaged Vehicle No: PC2003Z

S/no	Description	QTY	Price	Disc	Amount
------	-------------	-----	-------	------	--------

Replaced Parts

1	ARTWORK X NN	1 ST	\$350.00	-	\$350.00
2	EXCURSION BUS STICKER X NN	1 PC	\$15.00	-	\$15.00
3.	RHS Headlamp ✓scr	1 pc	893.67	25%	670.25

Labour Charges

1	LABOUR FOR RHS FRONT PORTION ✓	1	\$2,560.00 1280		\$2,560.00
2	SPRAY PAINTING ✓	1	\$1,600.00 700		\$1,600.00
3.	Labour for wiring ✓		30.00		

Sathya Sai
5/7/2018

- Part by Part
- Photo before paint

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5448.67

Sub Total

\$ 4,525.00

Authorised Signature



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S KHIM SEAH ENTERPRISE PTE LTD
NO 71 WOODLANDS IND PARK E9
#06-08 WAVE 9
SINGAPORE 757048
Insured KHIM SEAH ENTERPRISE PTE LTD
Policy VFX/P0902358/00259

Final Bill

GST Reg. No: 19-9800107D
Date: 7/7/2018
Our Case Ref. SC18/06/116/4KS-TP
Accident Date 16/4/2018

Damaged Vehicle No: PC2003Z

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	RHS HEADLAMP	1 PC	\$893.67	25.00%	\$670.25
<u>Labour Charges</u>					
1	LABOUR FOR RHS FRONT PORTION	1	\$1,280.00	-	\$1,280.00
2	LABOUR FOR WIRING	1	\$30.00	-	\$30.00
3	SPRAY PAINTING	1	\$700.00	-	\$700.00
Sub Total					\$ 2,680.25
GST (7%)					\$ 187.62
Total Amount					\$ 2,867.87

Authorised Signature

670.25
+ 1280.00
+ 30.00
+ 700.00

2680.25 @ 3 days

confirmed.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18011986/Vjb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 6202M	Veh. Inspected	PC 2003Z
Policy No.	DMHCSN1632341701	Coverage (\$)	0.00
Claim No.	SNM18D02357/C01/2	Excess (\$)	0.00
Assign From		Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COASTER	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTGEP538206000792	Colour	WHITE
Odometer	122553	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/75 R17	FIRENZA	6 mm
L/H Front Tyre	215/75 R17	FIRENZA	6 mm
R/H Rear Tyre	215/75 R17	FALKEN	6 mm
L/H Rear Tyre	215/75 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/04/2018	Inspection Date	05/07/2018
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD #03-01 SINGAPORE 758133		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2003Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RHS HEADLAMP	SCRATCHED	893.67	893.67
	LESS 25% DISCOUNT		-	-223.42
			893.67	670.25
<u>SPECIAL NETT ITEMS</u>				
1	ST ARTWORK (SN)	NOT NECESSARY	350.00	-
1	EXCURSION BUS STICKER (SN)	NOT NECESSARY	15.00	-
			365.00	-
<u>LABOUR</u>				
	LABOUR FOR RHS FRONT PORTION .		2,560.00	1,280.00
	SPRAY PAINTING.		1,600.00	700.00
	LABOUR FOR WIRING.		30.00	30.00
			4,190.00	2,010.00
GRAND TOTAL			5,448.67	2,680.25
RECOMMENDED COST OF REPAIRS				2,680.25

Report Ref No. CC6/CT118011986/Vjb3n2

SATHYA SAI KATHIRASEN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.