

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
TEL: 6458 2283 FAX: 6459 8863
EMAIL: kayautosg@yahoo.com

Merdeka Construction Co Pte Ltd

4 July 2018

Estimate To Repair Isuzu Lorry – YN 5384P

1pc	rear tail board
1pc	n/s rear tail lamp
1pc	o/s rear tail lamp
1pc	rear hook

less 20%

1pc	rear bumper beam
1set	bolt & screw
1pc	'60km/h' sticker
1pc	'20pax' sticker
1pc	rear number plate

To knock out dents & reweld rear end trim,
rear chassis, dismantle & fit the above parts.
To putty & spray painting

*Not Authorise
11 Lorry @?
Resurvey After Paint
3 days*

B	\$ 2,290.00	✓
CM	328.00	✓
LM	328.00	X
N	189.00	X

3135.00
627.00

	2508.00	
B	650.00 sn	✓
N	80.00 sn	4000
MC	15.00 sn	✓
N	15.00 sn	✓
LM	25.00 sn	X

750.00 5000
600.00 4000

Total : \$ 4,648.00

(Dollars Four Thousand Six Hundred Forty Eight Only)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: