

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not Allocated
date
2/5/18
2/7/18
Tel: 62898126

2/7/2018

M/S 716.

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLV2098Y

	NETT ITEM			
01)	1 PC	REAR BUMPER	DIS	\$ 532.40
02)	10 PCS	REAR BUMPER CLIPS	na	\$ 35.00
03)	1 PC	REAR BUMPER SIDE RETAINER LH BIG	Ref	\$ 36.30
04)	1 PC	REAR BUMPER SIDE RETAINER LH SMALL	Ref	\$ 36.30
05)	1 PC	REAR BUMPER SPONGE	11	\$ 37.00
06)	1 PC	REAR LAMP	11 220	\$ 279.00
07)	1 PC	REAR LH MUDGUARD	11	\$ 1,004.70
08)	1 PC	REAR LH MUDGUARD INNER SHIELD	11	\$ 17.60
09)	1 PC	REAR BOOT LID	11	\$ 787.50
10)	1 PC	REAR BOOT LID "LATIO" EMBLEM	11	\$ 80.90
11)	1 PC	REAR BOOT LID LOGO	11	\$ 59.70
12)	1 PC	REAR BOOT RUBBER	11	\$ 88.40
13)	1 PC	REAR PANEL		\$ 434.40
				\$ 3,429.20
			Less 10%	\$ (342.92)
				\$ 3,086.28
14)	1 PC	REVERSE SENSOR	shut	\$ 250.00
15)	1 PC	REAR END PANEL SEALANT		\$ 50.00
				\$ 300.00
16)		SPRAY PAINTING		\$ 1,100.00
17)		TO REMOVE AND REFIX CUSHION		\$ 120.00
18)		TUFF COAT		\$ 80.00
19)		CHECK WIRING		\$ 30.00
20)		REMOVE AND RENEW REVERSE SENSOR		\$ 80.00
21)		LABOUR CHARGE TO REMOVE AND RENEW PARTS		\$ 880.00
				\$ 2,290.00
			NETT TOTAL	\$ 5,676.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: