

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

02 JUL 2018

Estimate No. : b1 47502
Date Estimated : 02/07/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lai Mun Chiew
63 Hume Avenue
#05-05

singapore 598742

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDB8890L	J200784	30/04/2012	116iA/5	0

DESCRIPTION

To replace rear bumper & attachments including to knock out boot lid and dented area caused by the accident

850 2,550.00

To respray rear bumper and boot lid *

934 1,923.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To supply rear emboss number plate.

bt 83.00

Sundries.

? 80.00

Total Labour 1: 4,990.00

DESCRIPTION

REAR BUMPER CARRIER
RR BUMPER CENTER GUIDE
RR BUMPER RH SIDE GUIDE
DECORATIVE STRIP (LINE URBAN)
FLAP TOWING EYE PRIMED
REAR BUMPER PRIMED (LINES)
SET MOUNTS PDC SENSOR REAR
EMBLEM GROMMET
HEAT INSULATOR REAR SILENCER
PLAQUE 82MM
NUMBER PLATE LIGHT LED
DECOUPLING RING PDC TORQUE CONVERTER
RR PDC SENSOR ALPINWEISS (30)
(DG/SL) ADHESIVE SET K6

QTY	PRIC	VALUE
1	385.25	? 385.25
1	56.85	? 56.85
1	47.85	? 47.85
1	122.50	? 122.50
1	38.00	de 38.00
1	902.20	de 902.20
1	62.95	? 62.95
2	0.80	x 1.60
1	33.25	? 33.25
1	69.50	x 69.50
2	23.20	? 46.40
2	5.05	? 10.10
2	368.80	? 737.60
1	53.05	de 53.05

Total Parts : 2,567.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47502
Date Estimated : 02/07/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDB8890L	J200784	30/04/2012	116iA/5	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 16/7/15 1040 Excess \$5

Surveyor's Name Tanjun Sgn _____

Surveyor's Tel 97495749 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PML/C&B? SURVEYOR No PML Yes / No

Surveyor's E-mail tanjun @ lkkauto.com

No. of Working Days Recommend 3 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,990.00
Parts	:	2,567.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	529.00
Grand Total	:	8,086.10

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **