

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18008384/BSBE2-1

Date: 18/07/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 10118175

Claimant Vehicle No : GBE6343X

Insured Vehicle No : SDW2188K

Date of Loss: 03/05/2018

Nature of Claim: TP Claim No: 557553

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE6343X**

Make &amp; Model: NISSAN NV200, 1.5 D ABS AIRBAG 2WD 6DR (M)

Engine No: K9KC400D055195

Reg. Date: 30/01/2016 (Man. Year: 2015)

Chassis No: VSKYBAM20Z0120148

Colour: Silver

Odometer: 67595 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size: 205/55Z R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,382.60	997.91	4,384.69	81.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	910.00	1,060.00	53.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,352.60</b>	<b>1,907.91</b>	<b>5,444.69</b>	<b>74.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,352.60</b>	<b>1,500.00</b>	<b>5,852.60</b>	<b>79.60</b>

### INSPECTION

Date of Assignment: 07/05/2018

Date Inspected: 10/05/2018 Inspected At:

One Zone Autocare (HQ)  
7 SOON LEE STREET, #01-05 I SPACE  
BUILDING  
Singapore 627608

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 18 Jul 2018)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 D ABS AIRBAG 2WD 6DR (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE6343X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cut	1,150.00 FL	*650.00 FL
2	1		*REAR RIGHT FENDER ASSY	Repair	4,813.00 FL	*- FL
3	1		*REAR BUMPER SPONGE	Cut	196.00 FN	*98.90 FN
4	1		*REAR RIGHT BUMPER REFLECTOR	Cracked	60.00 FN	*60.00 FN
5	2		*REAR RIGHT DOOR PANEL HINGES	Bent	220.00 FN	*101.00 FN
6	1		*REAR RIGHT TAILLAMP	Cut	689.00 FN	*310.00 FN
7	12		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
8	1		*REAR RIGHT DOOR GLASS SEALANT	Not Necessary	80.00 FS	*- FS
9	1		*REAR LEFT DOOR 70KM/H STICKER	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,288.00</b>	<b>1,249.90</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	1,788.90	195.00
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	116.50	56.99
<b>Total Parts (\$\$)</b>	<b>5,382.60</b>	<b>997.91</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR RIGHT, REAR AFFECTED AREA AND REPLACE REAR RIGHT AND REAR DAMAGED PARTS	New	800.00	500.00
2	TO PUTTY AND SPRAY PAINTING REAR RIGHT AND REAR PORTION	New	800.00	300.00
3	TO CHECK WIRING AND REAR TAILLAMP	New	50.00	30.00
4	TO APPLY ANTI RUST PROOFING TO REAR RIGHT AFFECTED AREA	New	100.00	30.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	120.00	50.00
6	TOWING SERVICE	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,970.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**