

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0757/2018/KS
Date	:	4-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	SEET WEN CHENG, JASON
Address	:	Blk 174 Lompang Road #16-61 Singapore 670174
Telephone	:	+65 98309869
Type of Claim	:	Third Party Claims
Policy No.	:	5093344789
Vehicle No	:	SLR 3304 S
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Aug-17
Engine No	:	CHZ 398166
Chassis No	:	WAUZZZ8V0J1002311
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	1-Jul-18
Place of Accident	:	TAMPINES AVENUE 5 TRAFFIC LIGHT ALONG AIA BUILDING

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 3304 S.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To remove rear fittings, dismantle and renew rear bumper. Re-organise rear crash managements components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper.	\$ 800.00 550	
4	To reapply paint protection for rear bumper	S/N \$ 90.00 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,262.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 3304 S .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Repair</i>	\$ 1,697.00	X
2	BUMPER FIXING PARTS	\$ 167.00	X
3	REAR BUMPER SPOILER	\$ 206.00	X
4	REAR BUMPER GUIDE LH / RH	2 \$ 114.00	X
5	REAR REINFORCEMENT BEAM	\$ 501.00	X
6	REAR PARKING AID	\$ 211.00	X
7	PARKING AID SEAL RING	\$ 14.00	X
8	SUNDRIES	\$ 300.00	X
TOTAL SPARE PARTS CHARGES :		\$ 3,210.00	
TOTAL LABOUR CHARGES		\$ 2,262.00	
GRAND TOTAL		\$ 5,472.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : ~~Adrian Lim~~ 05/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Happy Car

UEN: 53358123X

www.facebook.com/happycar8

OFFICIAL RECEIPT

No.: HC 18 - 013

Date: 19/08/17

茲收到 Received from Jason Seet (white Audi A3 - SLR33045)

支付大銀 the sum of Dollars Two Hundred and Twenty only

系还 in payment of 9H coating wlo machine polish

\$220

Cash / Cheque No.:

HAPPY
CAR