

ANS REC BY: Rasu REF: CS/GAI18012024/R/qd3er

Surveyor: Rachel Tan ASSIGNMENT (Office) of GAI Date/Time: 3/7/18 @ 9:18am

Estimated Cost: _____ Bill to: _____

OD ☒ WS/TP RES / OD RES / EVA / INV / MV? CS

To Inspect Vehicle No: FBF FBE 1772T Insured: FBF 1833B

at Workshop n/s: Southern Motor Tel: 62730369

of: BK 1006, BKf Merah Lane 2 #01-10

Policy No: _____ Claim No: C1MOMVM000000307

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 25/6/18

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{1up}

Date/Time: 10:06am @ 3/7/18 Person Contacted: Mr. Lim Vehicle: ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>FBE 1772T - X</u>
	<u>FBF 1833B - NBA / MSG18011626/4</u>

04/7/18 @ 3:50pm revised to Rachel Tan by email

08/10/18 @ 5:14pm checked with Ah Kiat, the motorbike has not send in for repair due to awaiting liability issued.

09/10/18 Submit Pres. report.

16/11/18 Re-open ref. And submit final report.
 US \$1300, 3 days CRD \$813.30, 38% ^{Collect} 16/11/2018

22/11/18 reopen ref only, let close date 31/10/18 ↓

(08/11/13) • wel

A&S. REC. BY:

REF:

GAI

40126

ASSIGNMENT

From:

Date:

03/07/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBF 1772T

at Workshop m/s

Southern Motor

of

Bik 1006 Bkt March Lane 2 #01-10

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

FBF 1772T

Yr Regn: 2011 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA FZ16

C.C. 153

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

99999

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ME12165182026812

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70-17

R:

140/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 3 mm

R/Bal. 3 mm

L/Bal. mm

L/Bal. mm

D.O.A. 25/06/18

D.O.I. 03/07/18

Survey held at

Southern Motor

Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 9 OCT 2018

Date/Time, File Pass to?

1) 04/10 10:00

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

250

Report Format :

Lump Sum / I.B.I. (\$))



南方摩哆 SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 2nd July 2018
Motor Claims Department
Great American Insurance Company
3 Temasek Ave #16-01
Centennial Tower
Singapore 039180

Dear Sirs

Re: Cost of repairs to Yamaha FZ16 - FBF 17747

1 pc of	Head lamp complete	195.00	sur
"	Head lamp cover	90.00	sur
"	Handle bar	150.00	PA
"	Handle grips	25.00	cut
"	Brake lever	18.00	sur
"	Mirror	45.00	sur
"	Front footrest bracket	48.00	PA
"	Rear lever	35.00	Xsur
"	Brake pedal	20%	28.00
"	Exhaust pipe	1314.64	580.00
"	Tail cover	180.00	sur
"	Rear mudguard	43-1,300	65.00
"	Rear No plate mudguard		48.00
"	Rear signet		35.00
		3 days	1,437.00
			143.70
			1,293.30
			1337
			10%
			1203.30

consultants hence notify
if the following:
before/after spray painting

less 10%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Less 10%

Nett

Transport	30.00
Jack rear body	440 { 2100 100 sur
Kappa box	240.00 150 sur
No plate	10.00 CR
Labour	2100 150
	2,113.30

RASUL

HP 90010068

3 days

4/5

03/07/18 @ 1225

Resur after repair

Yours faithfully,
SOUTHERN MOTOR

5/7/18
Tel 6204 7846
Fax 6235 3354



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 1772T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEAD LAMP COMPLETE	SCRATCHED	195.00	195.00
1	HEAD LAMP COVER	SCRATCHED	90.00	90.00
1	HANDLE BAR	BENT	55.00	55.00
1	HANDLE GRIPS	CUT	25.00	25.00
1	BRAKE LEVER	SCRATCHED	18.00	18.00
1	MIRROR	SCRATCHED	45.00	45.00
1	FRONT FOOTREST BRACKET	BENT	48.00	48.00
1	GEAR LEVER	SERVICEABLE	35.00	-
1	BRAKE PEDAL	SCRATCHED	28.00	28.00
1	EXHAUST PIPE	SCRATCHED	580.00	580.00
1	TAIL COVER	SCRATCHED	180.00	180.00
1	REAR MUDGUARD	SERVICEABLE	65.00	-
1	REAR NO PLATE MUDGUARD	CRACKED	48.00	48.00
1	REAR SIGNAL	SCRATCHED	25.00	25.00
	LESS 10% DISCOUNT		-143.70	-133.70
			1,293.30	1,203.30
<u>SPECIAL NETT ITEMS</u>				
1	KAPPA BOX (SN)	SCRATCHED	280.00	150.00
1	NO PLATE (SN)	CRACKED	10.00	10.00
			290.00	160.00
<u>LABOUR</u>				
	TRANSPORT.		30.00	30.00
	JACK REAR BODY.		250.00	100.00
	LABOUR.		250.00	150.00
			-	-
			-	-
			-	-
			530.00	280.00
GRAND TOTAL			2,113.30	1,643.30

Report Ref No. CS/GAI18012024/R1qd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00
---	--	--	----------

Report Ref No. CS/GAI18012024/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.