

ASS. REC. BY:

REF:

CS/FCI18012026/Utd3n4

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

CWS

Joanne Yong

of

FCI

Date/Time:

3/7/18 @ 9:40am

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 271E

Insured:

SHD 3337T

at Workshop m/s:

Progressive Automotive

Tel:

6741 5336

of

Blk 3022A Ubi Road 1# 01-45/46

Policy No:

Claim No:

D18005076MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp?

H.O.D. Endorsement:

Date/Time:

9:47am @ 3/7/18

Person Contacted:

pei wen

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLG 271E - X

SHD 3337T - NS INC16023698/H/vh3m2

DOA: 9/12/2016

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 271at Workshop m/s NA ubi

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 69k.DAC Accident Report 2 Consistent? : Yes or NoGLA / PR Seen 2 Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLump Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction 27/8/18 confirmed final by 5812.24 with RayVeh No: SLG 271E Yr Regn: 9 16Type: C Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA 1Make: Mercedes 3 SP cc 1496Colour: Blue A/C: Insured / Std / Nil / NASp. Reading: 33706 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JM63M42A860345173Gen. Cond: 2 Good / Fair / Poor / BurntSteering: 2 In order / Jammed / Leaked / Burnt orBrake: 2 In order / Jammed / Leaked / Burnt orModi: 2 Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/6/18 D.O.A. 3/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 3/8 Typist ☐ : Prelim. Report☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TPLump Sum / I.B.: (\$) 5812.24Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

160
50
50
108
/
368

RECEIVED 03 AUG 2018

MOTOR SURVEY ASSIGNMENT

Date	28-06-2018	Our Ref No. D18005076MFSH
Accident Date	26-06-2018	Claim Type. Third Party
Insured Vehicle	SHD3337T	Third Party Vehicle. SLG271E
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46	
Contact Person.	L.K. SOO	
Contact No.	67415336/ 0	Fax No. 0
Survey Type		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241892)



PRI Documents



Close



PRI Header Details

Claim No	D18005076MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PROGRES
Workshop Name	PROGRESSIVE AUTOMOTIVE PTE LTD (Contact Person : L.K. SOO)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-45/46 Mobile: 0 , Phone: 67415336 , Fax: 0 EmailId: LKSOO@PROGAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor			
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3337T	TP Vehicle No	SLG271E
PRI Recieved Date	29-06-2018 05:07:48 PM	Surveyor Appointed Date	03-07-2018 09:39:43 AM	Surveyor Accept Date	03-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2230G
Vehicle Details	
Vehicle No.:	SLG271E
Vehicle to be Exported:	No
Intended De-registration Date:	03 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	P520372219
Chassis No.:	JM6BM42A8G0345173
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$20,268.00
Original Registration Date:	19 Sep 2016
First Registration Date:	19 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$15,376.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2026
PARF Rebate Amount:	\$11,532.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$42,277.00
Total Rebate Amount:	\$53,809.00

The information contained herein is correct as at 03 Jul 2018

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

5 Years COE, Renew Toyota Vios 1.5e Sports At \$30.8k.



100% Loan Available. Brand
New Paintwork And Comes With
2 Yrs In House Warranty.
StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

37 vehicles

Mazda 3

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 3		Any	Any	2016	Any	Any	Any	Available
	Mazda 3	1.5A	\$68,666	\$7,620 /yr	29-Sep-2016	1,496 cc	11,000 km	Sedan	Available
Sunroof Model! Agent Warranty. Car Like New. Most Popular Mazda Sedan For Your Family And Daily Usage. Good Fuel Consumption Superb Condition Inside Out! Call To Make Appointment Now.									
Creative Auto									
Posted: 03-Jul-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A Deluxe	\$68,000	\$7,490 /yr	29-Aug-2016	1,496 cc	29,000 km	Sedan	Available
Like New Condition. Pristine Interior And Exterior. No Accidents. Still Under Mazda Warranty, And Only Serviced At Mazda. Careful 1 Owner And Low Mileage. Well Taken Care And Ceramic Paint Protection ...									
Carro									
Posted: 02-Jul-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A	\$68,800	\$7,630 /yr	29-Sep-2016	1,496 cc	11,136 km	Sedan	Available
Fully Serviced By Agent With Warranty. Sunroof Model! Well Maintained By Previous Owner. STA/Vicom Inspection Welcome. No Repairs Needed. Flexible Bank And In-House High Loan Available At Low Interest...									
Imperium Car Motor Pte Ltd									
Posted: 01-Jul-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A	\$68,300	\$7,380 /yr	20-Dec-2016	1,496 cc	8,468 km	Sedan	Available
Made In Japan. Cheapest In The Market. Very Low Mileage Done! Original Condition! Like A New Car! Agent Warranty. Colours Available. Trade In Welcome! Flexible Bank Loan Or In House Loan Available! Don...									
Posted: 30-Jun-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
Car Buying									
Car Selling									
Car Ownership									
Car Aftermarket									
On The Move									
Lifestyle									
Buy Tyres Online!									
Latest Special Offers from Tyrepatch									
	Mazda 3	1.5A	\$63,680	\$7,010 /yr	29-Sep-2016	1,496 cc	-	Sedan	Available
Sunroof Model! Showroom Condition! See To Believe. Viewing At Sengkang Area Strictly By Appointment Only!									
Posted: 30-Jun-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A	\$67,000	\$7,760 /yr	27-May-2016	1,496 cc	26,619 km	Sedan	Available
1 Owner With Low Mileage Of 12,000KM Done A Year! Well-Maintained By Previous Owner! STA/VICOM Evaluation Are Welcome! Tip-Top Condition With No Repair Needed! View To Believe It! You Will Not Want To...									
Ka-Hup Vehicles Trading									
Posted: 30-Jun-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A	\$59,800	\$7,020 /yr	31-Mar-2016	1,496 cc	-	Sedan	Available
\$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Costs! Low Mileage! 100% Accident Free! In House Loan Or Bank Loan Ava...									
88 Motor Trading									
Posted: 30-Jun-2018 Tags: 2016 Mazda 3, Mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A Deluxe	\$73,900	\$8,970 /yr	04-Jan-2016	1,496 cc	48,000 km	Sedan	Available
Look No Further, Best Value For Your Money. Direct Owner's Red, Jan 2016 Mazda 3 1.5A Deluxe. Owned By 1 Private Owner Selling Due To Upgrading To New Car. Serviced And Maintained By Agent With Warrant...									

Compare

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

not Affected
Lak
to his photo before going
3/7/18

5-8/12-24

M/S : YANG ZHIHAO
BLK 121 POTONG PASIR AVENUE 1 #18-291
SINGAPORE 350121

Estimate No: EST1503784
Date: 27 Jun 2018
Policy No: MT/00407042
Veh Reg No: SLG271E
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chassis No: JM6BM42A8G0345173
Engine No: P520372219
Reg. Date: 19/09/2016

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5123
Claim Type: Third Party
Accident Date: 26/06/2018
TP Veh Reg No: SHD 3337 T

Estimate Repair Cost to Vehicle No :SLG271E

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>DIS</i>	1,074.800	1 PC	1,074.80	—
2 REAR BUMPER CLIPS <i>ner</i>	4.2000	10 PC	42.00	—
3 REAR BUMPER SIDE HOLDER - LH <i>ner</i>	36.1000	1 PCS	36.10	—
4 REAR BUMPER SIDE HOLDER - RH <i>ner</i>	36.1000	1 PCS	36.10	—
5 REAR BUMPER REINFORCEMENT <i>to/ser</i>	537.3000	1 PC	537.30	—
6 REAR BUMPER REFLECTOR - LH <i>11</i>	50.4000	1 PC	50.40	x
7 REAR BUMPER REFLECTOR - RH <i>11</i>	50.4000	1 PC	50.40	x
8 REAR BUMPER TOWING COVER - LH <i>ner</i>	16.2000	1 PCS	16.20	—
9 REAR BUMPER TOWING COVER - RH <i>ner</i>	16.2000	1 PCS	16.20	—
10 REAR BUMPER SENSOR <i>shunt</i>	193.9000	1 PC / set	775.60	2805.~
11 REAR PANEL	505.1000	1 PC	505.10	x
12 REAR PANEL TOP GARNISH <i>11</i>	85.1000	1 PCS	85.10	x
13 FRONT BUMPER <i>to/ser</i>	1,031.700	1 PC	1,031.70	—
14 FRONT BUMPER CLIPS <i>ner</i>	2.8000	10 PC	28.00	—
15 FRONT BUMPER SIDE HOLDER - LH <i>Bel</i>	18.7000	1 PCS	18.70	—
16 FRONT BUMPER SIDE HOLDER - RH <i>Bel</i>	18.7000	1 PCS	18.70	—
17 FRONT BUMPER REINFORCEMENT <i>to</i>	565.1000	1 PCS	565.10	—
18 FRONT BUMPER FOG LAMP - LH <i>11</i>	351.4000	1 PC	351.40	x
19 FRONT BUMPER FOG LAMP - RH <i>11</i>	351.4000	1 PC	351.40	x
20 FRONT BUMPER FOG LAMP COVER - LH <i>11</i>	46.4000	1 PCS	46.40	x
21 FRONT BUMPER FOG LAMP COVER - RH <i>11</i>	46.4000	1 PCS	46.40	x
22 FRONT BUMPER TOWING COVER - RH <i>11</i>	28.6000	1 PCS	28.60	x
23 FRONT BUMPER CENTRE LOWER GRILLE <i>11</i>	83.7000	1 PCS	83.70	x
24 FRONT BUMPER CENTRE LOWER GRILLE - LH (SMALL) <i>11</i>	28.0000	1 PCS	28.00	—
25 FRONT BUMPER CENTRE LOWER GRILLE - RH (SMALL) <i>11</i>	28.0000	1 PCS	28.00	x
26 FRONT BUMPER LOGO - MAZDA <i>ner</i>	44.2000	1 PCS	44.20	—
27 FRONT BUMPER NOZZLE COVER - LH <i>11</i>	85.1000	1 PCS	85.10	x
28 FRONT BUMPER NOZZLE COVER - RH <i>11</i>	85.1000	1 PCS	85.10	x
29 FRONT GRILLE ASSY <i>ner</i>	581.6000	1 PC	581.60	—
30 FRONT GRILLE CHROME MOULDING <i>ner 11</i>	176.7000	2 PCS	353.40	1 pc
31 BRACE PANEL <i>11</i>	38.8000	1 PC	38.80	x

Labour

re. n. f. m. p. protector
grille inner brackets

Tong
Hua 2 pcs

Less 20%

7,039.60
1,407.92 5,631.68

P-4777-8
3822-24

4251.4

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : YANG ZHIHAO
BLK 121 POTONG PASIR AVENUE 1 #18-291
SINGAPORE 350121

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5123
Claim Type: Third Party
Accident Date: 26/06/2018
TP Veh Reg No: SHD 3337 T

Estimate No: EST1503784
Date: 27 Jun 2018
Policy No: MT/00407042
Veh Reg No: SLG271E
Make/Model: MAZDA MAZDA3 4-
DOOR SEDAN 1.5L
SP.6EAT
Chassis No: JM6BM42A8G0345173
Engine No: P520372219
Reg. Date: 19/09/2016

Estimate Repair Cost to Vehicle No :SLG271E

Description	U/Price	Quantity	Price SS	Amount SS
32 TO KNOCK OUT DENTS, CUT/ WELD, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	700
33 TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.0000	1 JOB	900.00	850
34 TO CHECK WIRING	50.0000	1 JOB	50.00	30
35 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50
36 TO TUFF-KOTE	60.0000	1 JOB	60.00	4
37 TO REMOVE, REFIX REAR GARNISH, CUSHION, CARPET AND RELATED PARTS.	80.0000	1 JOB	80.00	/
			1,990.00	1,990.00
			Total	SS 7,621.68
			Add GST @ 7%	533.52
			Total Amount Payable	SS 8,155.20

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND ONE HUNDRED FIFTY FIVE AND CENTS TWENTY ONLY

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

16 Jun 17 10
S.V - 280

8042.80

LKK Auto Consultants hereby notify
the Employer of the following:

- to survey before spray painting
- to display damaged parts during resurvey
- All's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is to be used
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST: 201006949C RCB NO: 201006949C

M/S : YANG ZHIHAO
BLK 121 POTONG PASIR AVENUE 1 #18-291
SINGAPORE 350121

ATTN: FIRST CAPITAL INSURANCE

Your Ref No: TP 0618-5123
Claim Type: Third Party
Accident Date: 26/06/2018
TP Veh Reg No: SHD 3337 T

Estimate No: **EST1503784**
Date: 05 Jul 2018
Policy No: MT/00407042
Veh Reg No: **SLG271E**
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Chassis No: JM6BM42A8G0345173
Engine No: P520372219
Reg. Date: 19/09/2016

Estimate Repair Cost to Vehicle No :SLG271E

Description	U/Price	Quantity	Price <u>SS</u>	Amount <u>SS</u>
Supplementary Parts to Repair				
List Price				
1 GRILLE TOP GARNISH <i>10/ea</i>	335.0000	1 PC	335.00	—
2 FRONT BUMPER REINFORCEMENT PROTECTOR <i>To-1</i>	158.0000	1 PC	158.00	—
3 GRILLE INNER SIDE BRACKET <i>cm</i>	16.7000	2 PCS	33.40	—
			526.40	
		Less 20%	105.28	421.12
		Total		SS 421.12
		GST Amount		SS 29.48
		Total Amount Payable		SS 450.60

For **PROGRESSIVE AUTOMOTIVE PTE LTD**


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012026/Utd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3337T	Veh. Inspected	SLG 271E	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005076MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 SP (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0345173	Colour	BLUE	
Odometer	33706	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2018	Inspection Date	03/07/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 271E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	1,074.80	1,074.80
10	REAR BUMPER CLIPS @\$4.20	NECESSARY	42.00	42.00
1	REAR BUMPER SIDE HOLDER-LH	NECESSARY	36.10	36.10
1	REAR BUMPER SIDE HOLDER-RH	NECESSARY	36.10	36.10
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	537.30	537.30
1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	50.40	-
1	REAR BUMPER REFLECTOR-RH	NOT NECESSARY	50.40	-
1	REAR BUMPER TOWING COVER-LH	MISSING	16.20	16.20
1	REAR BUMPER TOWING COVER-RH	MISSING	16.20	16.20
1	REAR PANEL	TO REPAIR SEE LABOUR	505.10	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	85.10	-
1	FRONT BUMPER	DENTED / DEFORMED	1,031.70	1,031.70
10	FRONT BUMPER CLIPS @\$2.80	NECESSARY	28.00	28.00
1	FRONT BUMPER SIDE HOLDER-LH	BENT	18.70	18.70
1	FRONT BUMPER SIDE HOLDER-RH	BENT	18.70	18.70
1	FRONT BUMPER REINFORCEMENT	DENTED	565.10	565.10
1	FRONT BUMPER FOG LAMP-LH	NOT NECESSARY	351.40	-
1	FRONT BUMPER FOG LAMP-RH	NOT NECESSARY	351.40	-
1	FRONT BUMPER FOGLAMP COVER-LH	NOT NECESSARY	46.40	-
1	FRONT BUMPER FOGLAMP COVER-RH	NOT NECESSARY	46.40	-
1	FRONT BUMPER TOWING COVER-RH	NOT NECESSARY	28.60	-
1	FRONT BUMPER CENTRE LOWER GRILLE	NOT NECESSARY	83.70	-
1	FRONT BUMPER CENTRE LOWER GRILLE-LH (SMALL)	MISSING	28.00	28.00
1	FRONT BUMPER CENTRE LOWER GRILLE-RH (SMALL)	NOT NECESSARY	28.00	-
1	FRONT BUMPER LOGO-MAZDA	CRACKED	44.20	44.20
1	FRONT BUMPER NOZZLE COVER-LH	NOT NECESSARY	85.10	-
1	FRONT BUMPER NOZZLE COVER-RH	NOT NECESSARY	85.10	-
1	FRONT GRILLE ASSY	CRACKED	581.60	581.60
2	FRONT GRILLE CHROME MOULDING @\$176.70	N/S CRACKED	353.40	176.70

Report Ref No. CS/FCI18012026/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACE PANEL	NOT NECESSARY	38.80	-
1	GRILLE TOP GARNISH (ADDITIONAL)	DENTED / DEFORMED	335.00	335.00
1	FRONT BUMPER REINFORCEMENT PROTECTOR (ADDITIONAL)	TORN	158.00	158.00
2	GRILLE INNER SIDE BRACKET @\$16.70 (ADDITIONAL)	CRACKED	33.40	33.40
	LESS 20% DISCOUNT		-1,358.08	-955.56
			5,432.32	3,822.24
1	SET REAR BUMPER SENSOR (SN)	SHORTED	775.60	280.00
	LESS 20% DISCOUNT		-155.12	-
			620.48	280.00
	LABOUR			
	TO KNOCK OUT DENTS,CUT/WELD,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR PANEL.		800.00	700.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		900.00	850.00
	TO CHECK WIRING.		50.00	30.00
	TO TRANSFER REAR BUMPER SENSOR.		100.00	50.00
	TO TUFF-KOTE.	NOT NECESSARY	60.00	-
	TO REMOVE,REFIX REAR GARNISH,CUSHION,CARPET AND RELATED PARTS.		80.00	80.00
			1,990.00	1,710.00
GRAND TOTAL			8,042.80	5,812.24
RECOMMENDED COST OF REPAIRS				5,812.24

Report Ref No. CS/FCI18012026/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.