

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800200
Date: 02 Jul 2018
Veh Reg No: SKL1835H
Make/Model: TOYOTA VIOS E
GRADE AUTO
Chasis No: MR2BT9F3901000233
Reg. Date: 08/10/2013
Your Ref No: SLU2821G

Claim Type: Third Party
Accident Date: 29/06/2018
TP Veh Reg No: SLU2821G

Vic

Estimate Repair Cost to Vehicle No :SKL1835H

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR FENDER RH <i>Distorted</i>	899.60 ✓	
2	1 PC REAR FENDER TRIM RH <i>new</i>	237.90 ✕	
3	1 PC TAIL LAMP - RH <i>cracked</i>	357.10 ✓	
4	1 PC REAR BUMPER <i>Deh-d</i>	487.50 ✓	
5	1 PC REAR BUMPER RETAINER RH <i>new</i>	93.20 ✓	
6	1 PC REAR BUMPER RETAINER (SMALL) RH <i>new</i>	31.20 ✓	
7	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	87.70 ✕	
8	1 PC BOOT LID RUBBER <i>new</i>	186.50 ✕	
		2,380.70	
	Less 25%	595.18	1,785.55
Special Net			
9	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	48.00 ✕	
10	1 PC REAR FENDER STICKER	190.00 ✓	
11	1 PC REAR WINDSCREEN SEAL <i>new</i>	60.00 30	
12	1 PC REAR WINDSCREEN SEALANT	60.00 30	
13	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 50	
14	1 SET REAR BUMPER CLIPS <i>new</i>	48.00 50	
15	1 SET REAR BUMPER STICKER <i>new</i>	195.00 ✓	
16	1 PC REAR SPORTS RIM RH <i>lit</i>	800.00 400	
17	1 PC REAR TYRE RH <i>new</i>	480.00 ✕	
		1,951.00	1,951.00
Labour			
18	1 TO CHECK WIRING	50.00 30	
19	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 60	
20	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 100	
21	1 TO REPLACE STICKER	100.00 50	
22	1 TO CHECK WHEEL ALIGNMENT	120.00 80	
23	1 TO SPRAY UNDERSEAL	180.00 60	
24	1 (REAR) TO SPRAY PAINTING	900.00 400	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800200
Date: 02 Jul 2018
Veh Reg No: SKL1835H
Make/Model: TOYOTA VIOS E
GRADE AUTO
Chasis No: MR2BT9F3901000233
Reg. Date: 08/10/2013
Your Ref No: SLU2821G

Claim Type: Third Party
Accident Date: 29/06/2018
TP Veh Reg No: SLU2821G

Estimate Repair Cost to Vehicle No :SKL1835H

Quantity	Description	List Price	Amount
		SS	SS
25	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. 1380	1,000.00 600.	
		2,670.00	2,670.00
	Total		SS 6,406.55
	Add GST @ 7%		448.46
	Total Amount Payable		SS 6,855.01

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED FIFTY FIVE AND CENTS ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

3706.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
1/s 02/07/18
OS Pays.

total: 3516.45
1/s: 281.45
2950 ✓