

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 97E

AAD1806-266

*Not Notified
Running By part*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 97E
WDD2120012B224989
MERCEDES BENZ
E220 CDI
26.6.2018
AIG

		PART		LIST
1	1	Front Fender LH	\$	<i>N</i> 2,900.00 <i>X</i>
2	1	Front Fender LEDGE LH	\$	<i>nn</i> 108.00 <i>X</i>
3	1	Front Door mirror assy LH	\$	<i>sn</i> 1,750.00 <i>X</i>
4	1	Front Bumper	\$	<i>sn</i> 1,897.50 <i>✓</i>
5	1	Front Bumper Reinforcement	\$	984.00 <i>?</i>
6	1	Front Bumper Centre Inner Frame LH	\$	97.50 <i>?</i>
7	1	Front Bumper Side Retainer LH	\$	<i>sn</i> 132.00 <i>X</i>
8	1	Front Bumper Side Retainer RH	\$	<i>sn</i> 132.00 <i>X</i>
9	1	Front Bumper Centre Inner Frame RH	\$	<i>sn</i> 97.50 <i>X</i>
10	1	Front Bumper Side Inner Frame LH	\$	69.00 <i>?</i>
11	1	Front Bumper Side Inner Frame RH	\$	<i>sn</i> 69.00 <i>X</i>
12	1	Front Bumper Inner Sponge Centre	\$	<i>sn</i> 87.00 <i>X</i>
13	1	Front Bumper Inner Sponge Side LH	\$	82.50 <i>?</i>
14	1	Front Bumper Inner Sponge Side RH	\$	<i>sn</i> 82.50 <i>X</i>
15	1	Front Headlamp LH	\$	<i>Bo</i> 1,416.00 <i>✓</i>
16	1	Headlamp Bracket LH	\$	<i>N</i> 144.60 <i>X</i>
17	1	Radiator grille	\$	<i>sn</i> 1,580.00 <i>X</i>
18	1	Radiator assemble	\$	<i>sn</i> 2,520.00 <i>X</i>
19	1	Bonnet	\$	<i>N</i> 4,368.00 <i>X</i>

	\$	18,517.10
TOTAL	\$	475.80
10%	\$	4,282.20

Trans-cab Auto Services Pte Ltd

AAD1806-266

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 97E**Special Nett**

1SET	Rocker panel Fastener Clip	\$	<i>na</i> 80.00	X
1SET	Door LEDGE Clip FTR LH	\$	<i>na</i> 120.00	X
1 SET	Front Bumper Inner Frame Clip	\$	90.00	7
1 SET	Front Bumper Inner Frame Metal Clip	\$	60.00	7
1 SET	Front Bumper clip	\$	<i>na</i> 61.83	✓
1	Front Tyre LH	\$	<i>na</i> 400.00	X
1	Front Alloy Rim LH	\$	<i>na</i> 1,000.00	X

TOTAL \$ 1,811.83**TOTAL PARTS \$ 3,952.93**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>2500</i> 3,500.00
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	<i>na</i> 380.00 X
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	<i>na</i> 170.00 X
To Check Steering Geometry And Computer Wheel Alignment.	\$	<i>na</i> 220.00 X
Putty And Spray Painting Of The Affected Portion.	\$	<i>2500</i> 3,200.00

Trans-cab Auto Services Pte Ltd**AAD1806-266**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 97E

To Transfer Of Door Fittings, Attachment And
Perform Water Seepage Test.

\$

na 170.00 X

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$

na 170.00 X

TOTAL	\$	8,150.00
--------------	-----------	-----------------

Over All Total	\$	12,102.93
-----------------------	-----------	------------------

REPAIR DAYS (PART-BY-PART)~~10 DAYS~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: