

INS. CASE OWNER: SHORIN | CCP / 1111801 WNT, U 263% | LKK: IDAC:

Surveyor: MATIAS | DOI: ASSIGNMENT 4/7/18 | Date / Time: 1/7/18
 Registered in Meriden: 1/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SHC 7652M | Claim No.: ACT 1806087D
 Name of Insured: UTU | Policy No.: MLO M0015
 Insured Tel No.: _____ | HP: _____ | Make / Model: MERCEDES
 Excess Sec II :SS _____ | D.O.A: 1/6/18 | Place of Accident: P/E TRMS AFE
 Is driver the owner? (YES / NO) | Nature of Accident: _____
 If NO, Driver Name / Age: LIN BAR LINDA | OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: _____ | (V/L: YES / NO) | Insured Liability: % | Final ? Yes / No

SLG 1671T



INSRS: _____
 WSP: Auto
 Tel: N
 Liability: CARG
 RMKS: _____



INSRS: _____
 WSP: EKYM
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>10/2/18</u>	Non-Reporting Itr (1st):	
<u>11H</u>	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LDD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
<u>26-6-19</u>	<u>5:35 PM</u>	<u>SPOKEN W/ DANA LA, SITE WILL CHECK FOR RR.</u>
<u>26-6-19</u>		<u>LOD IN. FOR MANDATE</u>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____
 Repair Cost: 45 \$S 4,380.00 (5 days) Reduction: 64 %
 Confirm by: _____ Email Call

FINAL SETTLEMENT Date/Time: 09/07/19 Confirm with: SHORIN Email Call

Final Liability: 100 % (Agreed / Assessed) BOLA S/N No.: 27
 Repair Cost: 657 \$S 4,654.50
 Loss of Rental (LOR): \$S _____ (days)
 Loss of Use (LOU): \$S 500.00 x 10 (days)
 Loss of Income (LOI): \$S _____ (x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: \$S _____
 Medical: \$S _____
 Disbursement: \$S _____ (e.g. Tow/Independent)
 Legal Cost: \$S _____
 Total: \$S 5,154.50 Global Sum \$S: _____
 1) Claim status: Normal / Reject/Private Settle
 2) Report Format: _____
 3) Survey fee: \$600.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 5,154.50 Name 1: AUTO N CARB SERVICES P/B LOD
 Payee 2: (Strike if N.A.) \$S _____ Name 2: _____
 Payee 3: (Strike if N.A.) \$S _____ Name 3: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18012037/Uub3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 03-07-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3652M	Veh. Inspected	SLG 1631T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/06/2018	Inspection Date	04/07/2018
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Co. Reg: 200922097K GST Reg.No: 200922097K
 Auto Bay @ Kaki Bukit Bldg 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

1/5 @ 4350/2

Date : 2/7/2018

Total Pages : 2

TO: INDIA INTERNATIONAL INSURANCE PTE LTD
 64 Cecil Street
 #04/#05 IOB Building
 Singapore 049711

Our Customer : NEO TEONG BOON
 Vehicle No : SLG1631T
 Model : BMW 320I
 Manufacture Year : 30/10/2009
 Date of Accident : 27/06/2018
 Total Estimate Repair Days : 7

Attn : Motor Claim Department
 Fax : 62244174

Re: Repair Estimate For Third Party Claim against : SHC3652M

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A. Spare Parts					
1	Rear boot lid <i>Body/14C</i>	1	\$1,992.15	\$1,992.15	✓ 1232.29
2	Rear boot logo <i>neu</i>	1	\$110.10	\$110.10	✓ 62
3	Rear boot 320I <i>neu</i>	1	\$98.20	\$98.20	✓ 18
4	Rear boot lamp RH <i>neu</i>	1	\$592.20	\$592.20	✓ 245.32
5	Rear boot lamp LH <i>11</i>	1	\$592.20	\$592.20	11 X
6	Rear boot lock mechanism <i>neu</i>	1	\$328.10	\$328.10	neu ✓ 196.03
7	Rear bumper <i>D.S</i>	1	\$1,986.50	\$1,986.50	D.S ✓ 1043.23
8	Rear bumper RH ctr parking sensor <i>shut</i>	1	\$438.50	\$438.50	shut ✓ 235
9	Rear bumper LH ctr parking sensor <i>shut</i>	1	\$438.50	\$438.50	shut ✓ 235
10	Rear bumper tow hook cover <i>2</i>	1	\$98.20	\$98.20	2 X
11	Rear bumper RH retainer <i>11</i>	1	\$328.10	\$328.10	X
12	Rear bumper LH retainer <i>11</i>	1	\$328.10	\$328.10	X
13	Rear bumper ctr top garnish <i>1-</i>	1	\$380.50	\$380.50	X
14	Rear bumper ctr top garnish cover <i>11</i>	2	\$32.10	\$64.20	X
15	Rear bumper lower garnish <i>neu</i>	1	\$275.10	\$275.10	✓ 182.32
16	Rear bumper reinforcement <i>neu</i>	1	\$520.50	\$520.50	✓
17	Rear bumper clip <i>neu</i>	8	\$3.80	\$30.40	neu ✓
18	Rear bumper weather strip <i>neu</i>	1	\$312.10	\$312.10	neu ✓ 193.60
19	Rear end panel <i>2</i>	1	\$780.50	\$780.50	X
20	Rear boot lid damper <i>11</i>	2	\$170.20	\$340.40	11 X
21	Rear exhaust pipe <i>TR</i>	1	\$480.20	\$480.20	2 X
24			Sub Total	\$10,514.75	
			Less 10%		
			Sub-Total 1		4233.69
					10%
					3810.3
A. Spare Parts (S/Nett)					
1	Rear no plate	1	\$50.00	\$50.00	sent 40
2	Body sealant	1	\$50.00	\$50.00	neu ✓
			Sub-Total 2	\$100.00	
			Total Spare Parts	\$8,511.80	
B. Labour					
1	To knock & straighten the affected are, cut & weld damaged panel, adjust & realign the same			\$1,100.00	520
2	To putty & spray boot lid inner & outer, rear bumper, rear end panel inner & outer & rear spare tyre compt			\$1,000.00	800
3	To remove & refit rear end panel garnish, both side trimming to assist workload			\$100.00	60
4	To transfer tailgate fitting, fixtures and perform water seepage &			\$180.00	80
5	To remove & renew rear exhaust pipe			\$80.00	60
6	To check wiring & all lighting			\$80.00	30
			Total Labour	\$2,540.00	

1-45032

12,103.27

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8570D
Vehicle Details	
Vehicle No.:	SLG1631T
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320I AT 2.0L ABS D/AIRBAG HID 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	A388I508N46B20BD
Chassis No.:	WBAPG56030NM18146
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$42,040.00
Original Registration Date:	30 Oct 2009
First Registration Date:	30 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$42,040.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2019
PARF Rebate Amount:	\$23,122.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,901.00
COE Rebate Amount:	\$2,564.00
Total Rebate Amount:	\$25,686.00

The information contained herein is correct as at 05 Jul 2018

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 2 July 2018 4:03 PM
To: Jing Tong Choo; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sherini Pillai
Subject: RE: Accident involving SLG1631T AND VEHICLE SHC3652M ON 27/06/18

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLG1631T and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

4:22pm @ 2/7/2018
vehicle not in
person @ jayden

From: Jing Tong Choo [mailto:jtchoo@autoncars.com.sg]
Sent: 02 July, 2018 2:46 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Accident involving SLG1631T AND VEHICLE SHC3652M ON 27/06/18

Hi Gabriel,

We would like LKK to conduct the joint survey.

On Mon, Jul 2, 2018 at 1:38 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Jing Tong Choo [mailto:jtchoo@autoncars.com.sg]

Sent: 02 July, 2018 11:29 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Accident involving SLG1631T AND VEHICLE SHC3652M ON 27/06/18

ACCIDENT INVOLVING OUR CLIENT'S VEHICLE SLG1631T AND YOUR INSURED'S VEHICLE SHC3652M ON 27/06/2018 ALONG ALONG PIE(TUAS) BEFORE TPY EXIT

We refer to the above matter.

Our client's vehicle would like to arrange for a survey.

Failing which we shall proceed with the repair after the expiry of 48 hours notice.

Thank you

--

Best regards,



Jaden Choo

Autobay @ Kaki Bukit Ave 6

#01-04 Area 'A' S(417883)

Contact No: 6555 2909 / 81881361

Web: www.autoncars.com.sg

Email: JTChoo@autoncars.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--
Best regards,



Jaden Choo

Autobay @ Kaki Bukit Ave 6

#01-04 Area 'A' S(417883)

Contact No: 6555 2909 / 81881361

Web: www.autoncars.com.sg

Email: JTChoo@autoncars.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination

of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SLG1631T (MCT18060828)
[SHC3652M]**

TP

NEO TEONG BOON

Jun 27 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Auto N Cars Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/10/2019 11:09 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5154.50) - SLG1631T - Claim Handler: Sherini Pillai

Approved:5154.50.



Co. Reg: 200922097K GST Reg. No: 200922097K

PROFORMA INV: ANC0839/TP

Date : 20/07/2016

Bill To :

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/#05 10B Building
Singapore 04971

Our Customer

Name : NEO TEONG BOON
IC No : S1598570D
Address : Blk 201E Tampines Street 23 #04-72
Singapore 527201

Vehicle No : **SLG1631T**
Date of Accident : 8/7/2016
Model : Honda CRV 2.4L

No.	Item Descriptions	Qty	Unit Price	Amount
1	To supply labour and materials to repair the above-mentioned vehicle to its pre-accident condition (Lump Sum)	1	-	\$4,350.00
SUB-TOTAL				\$4,350.00
GST 7%				\$304.50
TOTAL				\$4,654.50

For Auto N Cars Services Pte Ltd

* All cheque should be crossed and make payable to "Auto N Cars Services Pte Ltd"

Auto Bay @ Kaki Bukit Blk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018 Edit Reg		02 Jul 2018 00:00 Edit Adj Rpt	\$54,350.00 Edit Estimates	\$54,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -									
Main Claimant: NEO TEONG BOON , ID: S1598570D									
Vehicle Reg. No.:	SLG1631T	Date of Loss:	27/06/2018 00:00 - :59 [103 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18060828	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. [Insured]:	SHC3652M	Policy No. (Claimant):	DMPCSN3109831701						
Excess:									
Repairer: Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6555 2909									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (30/10/2019): Alert - Adj Mandate Approved (\$5154.50) - SLG1631T - Claim Handler: Sherini Pillai • III_SG (02/07/2019): Alert - Adj Mandate Approved (\$5296.50) - SLG1631T - Claim Handler: Sherini Pillai • III_SG (11/07/2018): Alert - Adj Mandate Approved (\$40.00) - SLG1631T - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG1631T (MCT18060828)
 [SHC3652M]
 TP
 NEO TEONG BOON
 Jun 27 2018 12:00AM
 [COMFORT TRANSPORTATION PTE LTD]
 Auto N Cars Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/06/19 17:52	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	26/06/19 17:52	General View		Load JPG <input checked="" type="checkbox"/>
45	26/06/19 17:52	General View		Load JPG <input checked="" type="checkbox"/>
46	26/06/19 17:52	General View		Load JPG <input checked="" type="checkbox"/>
47	26/06/19 17:52	General View		Load JPG <input checked="" type="checkbox"/>
48	26/06/19 17:52	General View		Load JPG <input checked="" type="checkbox"/>
49	26/06/19 17:52	General View		Load JPG <input checked="" type="checkbox"/>
50	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	26/06/19 17:54	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 14:29	EMAIL FROM III DD 02072018		Load PDF
2	09/07/18 17:11	TP ESTIMATE- MARKED		Load PDF
3	28/06/19 12:06	LOD		Load PDF
4	14/11/19 12:07	WORKSHOP INVOICE		Load PDF
5	14/11/19 12:07	AUTHORISATION TO ACT FORM		Load PDF
6	14/11/19 12:07	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/07/18 09:05	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18012037/UHB3Q2

Date: 14/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant
Vehicle No : SLG1631T **Insured Vehicle No :** SHC3652M
Date of Loss: 27/06/2018 **Nature of Claim:** TP **Claim No:** MCT18060828

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG1631T**
 Make & Model: BMW 320i, 2.0 (A) Engine No: A388I508N46B20BD
 Reg. Date: 30/10/2009 (Man. Year: 2009) Chassis No: WBAPG56030NM18146
 Colour: Silver Odometer: 147903 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,563.27	3,900.32	5,662.95	59.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,550.00	990.00	38.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,103.27	5,450.32	6,652.95	54.97
Approved Total (Overridden) (S\$)		4,350.00		
(S\$)	12,103.27	4,350.00	7,753.27	64.06
+ GST 7.00/7.00% (S\$)	847.23	304.50	542.73	64.06
Nett Amount (S\$)	12,950.50	4,654.50	8,296.00	64.06
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		5,154.50		

INSPECTION

Date of Assignment: 02/07/2018
 Date Inspected: 04/07/2018 Inspected At: Auto N Cars Services Pte Ltd (HQ)
 Blk 1 Kaki Bukit Ave 6 #01-04,
 AutoBay @ Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Jun 2019)	
Parts:	N/A	BMW 320I 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG1631T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Badly Dented / Buckled	1,992.15 FL	*1,232.29 FL
2	1		*REAR BOOT LOGO	Necessary	110.10 FL	*62.00 FL
3	1		*REAR BOOT 320I	Necessary	98.20 FL	*58.00 FL
4	1		*REAR BOOT LAMP RH	Cracked	592.20 FL	*245.32 FL
5	1		*REAR BOOT LAMP LH	Not Necessary	592.20 FL	*- FL
6	1		*REAR BOOT LOCK MECHANISM	Twisted	328.10 FL	*196.03 FL
7	1		*REAR BUMPER	Distorted	1,986.50 FL	*1,043.23 FL
8	1		*REAR BUMPER RH CTR PARKING SENSOR	Shorted	438.50 FL	*235.00 FL
9	1		*REAR BUMPER RH CTR PARKING SENSOR L	Shorted	438.50 FL	*235.00 FL
10	1		*REAR BUMPER TOW HOOK COVER	Repair	98.20 FL	*- FL
11	1		*REAR BUMPER RH RETAINER	Not Necessary	328.10 FL	*- FL
12	1		*REAR BUMPER LH RETAINER	Not Necessary	328.10 FL	*- FL
13	1		*REAR BUMPER CTR TOP GARNISH	Not Necessary	380.50 FL	*- FL
14	2		*REAR BUMPER CTR TOP GARNISH COVER	Not Necessary	64.20 FL	*- FL
15	1		*REAR BUMPER LOWER GARNISH	Cracked	275.10 FL	*182.32 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	520.50 FL	*520.50 FL
17	8		*REAR BUMPER CLIP	Necessary	30.40 FL	*30.40 FL
18	1		*REAR BUMPER WEATHER STRIP	Necessary	312.10 FL	*193.60 FL
19	1		*REAR END PANEL	Repair	780.50 FL	*- FL
20	2		*REAR BOOT LID DAMPER	Not Necessary	340.40 FL	*- FL
21	1		*REAR EXHAUST PIPE	Repair	480.20 FL	*- FL
22	1		*REAR NO PLATE	Bent	50.00 FS	*40.00 FS
23	1		*BODY SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,614.75	4,323.69
- List Item Discount on L Items 10.00/10.00% (S\$)	1,051.48	423.37
Total Parts (S\$)	9,563.27	3,900.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN THE AFFECTED ARE CUT & WELD DAMAGED PANEL ,ADJUST & REALIGN THE SAME	New	1,100.00	520.00
2	TO PUTTY & SPRAY BOOT LID INNER & OUTER ,REAR BUMPER,REAR EDN PANEL INNER & OUTER & REAR SPARE TYRE COMPT	New	1,000.00	800.00
3	TO REMOVE & REFIT REAR END PANEL GARNISH ,BOTH SIDE TRIMMING TO ASSIST WORKLOAD	New	100.00	60.00
4	TO TRANSFER TAILGATE FITTING ,FIXTURES AND PERFORM WATER SEEPAGE &	New	180.00	80.00
5	TO REMOVE & RENEW REAR EXHAUST PIPE	New	80.00	60.00
6	TO CHECK WIRING & ALL LIGHTING	New	80.00	30.00
Gross Labour Cost (S\$)			2,540.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >