



Co. Reg: 200922097K GST Reg.No: 200922097K  
 Auto Bay @ Kaki Bukit Bk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883  
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 2/7/2018

TO: INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 Cecil Street  
 #04/#05 IOB Building  
 Singapore 049711

Total Pages : 2

Our Customer : NEO TEONG BOON  
 Vehicle No : SLG1631T  
 Model : BMW 320I  
 Manufacture Year : 30/10/2009  
 Date of Accident : 27/06/2018  
 Total Estimate Repair Days : 7

Attn : Motor Claim Department  
 Fax : 62244174

Re: Repair Estimate For Third Party Claim against : SHC3652M

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Rear boot lid <i>Body/duC</i>	1	\$1,992.15	\$1,992.15	✓ 1232.29
2	Rear boot logo <i>nu</i>	1	\$110.10	\$110.10	✓ 62
3	Rear boot 320I <i>nu</i>	1	\$98.20	\$98.20	✓ 28
4	Rear boot lamp RH <i>ca</i>	1	\$592.20	\$592.20	✓ 245.32
5	Rear boot lamp LH <i>11</i>	1	\$592.20	\$592.20	11 X
6	Rear boot lock mechanism <i>1-1</i>	1	\$328.10	\$328.10	Tur ✓ 196.03
7	Rear bumper <i>D.S</i>	1	\$1,986.50	\$1,986.50	D.S ✓ 1043.23
8	Rear bumper RH ctr parking sensor <i>shub</i>	1	\$438.50	\$438.50	shub ✓ 235
9	Rear bumper LH ctr parking sensor <i>shub</i>	1	\$438.50	\$438.50	shub ✓ 235
10	Rear bumper tow hook cover <i>11</i>	1	\$98.20	\$98.20	11 X
11	Rear bumper RH retainer <i>11</i>	1	\$328.10	\$328.10	X
12	Rear bumper LH retainer <i>11</i>	1	\$328.10	\$328.10	X
13	Rear bumper ctr top garnish <i>11</i>	1	\$380.50	\$380.50	X
14	Rear bumper ctr top garnish cover <i>11</i>	2	\$32.10	\$64.20	X
15	Rear bumper lower garnish <i>ca</i>	1	\$275.10	\$275.10	✓ 182.32
16	Rear bumper reinforcement <i>cut</i>	1	\$520.50	\$520.50	✓
17	Rear bumper clip <i>nu</i>	8	\$3.80	\$30.40	nu ✓
18	Rear bumper weather strip <i>nu</i>	1	\$312.10	\$312.10	nu ✓ 193.60
19	Rear end panel <i>11</i>	1	\$780.50	\$780.50	X
20	Rear boot lid damper <i>11</i>	2	\$170.20	\$340.40	11 X
21	Rear exhaust pipe <i>11</i>	1	\$480.20	\$480.20	11 X
			<b>Sub Total</b>	<b>\$10,514.75</b>	
			Less 10%		
			<b>Sub-Total 1</b>		
					4233.69
					10%
					3810.32
<b>A.</b>	<b>Spare Parts (S/Nett)</b>				
1	Rear no plate	1	\$50.00	\$50.00	net 40
2	Body sealant	1	\$50.00	\$50.00	nu ✓
			<b>Sub-Total 2</b>	<b>\$100.00</b>	
			<b>Total Spare Parts</b>	<b>\$8,511.80</b>	
<b>B.</b>	<b>Labour</b>				
1	To knock & straighten the affected are, cut & weld damaged panel, adjust & realign the same			\$1,100.00	520
2	To putty & spray boot lid inner & outer, rear bumper, rear end panel inner & outer & rear spare tyre compt			\$1,000.00	800
3	To remove & refit rear end panel garnish, both side trimming to assist workload			\$100.00	60
4	To transfer tailgate fitting, fixtures and perform water seepage &			\$180.00	80
5	To remove & renew rear exhaust pipe			\$80.00	60
6	To check wiring & all lighting			\$80.00	30
			<b>Total Labour</b>	<b>\$2,540.00</b>	

1450.32

1/5 @ 4350/2



Co. Reg: 200922097K GST Reg.No: 200922097K  
 Auto Bay @ Kaki Bukit Bk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883  
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

(* The above quoted are exclusive of GST.) Total Repair Cost	

Yours faithfully,

\_\_\_\_\_  
 Jaden  
 f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	<i>marcel zhe</i>
Contact	<i>90296608</i>
Survey Date	<i>4/7/18</i>
Recommender	Authorize / Not Authorize
Before Paint	<input checked="" type="checkbox"/> / No
Signature	

DATE	Remark From MR CHOO
11/7/2016	Please arrange for survey asap

*when photo after repair -  
 L/s # 4350  
 not about.  
 5 day.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:  
 Date: