



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD		NAME : Ms Chew Li-May		WIP : 19866		
36 ROBINSON ROAD		ADDRESS : 97 Jalan Sendudok		EXCESS :		
#16-01 CITY HOUSE		#03-59		DATE: 26-Jun-18		
SINGAPORE 068877		Singapore 769474				
ATTN. : MOTOR CLAIMS		TEL : 97494470				
FAX :						
VEH NO :	SLC5986P	DATE IN :		CONTACT PERSON :	Ronald 63957875	
CHASSIS NO :	JM6GJ1072G0233214	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM	
MODEL :	MAZDA6 2.0L	DATE REG.:	19-May-16	POLICY NO. :		
NATURE OF WORKS						
Parts Description						
NO	QTY			REVISED	PRICES	
1	FRONT BUMPER	1	MGHP9-50-031CBB	\$ 1,096.40	\$ 1,096.40	
2	RETAINER RHS	1	MGHP9-50-0T1B	\$ 16.20	\$ 16.20	
3	CLIP, FRONT BUMPER	6	MB455-56-135	\$ 19.20	\$ 19.20	
4	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$ 5.60	
5	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40	
6	FRONT FENDER RHS	1	MGHP9-52-111A	\$ 365.40	\$ 365.40	
7	STAY(RHS), FENDER	1	MGHY9-52-10YD	\$ 51.60	\$ 51.60	
8	MUDGUARD RHS	1	MGHP9-56-130K	\$ 108.80	\$ 108.80	
9	FASTENER, MUDGUARD	17	MB45A-56-146A	\$ 47.60	\$ 47.60	
10	HEADLAMP RHS	1	MGLJ7-51-0K0B	\$ 917.60	\$ 917.60	
11	CLIP, HEADLAMP	2	MF801-50-133C	\$ 7.60	\$ 7.60	
12	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30	\$ 3.30	
13	FRONT WHEEL RIM RHS	1	M9965-07-7570		\$ 1,277.10	
14	WHEEL BEARING RHS	1	MKD35-33-04XE		\$ 539.70	
15	KNUCKLE RHS	1	MGHP9-33-021A		\$ 387.70	
16	FRONT TYRE RHS	1			\$ 400.00	
17	TANK,WASHER	1	MGHR1-67-481	\$ 104.50	\$ 104.50	
TOTAL PARTS				\$ 2,749.20	\$ 5,249.20	
LESS 10%				\$ 274.92	\$ 524.92	
TOTAL PARTS COST				\$ 2,474.28	\$ 4,724.28	
Labour Description						
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 990.00	\$ 1,980.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.			\$ 1,260.00	\$ 1,890.00
3	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.				\$ 660.00