

22/03/2003

ASS. REC. BY:

REF: CS/EGJ18012041/T12d3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGJ

Date/Time:

3/7/18 @ 9:19am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 3012 G

Insured:

YN 4079C

at Workshop m/s

Volkswagen

Tel:

6305 7176

of

247 Alexandra Road

Policy No:

Claim No:

YN 4079C / SA / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/06/2018

CA / REV / REP. / REV 24 HRS

lup)

6/7/2018 @ 3pm owner waiting

H.O.D. Endorsement:

Date/Time: 10:08am @ 3/7/18

Person Contacted:

Charmaine

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 3012 G - x

YN 4079C - x

12/7/18 @ 4:18pm Revised to Steve Lim by email.

08/8/18 @ 10:11am confirmed with Pearlyn for 1 kg to 9497, 7 days by email.

(Red to 8943.53, 48%)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: YN4079C/SL/pl

Date: 12th July 2018

Our Ref: CS/EGI18012041/T1qd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKP 3012G .


We thank you for the instruction on 03/07/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/07/2018 at the premises of M/s VOLKSWAGEN and have the following to report:-

Workshop Estimate Amount	: S\$ <u>18,440.53</u> .
Revised Estimate Amount	: S\$ <u>9,686.00</u> .
"Check" Items Amount	: S\$ <u>2,242.17</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 7 days.

We have NOT authorise repair.

Yours faithfully

Taufikh
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 3 July 2018 9:19 AM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : YN4079C / TP : SKP3012G/LKK / DOA : 30/06/2018
Attachments: YN4079C - SAS.pdf; SKP3012G - SAS.pdf; SKP3012G - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **VOLKSWAGEN GROUP SINGAPORE LTD**

ADDRESS : 247 ALEXANDRA ROAD
SINGAPORE 159934

PERSON TO CONTACT : MEIY @ 6305 7176

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured's video, SAS and TP's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247
pei.li.yee@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 02.07.2018
Our Reference: YN 4079C/SA/pl
Your Reference: SKP 3012G

Sent via Fax ☐
or
Email ☐ shushi.tang@vw.com.sg

To: VOLKSWAGEN GROUP SINGAPORE P/L

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKP 3012G
Insured's Vehicle: YN 4079C
Date Of Accident: 30.06.2018


We acknowledge receipt of your request for PRS on: 02.07.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	<u>LKK</u>	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - SIT1</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 8 August 2018 10:11 AM
To: 'Cheong, Pearlyn (VWG Singapore)'; Taufikh (LKKAUTO); SUR; Admin A; Admin-D (LKKAUTO)
Cc: Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Foo, John (VWG Singapore)
Subject: RE: SKP3012G - FINALISE

Dear Pearlyn,

WITHOUT PREJUDICE

Confirm final fig \$9,497.00 before GST and 7 repair days.

Kindly send the relevant documents to ERGO Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>
Sent: Friday, 27 July 2018 1:59 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: SKP3012G - FINALISE

Dear Taufikh,

Please confirmed

COR \$9497.00 before GST

Total 7 working days repairs

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 12 July 2018 4:18 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; 'Steve Lim'
Cc: SUR
Subject: RE: YN4079C / TP : SKP3012G/LKK / DOA : 30/06/2018
Attachments: CSEGI18012041T1qd3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SKP 3012G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 3 July 2018 10:10 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YN4079C / TP : SKP3012G/LKK / DOA : 30/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 3 July 2018 9:19 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : YN4079C / TP : SKP3012G/LKK / DOA : 30/06/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **VOLKSWAGEN GROUP SINGAPORE LTD**

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Tanaka 97495749
6/7/18 3pm

PDI TUAS

WP

Resuming before paint
su@lucanauto.com
7 days

Phone No.
Fax No.
E-Mail

PDI TUAS

OKAZAKI MASAOKI LUCAS
453 CHOA CHU KANG AVENUE 4
#10-125
Singapore, 680453
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV026736
Quote No. SER/QUO/1801045
QuoteDate 02/07/18
Salesperson Lawrence Tan Say Ch
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TSI TL BMT (DSG)	57,182	
License No.	VIN	Initial Registration	Sales Advisor
SKP3012G	WVWZZZAUZEW389880	28/08/14	Lawrence Tan Say Chuan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CJZ 527126	5G12DZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	6	UNIT		2520 / 5,040.00
P B&P ALEX LABOUR	TRANSFER DOOR MECHANISM	1	UNIT		420 / 840.00
P B&P ALEX PAINT	SPRAY PAINT	6	UNIT		2400 / 4,800.00
P B&P CELETTE	VEHICLE ON BENCH- CELETTE (	1	Gram		photo ? 1,400.00 XM
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		✓ 480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	CHECK WIRE HARNESS, ECU, S	1	Time Un		✓ 280.00
	Nett				
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT NETT	1	Time Un		✓ 360.00
	Sum Labor				13,200.00
					na
P 533863288A	FELT STRIP	1	Pieces		? 20.55 X
P 5G0805969P	LHS FENDER LINER	1	Pieces		de 171.96
P 5G0807049A	BUMPER SIDE BRACKET LH	1	Pieces		net 19.54
P 5G0807050A	BUMPER SIDE BRACKET RH	1	Pieces		na X 19.54 X
P 5G0807217BNGRU	FRT BUMPER	1	Pieces		Rx 1,152.82 X
P 5G0821105A	FENDER LH	1	Pieces		bu 331.69
	Use Predecessor 5G0821105				
P 5G0821111B	FENDER SIDE ELEMENT LH	1	Pieces		net 68.20
P 5G0821135B	LHS FENDER BRACKET	1	Pieces		net 28.99
	Use Predecessor 5G0821135A				
P 5G0864237H	FENDER INNER TOP SPONGE L	1	Pieces		na 18.97
P 5G4831055AQ	LHS FRT DOOR	1	Pieces		ht 2,236.90
P 5G4837461H	REGULATOR	1	Pieces		na 457.53 X
	Use Predecessor 5G4837461G				
P 5G4837651B	DOOR SEAL	1	Pieces		na 107.41
	Use Predecessor 5G4837651A				

Sum carried forward

17,834.10

Payments to: - BBN: - Acc.-No.:

PDI TUAS

Phone No.
Fax No.
E-Mail

PDI TUAS

OKAZAKI MASA AKI LUCAS
453 CHOA CHU KANG AVENUE 4
#10-125
Singapore, 680453
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV026736
Quote No. SER/QUO/1801045
QuoteDate 02/07/18
Salesperson Lawrence Tan Say Ch
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TSI TL BMT (DSG)	57,182	
License No.	VIN	Initial Registration	Sales Advisor
SKP3012G	WVWZZZAUZEW389880	28/08/14	Lawrence Tan Say Chuan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CJZ 527126	5G12DZ

		Continued	17,834.10
P 5K2837015J	LOCK	1 Pieces	7,364.09
P 8K0831401D	HINGE UPPER * photo	1 Pieces	94.50
	Use Predecessor 8K0831401A		
P 8K0831401D	HINGE LOWER * photo	1 Pieces	94.50
	Use Predecessor 8K0831401A		
P D 378500A2	DOOR INSULATOR	1 Pieces	53.34
	Sum Item		5,240.53

Sum Labor	13,200.00
Sum Item	5,240.53

Total SGD	18,440.53
7% GST	1,290.84
Total SGD Incl. GST	19,731.37

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 18IP1745

CUSTOMER NO.: CV026736

CUSTOMER NAME: OKAZAKI MASAOKI LUCAS

TELEPHONE NO.:

ADDRESS: 453 CHOA CHU KANG AVENUE 4 #10-125

Singapore

VEH No.: SKP3012G

Order Date: 06/07/18

Reg Date: 28/08/14 KM: 59,509

VIN NO.: WVVZZZAUZEW389880

ENGINE NO:

SA: Kong Charmaine

MODEL: GOLF A7 1.2 TSI TL BMT (DSG) MODEL NO.: 5G12DZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		280
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
3	B&P WHEEL ALIGNMENT B&P WHEEL ALIGNMENT NETT	1	TU	360		360
4	B&P ALEX LABOUR LABOUR	3	UNIT	840		2,520
5	B&P ALEX PAINT SPRAY PAINT	3	UNIT	800		2,400
6	B&P ALEX LABOUR TRANSFER DOOR MECHANISM	0.5	UNIT	840		420
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
9	5G0807049A BUMPER SIDE BRACKET LH	1	PCS	19.54		19.54
10	5G0821105A FENDER LH	1	PCS	331.69		331.69
11	5G0821135B LHS FENDER BRACKET	1	PCS	28.99		28.99
12	5G0805969P LHS FENDER LINER	1	PCS	171.96		171.96
13	5G0864237H FENDER INNER TOP SPONGE LH	1	PCS	18.97		18.97
14	5G0821111B FENDER SIDE ELEMENT LH	1	PCS	68.20		68.20
15	5G4831055AQ LHS FRT DOOR	1	PCS	2,236.90		2,236.90
16	5G4837651B DOOR SEAL	1	PCS	107.41		107.41
17	D 378500A2 DOOR INSULATOR	1	PCS	53.34		53.34

Remarks : ERGO DIRECT SETTLEMENT

DOA 30.6.2018

SURVEYOR LKK

TP VEHICLE YN4079C

Service Order Confirmation

SERVICE ORDER NO: 18IP1745

CUSTOMER NO.: CV026736

CUSTOMER NAME: OKAZAKI MASAOKI LUCAS

TELEPHONE NO.:

ADDRESS: 453 CHOA CHU KANG AVENUE 4 #10-125
Singapore

VEH No.: SKP3012G

Order Date: 06/07/18

Reg Date: 28/08/14 KM: 59,509

VIN NO.: WVVZZZAUZEW389880 ENGINE NO:

SA: Kong Charmaine

MODEL: GOLF A7 1.2 TSI TL BMT (DSG) MODEL NO.: 5G12DZ

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	9,497.00
GST AMOUNT	664.79
TOTAL AMOUNT	10,161.79

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18012041/T1qd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 14-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4079C	Veh. Inspected	SKP 3012G	
Policy No.		Coverage (\$)	0.00	
Claim No.	YN4079C/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WWWZZZAUZEW389880	Colour	SILVER	
Odometer	59163	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2018	Inspection Date	06/07/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 3012G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FELT STRIP (SN)	NOT NECESSARY	20.55	-
1	LHS FENDER LINER (SN)	DEFORMED	171.96	171.96
1	BUMPER SIDE BRACKET LH (SN)	NECESSARY	19.54	19.54
1	BUMPER SIDE BRACKET RH (SN)	NOT NECESSARY	19.54	-
1	FRT BUMPER (SN)	TO REPAIR SEE LABOUR	1,152.82	-
1	FENDER LH (SN)	BUCKLED	331.69	331.69
1	FENDER SIDE ELEMENT LH (SN)	NECESSARY	68.20	68.20
1	LHS FENDER BRACKET (SN)	NECESSARY	28.99	28.99
1	FENDER INNER TOP SPONGE L (SN)	NECESSARY	18.97	18.97
1	LHS FRT DOOR (SN)	BENT	2,236.90	2,236.90
1	REGULATOR (SN)	NOT NECESSARY	457.53	-
1	DOOR SEAL (SN)	NECESSARY	107.41	107.41
1	LOCK (SN)	NOT NECESSARY	364.09	-
1	HINGE UPPER (SN)	NOT NECESSARY	94.50	-
1	HINGE LOWER (SN)	NOT NECESSARY	94.50	-
1	DOOR INSULATOR (SN)	NECESSARY	53.34	53.34
			5,240.53	3,037.00
	LABOUR			
	LABOUR INCLUSIVE OF THE REPAIR OF FRT BUMPER.		5,040.00	2,520.00
	TRANSFER DOOR MECHANISM.		840.00	420.00
	SPRAY PAINT.		4,800.00	2,400.00
	VEHICLE ON BENCH-CELETTE.	NOT NECESSARY	1,400.00	-
	CHECK WIRE HARNESS, ECU, S.		280.00	280.00
	B&P WHEEL ALIGNMENT.		360.00	360.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
			13,200.00	6,460.00
	GRAND TOTAL		18,440.53	9,497.00
	RECOMMENDED COST OF REPAIRS			9,497.00



Report Ref No. CS/EGI18012041/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.