

REF: CS/MSG18012043/Ntd302

Special Instruction:

SS. REC. BY:

Surveyor  
Meimien

Ngz

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time: 3/7/18 @ 10:09am

Estimated Cost:

OD / HP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6441K

Insured: SKE 5312K

Tel: 6544 6676

at Workshop m/s

Premier taxis

of

23 changi south Ave 2 #03-02

Policy No: 27833892 SMA

Claim No: 563016

Sum Insured:

Excess:

D.O.A. 02/07/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>lup</sup>

H.O.D. Endorsement:

Date/Time: 10:43am @ 3/7/18

Person Contacted:

Vincent


Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate                           | DUA: 21/9/2008 |
|-----------|---|----------------|
|           | SHC 6441K - CAIAIGD8026206/e/                             |                |
|           | SKE 5312K - x.  |                |
|           | lump sum \$2950, 4 days cred. 1498.45, 33% <sup>6</sup> ) |                |

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 6441K Yr Regn: 19 MAR 2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA OPTIMA C.C. 1685  
 Colour: SILVER A/C: Insured / Std / NI / NA  
 Sp. Reading: 497,258 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: KNAGM414MF5593272

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R16  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or MAXUS

Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 2/7/18 D.O.I. 4/7/18

Survey held at PREMIER CHANGI.  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|             | MSIG L/S             |
|             | RECEIVED 7 AUG 2018  |
|             | 6/8/2018             |

Date/Time, File Pass to? ☐ : Preli. Report  
 1) 6/8 Typist ☒ : Final Report  
 Date/Time, File Return to?

Days Of Repair: 4  
 Resurvey No. of Trip: -

Survey Fee:  
 Transportation:

Add Fee: ☐ : Site Insp (\$ ) S + RS. \$  
☐ : Interview (\$ ) Photos  
☐ : Tech. Invs (\$ ) Others  
☐ : Weekend (\$ )

Report Format : TP  
 Lump Sum / I.B.I. (\$) 29501

TOTAL

|     |
|-----|
| 150 |
| 10  |
| 160 |

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 02 Jul 2018 |               | 03 Jul 2018<br>10:09<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

|                             |   |                        |  |  |
|-----------------------------|---|------------------------|--|--|
| Insured:                    | R.KALAHVATHI, ID: S1739024D   |                        |  |  |
| Main Claimant:              | PREMIER TAXIS PTE LTD   |                        |  |  |
| Vehicle Reg. No.:           | SHC6441K  | Date of Loss:          | 02/07/2018 00:00 - :59<br>[39 Months and 13 Days From LTA Reg Date (Man Yr)] |  |
| Claim Type:                 | TP / 563016   | Policy/Cover Note No.: | 27833892SMA (Comprehensive)<br>Coverage: 21/02/2018 - 20/02/2019             |  |
| Vehicle Reg. No. (Insured): | SKE5312K  | Policy No. (Claimant): |  |  |
|                             |   | Excess:                | S\$500.00  |  |
| Repairer:                   | Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:                        |                        |  |  |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541] |                        |  |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/07/2018]                            |                        |  |  |
| Adj Asg. Remarks:           | OI NOT REPORTED. ASSIGN LKK AUTO CONSULTANTS CONTACT: 6544 6676 / 6544 6689                                   |                        |  |  |

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                   |
|----------------------------|-----------------------------------|
| Date Of Report             | 02/07/2018 13:45                  |
| Date Of Accident           | 02/07/2018 11:50                  |
| Exact Location Of Accident | SLE - CTE (AFTER WOODLANDS AVE 2) |
| Country/State of Loss      | SINGAPORE                         |

### DETAILS OF OWN VEHICLE

|                             |                       |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SHC6441K              |
| <b>Insured/Policyholder</b> |                       |
| Name Of Registered Owner    | PREMIER TAXIS PTE LTD |
| Co Reg No                   | 200304975H            |
| Email Address               | NOEMAIL               |
| Mobile Phone No             |                       |
| Alternative Phone No        | OFFICE-62148880       |

### Vehicle Particulars

|  |                  |
|--|------------------|
| Manufacturer   | KIA              |
| Model  | OPTIMA-1.7 D (A) |
| Exact Purpose for which vehicle was being used at time of accident           | HIRED & REWARDS  |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO               |
| If No, Please state action to be taken                                       | THIRD PARTY      |
| Vehicle Category   | TAXI             |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | THIRD PARTY                            |
| Fleet Policy              | YES                                    |
| Policy Number             | 5095103893                             |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | NEO AH FOO            |
| NRIC No              | S0533040H             |
| Date Of Birth        | 20/07/1949            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 05/10/1967            |
| Driving Experience   | 50 YEARS AND 8 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-97733474  |
| Fax Number           |                       |
| Contact Number       |                       |
| EEmail Address       | NOEMAIL               |

|   |                                   |
|---|-----------------------------------|
| Address   | BLK 830 #05-29<br>WOODLANDS ST 83 |
| Postcode  | 730830                            |
| Was driver an employee of the Insured's Company     | NO                                |
| If No, Relationship of the Driver with the Insured  | OTHER - RELIEF DRIVER             |
| Vehicle Registration Number of Driver's Own Vehicle | -                                 |
|   | -                                 |
|   | -                                 |
| Insurance Company of Driver's Own Vehicle           | -                                 |
|   | -                                 |
|   | -                                 |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   | 2   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

VEH. A - NO PAX VEH. B - 1 PAX

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                              |
|-------------------------------------|------------------------------|
| Vehicle Registration Number         | SKE5312K                     |
| Vehicle Make/Model/Colour           | HONDA FIT                    |
| Details Of Properties               | VEH. B                       |
| Vehicle Category                    | PRIVATE CAR                  |
| Name of Driver                      | EDMUND CHEONG YUE CHENG      |
| NRIC/Passport Number                | S9432201D                    |
| Contact Number                      |                              |
| Address                             |                              |
| Postcode                            |                              |
| Insurance Company Name              |                              |
| Nature Of Damage                    | DAMAGED ON THE FRONT PORTION |
| No. Of Passenger (Including Driver) | 2                            |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

✓ SIC 6441K


✓ 0533040/H

- 2 JUL 2019

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHC 6441K

B: SKE 5312K.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

0533040/11

-2 JUL 2010

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*(Signature)*



Sketch Plan Pg. 3

Describe Circumstance of the Accident.

ON 02/07/2018 @ 1150HRS, I WAS DRIVING MY TAXI (SHC 6441 K)  
TRAVELLING ALONG SLE TOWARDS CTE IN LANE 2.

WHILE I WAS MOVING STRAIGHT AHEAD - WITHIN MY LANE, SUDDENLY I FELT AN  
IMPACT FROM THE REAR.


WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SKE 5312 K - HONDA FIT)  
WHICH WAS APPROACHING FROM THE BACK, HAD COLLIDED ONTO THE REAR OF  
MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND VEHICLE  
B HAD DAMAGES ON THE FRONT PORTION.


NO INJURY INVOLVED.  
NO PASSENGERS ONBOARD MY TAXI & VEHICLE B HAD A PASSENGER ONBOARD.

\*VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



PREMIER  
TAXI



THIRD PARTY  
VEHICLE

 0533040717

Driver's Signature & NRIC Number  
Monday, July 02, 2018 @ 1:55:50 PM

(attended by





Text size + -

**Enquire Transaction History****Transaction History Details**

|                                     |                                 |                     |   |
|-------------------------------------|---------------------------------|---------------------|---|
| Log Date/Time:                      | 19 Mar 2015 / 09:48:06          | Receipt No.:        | AACCK001-AX239-150319-000014                  |
| Asset Type:                         | Vehicle                         | Transaction Amount: | \$65,578.00                                   |
| Asset ID:                           | SHC6441K                        | Channel:            | AA Counterless - CYCLE & CARRIAGE KIA PTE LTD |
| Transaction Type:                   | 01.02 Register New Vehicle (AA) |                     |   |
| Business Transaction Reference No.: | 20150319094806285902            |                     |   |

|                                |   |
|--------------------------------|---|
| Vehicle No.:                   | SHC6441K                                |
| Vehicle Type:                  | H10 - Public Transport Taxi (Motor Car) |
| Vehicle Attachment 1:          | Air-Con (Taxi)                          |
| Vehicle Attachment 2:          | -                                       |
| Vehicle Attachment 3:          | -                                       |
| Vehicle Scheme:                | Taxi (Company)                          |
| First Registration Date:       | 19 Mar 2015                             |
| Original Registration Date:    | 19 Mar 2015                             |
| Vehicle Make:                  | KIA                                     |
| Vehicle Model:                 | OPTIMA 1.7(A) DIESEL                    |
| Chassis No.:                   | KNAGM414MF5593272                       |
| Engine No.:                    | D4FDEH313562                            |
| Motor No.:                     | -                                       |
| Trailer Chassis No.:           | -                                       |
| Propellant:                    | Diesel                                  |
| Passenger Capacity:            | 4                                       |
| Engine Capacity:               | 1685                                    |
| Power Rating:                  | -                                       |
| Unladen Weight:                | 1584                                    |
| Maximum Laden Weight:          | 2050                                    |
| Primary Color:                 | Silver                                  |
| Secondary Color:               | -                                       |
| Manufacturing Year:            | 2014                                    |
| Open Market Value:             | \$21,318.00                             |
| Minimum PARF Benefit:          | \$8,607.00                              |
| PARF Eligibility:              | Y                                       |
| No. of Transfer:               | 0                                       |
| Effective Ownership Date/Time: | 19 Mar 2015 09:48:06                    |
| COE No.:                       | 2015031901002274Z                       |
| COE Expiry Date:               | 18 Mar 2023                             |
| COE Bid Category:              | -                                       |
| Actual QP/PQP Paid Amount:     | \$51,092.00                             |
| Lifespan Expiry Date:          | 18 Mar 2023                             |

**PREMIER AUTOMOTIVE SERVICES PTE LTD****23 Changi South Ave 2****#01-02, Singapore 486443****Assessment Number: MSIG0021****Version: PREMIERA/1****Assessor Report****Printed: 03/07/2018****Summary Information****Claim**

|  |            |                            |     |
|--|------------|----------------------------|-----|
| Claim Reference:                         | SHC6441K   | Insured:                   |     |
| Policy Number:                           |            | Third Party:               |     |
| Date of Decision:                        | 03/07/2018 | Able to Authorise Repairs: | TBA |
| Repairer:                                |            | Repairs Authorised?        | TBA |
| Estimated Repair Time<br>(Working Days): | 0.0        |                            |     |

**Insured's Liability**

|                        |                   |
|------------------------|-------------------|
| Excess:                | TBA               |
| Customer Contribution: | \$0.00 (excl GST) |

**Vehicle Details****Vehicle**

|                     |                                       |                     |        |
|---------------------|---------------------------------------|---------------------|--------|
| Registration:       | SHC6441K                              | VIN/Chassis Number: |        |
| Manufacturer:       | KIA                                   | Model:              | Optima |
| Registration Month: | March                                 | Registration Year:  | 2015   |
| Odometer:           | Not Known                             | Colour:             |        |
| Build Date:         |                                       |                     |        |
| Model Specs         | PREPARE OFF VEHICLE<br>BASECOAT CLEAR |                     |        |

**Vehicle Condition****Vehicle Status**

|                         |            |                      |            |
|-------------------------|------------|----------------------|------------|
| Date of Incident:       | 02/07/2018 | Market Value:        | Unknown    |
| Pre-Accident Condition: |            | Salvage Value:       | Unknown    |
| Pre-Accident Damage:    |            | Date of Inspection:  | 03/07/2018 |
| Steering Rim Ply:       |            | Place of Inspection: |            |
| Brake Pedal Travel:     |            |                      |            |
| Vehicle Status:         |            |                      |            |
| Damage Severity:        |            |                      |            |

**Tyres Condition:**

Tread Depth LHF:

Tread Depth RHF:

Tread Depth LHR:

Tread Depth RHR:

**Repair Information****LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR****Price/Dent = \$50.00/HR****Repair /**

| Guide Number | Repair Details   | WU   | Cost Price (\$) |
|--------------|--|------|-----------------|
| 86520R00     | RENEW REAR BUMPER (REMOVED)  | 11.0 | 55.00 ✓         |
| 69200R00     | RENEW BOOTLID  | 15.0 | 75.00 ✓         |
|              | INCLUDES: BOOTLID, BOTH<br>INN REARLAMP AND REQUIRED ATTACHED<br>PARTS |      |                 |
|              | REMOVE AND REFIT   |      |                 |
| 79210R00)    | R + R L/BOOTLID HINGE  | 5.0  | 25.00 X 11      |
| 79210R00)    | R + R R/BOOTLID HINGE  | 5.0  | 25.00 X 11      |
| 87321R00     | R + R BOOTLID SEAL   | 2.0  | 10.00 ✓         |
| NO NUMBER    | RENEW REAR END PANEL   | 49.0 | 245.00 ✓        |

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0021

Version: PREMIERA/1

Assessor Report

Printed: 03/07/2018

|           |                                 |       |        |
|-----------|---------------------------------|-------|--------|
| 68869R00) | R + R L/LOAD COMPARTMENT TRIM   | 1.0   | 5.00   |
| 68869R00) | R + R R/LOAD COMPARTMENT TRIM   | 1.0   | 5.00   |
| 85770R00  | R + R REAR END PANEL TRIM       | 2.0   | 10.00  |
| 85710R00  | R + R BOOT CARPET               | 2.0   | 10.00  |
| 68869R0B) | R + R L/- AND R/BOOT TRIM (ADD) | 2.0   | 10.00  |
| 3901      | REPAIR REAR FLOOR PANEL         | 20.0* | 100.00 |

## LABOUR COST

|                                      |         |            |
|--------------------------------------|---------|------------|
| Total Work Units                     | 115.0   |            |
| Corrosion Protection External Labour | 0.0HRS  | 0.00       |
| Corrosion Protection Internal Labour | 0.0HRS  | 0.00       |
| Sub Total                            | 11.5HRS | \$575.00   |
| Paint Labour                         | 10.1HRS | \$505.00   |
| Total Labour                         | 21.6HRS | \$1,080.00 |

## PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description WU Cost Price (\$)

|      |                                      |      |
|------|--------------------------------------|------|
|      | - PREPARE OFF VEHICLE                |      |
|      | - BASECOAT CLEAR                     |      |
| 2711 | REAR PANEL NEW PART PAINTING         | 22.0 |
| 2931 | BOOTLID NEW PART PAINTING            | 19.0 |
| 2583 | REAR BUMPER NEW PART PAINT K1R       | 14.0 |
| 2935 | BOOTLID OUT PANEL NEW PART PAINT K1R | 5.0  |
| 3901 | REAR FLOOR PANEL SURFACE PAINT       | 11.0 |

## LABOUR COST - PAINT

|                                    |         |          |
|------------------------------------|---------|----------|
| TIME(PAINT)                        | 71.0    |          |
| Preparation Main Work Plastic      | 5.0     |          |
| Preparation Main Work Metal        | 25.0    |          |
| Preparation Work Multi Layer Paint | 0.0     |          |
| Total Work Units (10WU/HR)         | 101.0   |          |
| Total Paintwork Labour             | 10.1HRS | \$505.00 |

## MATERIAL COST - PAINT

|                                    |          |
|------------------------------------|----------|
| New Part Painting                  | \$82.68  |
| New Part Painting - Plastic K1R    | \$85.12  |
| Material-Constant Main Work Metal  | \$28.60  |
| Surface-/Blend Paint               | \$35.11  |
| Material-Const Main Work Plastic   | \$9.00   |
| Total Excluding Pearlescent Uplift | \$240.51 |
| Pearlescent Uplift @ 0.0%          | \$0.00   |
| Total Paint Material Cost          | \$240.51 |

## PARTS

Price Valid: 01/06/2015

| Guide No. | Qty | Description          | Part Number | Supplier | Bet. | Price (\$) |
|-----------|-----|----------------------|-------------|----------|------|------------|
| 2944      | 1   | BOOT/TAILGATE SEAL   | 873212T001  |          | 0%   | 190.00*    |
| 2931      | 1   | BOOTLID              | 692002T510  |          | 0%   | 1,119.00*  |
| 2935      | 1   | BOOTLID OUT PANEL    | 873702T600  |          | 0%   | 290.00*    |
| 2953      | 1   | L/BOOTLID HINGE      | 792102T500  |          | 0%   | 66.00*     |
| 2617      | 1   | L/R BUMPER BRACKET   | 866132T501  |          | 0%   | 29.00*     |
| 2641      | 1   | L/R C-MEMBER BRACKET | 866412T500  |          | 0%   | 53.00*     |
| 3413      | 1   | L/R REFLECTOR        | 924052T500  |          | 0%   | 46.00*     |

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0021

Version: PREMIERA/1

Assessor Report

Printed: 03/07/2018

|               |   |                      |            |                           |                   |       |
|---------------|---|----------------------|------------|---------------------------|-------------------|-------|
| 2954          | 1 | R/BOOTLID HINGE      | 792202T500 | 0%                        | 66.00*            | X SVL |
| 2618          | 1 | R/R BUMPER BRACKET   | 866142T501 | 0%                        | 29.00*            | Coak  |
| 2642          | 1 | R/R C-MEMBER BRACKET | 866422T500 | 0%                        | 53.00*            | X SVL |
| 3414          | 1 | R/R REFLECTOR        | 924062T500 | 0%                        | 46.00*            | Coak  |
| 3015          | 1 | REAR BADGE           | 863202T500 | 0%                        | 47.60U            | Ne    |
| 2583          | 1 | REAR BUMPER          | 866112T500 | 0%                        | 696.00*           | DT    |
| 2644          | 1 | REAR BUMPER DAMPER   | 866202T500 | 0%                        | 114.00*           | DT    |
| 2770          | 1 | REAR BUMPER SPOILER  | 866122T500 | 0%                        | 206.00*           | DT    |
| 2640          | 1 | REAR BUMPER SUPPORT  | 866312T500 | 0%                        | 607.00*           | DT    |
| 2711          | 1 | REAR PANEL           | 691002T000 | 0%                        | 250.00*           | DT    |
| f: OEM Parts  |   |                      |            | Sub Total                 | \$3,907.60        |       |
| g: Original   |   |                      |            | Deduction from RRP (35 %) | -\$1,367.66       |       |
| h: Secondhand |   |                      |            | <b>Total Parts</b>        | <b>\$2,539.94</b> |       |
| p: Parallel   |   |                      |            |                           |                   |       |
| x: Exchange   |   |                      |            |                           |                   |       |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

| Description                  | Betterment | Price              |
|------------------------------|------------|--------------------|
| REVERSE SENSOR SPECIALIST    | 0%         | \$280.00 / deck 20 |
| REAR BUMPER CLIPS SPECIALIST |            | \$48.00 / Ne 22    |
| BOOT STICKER SPECIALIST      | 0%         | \$100.00 / Ne      |
| BUMPER PROTECTOR SPECIALIST  |            | \$80.00 / Ne 50    |
| FLOORBOARD SPECIALIST        | 0%         | \$80.00 X SVL      |
| PADDING                      |            |                    |
| <b>Total Extras</b>          |            | <b>\$588.00</b>    |

## Final Calculation

|                                   |                          |
|-----------------------------------|--------------------------|
| <b>Total Parts</b>                | <b>\$2,539.94</b>        |
| <b>Labour</b>                     |                          |
| Total Panel/Mechanical            | \$575.00 / 525           |
| Total Paintwork                   | \$505.00 / 370           |
| <b>Total Labour</b>               | <b>\$1,080.00</b>        |
| <b>Additional Costs</b>           |                          |
| Corr Prot Materials External      | \$0.00                   |
| Corr Prot Materials Internal      | \$0.00                   |
| Cost of Specialist                | \$588.00                 |
| <b>Total of Additional Costs</b>  | <b>\$588.00</b>          |
| <b>Total Paint/Material Costs</b> | <b>\$240.51</b> / 198.80 |
| <b>Grand Total Excludes GST</b>   | <b>\$4,448.45</b>        |
| GST @ 7 %                         | \$311.39                 |
| <b>Grand Total Includes GST</b>   | <b>\$4,759.84</b>        |

## Assessment Notes

NA2 LKIC  
4/7/18 1430  
LIS  
4 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

11/6/2018

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: SHC6441K  
Assessment Number: MSIG0021  
Version: LKKAUTOC/2  
Date Calculated: 16/07/2018 09:00

Full Report - V1  
Registration: SHC6441K  
Printed: 16/07/2018 16:00

### Summary Information

#### Claim

|                       |                                   |                            |            |
|-----------------------|-----------------------------------|----------------------------|------------|
| Location:             | Singapore (SG)                    | Currency:                  | SGD        |
| Printed by:           | LKK AUTO                          | Date of Incident:          | 02/07/2018 |
| Authorisation Status: | Interim                           | Able to Authorise Repairs: | TBA        |
| Work Provider:        | MSIG Insurance<br>(Singapore) Pte | Repairs Authorised:        | TBA        |
| Claim Reference:      | SHC6441K                          | Estimated Repair Time:     |            |
| Policy Number:        |                                   | Quote Due Date:            |            |
| Other Reference:      | LKK AUTO                          | Actual Repair Days:        |            |
| Third Party:          |                                   | Parts Ordered Date:        |            |
| Insured Amount:       |                                   | Hire Car Start:            |            |
| Under Warranty:       |                                   | Hire Car End:              |            |
| Warranty Expired:     |                                   | Vehicle Collected:         |            |

#### Vehicle Details

##### Vehicle

|                     |            |
|---------------------|------------|
| Manufacturer:       | KIA        |
| Model:              | Optima     |
| Sub Model:          | BASE MODEL |
| Model Sheet Number: | 2836 01    |
| Registration:       | SHC6441K   |
| Registration Month: | March      |
| Registration Year:  | 2015       |
| VIN Number:         |            |
| Odometer:           | Not Known  |
| Colour:             |            |
| Engine Number:      |            |
| Fuel Level:         | %          |



##### Model Specs

|                     |                |
|---------------------|----------------|
| PREPARE OFF VEHICLE | BASECOAT CLEAR |
|---------------------|----------------|

#### Vehicle Condition

##### Vehicle Status

|                         |                                  |            |
|-------------------------|----------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact:              |            |
| Steering:               | Vehicle Status on<br>Inspection: |            |
| Brakes Pedal Travel:    | Date of Inspection:              | 03/07/2018 |
| Place of Inspection:    |                                  |            |
| Pre-Accident Damage:    |                                  |            |
| Tyres Condition:        | Tread Depth RHF:                 |            |
| Tread Depth LHF:        | Tread Depth RHR:                 |            |
| Tread Depth LHR:        | Direction of Impact:             |            |
| Damage Areas:           |                                  |            |



## Addresses

## Cost Summary

|                           |            |
|---------------------------|------------|
| Total Labour              | \$895.00   |
| Total Paint/Material      | \$198.80   |
| Total Parts               | \$2,121.38 |
| Total of Additional Costs | \$508.00   |
| Excess:                   | TBA        |
| Grand Total Exc GST:      | \$3,723.18 |
| 7 % GST:                  | \$260.62   |
| Grand Total Inc GST:      | \$3,983.80 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
 Price/Dent = \$50.00/HR

### Repair /

#### Guide Number Repair Details

|           |                                    | WU    | Cost Price (\$) |
|-----------|------------------------------------|-------|-----------------|
| 86520R00  | RENEW REAR BUMPER (REMOVED)        | 11.0  | 55.00           |
| 86630R00) | R + R REAR BUMPER CARRIER          | 4.0   | 20.00           |
| 69200R00  | RENEW BOOTLID                      | 15.0  | 75.00           |
|           | INCLUDES: BOOTLID, BOTH            |       |                 |
|           | INN REARLAMP AND REQUIRED ATTACHED |       |                 |
|           | PARTS                              |       |                 |
|           | REMOVE AND REFIT                   | 2.0   | 10.00           |
| 87321R00  | R + R BOOTLID SEAL                 | 49.0* | 245.00          |
| NN        | REAR END PANEL R&R / NEW PARTS     | 2.0*  | 10.00           |
| 1000      | REMOVE&REFIT REAR END PANEL TRIM   | 2.0*  | 10.00           |
| 1000      | REMOVE&REFIT L/- AND R/BOOT TRIM   | 20.0* | 100.00          |
| 3901      | REPAIR REAR FLOOR PANEL            |       |                 |

### LABOUR COST

|                                      |         |          |
|--------------------------------------|---------|----------|
| Total Work Units                     | 105.0   |          |
| Corrosion Protection External Labour | 0.0HRS  | 0.00     |
| Corrosion Protection Internal Labour | 0.0HRS  | 0.00     |
| Sub Total                            | 10.5HRS | \$525.00 |
| Paint Labour                         | 7.4HRS  | \$370.00 |
| Total Labour                         | 17.9HRS | \$895.00 |

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

| Guide Number | Description                    | WU   | Cost Price (\$) |
|--------------|--------------------------------|------|-----------------|
|              | - PREPARE OFF VEHICLE          |      |                 |
|              | - BASECOAT CLEAR               |      |                 |
| 2931         | BOOTLID NEW PART PAINTING      | 19.0 |                 |
| 2583         | REAR BUMPER NEW PART PAINT K1R | 14.0 |                 |
| 3901         | REAR FLOOR PANEL SURFACE PAINT | 11.0 |                 |



|                                    |        |                   |
|------------------------------------|--------|-------------------|
| <b>LABOUR COST - PAINT</b>         |        |                   |
| TIME(PAINT)                        | 44.0   |                   |
| Preparation Main Work Plastic      | 5.0    |                   |
| Preparation Main Work Metal        | 25.0   |                   |
| Preparation Work Multi Layer Paint | 0.0    |                   |
| Total Work Units (10WU/HR)         | 74.0   |                   |
| Total Paintwork Labour             | 7.4HRS | \$370.00          |
| <b>MATERIAL COST - PAINT</b>       |        | <b>Cost Price</b> |
| New Part Painting                  |        | \$55.73           |
| New Part Painting - Plastic K1R    |        | \$70.36           |
| Material-Constant Main Work Metal  |        | \$28.60           |
| Surface-/Blend Paint               |        | \$35.11           |
| Material-Const Main Work Plastic   |        | \$9.00            |
| Total Excluding Pearlescent Uplift |        | \$198.80          |
| Pearlescent Uplift @ 0.0%          |        | \$0.00            |
| Total Paint Material Cost          |        | \$198.80          |

#### PARTS

|               |     |                     |                           | Price Valid: 01/06/2015 |                   |
|---------------|-----|---------------------|---------------------------|-------------------------|-------------------|
| Guide No.     | Qty | Description         | Part Number               | Supplier                | Bet. Price (\$)   |
| 2583          | 1   | REAR BUMPER         | 866112T500                |                         | 0% 551.06U        |
| 2617          | 1   | L/R BUMPER BRACKET  | 866132T501                |                         | 0% 29.00*         |
| 2618          | 1   | R/R BUMPER BRACKET  | 866142T501                |                         | 0% 29.00*         |
| 2640          | 1   | REAR BUMPER SUPPORT | 866312T500                |                         | 0% 607.00*        |
| 2644          | 1   | REAR BUMPER DAMPER  | 866202T500                |                         | 0% 114.00*        |
| 2770          | 1   | REAR BUMPER SPOILER | 866122T500                |                         | 0% 206.00*        |
| 2931          | 1   | BOOTLID             | 692002T510                |                         | 0% 1,119.00*      |
| 2944          | 1   | BOOT/TAILGATE SEAL  | 873212T001                |                         | 0% 190.00*        |
| 3015          | 1   | REAR BADGE          | 863202T500                |                         | 0% 47.60U         |
| 3017          | 1   | BADGE MODEL         | 863102T100                |                         | 0% (nee) 29.00*   |
| 3413          | 1   | L/R REFLECTOR       | 924052T500                |                         | 0% 46.00*         |
| 3414          | 1   | R/R REFLECTOR       | 924062T500                |                         | 0% 46.00*         |
| 1000          | 1   | REAR END PANEL      | Renew                     |                         | 0% 250.00*        |
| f: OEM Parts  |     |                     | Sub Total                 |                         | \$3,263.66        |
| g: Original   |     |                     | Deduction from RRP (35 %) |                         | -\$1,142.28       |
| h: Secondhand |     |                     | <b>Total Parts</b>        |                         | <b>\$2,121.38</b> |
| p: Parallel   |     |                     |                           |                         |                   |
| x: Exchange   |     |                     |                           |                         |                   |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

| <b>Extras</b>       |            | <b>Betterment</b> | <b>Price</b>    |
|---------------------|------------|-------------------|-----------------|
| REVERSE SENSOR      | SPECIALIST | 0%                | \$280.00        |
| REAR BUMPER CLIPS   | SPECIALIST |                   | \$48.00         |
| BOOT STICKER        | SPECIALIST | 0%                | \$100.00        |
| BUMPER PROTECTOR    | SPECIALIST |                   | \$80.00         |
| <b>Total Extras</b> |            |                   | <b>\$508.00</b> |

#### Final Calculation

|                         |          |                   |
|-------------------------|----------|-------------------|
| <b>Total Parts</b>      |          | <b>\$2,121.38</b> |
| <b>Labour</b>           |          |                   |
| Total Panel/Mechanical  | \$525.00 |                   |
| Total Paintwork         | \$370.00 |                   |
| <b>Total Labour</b>     |          | <b>\$895.00</b>   |
| <b>Additional Costs</b> |          |                   |



51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore  
**Claim Reference: SHC6441K**  
**Assessment Number: MSIG0021**  
**Version: LKKAUTOC/2**  
**Date Calculated: 16/07/2018 09:00**

**Full Report - V1**  
**Registration: SHC6441K**  
**Printed: 16/07/2018 16:00**

|                                   |          |                   |
|-----------------------------------|----------|-------------------|
| Corr Prot Materials External      | \$0.00   |                   |
| Corr Prot Materials Internal      | \$0.00   |                   |
| Cost of Specialist                | \$508.00 | \$508.00          |
| <b>Total of Additional Costs</b>  |          | <b>\$198.80</b>   |
| <b>Total Paint/Material Costs</b> |          | <b>\$3,723.18</b> |
| <b>Grand Total Excludes GST</b>   |          | <b>\$260.62</b>   |
| GST @ 7 %                         |          | <b>\$3,983.80</b> |
| <b>Grand Total Includes GST</b>   |          |                   |

### Assessment Notes

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore

408933

Claim Reference: SHC6441K  
Assessment Number: MSIG0021  
Version: LKKAUTOC/2  
Date Calculated: 17/08/2018 06:54

Full Report - V1  
Registration: SHC6441K  
Printed: 17/08/2018 13:55

## Summary Information

### Claim

|                       |                                   |                            |            |
|-----------------------|-----------------------------------|----------------------------|------------|
| Location:             | Singapore (SG)                    | Currency:                  | SGD        |
| Printed by:           | LKK AUTO                          | Date of Incident:          | 02/07/2018 |
| Authorisation Status: | Interim                           | Able to Authorise Repairs: | TBA        |
| Work Provider:        | MSIG Insurance<br>(Singapore) Pte | Repairs Authorised:        | TBA        |
| Claim Reference:      | SHC6441K                          | Estimated Repair Time:     |            |
| Policy Number:        |                                   | Quote Due Date:            |            |
| Other Reference:      | LKK AUTO                          | Actual Repair Days:        |            |
| Third Party:          |                                   | Parts Ordered Date:        |            |
| Insured Amount:       |                                   | Hire Car Start:            |            |
| Under Warranty:       |                                   | Hire Car End:              |            |
| Warranty Expired:     |                                   | Vehicle Collected:         |            |

### Vehicle Details

#### Vehicle

|                     |            |
|---------------------|------------|
| Manufacturer:       | KIA        |
| Model:              | Optima     |
| Sub Model:          | BASE MODEL |
| Model Sheet Number: | 2836 01    |
| Registration:       | SHC6441K   |
| Registration Month: | March      |
| Registration Year:  | 2015       |
| VIN Number:         |            |
| Odometer:           | Not Known  |
| Colour:             |            |
| Engine Number:      |            |
| Fuel Level:         | %          |



#### Model Specs

|                     |                |
|---------------------|----------------|
| PREPARE OFF VEHICLE | BASECOAT CLEAR |
|---------------------|----------------|

### Vehicle Condition

#### Vehicle Status

|                         |                                  |            |
|-------------------------|----------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact:              |            |
| Steering:               | Vehicle Status on<br>Inspection: |            |
| Brakes Pedal Travel:    | Date of Inspection:              | 03/07/2018 |
| Place of Inspection:    |                                  |            |
| Pre-Accident Damage:    |                                  |            |
| Tyres Condition:        | Tread Depth RHF:                 |            |
| Tread Depth LHF:        | Tread Depth RHR:                 |            |
| Tread Depth LHR:        | Direction of Impact:             |            |
| Damage Areas:           |                                  |            |



## Addresses

## Cost Summary

|                           |            |
|---------------------------|------------|
| Total Labour              | \$895.00   |
| Total Paint/Material      | \$198.80   |
| Total Parts               | \$2,215.59 |
| Total of Additional Costs | \$372.00   |
| Excess:                   | TBA        |
| Grand Total Exc GST:      | \$3,681.39 |
| 7 % GST:                  | \$257.70   |
| Grand Total Inc GST:      | \$3,939.09 |

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

### Repair /

### Guide Number Repair Details

|           |                                    | WU    | Cost Price (\$) |
|-----------|------------------------------------|-------|-----------------|
| 86520R00  | RENEW REAR BUMPER (REMOVED)        | 11.0  | 55.00           |
| 86630R00) | R + R REAR BUMPER CARRIER          | 4.0   | 20.00           |
| 69200R00  | RENEW BOOTLID                      | 15.0  | 75.00           |
|           | INCLUDES: BOOTLID, BOTH            |       |                 |
|           | INN REARLAMP AND REQUIRED ATTACHED |       |                 |
|           | PARTS                              |       |                 |
|           | REMOVE AND REFIT                   |       |                 |
| 87321R00  | R + R BOOTLID SEAL                 | 2.0   | 10.00           |
| NN        | REAR END PANEL R&R / NEW PARTS     | 49.0* | 245.00          |
| 1000      | REMOVE&REFIT REAR END PANEL TRIM   | 2.0*  | 10.00           |
| 1000      | REMOVE&REFIT L/- AND R/BOOT TRIM   | 2.0*  | 10.00           |
| 3901      | REPAIR REAR FLOOR PANEL            | 20.0* | 100.00          |

### LABOUR COST

#### Total Work Units

105.0

#### Corrosion Protection External Labour

0.0HRS

0.00

#### Corrosion Protection Internal Labour

0.0HRS

0.00

#### Sub Total

10.5HRS

\$525.00

#### Paint Labour

7.4HRS

\$370.00

#### Total Labour

17.9HRS

\$895.00

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

### Guide Number Description

|      |                                | WU   | Cost Price (\$) |
|------|--------------------------------|------|-----------------|
|      | - PREPARE OFF VEHICLE          |      |                 |
|      | - BASECOAT CLEAR               |      |                 |
| 2931 | BOOTLID NEW PART PAINTING      | 19.0 |                 |
| 2583 | REAR BUMPER NEW PART PAINT K1R | 14.0 |                 |
| 3901 | REAR FLOOR PANEL SURFACE PAINT | 11.0 |                 |

|                                    |        |                   |
|------------------------------------|--------|-------------------|
| <b>LABOUR COST - PAINT</b>         |        |                   |
| TIME(PAINT)                        | 44.0   |                   |
| Preparation Main Work Plastic      | 5.0    |                   |
| Preparation Main Work Metal        | 25.0   |                   |
| Preparation Work Multi Layer Paint | 0.0    |                   |
| Total Work Units (10WU/HR)         | 74.0   |                   |
| Total Paintwork Labour             | 7.4HRS | \$370.00          |
| <b>MATERIAL COST - PAINT</b>       |        | <b>Cost Price</b> |
| New Part Painting                  |        | \$55.73           |
| New Part Painting - Plastic K1R    |        | \$70.36           |
| Material-Constant Main Work Metal  |        | \$28.60           |
| Surface-/Blend Paint               |        | \$35.11           |
| Material-Const Main Work Plastic   |        | \$9.00            |
| Total Excluding Pearlescent Uplift |        | \$198.80          |
| Pearlescent Uplift @ 0.0%          |        | \$0.00            |
| Total Paint Material Cost          |        | \$198.80          |

#### PARTS

|               |     |                     |             | Price Valid: 01/06/2015   |                   |
|---------------|-----|---------------------|-------------|---------------------------|-------------------|
| Guide No.     | Qty | Description         | Part Number | Supplier                  | Bet. Price (\$)   |
| 2583          | 1   | REAR BUMPER         | 866112T500  |                           | 0% 696.00*        |
| 2617          | 1   | L/R BUMPER BRACKET  | 866132T501  |                           | 0% 29.00*         |
| 2618          | 1   | R/R BUMPER BRACKET  | 866142T501  |                           | 0% 29.00*         |
| 2640          | 1   | REAR BUMPER SUPPORT | 866312T500  |                           | 0% 607.00*        |
| 2644          | 1   | REAR BUMPER DAMPER  | 866202T500  |                           | 0% 114.00*        |
| 2770          | 1   | REAR BUMPER SPOILER | 866122T500  |                           | 0% 206.00*        |
| 2931          | 1   | BOOTLID             | 692002T510  |                           | 0% 1,119.00*      |
| 2944          | 1   | BOOT/TAILGATE SEAL  | 873212T001  |                           | 0% 190.00*        |
| 3015          | 1   | REAR BADGE          | 863202T500  |                           | 0% 47.60U         |
| 3017          | 1   | BADGE MODEL         | 863102T100  |                           | 0% 29.00*         |
| 3413          | 1   | L/R REFLECTOR       | 924052T500  |                           | 0% 46.00*         |
| 3414          | 1   | R/R REFLECTOR       | 924062T500  |                           | 0% 46.00*         |
| 1000          | 1   | REAR END PANEL      | Renew       |                           | 0% 250.00*        |
| f: OEM Parts  |     |                     |             | Sub Total                 | \$3,408.60        |
| g: Original   |     |                     |             | Deduction from RRP (35 %) | -\$1,193.01       |
| h: Secondhand |     |                     |             | <b>Total Parts</b>        | <b>\$2,215.59</b> |
| p: Parallel   |     |                     |             |                           |                   |
| x: Exchange   |     |                     |             |                           |                   |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

#### Extras

| Description                  | Betterment | Price           |
|------------------------------|------------|-----------------|
| REVERSE SENSOR SPECIALIST    | 0%         | \$200.00        |
| REAR BUMPER CLIPS SPECIALIST |            | \$22.00         |
| BOOT STICKER SPECIALIST      | 0%         | \$100.00        |
| BUMPER PROTECTOR SPECIALIST  |            | \$50.00         |
| <b>Total Extras</b>          |            | <b>\$372.00</b> |

#### Final Calculation

|                         |          |                   |
|-------------------------|----------|-------------------|
| <b>Total Parts</b>      |          | <b>\$2,215.59</b> |
| <b>Labour</b>           |          |                   |
| Total Panel/Mechanical  | \$525.00 |                   |
| Total Paintwork         | \$370.00 |                   |
| <b>Total Labour</b>     |          | <b>\$895.00</b>   |
| <b>Additional Costs</b> |          |                   |

|                                   |          |                   |
|-----------------------------------|----------|-------------------|
| Corr Prot Materials External      | \$0.00   |                   |
| Corr Prot Materials Internal      | \$0.00   |                   |
| Cost of Specialist                | \$372.00 |                   |
| <b>Total of Additional Costs</b>  |          | <b>\$372.00</b>   |
| <b>Total Paint/Material Costs</b> |          | <b>\$198.80</b>   |
| <b>Grand Total Excludes GST</b>   |          | <b>\$3,681.39</b> |
| GST @ 7 %                         |          | <b>\$257.70</b>   |
| <b>Grand Total Includes GST</b>   |          | <b>\$3,939.09</b> |

### **Assessment Notes**

---

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |             |   |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 02 Jul 2018 |               | 03 Jul 2018<br>10:09<br><a href="#">Edit Adj Rpt</a> | <b>S\$2,950.00</b><br><a href="#">Edit Estimates</a> | <b>S\$2,950.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|      |  |           |  |               |  |           |  |          |  |
|------|--|-----------|--|---------------|--|-----------|--|----------|--|
| Main |  | Reference |  | Claim Details |  | Documents |  | Show All |  |
|------|--|-----------|--|---------------|--|-----------|--|----------|--|

CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |  |  |  |                        |  |  |  |  |  |
|-----------------------------|--|--|--|------------------------|--|--|--|--|--|
| Insured:                    | R.KALAHVATHI, ID: S1739024D  |  |  |                        |  |  |  |  |  |
| Main Claimant:              | PREMIER TAXIS PTE LTD  |  |  |                        |  |  |  |  |  |
| Vehicle Reg. No.:           | SHC6441K   |  |  | Date of Loss:          | 02/07/2018 00:00 - :59<br>[39 Months and 13 Days From LTA Reg Date (Man Yr)] |  |  |  |  |
| Claim Type:                 | TP / 563016  |  |  | Policy/Cover Note No.: | 27833892SMA (Comprehensive)<br>Coverage: 21/02/2018 - 20/02/2019             |  |  |  |  |
| Vehicle Reg. No. (Insured): | SKE5312K   |  |  | Policy No. (Claimant): |  |  |  |  |  |
|                             |  |  |  | Excess:                | S\$500.00  |  |  |  |  |
| Repairer:                   | Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:   |  |  |                        |  |  |  |  |  |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]                    |  |  |                        |  |  |  |  |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 04/07/2018] |  |  |                        |  |  |  |  |  |
| Adj Asg. Remarks:           | OI NOT REPORTED. ASSIGN LKK AUTO CONSULTANTS CONTACT: 6544 6676 / 6544 6689  |  |  |                        |  |  |  |  |  |

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

\*SHC6441K (563016)  
 [SKE5312K]  
 TP  
 PREMIER TAXIS PTE LTD  
 Jul 2 2018 12:00AM  
 [R.KALAHVATHI]  
 Premier Taxis Pte Ltd - Changi

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** [View in Browser](#)

---

**Assessment Reports**

1 per page ☐

| No | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)   | Thumbnail | Print |
|----|----------------|---|-----------|-------|
| 1  | 04/07/18 14:29 | <b>Accident Statement</b><br><small>From: SC - Reg. No: SKE5312K, Claimant: R. KALAHVATHI</small> | Load HTML |       |

---

**Photos/Images**

3 per page ☐

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print                               |
|----|-----------------|-----------------------------------|-----------|-------------------------------------|
| 1  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 2  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 3  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 4  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 5  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 6  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 7  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 8  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 9  | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 10 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 11 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 12 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 13 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 14 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 15 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 16 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 17 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 18 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 19 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 20 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 21 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 22 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 23 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 24 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |
| 25 | 11/07/18 10:51  | General View                      | Load JPG  | <input checked="" type="checkbox"/> |

---

**Documentation**

1 per page ☐

| No | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
|----|----------------|---|-----------|-------|
| 1  | 02/07/18 15:56 | PRI - PREMIER TAXIS                       | Load PDF  |       |
| 2  | 04/07/18 14:21 | SHC6441K TP E-FILE REPORT                 | Load PDF  |       |

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
|----|-----------------|-----------------------------------|-----------|-------|
| 1  | 20/08/18 10:09  | Supplementary                     | Load PDF  |       |



## Documents Checklist

| DOCUMENTS CHECKLIST   | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured.                                  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>              |       |      |       |
| <div></div>   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer             |       |      |       |
| <small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012043/NTD3E2

Date: 20/08/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27833892SMA

Claimant Vehicle No: SHC6441K

Insured Vehicle No: SKE5312K

Date of Loss: 02/07/2018

Nature of Claim: TP

Claim No: 563016

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6441K

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDEH313562

Reg. Date: 19/03/2015 (Man. Year: 2014)

Chassis No: KNAGM414MF5593272

Colour: Silver

Odometer: 497288 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16  
Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm  
Front Right Side: Maxxis 5 mm Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 3,146.79   | 2,587.59   | 559.20     | 17.77  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 1,320.51   | 1,093.80   | 226.71     | 17.17  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 4,467.30   | 3,681.39   | 785.91     | 17.59  |
| Approved Total (Overridden) (S\$) |            | 2,950.00   |            |        |
| (S\$)                             | 4,467.30   | 2,950.00   | 1,517.30   | 33.96  |
| + GST 7.00/7.00% (S\$)            | 312.71     | 206.50     | 106.21     | 33.96  |
| Nett Amount (S\$)                 | 4,780.01   | 3,156.50   | 1,623.51   | 33.96  |

### INSPECTION

Date of Assignment: 03/07/2018

Date Inspected: 04/07/2018 Inspected At:

Premier Taxis Pte Ltd - Changi (HQ)  
23 Changi South Ave 2 #03-02  
Singapore 486443

Estimated Period of Repair: 4.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 20 Aug 2018)          |
| <b>Parts:</b>        | 143  | KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SHC6441K)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *  |  |

### Recommended Parts

| No. | Qty | Part No. | Particulars           | Condition   | Repairer's  | Amount       |
|-----|-----|----------|-----------------------|-------------|-------------|--------------|
| 1   | 1   |          | *BOOT/ TAILGATE SEAL  | Deformed    | 190.00 FL   | *190.00 FL   |
| 2   | 1   |          | *BOOTLID              | Dented      | 1,119.00 FL | *1,119.00 FL |
| 3   | 1   |          | *BOOTLID OUT PANEL    | Repair      | 290.00 FL   | *- FL        |
| 4   | 1   |          | *L/BOOTLID HINGE      | Serviceable | 66.00 FL    | *- FL        |
| 5   | 1   |          | *L/R BUMPER BRACKET   | Cracked     | 29.00 FL    | *29.00 FL    |
| 6   | 1   |          | *L/R C-MEMBER BRACKET | Serviceable | 53.00 FL    | *- FL        |
| 7   | 1   |          | *L/R REFLECTOR        | Cracked     | 46.00 FL    | *46.00 FL    |
| 8   | 1   |          | *R/BOOTLID HINGE      | Serviceable | 66.00 FL    | *- FL        |
| 9   | 1   |          | *R/R BUMPER BRACKET   | Cracked     | 29.00 FL    | *29.00 FL    |
| 10  | 1   |          | *R/R C-MEMBER BRACKET | Serviceable | 53.00 FL    | *- FL        |
| 11  | 1   |          | *R/R REFLECTOR        | Cracked     | 46.00 FL    | *46.00 FL    |
| 12  | 1   |          | *REAR BADGE           | Necessary   | 47.60 FL    | *47.60 FL    |
| 13  | 1   |          | *REAR BUMPER          | Bent        | 696.00 FL   | *696.00 FL   |
| 14  | 1   |          | *REAR BUMPER DAMPER   | Bent        | 114.00 FL   | *114.00 FL   |
| 15  | 1   |          | *REAR BUMPER SPOILER  | Bent        | 206.00 FL   | *206.00 FL   |
| 16  | 1   |          | *REAR BUMPER SUPPORT  | Dented      | 607.00 FL   | *607.00 FL   |
| 17  | 1   |          | *REAR PANEL           | Dented      | 250.00 FL   | *250.00 FL   |
| 18  | 1   |          | *REVERSE SENSOR       | Cracked     | 280.00 FS   | *200.00 FS   |
| 19  | 1   |          | *REAR BUMPER CLIPS    | Necessary   | 48.00 FS    | *22.00 FS    |
| 20  | 1   |          | *BOOT STICKER         | Necessary   | 100.00 FS   | *100.00 FS   |
| 21  | 1   |          | *BUMPER PROTECTOR     | Necessary   | 80.00 FS    | *50.00 FS    |
| 22  | 1   |          | *FLOORBOARD PADDING   | Serviceable | 80.00 FS    | *- FS        |
| 23  | 1   |          | *BADGE MODEL          | Necessary   | 29.00 FL    | *29.00 FL    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>4,524.60</b> | <b>3,780.60</b> |
| <b>- List Item Discount on L Items 35.00/35.00% (\$\$)</b> | <b>1,377.81</b> | <b>1,193.01</b> |
| <b>Total Parts (\$\$)</b>                                  | <b>3,146.79</b> | <b>2,587.59</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                  | Lab.Type | Repairer's | Amount   |
|-------------------------|------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                              |          |            |          |
| 1                       | TOTAL PANEL / MECHANICAL     | New      | 575.00     | 525.00   |
| 2                       | TOTAL PAINTWORK              | New      | 505.00     | 370.00   |
| 3                       | TOTAL PAINT / MATERIAL COSTS | New      | 240.51     | 198.80   |
| Gross Labour Cost (S\$) |                              |          | 1,320.51   | 1,093.80 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >