

ASS. REC. BY:

REF:

es/MSG18012044/RItd3e2/

Special Instruction:

Surveyor
Menmen

Rasul

ASSIGNMENT (Office)

65942560

From (Person):

clarah Milah Yeo

of

MSG

Date/Time:

3/7/18 @

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EC 21P

Insured:

at Workshop m/s

Borneo Motors

Tel:

9699 6192 / 66311505

of

2 pundan Crescent

Policy No:

27 606254 QMY

Claim No:

562 994

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

30/06/2018

CA / ☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:29am @ 3/7/18

Person Contacted:

Carine

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

EC 21P-NA/INCO9009466/r

WA: 01/05/2009

Parting Part 26154.30 (Red: 13637.00 ; 34%)

(08/11/13)

Surveyor: Alan

REF:

CS/MSG18012044/RH43

31554

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: EC 21Pat Workshop m/s Bornito motorof 2, Pandan CassiniInsured: MSH

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 121K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EC 21P Yr Regn: 2013 / NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA LEXUS RX270A c.c. 2672Colour: GRN A/C: Insured / Std / NI / NASp. Reading: 48574 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTJ2A11A502036298Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/06/18 D.O.I. 03/07/18Survey held at Bornito motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

4:11@ revert via merimen

05:17@ 8:01am - authorise repair by Chen How

05:17@ 8:46am - email to canne Yeo authorise repair

RECEIVED 5 DEC 2018

Date/Time, File Pass to?

1) 5/12 Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 15

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 250

Transportation: _____

S + RS: _____

Photos

Others

TOTAL

250Report Format: OPLump Sum / (B.I.): (\$ 26154.30)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Est Auth'd	Status
Main	02 Jul 2018		03 Jul 2018 10:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HO CHIN CHIN, ID: S1113155G, Tel: +6596321113, Email: NOEMAIL		
Vehicle Reg. No.:	EC21P	Date of Loss:	30/06/2018 10:00 - :59 [55 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 562994	Policy/Cover Note No.:	27606254QMY (Comprehensive) Coverage: 13/11/2017 - 12/11/2018
		Excess:	S\$600.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/07/2018]		
Driver/Custodian:	HO CHIN CHIN (74 / Female), NRIC: S1113155G, Tel: +6596321113		
Adj Asg. Remarks:	CAR IN, SURVEY TODAY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***EC21P (562994)**

OD

Jun 30 2018 10:00AM

[HO CHIN CHIN]

Borneo Motors (S) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on **05/07/2018 08:07 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6448.46) - EC21P - Claim Handler: Clara Milah Yeo

Approved:6448.46.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 5 July 2018 8:46 AM
To: Carine Yeo TCBC
Cc: SUR
Subject: EC21P / OD / MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **EC21P (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Carine Yeo TCBC <carine.yeo@borneomotors.com.sg>
Sent: Tuesday, 10 July 2018 4:50 PM
To: Denise Tay (LKKAUTO)
Cc: SUR; Alvin Lee Yee Peng PTCBC
Subject: RE: EC21P / OD / MSIG - URGENT

Dear Rasul

With reference to your tele-conversation with my manager Alvin Lee a while ago.

Kindly note that we will require the replacement of **COMPUTER ASSY, POWER.**

L89650-48390 Computer Assy. Power - \$1420.26 (after discount)

Thank You
Carine Yeo

From: Carine Yeo TCBC
Sent: Monday, 9 July 2018 2:27 PM
To: Denise Tay (LKKAUTO)
Cc: SUR
Subject: RE: EC21P / OD / MSIG - URGENT
Importance: High

Dear Denise,

Noted with Thanks.

We would appreciate if you could inform us in advance, before we proceed with repair and not half way thru the repair.

This is to enable us to work out the amount and see if we can still proceed with the repair.

For this case, we will proceed to Repair Limit of \$33k before deducting of Excess + before GST.

Thank You
Carine Yeo

From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Monday, 9 July 2018 2:07 PM
To: Carine Yeo TCBC
Cc: SUR
Subject: RE: EC21P / OD / MSIG - URGENT

Dear Carine,

As spoken between you and Rasul, the repair limit is at \$33K whichever lower.

Best Regards,

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3155G
Vehicle Details	
Vehicle No.:	EC21P
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS RX270 AUTO
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1AR0982898
Chassis No.:	JTJZA11A502036298
Maximum Power Output:	138.0 kW (185 bhp)
Open Market Value:	\$48,555.00
Original Registration Date:	13 Nov 2013
First Registration Date:	13 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$59,977.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2023
PARF Rebate Amount:	\$44,982.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$79,223.00
COE Rebate Amount:	\$41,027.00
Total Rebate Amount:	\$86,009.00

The information contained herein is correct as at 04 Jul 2018

OK

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 04 Jul 2018

Preliminary Advice

Vehicle No	: EC21P	Accident Date	: 30/06/2018
Make	: LEXUS RX270	Policy No.	: 27606254QMY
Assignment Date	: 03/07/2018	Excess	: S\$600.00
Date of Inspection	: 03/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,885.38
Revised Amount	:S\$	6,448.46
Check Items (Estimated)	:S\$	7,850.92
Total	:S\$	14,299.38
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	121,000.00
COE / PARF Rebate	:S\$	86,009.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,991.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

TYPE OF CLAIM: ☒ OD ☐ OD/UL ☐ DSMCA: Carine Yeo

MOTOR ACCIDENT REPORT

Date Of Report: 27/1/2018 Time: 1030 Date Of Accident: 30/6/2018 Time: 1800
Exact Location Of Accident: Scotts Road towards Orchard
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: EC 21 P Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 811131554
Name Of Registered Owner: Ho Chin Chin
Mobile Number: 98301788 Alternative No: 96321113 Email Address:

Vehicle Particulars

Manufacturer: Toyota ☐ Lexus ☒ Suzuki ☐ Hino ☐ Model: RX270
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIA
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: B27606254 Qmy

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Ho Chin Chin NRIC/ Passport / FIN No: 811131554
Date Of Birth: 31/8/1943 Occupation: Indoor ☒ Outdoor ☐
Date Of Driving Pass: 11/4/1967 Gender: Male ☐ Female ☒
Mobile Number: Fax No: Alternative No:
Address: 4 Cluny Road Postal Code: 259572
Email Address:

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: NA
Vehicle Registration Number of Driver's Own Vehicle (if applicable): NA
Insurance Company of Driver's Own Vehicle (if applicable): NA

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: HF Portion
Number of Passengers in the above vehicle (Including Driver): 1 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
Was any body injured in the Accident? No ☒ Yes ☐
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Number of vehicles involved in the accident: 2
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
Witness Name: Contact No.: Email:
Was there any other vehicle or property damaged? No ☒ Yes ☐
Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☒ Yes ☐
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SDF 9970L Vehicle Make/Model/Colour:
Details Of Properties Damage in Accident:
Vehicle Category:
Name of Driver: Xue Yan
NRIC/Passport/FIN Number: 88177412 I Contact Number: 91799617
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: R/R Portion No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time Hoch Chai 21/1/18

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Describe Circumstances of the Accident

I saw the car in front of me
I heard a bang & swung to my
Right, my steering wheel kept fast
turning & I felt my left hand
pain. Swivel off the queue car &
Stop.

Damage to my car on left hand
front portion.



Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #2-01, SGX Centre 2, Singapore 068807
 Tel: +65 6922 7000, Fax: +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1966 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form N.X.1
 Individual Ownership

MOTOR MAX PLUS
 Comprehensive

Certificate No. E 27606254 QMY

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 EC21P

2. Name of Policyholder
 Ho Chin Chin

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 13/11/2017

4. Date of Expiry of Insurance
 12/11/2018

5. Persons or Classes of Persons entitled to drive*
 Ho Chin Chin

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers


 for Chief Executive Officer

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1113155G



HO CHIN CHIN
何真真
Race
CHINESE
Date of Birth
21-08-1943
Sex
F
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S1113155G



HO CHIN CHIN

Birth Date: 21 Aug 1943
Issue Date: 21 Aug 2005

000752888

1320484



NRIC No. S1113155G



Blood Group: A+ Date of Issue: 02-10-1993

Address
4 CLUNY ROAD
SINGAPORE 1025

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	11 Apr 1967

MP 428A

License No. S1113155G





TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 118462
Tel no.: 6631 1389

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mdm Ho Chin Ching 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 02/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGW	L2	AGL10R	13/11/2013	EC0021P	0	15624 610D/EC0021P/300616

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:B27606254QMY ACC DATE: 30.06.2018 TOW/DRIVE IN: TOWED IN EXCESS: DATE-IN: 30.06.2018 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				180.00 50
2	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
3	B	BP-LAB TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON LHS FRONT FENDER, FRONT BUMPER AND FIX NEW PARTS				2448.00 1632
4	B	BP-RES TO SPRAY PAINT ON FRONT BUMPER AND LHS FRONT FENDER				2180.00 1400
5	B	BP-LAB TO REMOVE AND RE-INSTALL LHS HEADLAMP TO CHECK ON DAMAGES, REPLACE IF DAMAGE (NETT)				204.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 02/07/2018
TIME 11:36

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR 8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mdm Ho Chin Chin 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 02/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGW	L2	13/11/2013	EC0021P	0	15624	610D/EC0021P/30061E
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTJEA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
6	B	BP-LAB TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER (NETT)				204.00
7	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				204 612.00
8	B	BP-LAB TO REMOVE, RENEW AND BALANCE LHS FRONT RIM AND TYRE (NETT)				X 102.00
9	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT (NETT)				204 816.00
10	B	BP-LAB TOWING FEE				180.00
11	1	L52119-4D918 COVER, FR BUMPER	1.00	905.80	15.00	769.93
12	2	L52612-48020 ABSORBER FR BUMPER	1.00	88.80	15.00	75.48
13	3	L52611-48160 ABSORBER, FR BUMPER	1.00	100.60	15.00	85.51
14	4	L52131-48111 REINFORCEMENT, FR	1.00	723.80	15.00	615.23
15	5	L52536-48020 RETAINER, FR BUMPER R	1.00	98.40	15.00	83.64
16	6	L52126-48071 BRACKET, FOG LAMP	1.00	88.80	15.00	75.48
17	7	L47749-50090 CLIP	4.00	1.50	15.00	5.08
18	8	L53879-30040 RETAINER, FR FENDER	4.00	12.10	15.00	41.12
19	9	L52712-48030 GARNISH, FR BUMPER LH	1.00	165.70	15.00	140.84

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 02/07/2018
TIME 11:36PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MB 8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
M5IG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCU1	Mdm Ho Chin Chin 4 Cluny Road
	Document No 0	Singapore 259572
	Document Date 02/07/2018	Mobile: 98301738

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGKW	L2	13/11/2013	EC0021P	0	15624	610D/EC0021P/30061E

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
20	0	L81482-48150 COVER, FOG LAMP, LH	1.00	140.60	15.00	119.51
21	1	L52125-48081 BRACKET, FOG LAMP	1.00	99.10	15.00	84.23
22	2	L52197-30040 BUMPER BRACKET,	2.00	7.50	15.00	12.74
23	3	L53812-48130 FENDER, FR LH	1.00	1536.30	15.00	1305.85
24	4	L53806-48150 SHIELD SUB-ASSY	1.00	501.30	15.00	426.10
25	5	L53883-48040 SEAL, FR FENDER, LH	1.00	92.50	15.00	78.62
26	6	S52161-OK040 BUMPER CLIPS	2.00	4.00	15.00	6.80
27	7	L90467-07201 CLIP	10.00	2.90	15.00	24.60
28	8	T90467-07214 CLIP	10.00	2.20	15.00	18.70
29	9	L81185-48B30 UNIT, HEADLAMP LH	1.00	2935.80	15.00	2495.43
30	0	L52134-48040 REINFORCEMENT FR	1.00	122.80	15.00	104.38
31	1	L90981-20024 BULB, HEADLAMP	1.00	384.20	15.00	326.57
32	2	L90981-13084 BULB HEADLAMP NO.1	1.00	85.00	15.00	72.25
33	3	L90981-15021 BULB	1.00	6.60	15.00	5.61
34	4	L81107-75020 COMPUTER SUB-ASSY	1.00	692.20	15.00	588.37
35	5	T81220-12230 LAMP ASSY, FOG LH	1.00	289.60	15.00	246.16
L/F Rim - 442611 - 48641 - photo			1.0	2719.00	?	2311.15
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 02/07/2018
TIME 11:36PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : 196-8590000-9
ESTIMATE

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCU1	Mdm Ho Chin Chin 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 02/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGKW	L2	AGL10R	13/11/2013	EC0021P	0	15624 610D/EC0021P/30061E

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
UTJZ11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
36	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.				
37	T	RECORD FOR RECORD PURPOSE. - TO CHECK STEERING, CUSTOMER MENTIONED VEHICLE KEPT ON TURNING NON STOP AFTER THE ACCIDENT				

Repair
 Hp 900/10068
 6 days
 03/07/18 @ 1435
 Excess: 600
 Repair
 Recovery 5% paid

5/7/18

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total GST 7.00%	14,574.23 1,020.20
	Please acknowledge receipt of vehicle	Parts	7,668.23	
		Labour	6,766.00	
		Materials	0.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			Less	0.00
			Amount Due	15,594.43

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 02/07/2018
TIME 11:36

30791.38

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Borneo Centre
No. 2 Pandan Crescent
Singapore 121462
Tel no.: 6531 1388

Account Detail	Account No	Customer Detail
WSTG Insurance (Singapore) Pte Ltd 4 Shearson Way #21-01, SGX Center 2 Singapore 068807 Accident Motor Claims Dept	51000004 / 100001	Mrs Ho Chin Chin 4 Uliny Road Singapore 259572 Mobile: 98301739
	Document No 0	
	Document Date 13/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	NISSAN	LE	13/11/2013	EC0021P	0	16329	EC0021P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
UTJRA11A000036298	1A50902855	60	Carina Yeo C L		0:00	0:00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-BUNDRY SUPPLEMENTARY ESTIMATE POLICY NO.: ACT DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				
2	8	BP-ROD L/RH TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - 1/RSB				✓ 3224.00
3	8	BP-CHUF R/LR TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - 2/URS				✓ 1214.00
4	8	BP-MECH TO REMOVE AND RE-INSTALL FRONT CROSSMEMBER TO ENABLE REPAIR (NETT)				✓ 1632.00
5	8	BP-MECH TO REMOVE, LIFT UP AND RE-INSTALL ENGINE TO ENABLE REPAIR (NETT)				✓ 1632.00
6	8	BP-MECH TO REMOVE AND REPLACE FRONT STEERING COLUMN (NETT)				✓ 814.00
7	1	L45510-48630 GEAR ASSY, STEERING	1.00	2062.80	15.00	✓ 1713.36

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

13/11/2018
17:12

EC0021P

WORKSHOP

**Borneo Motors**


**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodywork Centre
49-5 Pandan Crescent
Singapore 117462
Tel no.: 6831 1343**ESTIMATE**

Account Detail	Account No	Customer Detail
MSIS Insurance (Singapore) Pte Ltd 11 Shenton Way #21-01 SWS Centre 1 Singapore 068807 Attn: Motor Claims Dept	51000001 / 100001	MSIS Motor Claim 4 Cluny Road Singapore 259472 Mobile: 98341730
	Document No 0	
	Document Date 13/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	ANTERA	L2	13/11/2013	EC0021P	0	16329	EC0021P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
7FJA11A502026298	1220962218	60	Carina Yeo C L		0.00	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
8	1	145470-48025 ROD ASSY, FR LH	1.00	165.10	15.00	BT 140.73
9	3	145250-48232 COLUMN ASSY	1.00	4702.10	15.00	BT 3996.78
10	4	145997-12020 BOLT	2.00	6.80	15.00	nee 11.56
11	4	145320-48191 SHAFT ASSY, STEERING	1.00	358.60	15.00	BT 305.81
12	6	145100-48460 CO WHEEL ASSY, STEERING	1.00	3644.90	15.00	BT 3099.16
13	7	152211-28029 F/CUSHION, SUSPENSION	2.00	124.90	15.00	nee 223.32
14	8	152215-28010 F/CUSHION, SUSPENSION	1.00	153.30	15.00	nee 129.41
15	9	152217-28010 CUSHION, FR SUSP	1.00	156.80	15.00	nee 133.26
16	0	140010-28050 LINK ASSY, FR	1.00	133.10	15.00	BT 113.03
17	1	140013-48070 ARM, SUSPENSION LH	1.00	782.20	15.00	BT 664.87
18	2	151100-48074 FRAME ASSY	1.00	1396.40	15.00	BT 1186.94
19	2	104307-48100 CABLE SUB-ASSY	1.00	1214.30	15.00	BT 1032.15
20	4	145340-48015 JOINT ASSY, BALL	1.00	223.70	15.00	BT 190.14
21	5	150410-48390 COMPUTER ASSY, POWER	1.00	1670.90	15.00	BT 1420.26

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts 15,376.02	GST 7.004	1,603.42
		Labour 6,528.00		
		Materials 0.00	Less	0.00
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	24,503.42

13/11/2018
17:12

EC0021P

WORKSHOP

**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004/ICCUA1	Mdm Ho Chin Chin 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 05/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGRW	L2	AGL10R	13/11/2013	EC0021P	0	15654 61SU/EC0021P/30061E

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				
2	B	BP-SUSP F/RH TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - F/RHS				photo 1224.00
3	B	BP-SUSP F/LH TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - F/LHS				photo 1224.00
4	B	BP-MECH TO REMOVE AND RE-INSTALL FRONT CROSSMEMBER TO ENABLE REPAIR (NETT)				photo 1632.00
5	B	BP-MECH TO REMOVE, LIFT UP ENGINE AND RE-INSTALL ENGINE TO ENABLE REPAIR (NETT)				photo 1632.00
6	B	BP-MECH TO REMOVE AND REPLACE FRONT STEERING COLUMN (NETT)				photo 816.00
7	1	L45510-48030 GEAR ASSY, STEERING	1.00	2062.80	15.00	? N/A 1753.38

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 05/07/2018
TIME 15:30

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
M&S Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mdm Ho Chin Chin 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 05/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGKW	L2	13/11/2013	EC0021P	0	15654	61SU/EC0021P/30061E
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	2	L45470-49025 ROD ASSY, TIE LH	1.00	165.10	15.00	140.33
9	3	L45250-48232 COLUMN ASSY	1.00	4702.10	15.00	3996.78
10	4	T45897-12020 BOLT	2.00	6.80	15.00	11.56
11	5	L45220-48191 SHAFT ASSY, STEERING	1.00	656.60	15.00	558.11
12	6	L45100-48460 CO WHEEL ASSY, STEERING	1.00	3644.90	15.00	3098.16
13	7	L52211-28020 F/CUSHION, SUSPENSION,	2.00	134.90	15.00	229.32
14	8	L52215-28010 F/CUSHION SUSPENSION,	1.00	169.90	15.00	144.41
15	9	L52217-28010 CUSHION, FR SUSP	1.00	156.90	15.00	133.36
16	0	L48820-28050 LINK ASSY, FR	1.00	139.10	15.00	118.23
17	1	L48069-48070 ARM, SUSPENSION LH	1.00	782.20	15.00	664.87
		L51100-48074 Frame assy	1-0	3396.40		2886.94
		L84307-48100 Cable subassy ✓cra	1-0	1214.30		1032.15
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.			14767.60			21295.60

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	17,376.51
	Please acknowledge receipt of vehicle	Parts 10,848.51	GST 7.00%	1,216.36
		Labour 6,528.00	Less	0.00
		Materials 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	18,592.87

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 05/07/2018
TIME 15:30

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 120462
 Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	MSIG Insurance (Singapore) Pte I 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept 68277888
	Document No 0	
	Document Date 13/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGKW	L2	AGL10R	13/11/2013	EC0021P	48574	15624 610D/EC0021P/30061E
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	05/07/2018	8.00	26/07/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:B27606254QMY ACC DATE: 30.06.2018 TOW/DRIVE IN: TOWED IN EXCESS: \$600.00 DATE-IN: 30.06.2018 DATE SURVEY: 03.07.2018 NO OF REPAIR DAYS: 6 + 9 BY: RASUL (LKK) AUTHORISED ON: 05.07.2018				50.00
2	B	BP-LAB TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON LHS FRONT FENDE R, FRONT BUMPER AND FIX NEW PARTS	*			1632.00
3	B	BP-RES TO SPRAY PAINT ON FRONT BUMPER AND LHS FRONT FENDER	*			1400.00
4	B	BP-LAB TO REMOVE AND RE-INSTALL LHS HEADLAMP TO CHECK ON DAMAGES, REPLACE IF DAMAGE	*			204.00
5	B	BP-LAB TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER	*			204.00
6	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)	18			204.00
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 13/11/2018
 TIME 14:30

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

**TAX INVOICE**

Co Reg No : 196700086Z
 GST Reg No : MP-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCUA1		Customer Detail			
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No 0		MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept 68277888			
				Document Date 13/11/2018					
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
13	AWTGKW	L2	13/11/2013	EC0021P	48574	15624	610D/EC0021P/30061E		
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTJZA11A502036298		1AR0982898	60	Carine Yeo C L	05/07/2018	8.00	26/07/2018 18.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
7	B	BP-WA (NETT)	TO CARRY OUT WHEEL ALIGNMENT			18			204.00
8	B	BP-LAB	TOWING FEE			*			180.00
9	B	BP-SUSP F/LH	TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - F/LHS			18			1224.00
10	B	BP-SUSP F/RH	TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - F/RHS			18			1224.00
11	B	BP-MECH	TO REMOVE AND RE-INSTALL FRONT CROSSMEMBER TO ENABLE REPAIR (NETT)			18			1632.00
12	B	BP-MECH	TO REMOVE, LIFT UP AND RE-INSTALL ENGINE TO ENABLE REPAIR (NETT)			18			1632.00
13	B	BP-MECH	TO REMOVE AND REPLACE FRONT STEERING COL UMN (NETT)			18			816.00
14	V	EXC	Excess element of insurance repair to be paid by the insured party			88			-600.00
15	1	L52119-4D918	COVER, FR BUMPER			1.00	905.80	15.00	769.93
16	2	L52536-48020	RETAINER, FR BUMPER R			1.00	98.40	15.00	83.64
17	3	L47749-50090	CLIP, PIN HOLD			4.00	1.50	15.00	5.08
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors			Customer's Signature			Change Summary			Total
			Please acknowledge receipt of vehicle			Parts Labour Materials Lubrication/Fluid Others			Less
									Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO EC0021P

CUSTOMER

DATE 13/11/2018
 TIME 14:30

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

**TAX INVOICE**

Co Reg No : 196700086Z
 GST Reg No : MB 8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail		Account No S1000004 / ICCUA1		Customer Detail					
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Document No 0		MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept 68277888					
		Document Date 13/11/2018							
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
13	AWTGK	L2	13/11/2013	EC0021P	48574	15624	610D/EC0021P/30061E		
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTJZA11A502036298		1AR0982898		60	Carine Yeo C L	05/07/2018 8.00	26/07/2018 18.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
18	4	L53879-30040	RETAINER, FR FENDER			4.00	12.10	15.00	41.12
19	5	L52197-30040	BRACKET, BUMPER			2.00	7.50	15.00	12.74
20	6	L53812-48130	FENDER, FR LH			1.00	1536.30	15.00	1305.85
21	7	S52161-0K040	PIECE, RR BUMPER			2.00	4.00	15.00	6.80
22	8	T90467-07201	CLIP			10.00	2.90	15.00	24.60
23	9	T90467-07214	CLIP			10.00	2.20	15.00	18.70
24	0	L45250-48232	COLUMN ASSY			1.00	4702.10	15.00	3996.78
25	1	T45897-12020	BOLT			2.00	6.80	15.00	11.56
26	2	L45220-48191	SHAFT ASSY, STEERING			1.00	656.60	15.00	558.11
27	3	L52211-28020	CUSHION, FR SUSP			2.00	134.90	15.00	229.32
28	4	L52215-28010	CUSHION, SUSPENSION			1.00	169.90	15.00	144.41
29	5	T52217-28010	F/SUSPNSION CUSHION,			1.00	156.90	15.00	133.36
30	6	T48820-28050	LINK ASSY, STABILIZER			1.00	139.10	15.00	118.23
31	7	L48069-48070	ARM, SUSPENSION LH			1.00	782.20	15.00	664.87
32	8	L51100-48074	FRAME ASSY			1.00	3396.40	15.00	2886.94
33	9	L45510-48030	GEAR ASSY, STEERING			1.00	2062.80	15.00	1753.38
34	0	L45470-49025	ROD ASSY, TIE LH			1.00	165.10	15.00	140.33
35	1	L43340-49035	JOINT ASSY, BALL			1.00	223.70	15.00	190.14
36	2	L89650-48390	COMPUTER ASSY, POWER			1.00	1670.90	15.00	1420.26
37	3	L84307-48100	CABLE SUB-ASSY			1.00	1214.30	15.00	1032.15
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature			Change Summary		Total		
		Please acknowledge receipt of vehicle			Parts	15,548.30	GST 7.00%	1,788.80	
					Labour	10,606.00			
					Materials	0.00	Less	0.00	
					Lubrication/Fluid	0.00			
					Others	0.00			
							Amount Due	27,343.10	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 13/11/2018
 TIME 14:30

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mdm Ho Chin Chin 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 05/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGKW	L2	AGL10R	13/11/2013	EC0021P	0	15654 61SU/EC0021P/30061E
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				
2	B	BP-SUSP F/RH TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - F/RHS				photo 1224.00 ✓
3	B	BP-SUSP F/LH TO REMOVE & RE-INSTALL/REPLACE SUSPENSION PARTS - F/LHS				photo 1224.00 ✓
4	B	BP-MECH TO REMOVE AND RE-INSTALL FRONT CROSSMEMBER TO ENABLE REPAIR (NETT)				photo 1632.00 ✓
5	B	BP-MECH TO REMOVE, LIFT UP ENGINE AND RE-INSTALL ENGINE TO ENABLE REPAIR (NETT)				photo 1632.00 ✓
6	B	BP-MECH TO REMOVE AND REPLACE FRONT STEERING COLUMN (NETT)				photo 816.00 ✓
7	1	L45510-48030 GEAR ASSY, STEERING	1.00	2062.80	15.00	photo 1753.38 ✓

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 05/07/2018
TIME 15:30

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR 8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 129462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mdm Ho Chin Chin 4 Cluny Road Singapore 259572 Mobile: 98301738
	Document No 0	
	Document Date 05/07/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	AWTGKW	L2	13/11/2013	EC0021P	0	15654	61SU/EC0021P/30061E
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTJZA11A502036298	1AR0982898	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	2	L45470-49025 ROD ASSY, TIE LH	1.00	165.10	15.00	140.33
9	3	L45250-48232 COLUMN ASSY	1.00	4702.10	15.00	3996.78
10	4	T45897-12020 BOLT	2.00	6.80	15.00	11.56
11	5	L45220-48191 SHAFT ASSY, STEERING	1.00	656.60	15.00	558.11
12	6	L45100-48460 CO WHEEL ASSY, STEERING	1.00	3644.90	15.00	3098.16
13	7	L52211-28020 F/CUSHION, SUSPENSION,	2.00	134.90	15.00	229.32
14	8	L52215-28010 F/CUSHION SUSPENSION,	1.00	169.90	15.00	144.41
15	9	L52217-28010 CUSHION, FR SUSP	1.00	156.90	15.00	133.36
16	0	L48820-28050 LINK ASSY, FR	1.00	139.10	15.00	118.23
17	1	L48069-48070 ARM, SUSPENSION LH	1.00	782.20	15.00	664.87

L51100-48074 Frame Assy

L84307-48100 Cable Subassy ✓cra

1-0 3396.40 2886.94

1-0 1214.30 1032.15

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 10,848.51	17,376.51
		Labour 6,528.00	GST 7.00% 1,216.36
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 18,592.87

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/07/2018
TIME 15:30

VEHICLE NO EC0021P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2018		03 Jul 2018 10:02 Edit Adj Rpt	\$26,154.30 Edit Estimates	\$26,154.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HO CHIN CHIN, ID: S1113155G, Tel: +6596321113, Email: NOEMAIL								
Vehicle Reg. No.:	EC21P	Date of Loss:	30/06/2018 10:00 - :59 [55 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 562994	Policy/Cover Note No.:	27606254QMY (Comprehensive) Coverage: 13/11/2017 - 12/11/2018						
		Excess:	S\$600.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/08/2018]								
Driver/Custodian:	HO CHIN CHIN (74 / Female), NRIC: S1113155G, Tel: +6596321113								
Adj Asg. Remarks:	CAR IN, SURVEY TODAY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (04/12/2018): Alert - Adj Mandate Approved (\$26154.30) - EC21P - Claim Handler: Clara Milah Y... - MSIG_SG (10/07/2018): Alert - Adj Mandate Approved (\$24645.90) - EC21P - Claim Handler: Clara Milah Y... - MSIG_SG (05/07/2018): Alert - Adj Mandate Approved (\$6448.46) - EC21P - Claim Handler: Clara Milah Ye...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EC21P (562994)
OD
Jun 30 2018 10:00AM
[HO CHIN CHIN]
Borneo Motors (S) Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	02/07/18 15:39	Accident Statement	 Load HTM	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/18 11:47	Adjuster Immediate Advice	 Load HTM	☒
2	06/07/18 14:59	Adjuster Immediate Advice	 Load HTM	☒
3	06/07/18 15:02	Adjuster Immediate Advice	 Load HTM	☒
4	06/07/18 15:23	Adjuster Immediate Advice	 Load HTM	☒
5	29/11/18 09:42	Adjuster Immediate Advice	 Load HTM	☒
6	29/11/18 12:33	Adjuster Immediate Advice	 Load HTM	☒
Photos/Images			3 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	02/07/18 15:39	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	02/07/18 15:39	Accident Scene Photo [Linked Accident Report Documents]	 Load JPG	☒
11	02/07/18 15:39	Accident Scene Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 15:04	General View	 Load JPG	☒
2	06/07/18 15:04	General View	 Load JPG	☒
3	06/07/18 15:04	General View	 Load JPG	☒
4	06/07/18 15:04	General View	 Load JPG	☒
5	06/07/18 15:04	General View	 Load JPG	☒
6	06/07/18 15:04	General View	 Load JPG	☒
7	06/07/18 15:04	General View	 Load JPG	☒
8	06/07/18 15:04	General View	 Load JPG	☒
9	06/07/18 15:04	General View	 Load JPG	☒
10	06/07/18 15:04	General View	 Load JPG	☒
11	06/07/18 15:04	General View	 Load JPG	☒
12	06/07/18 15:04	General View	 Load JPG	☒
13	06/07/18 15:04	General View	 Load JPG	☒
14	06/07/18 15:04	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
15	06/07/18 15:04	General View	 Load JPG	☒
16	06/07/18 15:04	General View	 Load JPG	☒
17	06/07/18 15:04	General View	 Load JPG	☒
18	06/07/18 15:04	General View	 Load JPG	☒
19	06/07/18 15:04	General View	 Load JPG	☒
20	06/07/18 15:04	General View	 Load JPG	☒
21	06/07/18 15:04	General View	 Load JPG	☒
22	06/07/18 15:04	General View	 Load JPG	☒
23	06/07/18 15:04	General View	 Load JPG	☒
24	06/07/18 15:04	General View	 Load JPG	☒
25	06/07/18 15:04	General View	 Load JPG	☒
26	06/07/18 15:04	General View	 Load JPG	☒
27	06/07/18 15:04	General View	 Load JPG	☒
28	06/07/18 15:04	General View	 Load JPG	☒
29	06/07/18 15:04	General View	 Load JPG	☒
30	06/07/18 15:04	General View	 Load JPG	☒
31	06/07/18 15:04	General View	 Load JPG	☒
32	06/07/18 15:04	General View	 Load JPG	☒
33	06/07/18 15:04	General View	 Load JPG	☒
34	06/07/18 15:04	General View	 Load JPG	☒
35	06/07/18 15:04	General View	 Load JPG	☒
36	06/07/18 15:04	General View	 Load JPG	☒
37	06/07/18 15:04	General View	 Load JPG	☒
38	06/07/18 15:04	General View	 Load JPG	☒
39	06/07/18 15:04	General View	 Load JPG	☒
40	06/07/18 15:04	General View	 Load JPG	☒
41	06/07/18 15:04	General View	 Load JPG	☒
42	06/07/18 15:04	General View	 Load JPG	☒
43	06/07/18 15:04	General View	 Load JPG	☒
44	06/07/18 15:04	General View	 Load JPG	☒
45	06/07/18 15:04	General View	 Load JPG	☒
46	06/07/18 15:04	General View	 Load JPG	☒
47	06/07/18 15:04	General View	 Load JPG	☒
48	06/07/18 15:04	General View	 Load JPG	☒
49	06/07/18 15:04	General View	 Load JPG	☒
50	06/07/18 15:04	General View	 Load JPG	☒
51	06/07/18 15:04	General View	 Load JPG	☒
52	06/07/18 15:04	General View	 Load JPG	☒
53	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
54	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
55	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
56	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
57	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
58	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
59	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
60	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
61	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
62	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
63	06/07/18 15:04	Reinspection Photo	 Load JPG	☒
64	06/07/18 15:04	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
65	06/07/18 15:04	Reinspection Photo		☒
66	06/07/18 15:04	Reinspection Photo		☒
67	06/07/18 15:04	Reinspection Photo		☒
68	06/07/18 15:04	Reinspection Photo		☒
69	06/07/18 15:04	Reinspection Photo		☒
70	06/07/18 15:04	Reinspection Photo		☒
71	06/07/18 15:04	Reinspection Photo		☒
72	06/07/18 15:04	Reinspection Photo		☒
73	06/07/18 15:04	Reinspection Photo		☒
74	06/07/18 15:04	Reinspection Photo		☒
75	06/07/18 15:04	Reinspection Photo		☒
76	06/07/18 15:04	Reinspection Photo		☒
77	06/07/18 15:04	Reinspection Photo		☒
78	06/07/18 15:04	Reinspection Photo		☒
79	06/07/18 15:04	Reinspection Photo		☒
80	06/07/18 15:04	Reinspection Photo		☒
81	06/07/18 15:04	Reinspection Photo		☒
82	06/07/18 15:04	Reinspection Photo		☒
83	06/07/18 15:04	Reinspection Photo		☒
84	06/07/18 15:04	Reinspection Photo		☒
85	06/07/18 15:04	Reinspection Photo		☒
86	06/07/18 15:04	Reinspection Photo		☒
87	06/07/18 15:04	Reinspection Photo		☒
88	06/07/18 15:04	Reinspection Photo		☒
89	06/07/18 15:04	Reinspection Photo		☒
90	06/07/18 15:04	Reinspection Photo		☒
91	06/07/18 15:04	Reinspection Photo		☒
92	06/07/18 15:04	Reinspection Photo		☒
93	06/07/18 15:04	Reinspection Photo		☒
94	06/07/18 15:04	Reinspection Photo		☒
95	06/07/18 15:04	Reinspection Photo		☒
96	06/07/18 15:04	Reinspection Photo		☒
97	06/07/18 15:04	Reinspection Photo		☒
98	06/07/18 15:04	Reinspection Photo		☒
99	06/07/18 15:04	Reinspection Photo		☒
100	06/07/18 15:04	Reinspection Photo		☒
101	06/07/18 15:04	Reinspection Photo		☒
102	06/07/18 15:04	Reinspection Photo		☒
103	06/07/18 15:04	Reinspection Photo		☒
104	06/07/18 15:04	Reinspection Photo		☒
105	06/07/18 15:04	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/07/18 17:25	COE/PARF		☒
2	02/07/18 17:26	CARINE REQUEST FOR SURVEY		☒
3	02/07/18 17:26	ESTIMATE + DRIVING LICENCE		☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	02/07/18 15:39	Accident Sketch Plan [Linked Accident Report Documents]		☒
2	02/07/18 15:39	Accident Sketch Plan [Linked Accident Report Documents]		☒
3	02/07/18 15:39	CI		☒

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
		[Linked Accident Report Documents]		☒
4	02/07/18 15:39	IC [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/18 11:42	ESTIMATE	 Load PDF	
2	06/07/18 15:03	SUPPLEMENTARY	 Load PDF	
3	29/11/18 09:59	ESTIMATE	 Load PDF	
4	29/11/18 12:34	SUPPLEMENTARY 2	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	02/07/18 15:39	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	02/07/18 15:39	Accident Photo	 Load JPG	☒
2	02/07/18 15:39	Accident Photo	 Load JPG	☒
3	02/07/18 15:39	Accident Photo	 Load JPG	☒
4	02/07/18 15:39	Accident Photo	 Load JPG	☒
5	02/07/18 15:39	Accident Photo	 Load JPG	☒
6	02/07/18 15:39	Accident Photo	 Load JPG	☒
7	02/07/18 15:39	Accident Photo	 Load JPG	☒
8	02/07/18 15:39	Accident Photo	 Load JPG	☒
9	02/07/18 15:39	Accident Photo	 Load JPG	☒
10	02/07/18 15:39	Accident Scene Photo	 Load JPG	☒
11	02/07/18 15:39	Accident Scene Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Leng Kee)	Thumbnail	Print
1	02/07/18 15:39	Accident Sketch Plan	 Load JPG	☒
2	02/07/18 15:39	Accident Sketch Plan	 Load JPG	☒
3	02/07/18 15:39	CI	 Load JPG	☒
4	02/07/18 15:39	IC	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18012044/R1TD3E2

Date: 10/12/2018

REFERENCE

Insured/Claimant:	HO CHIN CHIN	Policy No:	27606254QMY	Claim No:	562994
Date of Loss:	30/06/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EC21P	Engine No:	1AR0982898
Make & Model:	LEXUS RX270, 2.7 (A)	Chassis No:	JTJZA11A502036298
Reg. Date:	13/11/2013 (Man. Year: 2013)	Odometer:	48574 km
Colour:	Grey		
Engine Capacity:	2672 cc		
Market Value/New Car Price:	S\$121,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,597.38	15,598.30	10,999.08	41.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,194.00	10,556.00	2,638.00	19.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,791.38	26,154.30	13,637.08	34.27
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	39,191.38	25,554.30	13,637.08	34.80
+ GST 7.00/7.00% (S\$)	2,743.40	1,788.80	954.60	34.80
Nett Amount (S\$)	41,934.78	27,343.10	14,591.68	34.80

INSPECTION

Date of Assignment:	03/07/2018	
Date Inspected:	03/07/2018	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	15.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2018)
Parts: M1-SUV	LEXUS RX270 2.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for EC21P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER, FR BUMPER	Scratched	769.93 FS	*769.93 FS
3	1		*ABSORBER, FR BUMPER	Serviceable	75.48 FS	*- FS
4	1		*ABSORBER, FR BUMPER	Serviceable	85.51 FS	*- FS
5	1		*REINFORCEMENT, FR	Serviceable	615.23 FS	*- FS
6	1		*RETAINER, FR BUMPER R	Necessary	83.64 FS	*83.64 FS
7	1		*BRACKET, FOG LAMP	Serviceable	75.48 FS	*- FS
8	4		*CLIP	Necessary	5.08 FS	*5.08 FS
9	4		*RETAINER, FR FENDER	Necessary	41.12 FS	*41.12 FS
10	1		*GARNISH, FR BUMPER LH	Serviceable	140.84 FS	*- FS
11	1		*COVER, FOG LAMP, LH	Serviceable	119.51 FS	*- FS
12	1		*BRACKET, FOG LAMP	Serviceable	84.23 FS	*- FS
13	2		*BUMPER BRACKET	Necessary	12.74 FS	*12.74 FS
14	1		*FENDER, FR LH	Bent	1,305.85 FS	*1,305.85 FS
15	1		*SHIELD SUB-ASSY	Serviceable	426.10 FS	*- FS
16	1		*SEAL, FR FENDER, LH	Serviceable	78.62 FS	*- FS
17	2		*BUMPER CLIPS	Necessary	6.80 FS	*6.80 FS
18	10		*CLIP	Necessary	24.60 FS	*24.60 FS
19	10		*CLIP	Necessary	18.70 FS	*18.70 FS
20	1		*UNIT, HEADLAMP LH	Serviceable	2,495.43 FS	*- FS
21	1		*REINFORCEMENT FR	Serviceable	104.38 FS	*- FS
22	1		*BULB, HEADLAMP	Serviceable	326.57 FS	*- FS
23	1		*BULB HEADLAMP NO.1	Serviceable	72.25 FS	*- FS
24	1		*BULB	Serviceable	5.61 FS	*- FS
25	1		*LAMP ASSY, FOG LH	Serviceable	246.16 FS	*- FS
26	1		*L/F RIM	Not Necessary	2,311.15 FS	*- FS
27	1		*JOINT ASSY, BALL	Bent	190.14 FS	*190.14 FS
28	1		*COMPUTER ASSY, POWER	Shorted	1,420.26 FS	*1,420.26 FS
29	1		*GEAR ASSY, STEERING	Not Working	1,753.38 FS	*1,753.38 FS
30	1		*ROD ASSY, TIE LH	Bent	140.33 FS	*140.33 FS
31	1		*COLUMN ASSY	Bent	3,996.78 FS	*3,996.78 FS
32	2		*BOLT	Necessary	11.56 FS	*11.56 FS
33	1		*SHAFT ASSY, STEERING	Bent	558.11 FS	*558.11 FS
34	1		*WHEEL ASSY, STEERING	Serviceable	3,098.16 FS	*- FS
35	2		*F/CUSHION SUSPENSION	Necessary	229.32 FS	*229.32 FS
36	1		*F/CUSHION SUSPENSION	Necessary	144.41 FS	*144.41 FS
37	1		*CUSHION, FR SUSP	Necessary	133.36 FS	*133.36 FS
38	1		*LINK ASSY, FR	Bent	118.23 FS	*118.23 FS
39	1		*ARM, SUSPENSION LH	Bent	664.87 FS	*664.87 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRAME ASSY	Bent	2,886.94 FS	*2,886.94 FS
41	1		*CABLE SUB ASSY	Cracked	1,032.15 FS	*1,032.15 FS
42	1		*COMPUTER SUB-ASSY	Serviceable	588.37 FS	*- FS
Total Parts (S\$)					26,597.38	15,598.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON LHS FRONT FENDER, FRONT BUMPER AND FIX NEW PARTS	New	2,448.00	1,632.00
2	TO SPRAY PAINT ON FRONT BUMPER AND LHS FRONT FENDER	New	2,100.00	1,400.00
3	TO REMOVE AND RE-INSTALL LHS HEADLAMP TO CHECK ON DAMAGES, REPLACE IF DAMAGE	New	204.00	204.00
4	TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER	New	204.00	204.00
5	TO RESET ECU AND REPROGRAMME	New	612.00	204.00
6	TO REMOVE, RENEW AND BALANCE LHS FROM RIM AND TYRES	New	102.00	0.00
7	TO CARRY OUT WHEEL ALIGNMENT	New	816.00	204.00
8	TOWING FEE	New	180.00	180.00
9	TO REMOVE & RE-INSTALL / REPLACE SUSPENSION PARTS - F/RHS	New	1,224.00	1,224.00
10	TO REMOVE & RE-INSTALL / REPLACE SUSPENSION PARTS - F/LHS	New	1,224.00	1,224.00
11	TO REMOVE AND RE-INSTALL FRONT CROSSMEMBER TO ENABLE REPAIR	New	1,632.00	1,632.00
12	TO REMOVE, LIFT UP ENGINE AND RE-INSTALL ENGINE TO ENABLE REPAIR	New	1,632.00	1,632.00
13	TO REMOVE AND REPLACE FRONT STEERING COLUMN	New	816.00	816.00
Gross Labour Cost (S\$)			13,194.00	10,556.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >