

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0365/18

DATE : 28-JUN-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
MOTOR CLAIM MANGER VALENCIA

OWNER'S NAME : MR HO TIAN KEONG
ADDRESS : BLK 166 BISHAN STREET 13
#09-252
S(570166)
TELEPHONE NO : 91779251

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SLE5755D
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2302552A
CHASSIS NO : SJNFEAJ11U1710303
MILEAGE : 27551 KM
DATE IN : 28/06/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 28/06/2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

Not Allowed
date
3/7/18
The 3rd party.
HP 90096608
tel: 67418434
Sdy.

* 67038691 elmu@tanabong.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications
- Supplementary items are approved and
is subject to firm quotation from Insurance Company

Acknowledged by repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE5755D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW REAR END PANEL, REAR BUMPER & TRUNKLID	1400.00	625
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	700.00	✓
3	ZZ/003	RENEW H/BACK DOOR GLASS	350.00	✓
4	ZZ/004	APPLY SEALANT TO H/BACK DOOR	200.00	100
5	ZZ/005	APPLY SEALANT TO H/BACK DOOR GLASS	200.00	✓
6	ZZ/006	RENEW REVERSE SENSOR	55.00	✓
7	ZZ/007	RENEW RH H/BACK DOOR LID LAMP	48.00	✓
8	ZZ/008	TO INSTALL REAR H/BACK DOOR SOLAR FILM	11 250.00	X
TOTAL LABOUR CHARGES			3203.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE5755D

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		50.00 ?
2	REAR W/SCREEN SEALANT	SEALANT - 4		80.00 <i>nr</i> ✓
3	REAR LICENCE PLATE	RLP		80.00 <i>Ref</i> ✓
4	LOCK H/BACK DOOR	90502-4EA0B	116.70	? ✓
5	STRIKER-H/BACK DOOR	90570-4EA0A	31.70	<i>nr</i> X
6	GLASS-H/BACK DOOR	90300-4EA0D	930.00	<i>nr</i> X
7	RUBBER-DUM H/BACK DOOR	G2716-89901	60.20	<i>nr</i> ✓
8	WEATHER STRIP H/BACK DOOR	90830-4EA0A	158.70	? ✓
9	MOULDING H/BACK DOOR	90810-4ES0H	336.00	<i>nr</i> ✓
10	H/BACK DOOR	K0100-4EAAC	2936.80	<i>nr</i> ✓
11	PLATE-LUGGAGE REAR	84992-4EA0A	63.50	? ✓
12	REAR END PANEL	G9110-4EAMA	482.60	? ✓
13	STAY LH-REAR BUMPER	H5211-4EAMA	126.00	? ✓
14	RH STAY-REAR BUMPER	H5210-4EAMA	126.00	? ✓
15	REINFORCEMENT REAR BUMPER	H5030-4EAMA	619.20	? ✓
16	ENERGY ABSORBER REAR BUMPER	85090-4EA0B	126.40	? ✓
17	BRACKET-REAR BUMPER RH	85220-4EA0A	35.90	<i>nr</i> ✓
18	BRACKET-REAR BUMPER LH	85221-4EA0A	35.90	<i>nr</i> ✓
19	CLIP REAR BUMPER @1.20 EACH	01553-05933	7.20	<i>nr</i> ✓
20	REAR BUMPER	85022-4EA0H	717.00	<i>nr</i> ✓
SUB TOTAL			6909.80	0.00 210.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1381.96	0.00 0.00
GRAND TOTAL			5527.84	0.00 210.00
OVERALL TOTAL			5737.84	

Rear bumper sensor should

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE5755D

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLE5755D

TOTAL LABOUR CHARGES	3203.00
TOTAL SPARE PARTS CHARGES	5737.84

GRAND TOTAL	8940.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.