

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
143 Cecil Street #01-01 GB Building
069542

Attention : Motor Claim Department
Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000200

Date : 30/06/2018
Vehicle Num. : SLM 4593T (LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 21/01/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER ✓ <i>CUT</i>		500.00
3.	1	REAR BUMPER TOW COVER X		100.00
4.	1	REAR BUMPER REINFORCEMENT ✓ <i>BT</i>		340.00
5.	1	REAR LOWER BUMPER ✓ <i>CUT</i>		560.00
5.	1	REAR BOOTLID OUTER GARNISH R		680.00
List Total S\$:				2,180.00
25.00% Discount S\$:				545.00

				1,635.00

1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR BUMPER CLIP ✓ <i>NEC</i>		50.00 30
3.	1	REVERSE SENSOR		280.00 200
3.	1	REAR BOOTLID OUTER GARNISH CLIPS ✓ <i>NEC</i>		50.00 30
Special Nett Total S\$:				380.00

LABOUR :				
LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.				760.00 400
PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)				600.00 400
Labour Total S\$:				1,360.00

E. & O.E.

Total S\$: 3,375.00
=====

for WORLD AUTO PTE LTD

Sathya Sai
3/7/2018

3 days
LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: