

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 6 July 2018

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBM 8070C

CB 150R Manual Blue

ACCIDENT DATE: 12 June 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar <i>HH</i>	1 set	135.00 X
2 Throttle Grip <i>defused</i>	1 set	60.00 ✓
3 Mirror <i>Cut</i>	1 set	120.00 ✓
4 Balancer <i>Cut</i>	1 set	60.00 ✓
5 Clutch Lever <i>1st</i>	1	50.00 ✓
6 Front Footrest LH <i>Cut</i>	1	65.00 ✓
7 Gear Pedal LH <i>Cut</i>	1	55.00 ✓
		<i>410.00</i>
		<i>369.00</i>
	Sub-Total	545.00
	Less 10%	54.50
	Sub-Total	490.50

Nett items

1 Putty & touch paint work to fuel tank		<i>180.00</i> <i>80/-</i>
2 Towing fee	<i>230.00</i>	<i>40.00</i> <i>30/-</i>
3 Labour to remove & replace damaged parts		<i>160.00</i> <i>120/-</i>
	Sub-Total	380.00
	Nett Total	870.50

599.00

1/5 450/-

LKK Auto Consultants hence notify the Repairer of the following:

- To inspect only any other damage parts or
- To labour require when repair commences, we will advise you and submit supplementary item to you accordingly Without Prejudice* basis
- Third party
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is submitted to insurance company

Acknowledged by Repairer
Signature: _____
Date: _____

SG 98 MOTOR PTE LTD

03/07/2018 @ 1645hrs
HTA Antenna
1/5mm 2 days.
Ryan
LKK Antenna