

輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

29/06/2018

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR TOYOTA VELLFIRE - SLN7991C

|     |                                              |    |          |   |
|-----|----------------------------------------------|----|----------|---|
| 1pc | rear taillamp LH lower garnish               | \$ | 271.45   | 7 |
| 1pc | rear taillamp LH lower garnish side retainer | \$ | 132.25   | 7 |
| 1pc | rear bumper                                  | \$ | 1,711.10 | — |
| 1pc | rear bumper LH side retainer 1               | \$ | 132.25   | — |
| 1pc | rear bumper LH side retainer 2               | \$ | 141.45   | — |
| 1pc | rear bumper LH side reflector                | \$ | 174.25   | X |
| 1pc | rear bumper LH towing cover                  | \$ | 43.70    | X |
| 1pc | rear bumper parking sensor wire              | \$ | 371.45   | 7 |
| 1pc | rear bumper LH side garnish                  | \$ | 274.75   | — |
|     |                                              | \$ | 3,252.65 |   |
|     | less 25%                                     | \$ | 813.16   |   |
|     | balance c/f                                  | \$ | 2,439.49 |   |

|     |                               |      |    |        |   |
|-----|-------------------------------|------|----|--------|---|
| 1pc | rear bumper LH parking sensor | nett | \$ | 380.00 | 7 |
|     |                               |      | \$ | 380.00 |   |
|     | less 10%                      |      | \$ | 38.00  |   |
|     |                               |      | \$ | 342.00 |   |

|                |    |          |      |
|----------------|----|----------|------|
| wiring         | \$ | 80.00    | 151  |
| spray painting | \$ | 500.00   | 3501 |
| labour charges | \$ | 500.00   | 2501 |
| Total          | \$ | 3,861.49 |      |



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Art  
02/07/18  
(Kenneth)  
LKK

Not Authorized  
L1 Rep & 7  
Penny After Paint  
2-3 days