AXA Insurance has sent you a message for claim number S8M00KZY.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal. This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG. https://www.avg.com

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 1 December 2018 9:08 AM

To:

'Raymond'

Cc:

Admin A; Vic (LKKAuto); Marcus Chua (LKKAuto)

Subject:

RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF:

CC4/ASM18012059/Upb3

Without Prejudice

Hi Raymond,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 3,370.50
2. Loss of Use(5days x \$20.00)	\$ 100.00
TOTAL	\$ 3,470.50

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <a href="mailto:chewht@lkkauto.com">chewht@lkkauto.com</a> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond <raymond@bhh.com.sg>
Sent: Friday, 17 August 2018 11:37 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Marcus Chua (LKKAuto)

<MarcusChua@lkkauto.com>

Subject: RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF: CC4/ASM18012059/Upb3

Dear Hsiao Tong,

Noted with thanks.

Best Regards, Raymond Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at http://www.bhh.com.sq

Facebook: http://www.facebook.com/bhhsq

From: Raymond <raymond@bhh.com.sg>

Sent: Saturday, 1 December 2018 9:17 AM

To: Hsiao Tong (LKKAuto)

Cc: Admin A; Vic (LKKAuto); Marcus Chua (LKKAuto)

Subject: RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF:

CC4/ASM18012059/Upb3

Dear Hsiao Tong,

Thank you for your offer.

Regret to inform that we are unable to accept your offer at \$3,470.50.

We hereby counter offer at \$4,500.00 (all in).

Thanks

Best Regards, Raymond Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at http://www.bhh.com.sg

Facebook: http://www.facebook.com/bhhsq



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.si

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L















From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Saturday, 1 December, 2018 9:08 AM To: Raymond <raymond@bhh.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Marcus Chua (LKKAuto)

<MarcusChua@lkkauto.com>

Subject: RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF: CC4/ASM18012059/Upb3

Without Prejudice

Hi Raymond,

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu



# RE: Re:RE: Re:<SEEK MANDATE> - S8M00KZY [ACCIDENT INVOLVING SKG 9172K(OI) & FBG 9417L(TP) ON 16/06/2018]

Type

**Q** Question

### Message

Hi KC, third party rejected our offer at \$3,470.50(all-in) and proposed G/S \$4,500.00(all-in). For your further mandate/instruction please. Thanks. Hsiao Tong - 03 Dec 2018

Reply

From: Shu Pei (LKKAuto)

Sent: Monday, 3 December 2018 4:28 PM

To: Hsiao Tong (LKKAuto)

Subject: RE: New message for service request 54662, vehicle number FBG9417L

TYPE	SENT	FROM	SUBJECT	BODY	
0	12/3/18 1:30 PM	CHAN Kian	Re:RE: Re:RE: Re: <seek< td=""><td>REVISED</td><td>4</td></seek<>	REVISED	4
		Chuan	MANDATE> - S8MOOKZY	OFFER @	
			(ACCIDENT INVOLVING SKG 9172K(OI) & FBG 9417L(TP) ON	\$4,000.00	
			16/06/2018]		

Best Regards, Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----From: Admin-D (LKKAuto)

Sent: Monday, 3 December 2018 1:37 PM To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 54662, vehicle number FBG9417L

Best Regards,

Catherine Chong | Admin LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

----Original Message----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]

Sent: Monday, 3 December, 2018 1:31 PM

To: admin-d@lkkauto.com

Subject: New message for service request 54662, vehicle number FBG9417L

AXA Insurance has sent you a message for claim number S8M00KZY.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal. This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 8 December 2018 2:28 PM

To:

'Raymond'

Cc:

Admin A; Vic (LKKAuto); Marcus Chua (LKKAuto)

Subject:

RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF:

CC4/ASM18012059/Upb3

Without Prejudice

Hi Raymond,

We refer to your below email.

We have our principal instruction to improve our offer at a global sum of \$4,000.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond <raymond@bhh.com.sg> Sent: Saturday, 1 December 2018 9:17 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Marcus Chua (LKKAuto)

<MarcusChua@lkkauto.com>

Subject: RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF: CC4/ASM18012059/Upb3

Dear Hsiao Tong,

Thank you for your offer.

Regret to inform that we are unable to accept your offer at \$3,470.50.

We hereby counter offer at \$4,500.00 (all in).

Thanks

Best Regards, Raymond Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at http://www.bhh.com.sg

Facebook: http://www.facebook.com/bhhsq

From:

Raymond <raymond@bhh.com.sg>

Sent:

Monday, 10 December 2018 8:58 AM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A; Vic (LKKAuto); Marcus Chua (LKKAuto)

Subject:

RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF:

CC4/ASM18012059/Upb3

Dear Hsiao Tong,

Thank you for your offer.

We hereby counter offer at \$4,300.00 (all in).

Appreciate for you to consider our counter offer and revert with the settlement as soon as possible.

Thanks

Best Regards, Raymond Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at http://www.bhh.com.sg

Facebook: http://www.facebook.com/bhhsq



No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.st

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L















From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Saturday, 8 December, 2018 2:29 PM To: Raymond <raymond@bhh.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Marcus Chua (LKKAuto)

<MarcusChua@lkkauto.com>

Subject: RE: Accident Involving FBG9417L & SKG9172K on 16/06/2018 \*LKK REF: CC4/ASM18012059/Upb3

Without Prejudice

Hi Raymond,

Menu



# RE: Re:RE: Re:<SEEK MANDATE> - S8M00KZY [ACCIDENT INVOLVING SKG 9172K(OI) & FBG 9417L(TP) ON 16/06/2018]

Type

Question

Message

Hi KC, third party rejected our offer at \$4,000.00(all-in) and proposed G/S \$4,300.00(all-in). For your further mandate/instruction please. Thanks. Hsiao Tong - 15 Dec 2018

Reply

From:

Shu Pei (LKKAuto)

Sent:

Monday, 17 December 2018 9:41 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: New message for service request 54662, vehicle number FBG9417L

TYPE	SENT	FROM	SUBJECT	BODY	
0	12/15/18 9:06 PM	CHAN Kian	Re:RE: Re:RE: Re:RE: Re:	PLS	+
		Chuan	<seek mandate=""> -</seek>	PROCEED	
			S8MOOKZY [ACCIDENT		
			INVOLVING SKG		
			9172K(OI) & FBG		
			9417L(TP) ON		
			16/06/2018]		

Best Regards, Shu Pei| Admin LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----From: Admin-D (LKKAuto)

Sent: Monday, 17 December 2018 7:49 AM To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 54662, vehicle number FBG9417L

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

-----Original Message-----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]

Sent: Saturday, 15 December 2018 9:07 PM

To: admin-d@lkkauto.com

Subject: New message for service request 54662, vehicle number FBG9417L

AXA Insurance has sent you a message for claim number S8M00KZY.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.

https://www.avg.com

From:

Shu Pei (LKKAuto)

Sent:

Tuesday, 18 December 2018 6:29 PM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: New message for service request 54662, vehicle number FBG9417L

TYPE	SENT	FROM	SUBJECT	BODY	
0	12/18/18 1:36 PM	CHAN Kian	Re:RE: Re:RE:	YES	4
		Chuan	Re:RE: Re: <seek< td=""><td>SETTLEM</td><td></td></seek<>	SETTLEM	
			MANDATE> - S8M00KZY	ENT @	
			(ACCIDENT INVOLVING	\$4,300.00	
			SKG 9172K(OI) & FBG		
			9417L(TP) ON		
			16/06/2018]		

Best Regards, Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----From: Admin-D (LKKAuto)

Sent: Tuesday, 18 December 2018 1:47 PM To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 54662, vehicle number FBG9417L

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

----Original Message-----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]

Sent: Tuesday, 18 December, 2018 1:36 PM

To: admin-d@lkkauto.com

Subject: New message for service request 54662, vehicle number FBG9417L

AXA Insurance has sent you a message for claim number S8M00KZY.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

# THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKG 9172K (Insd vel	h)	Model:	YAMAHA FZ 16
	FBG 9417L (TP veh)			
Date of Accident: 16/06/2018				
Global Sum Settlen	nent : [X] Yes		[ ] No	
Repair Estimate		: \$	6,582.11	
Final Repair Cost		: \$	4,654.50	
Loss of Use		: \$	100.00	5 days at \$20.00 per day
Rental (if any)		: \$		days
LTA / GIA Search F	ee	: \$	2.00	
Others:		: \$		
		: \$		
Final Settlement Su	ım (GLOBAL SUM)	: \$	4,300.00	
below)	kshop GIA Registered	1?		X ] NO (Kindly indicate
A) For Non GIA R	Registered Workshop:		Agreed Liability _	
B) For GIA Regis	NOX.		- 120 	: Yes/ No BOLA Scenario No:
H	(%) bility to be filled only for	chain		y (*):(%) ses where BOLA does not apply.
Remarks	,			от пред поставания пред поставания пред поставания пост
<u></u>				
	on: Payee's Breakdow	n		
1) BAN HOCK H	IN CO., PTE LTD		: \$	4,300.0
	ILAH BTE ABDOL VAHAB		15/01/2019	
	11.11.10		Date	

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

RS		Affiliated to Federation Intern	ationale Des Experts En Auton	nobile
AXA	INSURANCE PTE	LTD	Ref : CC4/ASM1801	2059/Upb3s2
	HENTON WAY #24 TOWERSINGAPO		Date: 15-01-2019	
ATT	ATTN: KIAN CHUAN		Code: ASM	ASSESSMENT OF THE PARTY OF THE
1.		Policy Particula	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SKG 9172K	Veh. Inspected	FBG 9417L
	Policy No.	GA004198/1	Coverage (\$)	0.00
	Claim No.	S8M00KZY	Excess (\$)	0.00
	Assign From	KIAN CHUAN	Assign Date	03/07/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	YAMAHA FZ 16	c.c	153
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	ME121C0DBC2019884	Colour	GREEN / BLACK
	Odometer	99999	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	110/80-17	METZELER	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70-17	METZELER	6 mm
	L/H Rear Tyre			mm
4.		Descr	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE ETAILS.	FRONT PORTION, N/S AND	O/S BODY.
5.		Gen	eral Information	
	Accident Date	16/06/2018	Inspection Date	03/07/2018
	Survey held at	BAN HOCK HIN CO.PTE LT	D	
		NO 6 DEFU LANE 4 SINGAPORE 539410		
5a.			Remarks	
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		
5b.		Estim	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Day	ys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 9417L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	AXLE WHEEL FRONT (CONSISTENT)	SCRATCHED	24.00	24.00
2	BALANCER HANDLE @ \$7.00 (CHROME) (CONSISTENT)	MISSING / SCRATCHED	14.00	14.00
1	BAR FOOTREST FRONT LH (CONSISTENT)	BENT	16.00	16.00
1	BAR FOOTREST FRONT RH (CONSISTENT)	BROKEN	16.00	16.00
1	BAR HANDLE (CONSISTENT)	BENT	42.00	42.00
1	BAR HANDLE EXTENDER (CONSISTENT)	BENT	70.00	70.00
2	BEARING @ \$26.00 (CONSISTENT)	NECESSARY	52.00	52.00
1	BELLYPAN (AFTERMARKET) (CONSISTENT)	BENT	154.00	154.00
2	BOLT FOOTREST REAR @ \$5.00 (CONSISTENT)	NECESSARY	10.00	10.00
1	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT (CONSISTENT)	MISSING / CRACKED	202.00	202.00
1	BRACKET FOOTREST 1 (CONSISTENT)	BENT	82.00	82.00
1	BRACKET FOOTREST RH (CONSISTENT)	BENT	98.00	98.00
1	BRACKET LAMP SIGNAL FRONT LH (CONSISTENT)	BROKEN	5.00	5.00
1	BRACKET SIDE STAND (CONSISTENT)	TO REPAIR SEE LABOUR	12.00	
2	BUSH SWINGARM (METAL) @ \$9.50 (CONSISTENT)	NECESSARY	19.00	19.00
1	CASE AIR CLEANER (CONSISTENT)	CRACKED	26.00	26.00
1	COVER HEADLAMP LH (CONSISTENT)	BROKEN / MISSING	22.00	22.00
1	COVER OIL ELEMENT (CONSISTENT)	DAMAGED	26.00	26.00
1	COVER SIDE 2 (CONSISTENT)	CRACKED	62.00	62.00
1	COVER SIDE 4 (CONSISTENT)	CRACKED	45.00	45.00
1	COVER SIDE LH (CONSISTENT)	CRACKED	86.00	86.00
1	COVER TANK SIDE RH (CONSISTENT)	TO REPAIR SEE LABOUR	118.00	
1	CUSHION (RENTHAL) BAR HANDLE (CONSISTENT)	NOT NECESSARY	54.00	
2	EMBLEM @ \$8.50 (CONSISTENT)	NECESSARY	17.00	17.00
1	FOOTREST REAR 1 (CONSISTENT)	CUT	12.00	12.00
1	FORK FRONT ASSY RH (CONSISTENT)	BENT	335.00	335.00
1	GASKET ELEMENT COVER (CONSISTENT)	NECESSARY	8.00	8.00
1	GRIP HANDLE SET (PLAYLIFE) RH & LH	TORN	32.00	32.00

Report Ref No. CC4/ASM18012059/Upb3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	GROMMET @ \$4.00 (CONSISTENT)	NECESSARY	8.00	8.00
1	HEADLAMP ASSY (CONSISTENT)	CRACKED	155.00	155.00
1	LAMP SIGNAL FRONT LH (CONSISTENT)	BROKEN	22.00	22.00
1	LAMP SIGNAL REAR LH (CONSISTENT)	BROKEN	18.00	18,00
1	LAMP SIGNAL REAR RH (CONSISTENT)	BROKEN	18.00	18.00
1	SET MIRROR (AFTERMARKET) (CONSISTENT)	BROKEN	56.00	56.00
1	MUDGUARD FRONT (BLACK) (CONSISTENT)	BROKEN	98.00	98.00
1	MUDGUARD REAR (1) (CONSISTENT)	CUT	45.00	45.00
1	MUDGUARD REAR (2) (CONSISTENT)	WARPED	28.00	28.00
-1	PANEL 2 (CONSISTENT)	CRACKED	20.00	20.00
1	PEDAL BRAKE (CONSISTENT)	BENT	26.00	26.00
- 1	PLATE (CONSISTENT)	NECESSARY	1.50	1.50
2	RUBBER FOOTREST FRONT @ \$9.50 (CONSISTENT)	TORN	19.00	19.00
1	SCOOP GUIDE AIR 1 (CONSISTENT)	CUT	35.00	35.00
1	SCOOP GUIDE AIR 2 (CONSISTENT)	CUT	35.00	35.00
2	SEAL OIL SWING ARM @ \$20.00 (CONSISTENT)	NECESSARY	40.00	40.00
1	SHIFT PEDAL ASSY (CONSISTENT)	BENT	40.00	40.00
1	STAND MAIN (CONSISTENT)	BENT / TWISTED	60.00	60.00
1	STAND SIDE (CONSISTENT)	REPEATED	22.00	
- 1	STAY (CONSISTENT)	BENT	8.00	8.00
1	STAY HEADLIGHT (CONSISTENT)	BENT	33.00	33.00
1	SWING ARM REAR (CONSISTENT)	BENT	276.00	276.00
1	SWITCH HANDLE (CONSISTENT)	CRACKED	55.00	55.00
1	DUCT CYL BLOCK (CONSISTENT) (ADDITIONAL)	CRACKED	36.00	36.00
1	SHROUD AIR (CONSISTENT) (ADDITIONAL)	CRACKED	35.00	35.00
- 1	SET STEERING CONE (CONSISTENT) (ADDITIONAL)	NECESSARY	53.00	53.00
2	TUBE TOOL @ \$60.00 (CONSISTENT) (ADDITIONAL)	DAMAGED	120.00	120.00
1	COVER TAIL RH (BLACK) (CONSISTENT) (ADDITIONAL)	CRACKED	60.00	60.00
	LESS 10% DISCOUNT			-287.55
			3,081.50	2,587.95
	SPECIAL NETT ITEMS			
1	METER IU (12V) NEW MODEL (SN) (CONSISTENT)	CUT	200.00	165.00
1	PIPE EXHAUST (YOSHIMURA) ASSY (SN) (CONSISTENT)	DENTED / BENT	1,120.00	900.00

Report Ref No. CC4/ASM18012059/Upb3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	PLATE NUMBER FRONT (CURVED) (SN) (CONSISTENT)	MISSING	15.00	10.00
1	STICKER COVER SET (AFTERMARKET) (SN) (CONSISTENT)	NECESSARY	350.00	200.00
			1,685.00	1,275.00
	LABOUR		( )	
	ALIGNMENT BODY.		350.00	300.00
	LANOUR - FOR DISMANTLE AND ASSEMBLING PARTS QUOTED. INCLUSIVE OF THE REPAIR OF BRACKET SIDE STAND AND COVER TANK SIDE RH.		600.00	350.00
	SPRAY PAINTING.		400.00	300.00
	TRANSPORT CHARGES.		35.00	35.00
			1,385.00	985.00
	GRAND TOTAL		6,151.50	4,847.95

RECOMMENDED COST OF REPAIR SUM	4,350.00
--------------------------------	----------

Report Ref No. CC4/ASM18012059/Upb3s2

CHUA KANG SENG

Licensed Appraiser