

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9850Z****AAD1806-278***Not Authored  
4-Sep @ 365.00*

Vehicle No.:	<b>SHB 9850Z</b>
Chassis No.:	VF1ABL15AUC273431
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	28.6.2018
Third Party Insurer :	<b>AIG</b>

PART			LIST
1	1	BUMPER COVER FRT	\$ 1,259.42
2	1	BUMPER SPOILER FRT	\$ 181.75
3	1	BUMPER ABSORBER FRT	\$ 394.68
4	1	BUMPER RETAINER FRT LH	\$ 151.41
5	1	BUMPER SUPPORT FRT	\$ 123.88
6	1	BUMPER RETAINER FRT RH	\$ 150.77
7	1	BUMPER SUPPORT FRT	\$ 123.88
8	1	BUMPER UNDERTRAY FRT	\$ 472.83
9	1	BUMPER GRILLE LOWER FRT	\$ 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$ 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$ 207.21
12	1	BUMPER BEAM FRT	\$ 914.08
13	1	TOW COVER FRT	\$ 28.61
14	1	RADIATOR GRILLE	\$ 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$ 225.36
16	1	RADIATOR GRILLE FRAME	\$ 1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$ 615.90
18	1	FRAME FULL SUPPORT BRACKET	\$ 89.79
19	1	HEADLAMP LH	\$ 1,184.43
20	1	HEADLAMP RH	\$ 1,184.43
21	1	HEADLAMP PANEL FRT LH	\$ 152.15
22	1	HEADLAMP PANEL FRT RH	\$ 152.15
23	1	BONNET	\$ 1,941.63
24	1	BONNET INSULATOR	\$ 405.73
25	1	BONNET STRUT LH	\$ 88.61
26	1	BONNET STRUT RH	\$ 88.61
27	1	BONNET HINGE LH	\$ 348.31
28	1	BONNET HINGE RH	\$ 348.31

X

**Trans-cab Auto Services Pte Ltd**

**AAD1806-278**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9850Z**

29	1	BONNET CABLE COVER	\$	<i>SL</i>	161.03	X
30	1	BONNET SEAL OUTER	\$	<i>SL</i>	92.36	X
31	1	BONNET SEAL INNER	\$	<i>SL</i>	157.28	X
32	1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83	X
33	1	FENDER PANEL FRT RH	\$	<i>R</i>	783.83	X

<b>TOTAL</b>	<b>\$</b>	<b>16,347.81</b>
<b>10%</b>	<b>\$</b>	<b>1,634.78</b>
	<b>\$</b>	<b>14,713.03</b>

**Special Nett**

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i>	52.00	} X
2	1SET	BUMPER CLIP FRT	\$	<i>na</i>	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i>	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i>	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	
7	1	TOW COVER FRT	\$	<i>SL</i>	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	<i>na</i>	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i>	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i>	30.00	
21	1	Windscreen moulding	\$	<i>na</i>	100.00	
22	1SET	Front licence plate with holder	\$	<i>na</i>	80.00 <i>45.00</i>	

<b>TOTAL</b>	<b>\$</b>	<b>562.50</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>15,275.53</b>

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,450.00 *1000*

To apply paint protection system (PPS) maintain and enhancement

\$ *na* 380.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1806-278**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9850Z**

Putty and spray painting of the affected portion.	\$	2201 2,200.00	
To rust-proofing of the affected areas.	\$	na 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	na 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	na 380.00	X
To replace, refix and top up coolant for radiator	\$	na 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	na 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test	\$	na 170.00	X

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental charges are subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**TOTAL \$ 7,790.00**

**Over All Total \$ 23,065.53**

**(LUMP SUM) Repair Days**

**7 DAYS**  
1 day