

SEET AUTO SERVICE

Blk 17 Sector A Sin Ming (Sin Ming Industrial Est)
 #01-67 Singapore 575675 • Tel: 6453 4032
 Registration No: 498262001

发货 / 现金单
 INVOICE / CASH

NO. 13519

M/s OX 8189 C

主号
 先生

Date 16-01-17

数量 Quantity	货名 Description	金额 Amount
1/0	Timing belt	55.00
1/0	Timing belt tensioner	48.00
1/0	Timing belt idler bearing	55.00
1/0	oil pump housing rubber seal	28.00
1/0	crankshaft oil seal	26.00
1/0	camshaft oil seal	24.00
1/0	oil pump shaft oil seal	80.00
1/0	Lower timing belt cover	28.00
1/0	Timing belt cover rubber	36.00
2/0	Alternator belt	18.00
1/0	Aircon belt	24.00
1/0	Power steering belt	60.00
	Towing vehicle	180.00
1/0	New battery	220.00
2/0	New Yokohama tyres	60.00
5/0	Castrol V8 engine oil	22.00
1/0	oil filter	295.00
1/0	Aircon blower motor assy	
	Workmanship to repair engine timing	
	Belt & oil leak & up to 1000 km	1290.00
	总计 TOTAL \$	1634.00

All cheques should be crossed and make payable to "SEET AUTO SERVICE" E.&O.E

总计

TOTAL \$

1634.00

EB

PAID ON 6 Feb 17
 via A DBS BTF

\$1634 Txn: 77265

Issued by

收货人 Received by

经手人 Issued by

Blk 17 Sector A Sin Ming Upp. Ming Industrial Est.
401 67 Singapore 27 26 75 • Tel: 6453 4032
Registration No. K08 16002

NO. 13890

N/A

Q. 8189C

실험
조건

date 16-06-17

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E.&O.E.

总计
TOTAL \$

768	su
-----	----

收货人 Received by

怪手人 Issued by

SEET AUTO SERVICE

Blk 17 Sector A Sin Ming (Sin Ming Industrial Est)
#01-67 Singapore 575675 • Tel: 6453 4032
Registration No: 498262001


发货 / 现金单
INVOICE / CASH

NO. 13564

M/s AX 8189 C

宝号
先生

Date 31-03-17

数量 Quantity	货名 Description	金额 Amount
1	Air con cooling coil Refill air con gas flushing system replace above item	480.00
paid on 14 June 17 via A DBS BTIF \$480 		

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E.&O.E.

总计
TOTAL \$

480.00

收货人 Received by

经手人 Issued by

SEET AUTO SERVICE

Blk 17 Sector A Sin Ming (Sin Ming Industrial Est)
#01-67 Singapore 575675 • Tel: 6453 4032
Registration No: A98262001

SIN MING AUTO CITY
160 SIN MING DRIVE
#03-13 34575722
#86662215

发货 / 现金单
INVOICE / CASH

NO. 13713

M/s GX 8189C

宝号先生

Date 22-12-17

数量 Quantity	货名 Description	金额 Amount
1	Front RH upper arm & ball joint	385.00
1	Front LH upper arm & ball joint	385.00
2	Front RH & LH lower ball joints	180.00
2	Steering tie rod Assy	120.00
2	Steering rack end Assy	160.00
2	Front Shock absorber	180.00
2	Rear Shock absorber	180.00
2	Front Headlight Assy	90.00
3	Light bulb	15.00
6Ltr	Ultrolube V8 engine oil	60.00
1	Oil Filter	22.00
1 Can	Voltac DC diesel Stop Smoke	22.00
	Workmanship to repair front undercarriage noisy & replace upper arm & lower arm ball joints & repair steering rack & clack front & rear brakes & adjust rear brakes & wheel alignment & Servicing Working engine & undercarriage	295.00
		2094.00

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E.&O.E.

总计

TOTAL \$

paid on 24 Jan 18
via A DBS Internet
\$2094

[Signature]

收货人 Received by

[Signature]
经手人 Issued by

SEET AUTO SERVICE

Blk 17 Sector A Sin Ming (Sin Ming Industrial Est)
#01-67 Singapore 575675 • Tel: 6453 4032
Registration No: 49026200J

发货 / 现金单
INVOICE / CASH

NO. 13653

M/S Ax 8189C

宝号先生

EB

Date 15-09-17

数量 Quantity	货名 Description	金额 Amount
4L	Engine Fuel injector only	295.00
6L	Ultralube V8 engine oil	60.00
1L	oil filter	22.00
1L	AN filter	39.00
1Can	Ultronic D12 diesel smoke stop	22.00
	STA inspection fee	31.00
	workmanship 2 year	
	engine smoggy exhaust	
	replace air filter &	
	clock front & rear brakes	
	adjust rear brakes &	
	servicing & washing engine	185.00
	under carriage & gear	
	vehicle for inspection	

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E.&O.E.

总计

TOTAL \$

654.00

paid \$650
via A DBS BTF
on 5 Nov 2017

收货人 Received by

经手人 Issued by

SEET AUTO SERVICE

Blk 17 Sector A Sio Ming (Sio Ming Industrial Est)
#01-62 Singapore 529675 • Tel 6453 4032
Registration No. 498702001

发货 / 现金单
INVOICE / CASH

NO. 13637

Mr. Mr 8189C

宝号先生

Date 16-08-17

数量 Quantity	货名 Description	金额 Amount
1/2	Water pump Assy	128 00
1/2	Front lower gearbox mounting	85 00
4/8	Front brake pads	118 00
1 can	Brake fluid	14 00
5/8	Mobil 1 engine oil	110 00
1/2	oil filter	14 00
1/2	Air filter	32 00
1/2	Air con blower filter	38 00
4/8	Spark plug	48 00
1 can	Toyota radiator coolant	38 00
	workmanship to clock & repair radiator water leaking & replace water pump & gearbox mounting & front brake pads & clock & adjust rear brake & rotate tyres & servicing & washing engine & undercarriage	170 00

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E & O.E

总计

TOTAL \$

795 00

paid via ADBS Bank TF
\$795 on 13 Sept 2017

ttt Seet

收货人 Received by

经手人 Issued by

Unit 17 Sector A Sin Ming (Sin Ming Industrial Estate)
#01-67 Singapore 575625 • Tel: 6453 4032
Registration No. R56082400

NO 12628

94/5

劉錫

Quantity

售名	Description
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

1000

1. Room started again

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E.O.E.

	数量	重量	价值
总计	607.8	19.2	10.5

TOTAL \$

395

Paid \$395 via
A DBS BTF \$an
13 Sept 2017

收货人 Received by

經手人 Issued By


SEET AUTO SERVICE

Blk 17 Sector A Sin Ming (Sin Ming Industrial Est)
#01-67 Singapore 575875 • Tel: 6453 4032
Registration (The ASR22-100)

SIN MIN AUTO CITY
165 SIN MIN INDUSTRIAL
#01-67 575875/241
#96662218

发货 / 现金单
INVOICE / CASH

NO. 13632



08-08-17

M/s BX 8189C

宝号
先生

数量 Quantity	货名 Description	金额 Amount
2x	New Yokohama Tyres	220.00
1x	Keron alternator Assy	320.00
1x	Diesel Filter	55.00
1x	Amaron 105D31R new battery	160.00
	workman's do clock + repair alternator not charging battery + clock + adjust wheel alignment + replace above item	120.00

170809 A DBS BTF \$875
to Harry Seet Auto Inv 13632
on 9 Aug 2017

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E.&O.E.

总计

TOTAL \$

875.00

收货人 Received by

经手人 Issued by

LET AUTO SERVICE
Blk 17 Sector A Sin Ming (Sin Ming Industrial Est)
#01-67 Singapore 575675 • Tel: 6453 4032
Registration No. 498262001

NO. 13563

宝号先生

Date 29-03-17

[illegible]

All cheques should be crossed and make payable to
"SEET AUTO SERVICE"

E. & O. E.

总计
TOTAL \$

经手人 Issued by

收货人 Received by

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	02 Jul 2018	02 Jul 2018 13:00 S\$0.00	03 Jul 2018 14:11 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ADKEL SOLUTIONS LLP , Co. Reg. No.: T13LL0946F, Tel: +6588585019									
Vehicle Reg. No.: GX8189C		Date of Loss: 28/06/2018 09:00 - :59 [165 Months From LTA Reg Date (Man Yr)]							
Claim Type: OD / 563134		Policy/Cover Note No.: A28834218MKC (TP, Fire & Theft) Coverage: 05/10/2017 - 04/10/2018							
		Excess: S\$0.00							
Repairer: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Rohaizal Bin Abdul Rahim] ... [Final Rpt due 02/08/2018]									
Driver/Custodian: TAN ENG KWANG (CHEN YONGGUANG) (49 / Male), NRIC: S69008081, Tel: +6588585019									
Adj Asg. Remarks: Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. FIRE CASE - ASSIGN IMMEDIATELY TO LKK FOR SURVEY & INVESTIGATE									
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
• MSIG_SG (19/07/2018): Alert - Adj Mandate Revoked - GX8189C - Claim Handler: Eliza Ho Teng Boon									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GX8189C (563134)
 OD
 Jun 28 2018 9:00AM
 [ADKEL SOLUTIONS LLP]
 Lai Huat (Meng Kee) Motor Pte Ltd

View

1 per page

Assessment Reports

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/06/18 17:18	Accident Statement	Load HTM	☐
2	02/07/18 13:00	Repairer Estimates	Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/18 10:13	Adjuster Immediate Advice	Load HTM	☐
2	19/07/18 09:59	Adjuster Immediate Advice	Load HTM	☐

3 per page

Photos/Images

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/06/18 17:18	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	29/06/18 17:18	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	29/06/18 17:18	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	29/06/18 17:18	CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	☒
5	02/07/18 12:55	Accident Photo	Load JPG	☒
6	02/07/18 12:55	Front View Left	Load JPG	☒
7	02/07/18 12:55	Front View Right	Load JPG	☒
8	02/07/18 12:55	Engine Compartment	Load JPG	☒
9	02/07/18 12:55	Chassis Number	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/07/18 10:04	General View	Load JPG	☒
2	10/07/18 10:04	General View	Load JPG	☒
3	10/07/18 10:04	General View	Load JPG	☒
4	10/07/18 10:04	General View	Load JPG	☒
5	10/07/18 10:04	General View	Load JPG	☒
6	10/07/18 10:04	General View	Load JPG	☒
7	10/07/18 10:04	General View	Load JPG	☒
8	10/07/18 10:04	General View	Load JPG	☒
9	10/07/18 10:04	General View	Load JPG	☒
10	10/07/18 10:04	General View	Load JPG	☒
11	10/07/18 10:04	General View	Load JPG	☒
12	10/07/18 10:04	General View	Load JPG	☒
13	10/07/18 10:04	General View	Load JPG	☒
14	10/07/18 10:04	General View	Load JPG	☒
15	10/07/18 10:04	General View	Load JPG	☒
16	10/07/18 10:04	General View	Load JPG	☒
17	10/07/18 10:04	General View	Load JPG	☒
18	10/07/18 10:04	General View	Load JPG	☒
19	10/07/18 10:04	General View	Load JPG	☒
20	10/07/18 10:04	General View	Load JPG	☒
21	10/07/18 10:04	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
22	10/07/18 10:04	General View	 Load JPG	☒
23	10/07/18 10:04	General View	 Load JPG	☒
24	10/07/18 10:04	General View	 Load JPG	☒
25	10/07/18 10:04	General View	 Load JPG	☒
26	10/07/18 10:04	General View	 Load JPG	☒
27	10/07/18 10:04	General View	 Load JPG	☒
28	10/07/18 10:04	General View	 Load JPG	☒
29	10/07/18 10:04	General View	 Load JPG	☒
30	10/07/18 10:04	General View	 Load JPG	☒
31	10/07/18 10:04	General View	 Load JPG	☒
32	10/07/18 10:04	General View	 Load JPG	☒
33	10/07/18 10:04	General View	 Load JPG	☒
34	10/07/18 10:04	General View	 Load JPG	☒
35	10/07/18 10:04	General View	 Load JPG	☒
36	10/07/18 10:04	General View	 Load JPG	☒
37	10/07/18 10:04	General View	 Load JPG	☒
38	10/07/18 10:04	General View	 Load JPG	☒
39	10/07/18 10:04	General View	 Load JPG	☒
40	10/07/18 10:04	General View	 Load JPG	☒
41	10/07/18 10:04	General View	 Load JPG	☒
42	10/07/18 10:04	General View	 Load JPG	☒
43	10/07/18 10:04	General View	 Load JPG	☒
44	10/07/18 10:04	General View	 Load JPG	☒
45	10/07/18 10:04	General View	 Load JPG	☒
46	10/07/18 10:04	General View	 Load JPG	☒
47	10/07/18 10:04	General View	 Load JPG	☒
48	10/07/18 10:04	General View	 Load JPG	☒
49	10/07/18 10:04	General View	 Load JPG	☒
50	10/07/18 10:04	General View	 Load JPG	☒
51	10/07/18 10:04	General View	 Load JPG	☒
52	10/07/18 10:04	General View	 Load JPG	☒
53	10/07/18 10:04	General View	 Load JPG	☒
54	10/07/18 10:04	General View	 Load JPG	☒
55	10/07/18 10:04	General View	 Load JPG	☒
56	10/07/18 10:04	General View	 Load JPG	☒
57	10/07/18 10:04	General View	 Load JPG	☒
58	10/07/18 10:04	General View	 Load JPG	☒
59	10/07/18 10:04	General View	 Load JPG	☒
60	10/07/18 10:04	General View	 Load JPG	☒
61	10/07/18 10:04	General View	 Load JPG	☒
62	10/07/18 10:04	General View	 Load JPG	☒
63	10/07/18 10:04	General View	 Load JPG	☒
64	10/07/18 10:04	General View	 Load JPG	☒
65	10/07/18 10:04	General View	 Load JPG	☒
66	10/07/18 10:04	General View	 Load JPG	☒
67	10/07/18 10:04	General View	 Load JPG	☒
68	10/07/18 10:04	General View	 Load JPG	☒
69	10/07/18 10:04	General View	 Load JPG	☒
70	10/07/18 10:04	General View	 Load JPG	☒
71	10/07/18 10:04	General View	 Load JPG	☒

Assessment Reports			1 per page	Thumbnail	Print
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)			
72	10/07/18 10:04	General View	1	Load JPG	✓
73	10/07/18 10:04	General View	1	Load JPG	✓
74	10/07/18 10:04	General View	1	Load JPG	✓
75	10/07/18 10:04	General View	1	Load JPG	✓
76	10/07/18 10:04	General View	1	Load JPG	✓
77	10/07/18 10:04	General View	1	Load JPG	✓
78	10/07/18 10:04	General View	1	Load JPG	✓
79	10/07/18 10:04	General View	1	Load JPG	✓
80	10/07/18 10:04	General View	1	Load JPG	✓
81	10/07/18 10:04	General View	1	Load JPG	✓
82	10/07/18 10:04	General View	1	Load JPG	✓
83	10/07/18 10:04	General View	1	Load JPG	✓
84	10/07/18 10:04	General View	1	Load JPG	✓
85	10/07/18 10:04	General View	1	Load JPG	✓
86	10/07/18 10:04	General View	1	Load JPG	✓
87	10/07/18 10:04	General View	1	Load JPG	✓
88	10/07/18 10:04	General View	1	Load JPG	✓
89	10/07/18 10:04	General View	1	Load JPG	✓
90	10/07/18 10:04	General View	1	Load JPG	✓
91	10/07/18 10:04	General View	1	Load JPG	✓
92	10/07/18 10:04	General View	1	Load JPG	✓
93	10/07/18 10:04	General View	1	Load JPG	✓
Documentation			1 per page	Thumbnail	Print
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)			
1	29/06/18 15:07	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	29/06/18 15:08	POLICE REPORT [Linked Accident Report Documents]	1	Load TIF	
3	29/06/18 15:08	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	1	Load JPG	✓
4	29/06/18 15:08	DRIVER'S NRIC & DRIVING LICENCE [Linked Accident Report Documents]	1	Load TIF	
5	02/07/18 13:00	E-filed GIA report	1	Load PDF	
6	02/07/18 13:00	Driver's NRIC + Driving License	1	Load PDF	
7	02/07/18 13:00	Certificate of Insurance	1	Load PDF	
8	02/07/18 13:00	Enquire PARF / COE Rebate for Registered Vehicle	1	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/07/18 17:27	MAINTAINENCE RECORD - 16.03.2018	1	Load JPG	✓
2	04/07/18 17:27	LTA TEST CERTIFICATE	1	Load JPG	✓
3	04/07/18 17:32	MAINTAINENCE RECORD - 22.12.2017	1	Load JPG	✓
4	04/07/18 17:32	MAINTAINENCE RECORD - 15.09.2017	1	Load JPG	✓
5	04/07/18 17:33	MAINTAINENCE RECORD - 11.08.2017	1	Load JPG	✓
6	04/07/18 17:33	MAINTAINENCE RECORD - 16.08.2017	1	Load JPG	✓
7	04/07/18 17:34	MAINTAINENCE RECORD - 16.06.2017	1	Load JPG	✓
8	04/07/18 17:34	MAINTAINENCE RECORD - 08.08.2017	1	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/18 09:52	INVESTIGATION REPORT	1	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	1 per page	Thumbnail Print

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/06/18 17:18	Accident Statement		Load HTM
2	17/07/18 13:45	Addendum Sheet		Load TIF
3	17/07/18 13:45	Accident Statement Addm. #1		Load HTM

Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/06/18 17:18	Accident Photo		Load JPG
2	29/06/18 17:18	Accident Photo		Load JPG
3	29/06/18 17:18	Accident Photo		Load JPG
4	29/06/18 17:18	CHASSIS NUMBER		Load JPG

Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/06/18 15:07	Sketch Plan		Load TIF
2	29/06/18 15:08	POLICE REPORT		Load TIF
3	29/06/18 15:08	CERTIFICATE OF INSURANCE		Load JPG
4	29/06/18 15:08	DRIVER'S NRIC & DRIVING LICENCE		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18012062/ZVD3E2

Date: 19/07/2018

REFERENCE

Insured/Claimant: ADKEL SOLUTIONS LLP Policy No: A28834218MKC
Date of Loss: 28/06/2018 Nature of Claim: OD Claim No: 563134

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GX8189C** Engine No: 3C3999762
Make & Model: TOYOTA LITEACE, 2.2 D (M) Chassis No: CR425010314
Reg. Date: 28/09/2004 (Man. Year: 2004) Odometer: 0 km
Colour: Silver
Engine Capacity: 2184 cc
Market Value/New Car Price: S\$11,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 165 R13 Rear Tyre Size: 165 R13
Front Left Side: Yokohama 3 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 3 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/07/2018 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 05/07/2018 Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair: 0.0 days

Adjuster: Rohaizal Bin Abdul Rahim

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

TOTAL LOSS ASPECT

Market Value :	\$11,000.00
OMV :	\$18,689.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$21,466.00
COE Rebate (2) :	\$4,893.00
Total Rebate (1) + (2) = :	\$4,893.00

The total amount incurred will be Market Value \$11,000.00 minus Total Rebate \$4,893.00 = \$6,107.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS**Reference****Part Source:**

Parts: N/A TOYOTA LITEACE 2.2 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GX8189C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >