

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9940L**AAD1806-284***Not Authorised
L1 Imp & J 2001*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9940L

VF1ABL15AUC277903

RENAULT

LATITUDE

29.6.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Per</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Per</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPR RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Per</i> 323.05	<i>50%</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Per</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Per</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

161.525

Trans-cab Auto Services Pte Ltd**AAD1806-284**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9940L

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Su</i> 671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Su</i> 543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Su</i> 671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Su</i> 543.47	
37	1 TAILLAMP RH	\$	<i>mgem</i> 552.55	✓
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	X
39	1 TAILLAMP LH	\$	<i>mgem</i> 552.55	✓
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	X
41	1 OUTER PANEL REAR (End Panel)	\$	<i>B</i> 1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>cm</i> 404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Su</i> 612.21	X
45	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	X
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49	X
47	1 FUEL FLAP L70Y	\$	<i>Su</i> 343.57	X
48	1 CHASSIS PANEL REAR LH	\$	<i>R</i> 3,766.43	X
TOTAL		\$	42,823.60	
10%		\$	4,282.36	
		\$	38,541.24	

Special Nett

1	1SET PARKING AID	\$	<i>Su</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>me</i> 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>me</i> 33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>me</i> 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Su</i> 17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>me</i> 30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	<i>me</i> 30.00	✓

Trans-cab Auto Services Pte Ltd**AAD1806-284**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9940L

14	1 BOOT INNER TRIM CLIP	\$	<i>nn</i> 45.00 X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00 X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00 X
17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 X
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 X
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 ✓
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00 ✓
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 X
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i> 385.00 X
25	1 SPARE TYRE	\$	<i>nn</i> 330.00 X

TOTAL	\$	2,225.02
--------------	-----------	-----------------

TOTAL PARTS	\$	40,766.26
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>6000</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>6000</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>600</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>600</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-284**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9940L

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>

TOTAL \$ 12,540.00**Over All Total \$ 53,306.26****(LUMP SUM)****Repair Days***20 DAYS*
*5 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: