

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1305J
 Ref. No : TAX/06/18/2138
 Reg. Date : 19/03/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : HIRAMAT KHAN S/O MOKLIS KHAN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 27/06/2018 01:45:00 PM
 Accident Reported Date / Time : 28/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 28/06/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096765
 Special Instruction to ARC, if any :
 TOWED \$40 / SGH7222E - AXA
 Prepared Date : 28/06/2018 02:10:27 PM



Sathya Sai
 2/7/2018
 SathyaSai @ lkkauto.com

4 days.

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U605738619

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 1,836.00	0.00
Total Material Charges	: 11,909.35	11,909.35
Other Charges	: 1,274.44	0.00
TOTAL	: 16,371.79	0.00
Lum Sum Total	: 16,350.00	0.00
No. of Repair Days	: 9.00	0.00 4 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 29/06/2018 10:39:38 AM	01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/06/2018 09:40:38 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY APRON PANEL LH	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 100
TO RESPRAY FRT MEMBER, LH	180.00	0.00 ?
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 x
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 x
TO RESPRAY RADIATOR SUPPORT LOWER	180.00	0.00 x
Total Spray Painting & Panel Beating	1,836.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 40
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 ✓
TO TOP UP A/C GAS	120.00	0.00 x
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 60
TO REMOVE AND REFIT TYRE	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
TO ALIGN CHASSIS	350.00	0.00 x
Total Other Costs	1,274.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53802-47050		6505558	FENDER FRT/LH ✓OT	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) ✓NEC	1	51.90	25.00	38.92	Replace	Replace	No
53876-47030		6505554	FENDER LINER FRT/LH ✓Deform	1	171.70	25.00	128.77	Replace	Replace	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH ?	1	49.30	25.00	36.97	Replace	Replace	No
53702-47050			FENDER APRON SUB FRT/LH ?	1	637.80	25.00	478.35	Replace	Replace	No
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT ✓cut	1	1,484.20	25.00	1,113.15	Replace	Replace	No
		6503707	TYRE ✓cut	1	126.74	0.00	126.74	Replace	Replace	No
48520-80294			SHOCK ABSORBER FRT/LH ?	1	394.20	25.00	295.65	Replace	Replace	No
48619-28010			SHOCK ABSORBER BEARING, FRT LH/RH ?	1	34.00	25.00	25.50	Replace	Replace	No
48820-47020			STABILIZER BAR LINK FRT/RH/LH ?	1	195.00	25.00	146.25	Replace	Replace	No
43202-47030			STEERING KNUCKLE LH FRT ?	1	580.80	25.00	435.60	Replace	Replace	No
45047-49165			TIE ROD END LH ?	1	159.30	25.00	119.47	Replace	Replace	No
48069-47050			LOWER ARM FRT/LH ?	1	625.90	25.00	469.42	Replace	Replace	No
43420-47030			DRIVE SHAFT LH ?	1	1,543.80	25.00	1,157.85	Replace	Replace	No
43550-47011			WHEEL HUB FRT ?	1	549.70	25.00	412.27	Replace	Replace	No
52256-12010			SIDE CHASSIC BRACE FRT/LH ?	1	103.80	25.00	77.85	Replace	Replace	No
51444-12050		6505472	UNDER COVER SIDE/LH ✓Deform	1	46.10	25.00	34.57	Replace	Replace	No
5702812020			MEMBER SUB-ASSY, FR LH ?	1	810.70	25.00	608.02	Replace	Replace	No
52119-47930		6505517	BUMPER FRT ✓cut	1	482.00	25.00	361.50	Replace	Replace	No
90467-07211			BUMPER CLIPS ✓NEC	10	2.10	25.00	15.75	Replace	Replace	No
52116-47040		6505516	BUMPER SUPPORT F/LH X	1	76.40	25.00	57.30	Replace	Replace	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER X	1	311.10	25.00	233.32	Replace	Replace	No
82113-47180			WIRE, ENGINE ROOM, NO.3 ?	1	242.00	10.00	217.80	Replace	Replace	No
31220-12230		6505438	FOG LAMP LH X	1	280.10	10.00	252.09	Replace	Replace	No
31521-17050			LENS & BODY, FR TURN LH ?	1	511.80	10.00	460.62	Replace	Replace	No
76851-17020		6505616	BUMPER LIP FRT ✓Deform	1	139.60	25.00	104.70	Replace	Replace	No
12618-17050		6505540	BUMPER FRT ABSORBER LOWER ?	1	127.70	25.00	95.77	Replace	Replace	No
11410-2105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace	No

Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
81170-47500		6505436	HEAD LAMP LH ✓ <i>SCR</i>	1	945.20	10.00	850.68	Replace	Replace	No
53201-47902			SUPPORT SUB-ASSY ?	1	1,460.40	25.00	1,095.30	Replace	Replace	No
88460-47150			A/C CONDENSER ✕	1	1,181.90	25.00	886.42	Replace	Replace	No
16400-37230		6505302	RADIATOR ASSY ✕	1	1,496.90	25.00	1,122.67	Replace	Replace	No
16572-37120			RADIATOR HOSE ✕ LOWER	1	42.40	25.00	31.80	Replace	Replace	No
G9010-47031			RADIATOR ASSY, ✕ UPPER	1	679.60	25.00	509.70	Replace	Replace	No
	COMMO N		COOLANT ✕	1	12.32	0.00	12.32	Replace	Replace	No
16711-37040			FAN SHROUD ✕	1	244.50	25.00	183.37	Replace	Replace	No
16712-37030			FAN SHROUD TOP ✕	1	99.60	25.00	74.70	Replace	Replace	No
16361-37010			FAN BLADE ✕	1	158.60	25.00	118.95	Replace	Replace	No
16361-28360			FAN BLADE NO 2 ✕	1	204.20	25.00	153.15	Replace	Replace	No
16363-37010			FAN MOTOR NO 1 ✕	1	538.30	25.00	403.72	Replace	Replace	No
16363-37020			FAN MOTOR NO 2 ✕	1	538.30	25.00	403.72	Replace	Replace	No
57104-47020		6505507	RADIATOR LOWER SUPPORT ✕	1	876.30	25.00	657.22	Replace	Replace	No
TOTAL MATERIALS								14,886.78	14,886.69	
TOTAL MATERIALS(Discounted)								11,909.35	11,909.35	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									