

22/03/2002

ASS. REC. BY:

REF:

CS/SPF 18012070/ Gt bez

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 03072018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / FD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 7041T Insured: QX 207T

at Workshop m/s Ryder Auto Tel: \_\_\_\_\_

of Blk 1 Kaki Bukit Ave 6 #01-56

Policy No: \_\_\_\_\_ Claim No: AEKD / 105/009 / 2018 / 081

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 29062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp' 06072018 @ H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 03072018 Person Contacted: Mr. Chan Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 7041T - NA / A/GI 8011902/h4 D.O.A: 29062018
	QX 207T - X
	Submit \$2200, 3 days. Uped: 5925.321.72%

**ASSIGNMENT**

SLS7041T

From: \_\_\_\_\_ Date: 6/7/18

Estimated Cost: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS-7041T

at Workshop m/s Ryder Auto

of Bkt1 Kaki Bkt Ave 6 #01-56

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record) after 11am

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: ~~SLS7041T~~ Yr Regn: 29 Sep 2017

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496

Colour: ~~Black~~ Silver A/C: Insured / Std / NI / NA

Sp. Reading: 5368 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: JM6BN22A-8J 0179180

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60R16  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 8 mm

Rear R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. \_\_\_\_\_ D.O.I. 06-07-18

Survey held at W/S 4:20AM

Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 JUL 2018

Date/Time, File Pass to?  : Preli. Report

1) 2017 Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I. (\$) 2200

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: 280

Transportation: \_\_\_\_\_

S + RS, SI \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

280



**SINGAPORE  
POLICE FORCE**

**SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333**

**Your Ref :** SLS7041T

**Our Ref :** AEMD/105/009/2018/081

**Date :** 3 July 2018

**Tel:** 64784840

**Fax:** 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

**Via Fax only: 62564315**

Dear Sir/Madam,

**RTA ON 29 JUNE 2018 INVOLVING GOVT VEH QX207T AND OTHER VEH SLS7041T**

We refer to the above matter.

- 2 Please arrange for a Pre Repair Inspection of vehicle no. **SLS7041T** at **M/s Ryder Auto Pte Ltd** of **1 Kaki Bukit Ave 6 #01-56, Autobay@Kaki Bukit, Singapore 417883.**
- 3 For appointment please contact **Chan (97924673** or **Orson (90908277).**
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours sincerely,

Abdul Rahman  
Accident Claims Officer  
for Assistant Director

## ESTIMATE OF REPAIR

(Without Prejudice)

Veh # : SLS7041T Model : MAZDA 3

Date Of Accident: 29/6/2018

Location : IN BETWEEN BLK 252 & 254 JURONG EAST ST 24

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>List Items</u>				
1 pc	Front bumper / ee		825.5	1,192.90	? /
10 pcs	Front bumper clips / mc			45.00	/ /
1 pc	Front bumper enforcement X NN			410.00	X
1 pc	Front bumper insulator X / CRA			289.30	/ /
1 pc	Front bumper tow cover X			101.60	X
1 pc	Front bumper o/s fog lamp X			338.45	X
1 pc	Front bumper o/s fog lamp bracket X } NN			68.40	X
1 pc	Front bumper o/s corner clips / mc			75.00	/ /
1 pc	Front bumper grille (Lower) X NN			211.20	X
1 pc	Front bumper o/s retainer / ee			80.70	/ /
1 pc	Front bumper o/s indicator lamp X NN			486.20	X
1 pc	Front grille / cut		129	482.60	? /
4 pcs	Front grille clips / mc			18.70	/ /
1 pc	Front grille moulding X / GAT NN			322.20	X
1 pc	Front grille emblem / mis			61.00	/ /
2 pcs	Front grill chrome / 1 pc CRA			295.00	? /
1 pc	Front support panel X			655.00	X
1 pc	Front support panel garnish X			96.80	X
8 pcs	Front support panel garnish clips X } NN			37.40	X
1 pc	Front support panel bracket X			81.80	X
1 pc	Front o/s head lamp X / CRA		1019.5	2,794.60	? /
2 pcs	Front o/s head lamp clips X NN			10.30	X
	Sub-Total			8,154.15	
	After -20%			<b>6,523.32</b>	

# Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: ryderautoworkshop@gmail.com

Fax: 64815390

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$
<u>Special Nett Items</u>				
1 pc	Front reg. no. plate / CPA			45.00
1 pc	Front reg. no. plate bracket X NN			29.00
Sub-Total				<b>74.00</b>
Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$
<u>Labour</u>				
1	To remove and refit front damage parts		200	800.00
2	To spray painting		200	1,000.00
5	To check wiring and align front head lamp		R ✓	30.00
6	To re-seal anti-rust	NN X		80.00
Sub-Total				<b>1,910.00</b>
After -20%				<b>1,528.00</b>
Total				<b>8,125.32</b>

3 Days.

lump sum repair.

After repair photos.

Guo Qiang - 82880282

06/7/18.

*[Signature]*  
10/7/18

8507.32

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/06/2018 16:14
Date Of Accident	29/06/2018 11:20
Exact Location Of Accident	IN BETWEEN BLK 252 & 254 JURONG EAST ST 24
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS7041T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE CHAN MIN
NRIC No	S0218944E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93741966
Alternative Phone No	OFFICE-93741966
<b>Vehicle Particulars</b>	
Manufacturer	MAZDA
Model	MAZDA3 SEDAN 1.5 AT EU6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700069396
Cover Note Number	-

### Driver

Name of Driver	LEE CHAN MIN
NRIC No	S0218944E
Date Of Birth	20/12/1941
Occupation	INDOOR
Date Of Driving Pass	07/02/1961
Driving Experience	57 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93741966
Fax Number	
Contact Number	OFFICE-93741966
EMail Address	NOEMAIL



**SINGAPORE  
POLICE FORCE**



T/20180629/2108

2 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180629/2108

**CONTINUATION OF REPORT**

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS7041T	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700069396	29/09/2017	28/09/2018

**Brief Details.**

ON THE ABOVE MENTIONED DATE TIME AND LOCATION

I JUST FINISHED BUYING FOOD AT BLK 254 AND WAS DRIVING AWAY. I WAS DRIVING AT QUITE A FAST SPEED TO GO OUT OF THE CARPARK. AS I WAS DRIVING, I SAW A POLICE VAN(QX207T) GOING OUT OF THE DROP-OFF POINT OF THE CARPARK. I STOPPED MY CAR FOR THE POLICE VAN. AS I STOPPED, THE POLICE VAN DID NOT STOP AT THE STOP LINE AND WAS GOING TO TURN RIGHT WHEN THEY HIT THE FRONT OF MY CAR. POLICE CAME. NOONE WAS INJURED.

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8944E
Vehicle Details	
Vehicle No.:	SLS7041T
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	P520469107
Chassis No.:	JM6BN22A8J0179180
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,726.00
Original Registration Date:	29 Sep 2017
First Registration Date:	29 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$10,726.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2027
PARF Rebate Amount:	\$8,044.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$39,553.00
<b>Total Rebate Amount:</b>	<b>\$47,597.00</b>

The information contained herein is correct as at 09 Jul 2018

OK





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref :	CS/SPF18012070/Gtbe2
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date :	28-08-2018
ATTN : ABDUL RAHMAN		Code :	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 207T	Veh. Inspected	SLS 7041T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/081	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	03/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8J0179180	Colour	SILVER
Odometer	5368	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	8 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	8 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	8 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	29/06/2018	Inspection Date	06/07/2018
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 7041T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	1,192.90	825.50
10	FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	FRONT BUMPER ENFORCEMENT	NOT NECESSARY	410.00	-
1	FRONT BUMPER INSULATOR	CRACKED	289.30	289.30
1	FRONT BUMPER TOW COVER	NOT NECESSARY	101.60	-
1	FRONT BUMPER O/S FOG LAMP	NOT NECESSARY	338.45	-
1	FRONT BUMPER O/S FOG LAMP BRACKET	NOT NECESSARY	68.40	-
1	FRONT BUMPER O/S CORNER CLIPS	NECESSARY	75.00	75.00
1	FRONT BUMPER GRILLE (LOWER)	NOT NECESSARY	211.20	-
1	FRONT BUMPER O/S RETAINER	DEFORMED	80.70	80.70
1	FRONT BUMPER O/S INDICATOR LAMP	NOT NECESSARY	486.20	-
1	FRONT GRILLE	CUT	482.60	129.00
4	FRONT GRILLE CLIPS	NECESSARY	18.70	18.70
1	FRONT GRILLE MOULDING	NOT NECESSARY	322.20	-
1	FRONT GRILLE EMBLEM	MISSING	61.00	61.00
2	FRONT GRILL CHROME	CRACKED-1PC ONLY	295.00	295.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	655.00	-
1	FRONT SUPPORT PANEL GARNISH	NOT NECESSARY	96.80	-
8	FRONT SUPPORT PANEL GARNISH CLIPS	NOT NECESSARY	37.40	-
1	FRONT SUPPORT PANEL BRACKET	NOT NECESSARY	81.80	-
1	FRONT O/S HEAD LAMP	CRACKED	2,794.60	1,019.50
2	FRONT O/S HEAD LAMP CLIPS	NOT NECESSARY	10.30	-
	LESS 20% DISCOUNT		-1,630.83	-567.74
			6,523.32	2,270.96
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT REG. NO. PLATE (SN)	CRACKED	45.00	45.00
1	FRONT REG. NO. PLATE BRACKET (SN)	NOT NECESSARY	29.00	-
			74.00	45.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIT FRONT DAMAGE PARTS.		800.00	200.00
	TO SPRAY PAINTING.		1,000.00	200.00
	TO CHECK WIRING AND ALIGN FRONT HEAD LAMP.		30.00	30.00

Report Ref No. CS/SPF18012070/Gtbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SEAL ANTI-RUST.	NOT NECESSARY	80.00	-
			1,910.00	430.00
	<b>GRAND TOTAL</b>		<b>8,507.32</b>	<b>2,745.96</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,200.00</b>

Report Ref No. CS/SPF18012070/Gtbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Address 57 HUME AVE #10-02  
 Postcode 598753  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD ON COLLISION  
 Weather Conditions DRIZZLING  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TRAFFIC POLICE DIVISION HQ  
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 65470000 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO POLICE REPORT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: WITH DRIVER  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number QX207T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category GOVERNMENT  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name