

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBC 3389U

DATE ACCIDENT : 25.01.2017

MAKE / MODEL : KTM 400

S/No	DESCRIPTION	AMOUNT
1	F BRAKE DISC	\$? 295.00
2	HANDLER BAR	\$? 285.00
3	UNDLER BRACKET	\$? 498.00
4	STEERING CON	\$? 150.00
5	FORK INNER TUBE x2	\$? 2,700.00
6	R/H RADIATOR ASSY	\$ bt- 650.00
7	L/H RADIATOR ASSY	\$? 650.00
8	F WHEEL RIM	\$? 680.00
9	F WHEEL SPOKE	\$? 265.00
10	R/H SIDE PANEL	\$ cut ✓ 110.00
11	F FENDER	\$ cut ✓ 120.00
12	REAR SUB FRAME	\$? 950.00
13	SWING ARM	\$? 1,350.00
14	CHAIN GUARD	\$ bt- 95.00
15	GEAR LEVER	\$? 130.00
16	GEAR SHAFT	\$? 165.00
17	SHAFT SEAL	\$? 28.00
18	CLUTCH GASKET	\$? 45.00
19	4T OIL x2	\$? 60.00
20	COOLANT	\$ nu- 50.00
21	FORK OIL	\$? 80.00
22	FORK OIL SEAL	\$? 120.00
	TRANSPORT	\$ 60 80.00
	LABOUR	\$ 300 650.00
	Tanjil 97995749 ~ WP' 4/7/18 Resurvey new parts shop lkkauto.com 5 days.	
	Total	\$ 10,206.00

LKK Auto Consultants hence
the Repeater of the following:

- To resurvey before/after spray pain
- To display damaged part(s) during
- Parts prices are subject to confirm
- Third party survey is on a "Without
- No illegal modification(s) is allowed
- Supplementary item(s) must be res
- is subject to final approval from Ins

Acknowledged by Repairer
Signature:
Date: