

INS. CASE OWNER:

CC 3/AIG1801 WTB; T. WTB

LKK
IDAC

Surveyor:

MTH

DOI:

ASSIGNMENT

1/6/18

Date / Time

2/7/18

Registered in Merimen:

2/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SJL 9507P

Name of Insured

TAN BOON LENG KENNETH

Insured Tel No.

HP: 9722300

Excess Sec II :SS

D.O.A: 2/6/18

Is driver the owner?

YES

Nature of Accident:

If NO, Driver Name / Age:

TAN BOON LENG KENNETH

Driver Tel No.:

(VA) YES / NO

Claim No.

264267476959

Policy No.

20016450-09

Make / Model

mitsubishi

Place of Accident

PLE Tngs Tngs

Of GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

SKE 4255T



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

5/7/18

TTH

9/7/18

Called OI no response.

Spoke to OI he confirmed the accident details. Informed TP claim and he agree to settle.

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

YTHIM 18/7

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

ITA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time

Sent By:

FINALIZATION

Date/Time: 20-12-18

Confirm with: CHIRLING

Confirm by: PTH

Repair Cost:

P/P

\$5,583.71

(3 days) Reduction:

7 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 05-01-19

Confirm with: CHIRLING

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

WSP:

\$5,583.71

Loss of Rental (LOR):

\$5

(3 days)

Loss of Use (LOU):

\$5

(\$ 100 x 3 days)

Loss of Income (LOI):

\$5

(\$ x 3 days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/TA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +320 + *20

Total:

\$5,583.71

Global Sum SS:

FINAL PAYMENT

Date/Time: 06-01-19

Confirm with: CHIRLING

Email ☒ Call ☐

Payee 1:

\$5,583.71

Name 1:

PERFORMANCE MOTOR LIMITED

Payee 2 (Strike if N.A.):

\$5

Name 2:

Payee 3 (Strike if N.A.):

\$5

Name 3:

COPY SENT

Surveyor:

Tanja

REF:

ALG

U

e

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 960K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Alan

Vehicle: IN / OUT

Veh No: SICE 4355T Vt Regn: 2012, MarchType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW X1 c.c. 1995Colour: Black A/C: Insured / Std / NI / NASp. Reading: 39554 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAVL32070V E 9 2739Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 275/50R12R: 7 -BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 1/8/18Survey held at PMCDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP: \$5,216.55 (GID: \$392.95 7%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$ _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7245Z
Vehicle Details	
Vehicle No.:	SKE4355T
Vehicle to be Exported:	No
Intended De-registration Date:	02 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I AT D/AB 2WD 5DR GAS/D SR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	A021J011N46B20BD
Chassis No.:	WBAVL32070VP92739
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$28,977.00
Original Registration Date:	01 Mar 2012
First Registration Date:	01 Mar 2012
Transfer Count:	0
Actual ARF Paid:	\$28,977.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2022
PARF Rebate Amount:	\$18,835.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,340.00
COE Rebate Amount:	\$25,882.00
Total Rebate Amount:	\$44,717.00

The information contained herein is correct as at 02 Aug 2018

OK




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/AIG18012076/wb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 03-07-2018	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 9507P	Veh. Inspected	SKE 4355T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/06/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Mon 16/07 @ 10am

SKE43551

S&R Change to Mon 30/07 @ 8am (S&R)

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401555W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63443773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

02 JUL 2018

Estimate No. : b1 47477
Date Estimated : 28/06/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Krishnaveni D/O P Kasivisvanathan
4 Jalan Minggu

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 577337

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper & attachments including to knock out dented area caused by the accident.

850 1,275.00

To respray rear bumper

934 1,038.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION

BODY NUT
RR BUMPER TOW HOOK COVER (SE)
RR BUMPER CTR GUIDE
RR BUMPER CARRIER
RR BUMPER LOWER COVERING
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER (PRIMED)
RR BUMPER BOTTOM (XLINE/PDC)
EXPANDING RIVET
RR BUMPER LH REFLECTOR
RR BUMPER RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (SCHWARZ)- ELBOW

QTY	PRIC
10	0.90
1	62.10
1	61.35
1	411.25
1	31.45
1	56.95
1	56.95
1	831.40
1	322.35
30	1.35
1	35.20
1	35.20
2	5.05
2	236.85

VALUE
NV? 9.00
de 62.10
NV? 61.35
NV? 411.25
NV? 31.45
NV? 56.95
NV? 56.95
de 831.40
de 322.35
NV 40.50
NV 35.20
NV 35.20
NV 10.10
NV 473.70

Total Parts : 2,437.50

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190523/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47477
Date Estimated : 28/06/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 1/6/18 @ 2:15 Excess S\$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 9749 5249 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail TanJiah@Performance.com

No. of Working Days Recommend 03 days

Labour 1	:	2,747.00
Parts	:	2,437.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	362.92
Grand Total	:	<u>5,547.42</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47477
Date Estimated : 28/06/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Krishnaveni D/O P Kasivisvanathan
4 Jalan Minggu

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 577337

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
#	To tow accident vehicle to PML workshop	195.00		195.00 ✓
#	To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER TOW HOOK COVER (SET) *	62.10	1.00		62.10 - Repair.

Total Labour : 425.00
Total Parts : 62.10
Total Labour & Parts : 487.10

Performance Motors Limited

A member of the Silver Star Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-K



FINAL REPORT

Estimate No. : b1 47477
Date Estimated : 28/06/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Krishnaveni D/O P Kasivisvanathan
4 Jalan Minggu

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 577337

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
* To replace rear bumper and attachments include making good the trunk floor panel and knocking out dented areas caused by the accident	1275.00		1,275.00		
* To respray rear bumper and trunk floor panel	1412.00		1,412.00		
To remove and install old PDC assembly reconnect to new bumper include conducting checks for proper function	150.00		150.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00		
# To tow accident vehicle to PML workshop	195.00		195.00		
# To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00		
Sundries	80.00		80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER TOW HOOK COVER (SET) *	62.10	1.00		62.10
RR BUMPER CARRIER	411.25	1.00		411.25
RR BUMPER RH GUIDE	56.95	1.00		56.95
RR BUMPER (PRIMED)	831.40	1.00		831.40
RR BUMPER BOTTOM (XLINE/PDC)	322.35	1.00		322.35
EXPANDING RIVET	1.35	30.00		40.50

SUPPLEMENTARY ITEMS

Total Labour :	3,492.00
Total Parts :	1,724.55
Total Labour & Parts :	5,216.55
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,216.55
GST @7%:	365.16
Grand Total :	5,581.71

Mon 14/07 @ 10am

SKE4355T

O/R Change to Mon 30/07 @ 8am (S&R)

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 1571111M SGT Reg. No. M2-0020081-X

151, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63196100 (Sales & Admin)
63196111 (AfterSales)
Fax: 63196170

159, Tampung Road
East Coast Centre
Singapore 456199
Tel: 63156600 (AfterSales)
Fax: 63156711

311, Alexandra Road
Sime Darby Business Centre
Singapore 159941
Tel: 63196120 (AfterSales)
63196133/318 (Motorcard)
Fax: 63196601 (AfterSales)
63196624 (Motorcard)



1288382

GST REG. NO : M2 - 0020081 - X

02 JUL 2018

ESTIMATE

Estimate No.	: b1 47477	Page No. : 1 of 5
Date Estimated	: 28/06/2018	
Prepared By	: Han Kwan Yong	

- ESTIMATE REPAIR FOR - Krishnaveni D/O P Kasivisvanathan 4 Jalan Minggu Singapore 577337	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper & attachments including to knock out
dent area caused by the accident.

1275 ~~850~~ 1,275.00

To respray rear bumper

1412 934 1,038.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries. ~~SUPPLEMENT~~

No photos taken
on RR for trunk floor

? 80.00

*195 towing

*R/I boot carpet

23%

Total Labour 1: 2,747.00

DESCRIPTION

BODY NUT
RR BUMPER TOW HOOK COVER (SE)
RR BUMPER CTR GUIDE
RR BUMPER CARRIER
RR BUMPER LOWER COVERING
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER (PRIMED)
RR BUMPER BOTTOM (XLINE/PDC)
EXPANDING RIVET
RR BUMPER LH REFLECTOR
RR BUMPER RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (SCHWARZ) ELBOW

QTY	PRIC	VALUE
10	0.90	? 9.00
1	82.10	de 82.10
1	81.35	? 81.35
1	411.25	? 411.25
1	31.45	? 31.45
1	56.95	? 56.95
1	56.95	? 56.95
1	831.40	de 831.40
1	322.35	de 322.35
30	1.35	de 40.50
1	35.20	? 35.20
1	35.20	? 35.20
2	5.05	? 10.10
2	236.85	? 473.70

Total Parts : 2,437.50

FR BUMPER RM REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (SCHWARZ)- ELBOW

1	35.20	?	35.20
2	5.05	?	10.10
2	236.85	?	473.70
Total Parts :			2,437.50

Performance Motors Limited

A member of the Sun Dairy Group
CR Reg. No. 19742111M GST Reg. No. M2-0020081-X

111, Alexandra Road
Sun Dairy Performance Centre
Singapore 119941
Tel 63461111 (Sales & Admin)
63461112 (AfterSales)
Fax 63461113

111, Singapore Road
East Coast Centre
Singapore 439100
Tel 63461111 (AfterSales)
Fax 63461113

111, Alexandra Road
Sun Dairy Performance Centre
Singapore 119941
Tel 63461111 (AfterSales)
63461112/63461113 (AfterSales)
Fax 63461113 (AfterSales)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47477
Date Estimated : 28/06/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0

Claims OO / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date/Time 1/6/18 09:15 Excess \$S _____
Surveyor's Name Tan Jiah Sign [Signature]
Surveyor's Tel 97495429 Authorized Yes/No
Authorized Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PMA Yes/No
Surveyor's E-mail tanjiah@kuanb.com
No. of Working Days Recommend 03 days

Labour 1	:	2,747.00
Parts	:	2,437.50
Labour 2	:	0.00

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz

Workwide Partners

Date: 25/06/18 Time: 1441
 Technician Name: Woodoss
 Reg. No: SKE43557 Job No:
 Odometer Reading (Customer Vehicle):
 KM Travelled by Assistance Vehicle: (1 way)
 Fault Reported: Accident → back
 Fault Found:
 How was vehicle repaired? ND tow Han

Customer Name: Han
 Customer Telephone: 97974559
 Make/Model: Bmw x1 E84
 Location: 4 Jalan mangrove
 Time on Scene: 1530
 Time Job Completed:
 Repaired at Breakdown Scene: Y/N
 VIN No:

Hubcaps Y/N

Spare Wheel Y/N

Tools Y/N

Audio System Y/N

Keys + Remote Y/N

Aerial Y/N

Cashcard (RM) Y/N

Fuel E F

Interior Condition :

Front Seats

Rear Seats

Floor Covering

Headlining



Day/Night

Wet/Dry

Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent



Delivery to Dealership / Date and Time:

Vehicle received in the above condition YES/NO

If not stated as above specify difference:

303 Alexandra Rd

CUSTOMER DECLARATION

- I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
- I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

PERFORMANCE MOTORS LIMITED

Customers Signature (white copy)	Dealer/Workshop Signature (pink copy)	Operators Signature (yellow copy)
	UEN No: 107401008W 303 Alexandra Road Sima Darby Performance Centre Singapore 159941 Tel: 1800-2255-269	Received from CSA Chris Goh 26/06/18 3:55pm

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKC42557	Model:	
Date of Accident:	23.6.2018		

Global Sum Settlement	: <input type="checkbox"/> Yes <input type="checkbox"/> No	
Repair Estimate	: \$	
Final Repair Cost	: \$	5581.71
Loss of Use	: \$	3000
Rental (if any)	: \$	3 days at \$100 per day
LTA / GIA Search Fee	: \$	200
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	5883.71

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 5581.71
2)	Performance Motors Ltd	: \$ 200
3)	Krishnaveni P/O P Kasivisvandan	: \$ 3000

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1257245Z



Name
KRISHNAVENI D/O P
KASIVISVANATHAN

Race
INDIAN
Date of Birth
09-12-1957
Country of Birth
SINGAPORE

Sex
F

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S1257245Z
Name:

KRISHNAVENI D/O P
KASIVISVANATHAN

Birth Date: 09 Dec 1957
Issue Date: 22 Aug 2005



NRIC No: S1257245Z



Blood Group: O+
Date of issue: 19-09-1994

Singapore Police
Singapore S1257245Z
NRIC No: S1257245Z

Date: 09-09-1997

No: 2230680

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver, and motor tractors / vehicles <= 2500 kg

11 Jun 1967



**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel: +65 6827 7888, Fax: +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

SIME MOTOR PRIVATE**RENEWAL CERTIFICATE**

Policy Number	Period of Insurance	Place of Issue
B 27282369 SMP	01/03/2018 to 28/02/2019	SINGAPORE
Name and Address of Insured		Date of Issue
Krishnaveni d/o P Kasivisvanathan 4 Jalan Minggu Singapore 577337		01/02/2018
		Account Number
		212165
Premium	GST	Total Due
SGD1,004.53	SGD70.31	SGD1,074.84

RISK NUMBER 1**SIME MOTOR PRIVATE****OCCUPATION**

Managing Director

FINANCIAL INTEREST

United Overseas Bank Limited
 as Hire Purchase Owners

SCOPE OF COVER Comprehensive**INTEREST INSURED**

REGISTRATION NO. \ SKE4355T
 MAKE/MODEL \ BMW X1 SDrive 10i
 ENGINE NUMBER A021J011N46B20BD
 CHASSIS NUMBER WBAVL32070VP92739
 YEAR OF MFG \ 2011
 CAPACITY \ 1995 C.C.
 SEATING CAPACITY 5 (INCL. DRIVER)
 WINDSCREEN UNLIMITED

SUM INSURED MARKET VALUE
 INCL. COE/PARF YES
 OFF-PEAK CAR NO
 NO CLAIM DISCOUNT 50.00% (or F/D)
 GOOD DRIVER'S
 DISCOUNT SGD52.87
 NCD PROTECTOR COVERED
 EXCESS SGD500
 ANNUAL PREMIUM SGD1,004.53

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit,
 rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Krishnaveni d/o P Kasivisvanathan



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18012076/ub3

18 JULY 2018

TAN BOON LENG KENNETH
BLK 143 TOA PAYOH LORONG 2
#16-186
SINGAPORE 310143

Dear Sir/Madam,

ACCIDENT INVOLVING SJL 9507P & SKE 4355T ON 23/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

As spoken, based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 5 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

RELEASE VOUCHER
(AIG Express Third Party Claim)

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 5581.71 (Repair Cost), S\$ 300 (Loss of rental/use), S\$ 2 (Disbursement), for vehicle no. SKE4355T that was damaged pursuant to the accident which occurred on 23.6.18 (date) along PUE HUNTLEY ROAD (location) involving vehicle no/s SJL9507P. This is pursuant to the inspection conducted on 1.8.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Krishnaveni 90 Kasiviswanathan ("the third party claimant") of vehicle no. SKE4355T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKE4355T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of June (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

MS Krishnaveni D/o
I, P Kasivisvarathan (the third party claimant) of 4 Jalan
Minggu, S'pore 577337 (address), owner of SKE4355T (vehicle no.)
hereby authorize PERFORMANCE MOTORS LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKE4355T that was damaged pursuant to the accident which occurred on 23/06/18
(date) along PIE Whitley Road (location) involving vehicle no/s
SJL9507P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 28 (day) of JUN (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941



Signed by "the workshop"
(with chop)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438160
Tel. 63190888 (AfterSales)
Fax. 63449773111, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1288382

Date IN : 01/08/2018

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 1 of 2

Invoice Number : 2046944 / WSB

Invoice Date : 27/12/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Ms Krishnaveni D/O P Kasivisvanathan
4 Jalan Minggu

Singapore 577337

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 SDRIVE18I	39554

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to make good the trunk floor panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.

To respray rear bumper and trunk floor panel.

To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To tow accident vehicle to PML workshop.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 23.6.2018. 3RD PARTY CAR : SJL9507P.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 1.8.2018 AT 2.15 PM. AUTHORISED REPAIR BY MS THIN THIN HLAING FROM LKK ON 9.7.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X3. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

1,275.00

1,412.00

150.00

150.00

230.00

195.00

80.00

0.00

0.00

0.00

Total Labour 1: 3,492.00

- - - - PARTS - - - -

RR BUMPER (PRIMED)

RR BUMPER BOTTOM (XLINE/PDC)

EXPANDING RIVET

RR BUMPER CARRIER

RR BUMPER RH GUIDE

RR BUMPER TOW HOOK COVER (SET)

Qty	Retail Price
1	831.40
1	322.35
30	1.35
1	411.25
1	56.95
1	62.10

NETT

831.40

322.35

40.50

411.25

56.95

62.10

Total Parts : 1,724.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401859W GST Reg. No M2-0020821-a



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1288382

Date IN : 01/08/2018

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 2 of 2

Invoice Number : 2046944 / WSB

Invoice Date : 27/12/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

Labour Charges :	3,217.00	Total Labour & Parts Charges :	S\$ 5,216.55
Parts Charges :	1,724.55	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	275.00	Invoice Total Amount Exclude GST :	S\$ 5,216.55
		GST @ 7% :	S\$ 365.16
		Invoice Total Amount Include GST :	S\$ 5,581.71

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 5,581.71

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-098813
Date of Request: 28/06/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 28/06/2018
Enquiry By: Han Kwan Yong
TP Vehicle No.: SJL9507P
Accident Date: 23/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJL9507P	AIG Asia Pacific Insurance Pte. Ltd.	07/12/2017-06/12/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the report or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-098813

Date of Request: 28/06/2018

Your Ref No:

Online Purchase

 Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

 Enquiry Date: 28/06/2018
 Enquiry By: Han Kwan Yong
 TP Vehicle No: SJL9507P
 Accident Date: 23/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1
GST Amount	0
Total Amount Due (GST Inclusive)	2

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2018 Edit Reg		01 Aug 2018 00:00 Edit Adj Rpt	S\$5,216.55 Edit Estimates	S\$5,216.55 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN BOON LENG KENNETH , ID: S1628031C								
Main Claimant:	KRISHNAVENI D/O P KASIVISVANATHAN , ID: S1257245Z								
Vehicle Reg. No.:	SKE4355T	Date of Loss:	23/06/2018 20:00 - :59 [75 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2847624269SG	Policy/Cover Note No.:	2100110450 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJL9507P	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE4355T (2847624269SG)
[SJL9507P]

TP

KRISHNAVENI D/O P KASIVISVANATHAN

Jun 23 2018 8:00PM

[TAN BOON LENG KENNETH]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 12:15	Odometer Reading		Load JPG
2	03/01/19 12:15	Chassis Number		Load JPG
3	03/01/19 12:15	General View		Load JPG
4	03/01/19 12:15	General View		Load JPG
5	03/01/19 12:15	General View		Load JPG
6	03/01/19 12:15	General View		Load JPG
7	03/01/19 12:15	General View		Load JPG
8	03/01/19 12:15	General View		Load JPG
9	03/01/19 12:15	General View		Load JPG
10	03/01/19 12:15	General View		Load JPG
11	03/01/19 12:15	General View		Load JPG
12	03/01/19 12:15	General View		Load JPG
13	03/01/19 12:15	General View		Load JPG
14	03/01/19 12:15	General View		Load JPG
15	03/01/19 12:15	General View		Load JPG
16	03/01/19 12:15	General View		Load JPG
17	03/01/19 12:15	General View		Load JPG
18	03/01/19 12:15	General View		Load JPG
19	03/01/19 12:15	General View		Load JPG
20	03/01/19 12:15	General View		Load JPG
21	03/01/19 12:15	General View		Load JPG
22	03/01/19 12:15	Reinspection Photo		Load JPG
23	03/01/19 12:15	Reinspection Photo		Load JPG
24	03/01/19 12:15	Reinspection Photo		Load JPG
25	03/01/19 12:15	Reinspection Photo		Load JPG
26	03/01/19 12:15	Reinspection Photo		Load JPG
27	03/01/19 12:15	Reinspection Photo		Load JPG
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 17:08	TP ESTIMATE		Load PDF
2	03/07/18 17:08	TP GIA REPORT		Load PDF
3	03/08/18 09:09	TP ESTIMATE- MARKED		Load PDF
4	15/01/19 09:11	WORKSHOP INVOICE		Load PDF
5	15/01/19 09:11	AUTHORISATION TO ACT FORM		Load PDF

Letters/Correspondences			1 per page	<input type="checkbox"/>
No	Finalized On			
LKK Auto Consultants Pte Ltd (HQ)				
6	15/01/19 09:11	Release Voucher		Thumbnail Print
7	15/01/19 09:11	GIA SEARCH		Load PDF
8	15/01/19 09:11	LETTER TO OI		Load PDF
AIG Asia Pacific Insurance Pte. Ltd. (SG)				
No	Finalized On			
1	04/07/18 11:17	OI GIA REPORT		Thumbnail Print
				Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJL9507P (Insd veh)	Model:	BMW X1 1.5 SDRIVE 18i (A)
	SKE4355T (TP veh)		
Date of Accident:	23/06/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		6,468.79
Final Repair Cost	: \$		5,581.71
Loss of Use	: \$		300.00
Rental (if any)	: \$		0.00
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		5,883.71

3.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	5,883.71
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

15 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18012076/T1EB3Q2

Date: 15/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100110450
Claimant Vehicle No : SKE4355T **Insured Vehicle No :** SJL9507P
 Date of Loss: 23/06/2018 Nature of Claim: TP Claim No: 2847624269SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE4355T**
 Make & Model: BMW X1, 1.5 SDRIVE 18i (A) Engine No: A021J011N46B20BD
 Reg. Date: 01/03/2012 (Man. Year: 2011) Chassis No: WBAVL32070VP92739
 Colour: Black Odometer: 39554 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/50 R12 Rear Tyre Size: 275/50 R12
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,579.60	1,804.55	775.05	30.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,466.00	3,412.00	54.00	1.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,045.60	5,216.55	829.05	13.71
+ GST 7.00/7.00% (S\$)	423.19	365.16	58.03	13.71
Nett Amount (S\$)	6,468.79	5,581.71	887.08	13.71
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,883.71		

INSPECTION

Date of Assignment: 01/08/2018
 Date Inspected: 01/08/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	10		*BODY NUT	Not Necessary	9.00 FS	*- FS
3	1		*RR BUMPER TOW HOOK COVER (SE)	Deformed	62.10 FS	*62.10 FS
4	1		*RR BUMPER CTR GUIDE	Not Necessary	61.35 FS	*- FS
5	1		*RR BUMPER CARRIER	Necessary	411.25 FS	*411.25 FS
6	1		*RR BUMPER LOWER COVERING	Not Necessary	31.45 FS	*- FS
7	1		*RR BUMPER LH GUIDE	Not Necessary	56.95 FS	*- FS
8	1		*RR BUMPER RH GUIDE	Necessary	56.95 FS	*56.95 FS
9	1		*RR BUMPER (PRIMED)	Deformed	831.40 FS	*831.40 FS
10	1		*RR BUMPER BOTTOM (XLINE/PDC)	Deformed	322.35 FS	*322.35 FS
11	1		*EXPANDING RIVET (30 PCS)	Necessary	40.50 FS	*40.50 FS
12	1		*RR BUMPER LH REFLECTOR	Not Necessary	35.20 FS	*- FS
13	1		*RR BUMPER RH REFLECTOR	Not Necessary	35.20 FS	*- FS
14	2		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	10.10 FS	*- FS
15	2		*BUMPER PDC SENSOR (SCHWARZ) -ELBOW	Not Necessary	473.70 FS	*- FS
16	1		*SET RR BUMPER TOW HOOK COVER	Repeated	62.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 2,579.60 1,804.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
2	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	230.00	230.00
3	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	1,275.00
4	TO RESPRAY REAR BUMPER	New	1,412.00	1,412.00
5	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			3,466.00	3,412.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >