

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0760/2018/PH  
**Date** : 4-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SKD 8747 A

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Miss Ho Shu Min  
**Address** : 1 Youngberg Terrace  
#12-07  
Singapore 357741  
**Telephone** : HP +65 93633048  
**Type of Claim** : Third Party Claims  
**Policy No.** : 1800076240  
**Vehicle No** : **SLJ 1784 U**  
**Model Code** : Audi A3 Sedan 1.0 TFSI (A)  
**Model / Year** : Jun-18  
**Engine No** : CHZ 938231  
**Chassis No** : WAUZZZ8V4J1066061  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 2-Jul-18  
**Place of Accident** : The turning BTW Upper Serangoon Rd & Braddell Rd

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLJ 1784 U .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper.Re-organise rear crash management components.Reinstall all parts removed.	\$ <del>900.00</del> 500	
3	To respray rear bumper.	\$ <del>800.00</del> 550	
4	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ <u>2,172.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLJ 1784 U .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	BUMPER COVER <i>Deformed</i>	\$ 1,697.00	✓
2	FIXING PARTS FOR BUMPER <i>Not nec</i>	\$ 166.00	X
3	GUIDE SECTION - LH/RH <i>} Not nec</i>	2 \$ 28.00	X
4	LOCKING MECHANISM <i>} Not nec</i>	2 \$ 50.00	X
5	SPOILER <i>Cut</i>	\$ 206.00	✓
6	REAR LIGHT REFLECTOR - LH/RH <i>} Not nec</i>	2 \$ 70.00	X
7	SENSOR - INNER/OUTER <i>} Not nec</i>	2 \$ 421.00	X
8	SEAL RING <i>} Not nec</i>	4 \$ 15.00	X
9	SIDE REINFORCEMENT <i>} Not nec</i>	\$ 501.00	X
10	BRACKET <i>} Not nec</i>	2 \$ 48.00	X
11	SUNDRIES ?	\$ 300.00	?

<b>TOTAL SPARE PARTS CHARGES</b>	:	<b>\$ 3,502.00</b>
<b>TOTAL LABOUR CHARGES</b>	:	<b>\$ 2,172.00</b>
<b>GRAND TOTAL</b>	:	<b>\$ 5,674.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian King.  
**Surveyed Date** : 10/07/18.  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : Not Authorised, 03 Days

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant