

Survivor

Meimen

ASSIGNMENT (Office)

From (Person)

chung Boon Sen

of

CTI

Date/Time

4/7/18 @ 11:55am

Estimated Cost

Bill to

OD (TP) / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No

PC 6656M

Insured

GBE 7261S

at Workshop m/z

Xinya Auto

Tel

6270 3481

of

BIK 1002 # 01-75 Bkt Meruh Leine 3

Policy No

DMCVSN 3005831800

Claim No

SNM18D 03031C02

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

14/06/2018

CA / REV / REP. / REV 24 HRS

Imp

09.07.2018 @ 10am

H.O.D. Endorsement

Date/Time

12.14pm @ 4/7/18

Person Contacted

Mei

Vehicle IN/

OUT


Date/Time	Action/Instruction
	(✓) Estimate 5/11/2 10am went to arrange.
	PC 6656M-x
	GBE 7261S - CS/INC16008574/ Gvbd1 DOA: 6/5/2016
24/06/18 @ 5.12pm	confirmed with wksp us \$1200, 3 days.
	(Red & 214.49, 64%)

ASSIGNMENT

From: _____ Date: **9/7/18**
 Estimated Cost: _____
 OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **PC 6656M**
 at Workshop m/s: **Xanya Auto**
 of **BLK 1002 # 01-75 BLK Mexh lene 3**
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) **10 am**
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS **up**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **PC 6656M** Yr Regn: **2011 / Jan**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **Mini-Bus**

Make: **TOYOTA COMSTAR** c.c. **4009**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: **244319** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JTGEF538306000199**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ order / Jammed / Leaked / Burnt orBrake: ☒ order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/75R17.5**
 R: **7.2** **3/8**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. **7** mm R/Bal. **7/7** mm
 L/Bal. **7** mm L/Bal. **7/7** mm
 D.O.A. **14/06/18** D.O.I. **09/07/18**

Survey held at **XANYA AUTO**Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **3**

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation: _____ S + RS, _____ SI

Report Format : **mer-7p**Lump Sum / I.B.I. (\$) **1200**☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2018		04 Jul 2018 11:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	THE PAINT COMPANY PTE LTD, Co. Reg. No.: 201533894Z		
Main Claimant:	HARD ROCK MARINE AGENCY & TRADING, Co. Reg. No.: 44415700W		
Vehicle Reg. No.:	PC6656M	Date of Loss:	14/06/2018 18:00 - :59
Claim Type:	TP / SNM18D03031C02	Policy/Cover Note No.:	DMCVSN3005831800 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GBE7261S	Policy No. (Claimant):	P1022763
		Excess:	S\$0.00
Repairer:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/07/2018]		
Driver/Custodian (Insured):	KLASS JOSEPH CECIL (53 / Male), NRIC: S1648276E, Tel: +6590259937		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Xinya Auto Services <xinyaauto@singnet.com.sg>
Sent: Wednesday, 24 October 2018 5:12 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: PC 6656M FINALISATION SURVEYED 09/07/18

Hi, Shiau Chan

Pls. close case \$1200.00

Thank you

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, October 9, 2018 3:43 PM
To: Xinya Auto Services <xinyaauto@singnet.com.sg>
Subject: RE: PC 6656M FINALISATION SURVEYED 09/07/18

Dear Kevin,

How you get the amount?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xinya Auto Services <xinyaauto@singnet.com.sg>
Sent: Monday, 8 October 2018 6:57 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: PC 6656M FINALISATION SURVEYED 09/07/18

H I Shiau Chan

Could we close matter at \$1400/=

Thank you

Regards
Kevin



Virus-free. www.avg.com

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002 BUKIT MERAH LANE 3 # 01-75, SINGAPORE 159719 TEL : 6270 3481 FAX : 62737522

E-mail : xinyaauto@singnet.com.sg

Date : 19-Jun-18

Address : HARD ROCK MARINE AGENCY & TRA.
BLK 979C BUANGKOK CRESCENT
#13-111
SINGAPORE 533979

Reference : TP 1160/06/18
Vehicle No : PC 6656M
Make/Model : TOYOTA COASTER
Insurance Co. : AXA

RE : QUOTATION REPAIRS TO PC 6656M FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	COST	AMT \$
1) REAR BUMPER	1		\$920.00 PA -
2) REAR BUMPER BRACKET	1		\$82.00 ? XSKC
3) REAR BUMPER BOLT & NUT	8		\$48.00 ? XMM
LIST PRICE TOTAL			\$1,050.00
LESS DISCOUNT 25%			\$262.50
LIST PRICE TOTAL AFTER LESS			\$787.50
NETT PRICE TOTAL			\$0.00
TOTAL PARTS COST			\$787.50

LABOUR AND MISCELLANEOUS CHARGES

- | | | |
|----|--|--------------------------------------|
| 1) | TO REMOVE & REPLACE REAR BUMPER, TO PANEL BEAT, CUT & WELD REAR END PANEL & DOOR PANEL. | \$800.00 400
(4 Days) |
| 2) | TO PUTTY & SPRAY PAINT TO REAR BUMPER & REAR END PANEL & DOOR PANEL & OTHER AFFECTED AREA. | \$800.00 400
(4 Panel) |

LABOUR TOTAL

\$1,600.00

TOTAL ESTIMATED REPAIR COST

2387.50

\$ 3,324.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Dear Sir,
offer US \$ 1200,
& 3 days
Kindly confirm.
Thanks & regards,
Shiau Chuan
LKK Auto
Consultants PL

Rasul
Hy 90010068

3 days

4/5

09/07/18 @ 1115

Reg after repair

12/7/18

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012123/R1QD3N2

Date: 26/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3005831800
Claimant Vehicle No :	PC6656M	Insured Vehicle No :	GBE7261S
Date of Loss:	14/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03031C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6656M	Engine No:	N04CUH13259
Make & Model:	TOYOTA COASTER, 4.0 D SUPER LWB (M)	Chassis No:	JTGEP538306000199
Reg. Date:	11/01/2011 (Man. Year: 2010)	Odometer:	244319 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7/7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	787.50	690.00	97.50	12.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	800.00	800.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,387.50	1,490.00	897.50	37.59
Approved Total (Overridden) (\$\$)		1,200.00		
Nett Amount (\$\$)	2,387.50	1,200.00	1,187.50	49.74

INSPECTION

Date of Assignment:	04/07/2018	
Date Inspected:	09/07/2018	Inspected At:
		Xinya Auto Services Pte Ltd (HQ)
		Blk 1002, #01-75, Bukit Merah Lane 3
		Singapore 159719
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Oct 2018)	
Parts:	N/A	TOYOTA COASTER 4.0 D SUPER LWB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6656M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	920.00 FL	*920.00 FL
2	1		*REAR BUMPER BRACKET	Serviceable	82.00 FL	*- FL
3	8		*REAR BUMPER BOLT & NUT	Not Necessary	48.00 FL	*- FL
					Sub Total (S\$)	1,050.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	262.50
					Total Parts (S\$)	787.50
						920.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE REAR BUMPER,TO PANEL BEAT,CUT & WELD REAR END PANEL & DOOR PANEL	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT TO REAR BUMPER & REAR END PANEL & DOOR PANEL & OTHER AFFECTED AREA	New	800.00	400.00
Gross Labour Cost (\$\$)			1,600.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >