

REF: CS/CTI 18 01/21/24/RVd36

Surveyor  
MehmetRahsul  
Irene Tay

## ASSIGNMENT (Office)

CTI

Date/Time 4/7/18 @ 11:05am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 71494

Insured:

SKM 53972

at Workshop in/

Sin Sheng Engineering

Tel:

6863 9595

of

3 Teoh Park Crescent

Policy No:

DMHCSN 1747 361700

Claim No:

SNM18D 03291002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 90/06/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement

Date/Time:

12:09pm @ 4/7/18

Person Contacted:

Susan

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

GBC 71494-X

SKM 53972-X

3/7/18

LS \$3500 confirmed by email (Reel 15549.65, 421)

2/8/18

@ 5:15pm LS \$3500 confirmed with Susan

Stromer *Farouk*

REF:


1196N

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: *GBC 7149U*  
 at Workshop m/s: *SIN SHENG*  
 of *3, TOTT PARK CRES*  
 Insured: *CTI / YP*  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *GBC 7149U* Yr Regn: *2013 / Aug*  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: *NISSAN URBAN 3-0* c.c. *2953*  
 Colour: *BLUE* A/C: Insured / Std / NI / NA  
 Sp. Reading: *143587* T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *JN1M64E2520796971*  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / SiRim / STD A/Rim or  
 Tyre Size: F: *195R15C*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or *Aubone*  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. *6* mm R/Bal. *6* mm  
 L/Bal. *6* mm L/Bal. *6* mm  
 D.O.A. *30/06/18* D.O.I. *18/07/18*  
 Survey held at *SIN SHENG*  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
*FR O/S*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

*Rasul, PLS check parts prices*

RECEIVED 01 AUG 2018

*Junaid*  
*20/7*

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) *1/8 - typist*

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

1) \$ + RS. \$ \_\_\_\_\_

1) Photos \_\_\_\_\_

1) Others \_\_\_\_\_

TOTAL

Report Format: *merimen*

Lump Sum / I.B.I: (\$) *3500/-*

Add Fee: ☐ Site Insp (\$) \_\_\_\_\_

☐ Interview (\$) \_\_\_\_\_

☐ Tech Invs (\$) \_\_\_\_\_

☐ Weekend (\$) \_\_\_\_\_

*20*

*220*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18012124/R1vd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-07-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 5397Z	Veh. Inspected	GBC 7149U
Policy No.	DMHCSN1747361700	Coverage (\$)	0.00
Claim No.	SNM18D03291C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	04/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	30/06/2018	Inspection Date
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018		04 Jul 2018 11:05 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WILSON THAM CHAUFFEUR SERVICES, Co. Reg. No.: 533648918		[Created by insurer]	
Main Claimant:	MOHAMAD ZULKARNAIN BIN MD TAHIR, ID: S71335238			
Vehicle Reg. No.:	GBC7149U	Date of Loss:	30/06/2018 13:00 - :59	
Claim Type:	TP / SNM18D03291C02	Policy/Cover Note No.:	DMHCSN1747361700 (Comprehensive)	
Vehicle Reg. No. (Insured):	SKM5397Z	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/07/2018]			
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.			

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/07/2018 14:58
Date Of Accident	30/06/2018 13:30
Exact Location Of Accident	CHANGI RD (CARPARK OF S'PORE EXPO NEAR HALL 2 & 3)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC7149U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	URVAN-3.0 5DR 5MT ABS A/B 2WD (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29004183
Cover Note Number	

### Driver

Name of Driver	MOHAMAD ZULKARNAIN BIN MD TAHIR
NRIC No	S7133523B
Date Of Birth	26/09/1971
Occupation	OUTDOOR
Date Of Driving Pass	25/01/1992
Driving Experience	26 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90992636
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 203E COMPASSVALE ROAD #13-65  
 Postcode 545203  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - LESSEE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name KAMPONG UBI NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7479999 - FAX NO: 67453410  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT NO. T/20180630/2139 - ON 30/06/2018 AT ABOUT 1330HRS, I WAS IN THE CARPARK AT SINGAPORE EXPO NEAR THE EXIT OF THE EXPO HALL 2 AND 3 AND WAS HEADING TOWARDS THE EXIT OF EXPO HALL 6 TOWARDS TPE. I WAS DRIVING MY COMPANY VAN. THERE WAS A CROSS JUNCTION WHERE MY LANE WAS HEADED TOWARDS HALL 6 AND THE LANE OF THE CROSS JUNCTION WAS TOWARDS THE EXIT TO SIMEI ROAD. AS I WAS DRIVING PAST THE CROSS JUNCTION, THE VEHICLE SKM5397Z SUDDENLY DROVE OUT FROM THE RIGHT SIDE AND I HAD SLAMMED MY BRAKES, HOWEVER IT WAS TOO LATE AND THE FRONT RIGHT SIDE OF MY VEHICLE HIT HIS FRONT LEFT SIDE OF HIS VEHICLE. I CAME OUT TO MAKE A CHECK WITH THE OTHER DRIVER AND THERE WAS NO INJURY. NO IMMEDIATE MEDICAL ATTENTION WAS NEEDED. MY FRONT RIGHT SIDE LIGHT AND BUMPER WAS DENTED IN AND DAMAGED. I AM ALSO UNABLE TO PROPERLY OPEN THE DOOR. HIS FRONT LEFT SIDE OF HIS BUMPER WAS DENTED IN AND HIS FRONT LEFT HEADLIGHT WAS ALSO DAMAGED. WE EXCHANGED PARTICULARS AND WE DECIDED TO TAKE SETTLE THIS INCIDENT WITH OUR INSURANCE. I OBSERVED THAT THERE WAS A STOP LINE ON HIS LANE TOWARDS THE EXIT TO SIMEI ROAD AND HE WAS SUPPOSE TO STOP FOR VEHICLE ON MY LANE. HOWEVER HE DID NOT STOP. I HAVE IN-CAR CAMERA INSTALLED IN THE BACK AND FRONT OF MY VEHICLE. I DID NOT NOTICE ANY IN-CAR CAMERA IN HIS VEHICLE. THERE WAS CCTV AROUND THE CARPARK AND I WOULD LIKE TO INFORM THAT THE SINGAPORE EXPO MANAGEMENT CAME TO THE SCENE TO ASSIST AND INFORM THAT THEY HAVE THE CCTV FOOTAGE OF THE INCIDENT IF NEEDED. I AM LODGING THIS REPORT FOR MY COMPANY FOR INSURANCE CLAIMS.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKM5397Z

Vehicle Make/Model/Colour	NISSAN / ALMERA
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	THAM KUM WAI
NRIC/Passport Number	S1563483I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LEFT SIDE PORTION
No. Of Passenger (Including Driver)	1

## Sketch Plan

### **SKETCH PLAN**

#### **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 30/06/2018 @ 1320hrs, I was driving my vehicle GBC 714911 in the Singapore Expo near the exit of Expo hall 2 and 3 heading towards the exit of Expo hall 6 towards TPE. While I was driving near to a cross junction, suddenly the third party vehicle SKM 53572 dash from my right side and hit onto my vehicle right hand side front body causes damage to my vehicle. My vehicle had installed in-car cam and catches the whole incident. The third party fail to stop his vehicle and the stop line and dash forward without checking.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002530

Date : 17/07/2018

Vehicle Num. : GBC7149U

Make/Model : NISSAN URVAN-2011

Chassis/Eng# : URVAN 3.0 5MT ABS AB 5DR/ZD3029

Accident Date : 30/06/2018

Claim No. : SNM18D03291

Reference : SKM5397Z

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER	DE ✓ 962.10	
2.	1	BUMPER SIDE BRACKET, LH	ME ✓ 185.20	
3.	1	BUMPER SPOTLAMP	CP ✓ 295.30	
4.	1	SPOTLAMP COVER	DE ✓ 145.20	
5.	1	HEADLAMP, RHS	SC ✓ 953.20	
6.	1	SIGNAL LAMP, RHS	CA ✓ 165.20	
7.	1	FRONT GRILLE	SC ✓ 678.20	
8.	1	NISSAN EMBLEM	ME ✓ 85.20	
9.	8	BUMPER CLIP	9.50 ME ✓ 76.00	
10.	1	INTERCOOLER	2121.60 PA ✓ 1,856.20	
11.	1	CORNER PANEL, RHS	repair 695.20	
12.	1	STEP GARNISH, RHS	MM X 362.50	
List Total S\$ :			6724.90	6,459.50
30.00% Discount S\$ :				1,937.85
			4707.43	4,521.65
NETT ITEMS :				
1.	1	COMPANY REGISTRATION STICKER	AA ✓ 20.00	
Nett Total S\$ :				20.00
10.00% Discount S\$ :				2.00
				18.00

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002530

Date : 17/07/2018

Vehicle Num. : GBC7149U

Make/Model : NISSAN URVAN-2011

Chassis/Eng# : URVAN 3.0 5MT ABS AB 5DR/ZD3029

Accident Date : 30/06/2018

Claim No. : SNM18D03291

Reference : SKM53972

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO PANEL BEAT/REPAIR RH BODY

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

TO APPLY NEW LOGO

LOSS OF USE : 6 DAYS @ \$ 120/DAY

Labour Total S\$ :

500

400

650.00

500 400

680.00

180.00

100

1,510.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

5 days

4)

18/07/18 @ 1015

20/7/18

Total S\$ : 6,049.65

Recy after repair

SIN SHENG ENGINEERING SERVICES

6235-43

**Veron Chen (LKKAUTO)**

---

**From:** sinsheng engineering services <sinsheng1981@gmail.com>  
**Sent:** Wednesday, 1 August 2018 11:00 AM  
**To:** Veron Chen (LKKAUTO)  
**Cc:** Rasul (LKKAUTO); SUR  
**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Hi Ms Veron,

Noted.

*Thank You*

*Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On 31 July 2018 at 17:53, Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)> wrote:

Dear Susan,

Noted with thanks.

**Kindly send Final invoice and all supporting documents to CHINA TAIPING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineering services <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>

**Sent:** Tuesday, 31 July 2018 5:42 PM

**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Cc:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Hi Ms Veron,

We are agreed.

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477

On 31 July 2018 at 15:30, Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)> wrote:

Dear Susan,

WITHOUT PREJUDICE

Offer Lump Sum \$3500 @ 5 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)

**Sent:** Monday, 23 July 2018 11:49 AM

**To:** sinsheng engineerservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Cc:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Dear Sir/ Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/CTI18012124/R1vd3	Veron

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineeringservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>

**Sent:** Monday, 23 July, 2018 10:13 AM

**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018

Hi Mr Rasul,

Please find attached and have your finalized please.

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*

On 3 July 2018 at 10:39, sinsheng engineeringservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)> wrote:

Dear Officer In Charge,

We are repairer of vehicle GBC7149U. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) workings days upon receipt of this email. Enclosed Accident Statement & LTA search fee for your attention please.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue if direct settlement is in order.

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*



## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 1 August 2018 2:10 PM  
**To:** 'sinsheng engineeringservices'  
**Cc:** Rasul (LKKAuto); SUR  
**Subject:** RE: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Dear Susan,

We have check intercooler is \$1920.50

Lump Sum remain \$3500 @ 5 working days.

Please confirmed.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineeringservices <sinsheng1981@gmail.com>  
**Sent:** Wednesday, 1 August 2018 1:30 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Hi Ms Veron,

We had discover the list price for intercooler is \$2121.60, pls revised the finalized amount.

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*

On 1 August 2018 at 10:59, sinsheng engineeringservices <sinsheng1981@gmail.com> wrote:

Hi Ms Veron,

Noted.

Thank You  
Regards

Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477

On 31 July 2018 at 17:53, Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)> wrote:

Dear Susan,

Noted with thanks.

**Kindly send Final invoice and all supporting documents to CHINA TAIPING**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

**From:** sinsheng engineeringservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>

**Sent:** Tuesday, 31 July 2018 5:42 PM

**To:** Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Cc:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Hi Ms Veron,

We are agreed.

Thank You  
Regards

Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477

On 31 July 2018 at 15:30, Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)> wrote:

Dear Susan,

WITHOUT PREJUDICE

Offer Lump Sum \$3500 @ 5 working days.

Kindly confirm.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)

**Sent:** Monday, 23 July 2018 11:49 AM

**To:** sinsheng engineering services <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Cc:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CT118012124/R1vd3

Dear Sir/ Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/CT118012124/R1vd3	Veron

Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineering services <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>  
**Sent:** Monday, 23 July, 2018 10:13 AM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018

Hi Mr Rasul,

Please find attached and have your finalized please.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On 3 July 2018 at 10:39, sinsheng engineering services <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)> wrote:

Dear Officer In Charge,

We are repairer of vehicle GBC7149U. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) workings days upon receipted of this email. Enclosed Accident Statement & LTA search fee for your attention please.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue if direct settlement is in order.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park*

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 31 July 2018 5:53 PM  
**To:** 'sinsheng engineering services'  
**Cc:** Rasul (LKKAuto); SUR  
**Subject:** RE: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Dear Susan,

Noted with thanks.

**Kindly send Final invoice and all supporting documents to CHINA TAIPING**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineering services <sinsheng1981@gmail.com>  
**Sent:** Tuesday, 31 July 2018 5:42 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Hi Ms Veron,

We are agreed.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On 31 July 2018 at 15:30, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Susan,

WITHOUT PREJUDICE

Offer Lump Sum \$3500 @ 5 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)

**Sent:** Monday, 23 July 2018 11:49 AM

**To:** sinsheng engineerservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Cc:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: Accident Involving GBC7149U with SKM5397Z on 30/06/2018 \*\*\* LKK REF: CS/CTI18012124/R1vd3

Dear Sir/ Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/CTI18012124/R1vd3	Veron



Our respective case handler will look into the matter and revert to you in due course.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** sinsheng engineerservices <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)>

**Sent:** Monday, 23 July, 2018 10:13 AM

**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Re: Accident Involving GBC7149U with SKM5397Z on 30/06/2018

Hi Mr Rasul,

Please find attached and have your finalized please.

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*

On 3 July 2018 at 10:39, sinsheng engineering services <[sinsheng1981@gmail.com](mailto:sinsheng1981@gmail.com)> wrote:

Dear Officer In Charge,

We are repairer of vehicle GBC7149U. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two(2) workings days upon receipt of this email. Enclosed Accident Statement & LTA search fee for your attention please.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue if direct settlement is in order.

*Thank You*

*Regards*

*Susan*

*Sin Sheng Engineering Services*

*3 Tech Park Crescent*

*Tuas Tech Park*

*Singapore 638129*

*Tel: 6863 9595*

*Fax: 6863 6477*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018		04 Jul 2018 11:05 <a href="#">Edit Adj Rpt</a>	<b>S\$3,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	<b>WILSON THAM CHAUFFEUR SERVICES</b> , Co. Reg. No.: 53364891B								
Main Claimant:	<b>MOHAMAD ZULKARNAIN BIN MD TAHIR</b> , ID: S7133523B								
Vehicle Reg. No.:	<b>GBC7149U</b>	Date of Loss:	30/06/2018 13:00 - :59 <b>[58 Months From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / SNM18D03291C02</b>	Policy/Cover Note No.:	DMHCSN1747361700 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKM5397Z</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Sin Sheng Engineering Services (HQ)</b> 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 13/07/2018]</b>								
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















## Claim Documents

\*GBC7149U (SNM18D03291C02)  
[SKM5397Z]  
TP  
MOHAMAD ZULKARNAIN BIN MD TAHIR  
Jun 30 2018 1:00PM  
[WILSON THAM CHAUFFEUR SERVICES]  
Sin Sheng Engineering Services

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 17:22	Accident Statement	Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	02/07/18 17:21	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/18 15:17	General View	Load PDF	
2	31/07/18 15:17	Reinspection Photo	Load PDF	
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/07/18 11:04	PRS	Load PDF	
2	04/07/18 11:04	OI GIA	Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 17:19	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	02/07/18 17:21	IC,CI,DL [Linked Accident Report Documents]	Load TIF	

## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 17:22	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	02/07/18 17:21	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 17:19	Sketch Plan	 Load TIF	
2	02/07/18 17:21	IC,CI,DL	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012124/R1VD3E2

Date: 07/08/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1747361700

Claimant Vehicle No: GBC7149U Insured Vehicle No: SKM5397Z

Date of Loss: 30/06/2018 Nature of Claim: TP Claim No: SNM18D03291C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBC7149U

Make & Model: NISSAN URVAN, 3.0 5DR 5MT ABS A/B 2WD (M) Engine No: ZD30299094K

Reg. Date: 30/08/2013 (Man. Year: 2011) Chassis No: JN1MG4E25Z0796971

Colour: Blue Odometer: 143587 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm

Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,725.43	3,331.17	1,394.26	29.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	1,100.00	410.00	27.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,235.43	4,431.17	1,804.26	28.94
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	6,235.43	3,500.00	2,735.43	43.87
+ GST 7.00/7.00% (S\$)	436.48	245.00	191.48	43.87
Nett Amount (S\$)	6,671.91	3,745.00	2,926.91	43.87

## INSPECTION

Date of Assignment: 04/07/2018

Date Inspected: 18/07/2018 Inspected At:

Sin Sheng Engineering Services (HQ)  
3 Tech Park Crescent, Tuas Tech Park  
Singapore 638129

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 Aug 2018)	
<b>Parts:</b>	N/A	NISSAN URVAN 3.0 5DR 5MT ABS A/B 2WD (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC7149U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	962.10 FL	*654.60 FL
2	1		*BUMPER SIDE BRACKET, LH	Necessary	185.20 FL	*95.20 FL
3	1		*BUMPER SPOTLAMP	Cracked	295.30 FL	*295.30 FL
4	1		*SPOTLAMP COVER	Deformed	145.20 FL	*145.20 FL
5	1		*HEADLAMP, RHS	Scratched	953.20 FL	*948.40 FL
6	1		*SIGNAL LAMP, RHS	Cracked	165.20 FL	*165.20 FL
7	1		*FRONT GRILLE	Scratched	678.20 FL	*347.50 FL
8	1		*NISSAN EMBLEM	Necessary	85.20 FL	*85.20 FL
9	8		*BUMPER CLIP	Necessary	76.00 FL	*76.00 FL
10	1		*INTERCOOLER	Bent	2,121.60 FL	*1,920.50 FL
11	1		*CORNER PANEL, RHS	Repair	695.20 FL	*- FL
12	1		*STEP GARNISH, RHS	Not Necessary	362.50 FL	*- FL
13	1		*COMPANY REGISTRATION STICKER	Necessary	20.00 FN	*20.00 FN
					<b>Sub Total (S\$)</b>	<b>6,744.90</b>
					- List Item Discount on L Items 30.00/30.00% (S\$)	2,017.47
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	2.00
					<b>Total Parts (S\$)</b>	<b>4,725.43</b>
						<b>3,331.17</b>

F=Franchise part. L=ListItemDisc. N=NetItemDisc.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT / REPAIR RH BODY.TO DISMANTLE / REPLACE ABOVE MENTIONED PARTS	New	650.00	500.00
2	SPRAY PAINTING	New	680.00	500.00
3	TO APPLY NEW LOGO	New	180.00	100.00
Gross Labour Cost (S\$)			1,510.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >