

ASS. REC. BY:

REF: CS/CT118012125/T1362

Special Instructions:

Surveyor
Maimen

Taufik

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTI

Date/Time:

03/07/2018 5:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 425Z

Insured:

SKS 9240J

at Workshop m/s

Vermogen

Tel:

6 358 3031

of

6 Bengi Sector.

Policy No:

DMP CGN 5039661800

Claim No:

SNM18D03087002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. endorsement:

Date/Time:

04/07/2018 10:10am

Person Contacted:

P14

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 425Z -x

SKS 9240J -x

05/11/17

Confirmed HS \$ 11,000/- @ 9 days with Taufik.

(\$ 24,612.31 Red - 67%)

ACCIDENT

Tanjik

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop mis: _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____

SLH/425Z

Yr Regn: _____

2016 out

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: _____

Toyota Sienta

CC 1496

Colour: _____

white

A/C: Insured / Std / NI / NA

Sp. Reading: _____

114/38

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

NSP1707016683

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front: _____

Rear: _____

R/Bal: _____

6

mm

R/Bal: _____

6

mm

L/Bal: _____

6

mm

L/Bal: _____

6

mm

D.O.A: _____

D.O.I: _____

4/7/18

Survey held at: _____

Varmogen Bens.

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____

Action / Instruction: _____

Tanjik
fupr.

pls check parts prices.

RECEIVED 08 NOV 2018


 11/7

Date/Time: File Pass to?

08/11/18

Type 3+

Date/Time: File Return to?

2)

Report Format: _____

Lump Sum / I.B.E: 11,000/- L/S

☐

Prel. Report

☐

Final Report

Days Of Repair: _____

7

Resurvey No. of Trip: _____

2

Add Fee: ☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Workshop (\$

Survey Fee

220

Transportation

) \$ + P.E. \$

) P.E.

) Other

TOTAL

220

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop

Darren Ng
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Friday, June 08, 2018 1:13 PM

To: CLAIMS TEAMWORK <claims@teamworkgarage.com>

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: ***SPAM*** CMTD1802408/NSW - PRI/ SLB46028 & SLE352R ACC ON 06.06.18 \YR REF : 1806-10

Our Reference: CMTD1802408/NSW
Your Reference: 1806-10

Without Prejudice

Date: 8th June 2018

Attention:
M/S TEAMWORK GARAGE PTE LTD

Dear Allison,

ACCIDENT INVOLVING SLB46028 & SLE352R ON 06.06.2018

We refer to your Notice of Accident dated 08/06/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018		03 Jul 2018 17:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN CHENG YU, ID: 575365808								
Main Claimant:	ISWANDY BIN SAMADI, ID: 574018608								
Vehicle Reg. No.:	SLH425Z	Date of Loss:	30/05/2018 18:00 - :59						
Claim Type:	TP / SNM18D03287C02	Policy/Cover Note No.:	DMPCSN3039661800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKS9240J	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (wcega Plaza) (HQ) 1 Bukit Batok Crescent, #05-23 WCEGA Plaza, 658064 Bukit Batok - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/07/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18012125/T1sb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-07-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKS 9240J	Veh. Inspected	SLH 425Z	
Policy No.	DMPCSN3039661800	Coverage (\$)	0.00	
Claim No.	SNM18D03287C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/06/2018	Inspection Date	04/07/2018	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 8 November 2018 3:20 PM
To: minoko@vermogen-group.com; Taufikh (LKKAuto)
Cc: SUR; 'Pila Ng'; 'Tejano Exequiel Dawal'; 'Juan paulo baldoz'; 'Desmond Kor'; 'Vmg admin'; 'Vermogen Ace'
Subject: RE: SLH425Z FINALISE

Hi Minoko,

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: minoko@vermogen-group.com [mailto:minoko@vermogen-group.com]
Sent: Thursday, 8 November 2018 2:58 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>; 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'Juan paulo baldoz' <paulovermogenace@gmail.com>; 'Desmond Kor' <desmond@vermogen-group.com>; 'Vmg admin' <vmg@vermogen-group.com>; 'Vermogen Ace' <ACE@VERMOGEN-GROUP.COM>
Subject: RE: SLH425Z FINALISE

Dear Taufik/Shirley,

We agreed to accept your revised @ COR \$11,000.00 & 9 repair days (excluding PRS/RS/Weekend & PH).

Thank you

Best Regards,

Minoko
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Weega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 8 November 2018 10:45 AM

To: minoko@vermogen-group.com; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'Juan paulo baldoz' <paulovermogenace@gmail.com>; 'Desmond Kor' <desmond@vermogen-group.com>; 'Vmg admin' <vmg@vermogen-group.com>; 'Vermogen Ace' <ACE@VERMOGEN-GROUP.COM>

Subject: RE: SLH425Z FINALISE

Dear Minoko,

Please confirm final fig of \$ 11,000.00 (lump sum) @ 9 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: minoko@vermogen-group.com [mailto:minoko@vermogen-group.com]

Sent: Thursday, 1 November 2018 10:53 AM

To: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>

Cc: 'SUR' <sur@lkkauto.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'Juan paulo baldoz' <paulovermogenace@gmail.com>; 'Desmond Kor' <desmond@vermogen-group.com>; 'Vmg admin' <vmg@vermogen-group.com>; 'Vermogen Ace' <ACE@VERMOGEN-GROUP.COM>

Subject: FW: SLH425Z FINALISE

1st REMINDER.

Dear Taufik,

SLH425Z DOA:30/06/2018

Kindly check & revert to us as soon as possible, to expedite the claim.

Please send us your calculation.

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Weega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

From: minoko@vermogen-group.com <minoko@vermogen-group.com>

Sent: Tuesday, 16 October 2018 1:01 PM

To: taufikh@lkkauto.com

Cc: 'SUR' <sur@lkkauto.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'Juan paulo baldoz' <paulovermogenace@gmail.com>; 'Desmond Kor' <desmond@vermogen-group.com>; 'Vmg admin' <vmg@vermogen-group.com>; 'Vermogen Ace' <ACE@VERMOGEN-GROUP.COM>

Subject: SLH425Z FINALISE

Dear Taufik,

Refer to attachment, kindly confirm & acceptance finalise @ COR \$13,300.00 & 9 repair days (excluding PRS/RS/Weekend & PH).

please revert.ASAP

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Weega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2018 13:06
Date Of Accident	30/06/2018 18:30
Exact Location Of Accident	PIE TOWARDS TUAS NEAR CLEMENTI EXIT WOODLAND EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH425Z
Insured/Policyholder	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995152
Cover Note Number	

Driver

Name of Driver	ISWANDY BIN SAMADI
NRIC No	S7401860B
Date Of Birth	03/02/1974
Occupation	OUTDOOR
Date Of Driving Pass	17/04/2012
Driving Experience	6 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI ROAD BLK B (6 BENOI SECTOR)
Postcode	629904
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SPOUSE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG NPP
Police Station Address	ROAD: 158 YUNG LOH ROAD #01-58 , POSTCODE: 610158 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED. THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKS9240J
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	TAN CHENG YU
NRIC/Passport Number	
Contact Number	93218287
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJZ6612P

Vehicle Make/Model/Colour

Details Of Properties

VEH. C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

ISWANDY BIN SAMADI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLH425Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN

- (A) SLH425Z →
 (B) SKS9240J →
 (C) SJZ6612P → C B A / Road works
 PIE (towards Tuar, Near Clementi)
 Woodland exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report no: T/20180702/2070 and
 police report no: T/20180701/2079.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/25180702/0070

1 of 1

Report No: T/25180702/0070

Police Station Of Origin:
Jurong NPP
158 Yung Lok Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/07/2018 14:54 Vide Report No: T/25180702/0070 Station Diary No: 19

Informant's Particulars

Name of Informant: ISWANDY BIN SAMADI	Address: APT BLK 339C KANG CHING ROAD #04-338 SINGAPORE 613338		
ID Type / ID No: NRIC NO / S74018608	Contact No.: Home/Office	Mobile: 93530541	
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 44	Date of Birth: 03/02/1974	Type of Informant: Driver
Race: Malay	Language:		Institution / School Name:
Occupation: GRAB DRIVER	Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident: Injury Others	Drink Drive: No	Date/Time of Accident: 30/06/2018 18:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY ALONG PIE TOWARDS TUAS NEAR CLEMENTI WOODLANDS EXIT			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJZ6612P	Car					0
5K59240J	Car					2
SLH425Z	Car				Seriously Damaged	1

Accident Sketch Plan Pg. 4



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong NPP
120 Yung Lee Road #01-58 SINGAPORE
610158
Tel No: 1800-2850089



7725402502079

2 of 4

Report No: T001807530016

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
Driver		Use of Pedestrian Crossing: NA	
Name	TAN CHENG YU	ID No.	S7530580B
Related Vehicle	SK58240J (Car)	Contact No.	93218287
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ISWANDY BIN SAMADI	ID No.	S7401860B
Related Vehicle	SLH425Z (Car)	Contact No.	93530541
Hospital/Clinic	NORTHEAST (BUKIT BATOK) 24 HR FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	AZRINDAH BINTE JAAFAR	ID No.	S7543051F
Related Vehicle	SLH425Z (Car)	Contact No.	93378604
Hospital/Clinic	NORTHEAST (BUKIT BATOK) 24 HR FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 30/06/2016 at about 1830hrs, I was driving my vehicle SLH425Z on the first lane of PIE towards Tuas, near Clementi/Woodlands exit together with my wife. I noticed that there was roadworks on the first lane in-front of me. I slowed down, signaled and stopped, preparing to change lane. When the second lane is clear, before I was about to move off to change lane, I suddenly feel an impact coming from my rear. (My car is still on the first lane when the accident occur).

Subsequently, the driver and I alighted from our vehicle and we make a check on the our vehicles. We then discovered that it is a chain collision. A car with registration number SJ26612P had collided onto the



SINGAPORE
POLICE FORCE



1/201607022070

3 of 4

Police Station Of Origin:
Jurong NPP
158 Yung Lok Road #01-98 SINGAPORE
610158
Tel No: 1800-2659999

Report No: 1201607020070

CONTINUATION OF REPORT

rear of the car behind me SK59240J. As such, the impact caused SK59240J to collide onto my rear. Me and the driver behind me manage to exchange particulars.

The rear part of my car was badly damaged. I wish to inform that me and my wife had obtain 3 days of MC each. My wife felt pain on her shoulders and head. I wish to add that I have in-front camera installed



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong NPP
158 Yung Lok Road #01-58 SINGAPORE
610188
Tel No: 1800-2622222



Report No: T20180702-018

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference

Signature Of Officer Recording The Report

J /
Sgt 3 MUHAMMAD AFRIN BIN WARIN

Signature Of Informant

Signature Of Interpreter

Not applicable

Date/Time:
02/07/2018 14:54

Officer In Charge Of Case:

TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No: 65475438

Classification Of Case:

Authentication Stamp
NP158

Singapore Police Force



**SINGAPORE
POLICE FORCE**



T/20180701/2079

1 of 3

Report No. T/20180701/2079

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/07/2018 21:14		Vide Report No.: T/20180630/2132		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: ISWANDY BIN SAMADI			Address: APT BLK 339C KANG CHING ROAD #04-338 SINGAPORE 613339		
ID Type / ID No.: NRIC NO / S7401860B			Contact No.: Home/Office:		Mobile:
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 44	Date of Birth: 03/02/1974	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 30/06/2018 18:30	Type of Location:
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along PIE towards Tuas, near to Clementi Woodlands exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKS9240J	Car	BMW				2
SLH425Z	Car	TOYOTA	SIENTA	White	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180701/2079

2 of 3

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

Report No. T/20180701/2079

CONTINUATION OF REPORT

Driver		ID No.		S7536580B	
Name	TAN CHENG YU		Contact No.		
Related Vehicle	SKS9240J (Car)		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Hospital/Clinic	NIL		Date Discharge	NIL	
Date Treatment	NIL		Degree of Injury	NIL	
No. of Days granted Medical Leave	NIL				
Driver		ID No.		S7401860B	
Name	ISWANDY BIN SAMADI		Contact No.		
Related Vehicle	SLH425Z (Car)		Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL	
Hospital/Clinic	NIL		Date Discharge	NIL	
Date Treatment	NIL		Degree of Injury	NIL	
No. of Days granted Medical Leave	NIL				

Brief Details.

With regards to T/20180630/2132, I wish to state that me and my wife felt pain on our back and thus, we went to Northeast Medical Group (Bukit Batok) and was given a total of 03 days MC (01/0718 to 03/07/18).



**SINGAPORE
POLICE FORCE**



T/20180701/2079

Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

3 of 3

Report No. T/20180701/2079

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/
Sgt 1 CHEW WEI XIANG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No: 65476436

Signature Of Informant

Date/Time:
01/07/2018 21:14

Classification Of Case:

Authentication Stamp



SN 124

Signature :

Singapore Police Force

NRIC AND LICENSE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7401860B



Name
ISWANDY BIN SAMADI

Race
MALAY

Date of birth
03-02-1974

Country of birth
SINGAPORE

Sex
M

U-TAG NUMBER
4837812

VMG USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENSE

License Number: **S7401860B**

Name
ISWANDY BIN SAMADI

Date of birth: **03 Feb 1974**

Issue Date: **17 Apr 2012**




4837812



NRIC No: **S7401860B**

VMG USE ONLY



Date of issue
12-03-2012

Address
**AFT BLK 338C KANG CHANG ROAD
#04-338
SINGAPORE 413339**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EXPIRING DATE: **17 Apr 2012**

Class 3A. Motor cars without clutch pedals (Auto) <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles without clutch pedals <= 2000kg

NP 425A

License No: **S7401860B**





SLH425Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 30-06-18

Vehicle Reg. No. : SLH425Z
Vehicle Reg. Date: 21-Oct-2016
Make / Model : T. SIENTA 1.5G A
Engine No. : 2NR8566921
Chassis No. : NSP170716603

COST OF CLAIMS

Parts Cost / List Items : \$ 35,159.75
Plus/Less 25% \$ 8,789.94
Total Cost / List : \$ 26,369.81
Special Nett Items : \$ 1,313.00
Total Parts Amount : \$ 27,682.81
Total Labour Amount : \$ 7,930.00
Gross Total : \$ 35,612.81
GST % : 7% \$ 2,492.90
Nett Amount : \$ 38,105.71

Surveyor Name and Company :

Tan Jiah 97495749

Date of survey : 4/7/18

Part by Part / Lump Sum : 9 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@lkhauto.com

Fax No : _____

HP No : _____

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH425Z**
 Vehicle Reg. Date: **21-10-16**
 Make / Model : **T. SIENTA 1.5G A**
 Engine No. : **2NR8566921**
 Chassis No. : **NSP170716603**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAILGATE	bt ✓	\$ 1,895.80	1086	
2	2	TAILGATE DAMPER	Rx ✓	\$ 320.00		
3	2	TAILGATE HINGE	Rx ✓	\$ 280.00		
4	1	TAILGATE INNER TRIM	de ✓	\$ 280.00		
5	1	TAILGATE INNER TIRM CLIPS - SET	nei ✓	\$ 40.00		
6	1	TAILGATE LOCK	ht ✓	\$ 790.70	235.60	
7	1	TAILGATE LOCK CATCH	bt ✓	\$ 45.00		
8	1	TAILGATE HANDLE SWICTH	? ✓ dig	\$ 295.30		
9	1	TAILGATE WINDSCREEN GLASS	x nm	\$ 2,100.00		
10	1SET	TAILGATE WINDSCREEN GLASS MOULDING	lee ✓	\$ 320.00		
11	1	TAILGATE OUTER GARNISH	de ✓	\$ 287.60		
12	1	TAILGATE OUTER GARNISH CLIP - SET	nei ✓	\$ 30.00		
13	1	TAILGATE LOGO	nei ✓	\$ 92.80		
14	2	TAILGATE STOPPER	nei ✓	\$ 100.00		
15	1	TAILGATE WIPER MOTOR	? ✓ jm	\$ 400.00		
16	1	TAILGATE WIPER ARM	? x nm	\$ 200.00		
17	1	TAILGATE WIPER LINK	? x nm	\$ 240.00		
18	1	TAILGATE WEATHERSTRIP	nei ✓	\$ 495.70	285.50	
19	1	TAILGATE INNER HANDLE	de ✓	\$ 89.60		
20	2	TAILGATE LAMP	nei ✓	\$ 991.58		
21	1	TAILGATE ANTENNA SENSOR	nei ✓	\$ 181.20		
22	1	REAR BUMPER	de ✓	\$ 596.50		
23	1	REAR BUMPER CLIPS - SET	nei ✓	\$ 50.00	30	
24	1	REAR BUMPER GARNISH CENTER	de ✓	\$ 395.80		
25	2	REAR BUMPER GARNISH	nei ✓	\$ 553.80	391	
26	2	REAR BUMPER RELECTOR	x nm	\$ 195.40		
27	2	REAR BUMPER SIDE RETAINER	nei ✓	\$ 90.00		
28	1	REAR BUMPER SMALL GARNISH	x nm	\$ 24.00		
29	1	REAR BUMPER SPONGE	de ✓	\$ 45.00		
30	1	REAR END PANEL INNER	bb ✓	\$ 697.70	498.20	
31	1	REAR END PANEP OUTER	bt ✓	\$ 478.01		
32	1	REAR END PANEL TOP GARNISH	nei ✓	\$ 279.50	195.20	
33	1	REAR END PANEL TOP GARNISH CLIP - SET	nei ✓	\$ 40.00		
34	2	TAILLAMP	2LH-2RH-RH-MIS	\$ 1,359.00	1020.60	
35	2	TAILLAMP BRACKET	nei ✓	\$ 390.54		
36	2	TAILLAMP PANEL	Rx ✓	\$ 2,790.00		
37	2SET	TAILLAMP CLIPS	nei ✓	\$ 80.00		
38	1	SPARE TYRE PANEL	nei ✓	\$ 1,379.60	899.10	
39	1	SPARE TYRE BRACKET	Rx ✓	\$ 182.22		
40	1	SPARE TYRE INSULATOR	de nei ✓	\$ 279.90		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH425Z**
 Vehicle Reg. Date: **21-10-16**
 Make / Model : **T. SIENTA 1.5G A**
 Engine No. : **2NR8566921**
 Chassis No. : **NSP170716603**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	SPARE TYRE TOOL TRAY	de	\$ 757.90	429	
42	2	SPRAY TYRE TOP BOARD	de	\$ 512.00		
43	2	REAR FENDER	X NH	\$ 3,352.00		
44	2	REAR FENDER AIR DUCT	de	\$ 129.60		
45	2	REAR FENDER INNER TRIM	de	\$ 1,941.00		
46	2	REAR FENDER INNER TRIM CLIPS - SET	nei	\$ 100.00		
47	2	REAR FENDER INNER SHIELD	X NH	\$ 384.20		
48	2	REAR FENDER INNER SHIELD CLIPS - SET	X NH	\$ 20.00		
49	1	EXHAUST MUFFLER	Ry	\$ 795.60		
50	1	EXHAUST HEATSHIELD	X NH	\$ 89.90		
51	2	EXHAUST MOUNTING	X NH	\$ 100.00		
52	1	REAR TOW HOOK	X NH	\$ 61.30		
53	1	REAR NUMBER PLATE				
54	1	REAR NUMBER PLATE CASING				
55	1	REVERSE SENSOR				
56	2	REAR BUMPER EXTENSION GROMMET SCREW	nei			
57	2	REAR BUMPER EXTENSION FASTENER	nei			
58	2	REAR BUMPER FASTENER	nei			
59	1	TAILGATE WINDSCREEN PRIMER	nei			
60	2	TAILGATE WINDSCREEN SEALANT	nei			
61	1	TAILGATE WINDSCREEN SUPPORT SPONGE	nei			
62	1	REAR END PANEL SEALANT	nei			
63	1	SPARE TYRE SEALANT	nei			
64	1	SPARE TYRE SOUND DAMPER SET	nei			
65	1	TAILGATE SEALANT	nei			
66	2	TAILLAMP PAD	nei			
67	3	EXHAUST RUBBER HOOK	NH X			
68	1	EXHAUST GASKET	NH X			
69	2	REAR CHASSIS MEMBER	NH X	\$ 2,954.00		
70	2	REAR DOOR	NH X	\$ 3,316.00		
71	2	Rear fender garnish lower LH/RH	NH X	\$ 188.00		
72	2	Rear fender garnish upper LH/RH	NH X	\$ 360.00		
73	2	REAR FENDER UPPER INNER TRIM	NH X	\$ 716.00		
74	2	REAR FENDER UPPER INNER TRIM CLIP SET	NH X		\$ 80.00	
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	2				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Chassis No. : NSP170716603

Estimates on Labour

[illegible]

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO:

TAUFIKH

Surveyor Name and Company

BILL TO:

CHINA TAIPING

TP Insurer

TYPE OF CLAIM:

TP

VEHICLE REG. NO.

SLH425Z

COST OF CLAIMS

Parts Cost / List : \$ 16,851.13

Supp. Parts : \$ -

Special Nett : \$ 673.00

Total Parts : \$ 13,311.35

Total Labour : \$ 3,340.00

TOTAL REPAIR COST : \$ 16,651.35

Total Parts Cost/List :	<u>\$ 16,851.13</u>
Plus / Less : <u>25%</u>	<u>\$ 4,212.78</u>
Total :	<u>\$ 12,638.35</u>

Lump Sum Discount : <u>20%</u>	<u>\$ 3,330.27</u>
	<u>\$ 13,321.08</u>

Final Lump Sum Amount : \$ 13,300.00

Submitted by / Date : MINOKO

No. of Repair Days: 9

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH425Z**
 Vehicle Reg. Date: **21/10/2016**
 Make / Model : **T. SIENTA 1.5G A**
 Engine No. : **2NR8566921**
 Chassis No. : **N5P170716603**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAILGATE		\$ 1,895.80		\$ 1,895.80
2	2	TAILGATE DAMPER		\$ 320.00		
3	2	TAILGATE HINGE		\$ 280.00		
4	1	TAILGATE INNER TRIM		\$ 280.00		\$ 280.00
5	1	TAILGATE INNER TIRM CLIPS - SET		\$ 40.00		\$ 40.00
6	1	TAILGATE LOCK		\$ 790.70		\$ 790.70
7	1	TAILGATE LOCK CATCH		\$ 45.00		\$ 45.00
8	1	TAILGATE HANDLE SWICTH		\$ 295.30		\$ 295.30
9	1	TAILGATE WINDSCREEN GLASS		\$ 2,100.00		
10	1SET	TAILGATE WINDSCREEN GLASS MOULDING		\$ 320.00		\$ 320.00
11	1	TAILGATE OUTER GARNISH		\$ 287.60		\$ 287.60
12	1	TAILGATE OUTER GARNISH CLIP - SET		\$ 30.00		\$ 30.00
13	1	TAILGATE LOGO		\$ 92.80		\$ 92.80
14	2	TAILGATE STOPPER		\$ 100.00		\$ 100.00
15	1	TAILGATE WIPER MOTOR		\$ 400.00		\$ 400.00
16	1	TAILGATE WIPER ARM		\$ 200.00		
17	1	TAILGATE WIPER LINK		\$ 240.00		
18	1	TAILGATE WEATHERSTRIP		\$ 495.70		\$ 495.70
19	1	TAILGATE INNER HANDLE		\$ 89.60		\$ 89.60
20	2	TAILGATE LAMP		\$ 991.58		\$ 991.58
21	1	TAILGATE ANTENNA SENSOR		\$ 181.20		\$ 181.20
22	1	REAR BUMPER		\$ 596.50		\$ 596.50
23	1	REAR BUMPER CLIPS - SET		\$ 50.00		\$ 50.00
24	1	REAR BUMPER GARNISH CENTER		\$ 395.80		\$ 395.80
25	2	REAR BUMPER GARNISH		\$ 553.80		\$ 553.80
26	2	REAR BUMPER RELECTOR		\$ 195.40		
27	2	REAR BUMPER SIDE RETAINER		\$ 90.00		\$ 90.00
28	1	REAR BUMPER SMALL GARNISH		\$ 24.00		
29	1	REAR BUMPER SPONGE		\$ 45.00		\$ 45.00
30	1	REAR END PANEL INNER		\$ 697.70		\$ 697.70
31	1	REAR END PANEP OUTER		\$ 478.01		\$ 478.01
32	1	REAR END PANEL TOP GARNISH		\$ 279.50		\$ 279.50
33	1	REAR END PANEL TOP GARNISH CLIP - SET		\$ 40.00		\$ 40.00
34	2	TAILLAMP		\$ 1,359.00		\$ 1,359.00
35	2	TAILLAMP BRACKET		\$ 390.54		\$ 390.54
36	2	TAILLAMP PANEL		\$ 2,790.00		
37	2SET	TAILLAMP CLIPS		\$ 80.00		\$ 80.00
38	1	SPARE TYRE PANEL		\$ 1,379.60		\$ 1,379.60
39	1	SPARE TYRE BRACKET		\$ 182.22		
40	1	SPARE TYRE INSULATOR		\$ 279.90		\$ 279.90

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLH425Z**Vehicle Reg. Date: **21/10/2016**Make / Model : **T. SIENTA 1.5G A**Engine No. : **2NR8566921**Chassis No. : **N5P170716603**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	SPARE TYRE TOOL TRAY		\$ 757.90		\$ 757.90
42	2	SPRAY TYRE TOP BOARD		\$ 512.00		\$ 512.00
43	2	REAR FENDER		\$ 3,352.00		
44	2	REAR FENDER AIR DUCT		\$ 129.60		\$ 129.60
45	2	REAR FENDER INNER TRIM		\$ 1,941.00		\$ 1,941.00
46	2	REAR FENDER INNER TRIM CLIPS - SET		\$ 100.00		\$ 100.00
47	2	REAR FENDER INNER SHIELD		\$ 384.20		
48	2	REAR FENDER INNER SHEILD CLIPS - SET		\$ 20.00		
49	1	EXHAUST MUFFLER		\$ 795.60		
50	1	EXHAUST HEATSHIELD		\$ 89.90		
51	2	EXHAUST MOUNTING		\$ 100.00		
52	1	REAR TOW HOOK		\$ 61.30		
53	1	REAR NUMBER PLATE			\$ 20.00	
54	1	REAR NUMBER PLATE CASING			\$ 25.00	
55	1	REVERSE SENSOR			\$ 200.00	
56	2	REAR BUMPER EXTENSION GROMMET SCREW			\$ 8.00	
57	2	REAR BUMPER EXTENSION FASTENER			\$ 7.00	
58	2	REAR BUMPER FASTENER			\$ 8.00	
59	1	TAILGATE WINDSCREEN PRIMER			\$ 40.00	
60	2	TAILGATE WINDSCREEN SEALANT			\$ 65.00	
61	1	TAILGATE WINDSCREEN SUPPORT SPONGE			\$ 60.00	
62	1	REAR END PANEL SEALANT			\$ 40.00	
63	1	SPARE TYRE SEALANT			\$ 40.00	
64	1	SPARE TYRE SOUND DAMPER SET			\$ 120.00	
65	1	TAILGATE SEALANT			\$ 40.00	
66	2	TAILLAMP PAD				
67	3	EXHAUST RUBBER HOOK				
68	1	EXHAUST GASKET				
69	2	REAR CHASSIS MEMBER		\$ 2,954.00		
70	2	REAR DOOR		\$ 3,316.00		
71	2	Rear fender garnish lower LH/RH		\$ 188.00		
72	2	Rear fender garnish upper LH/RH		\$ 360.00		\$ 360.00
73	2	REAR FENDER UPPER INNER TRIM		\$ 716.00		
74	2	REAR FENDER UPPER INNER TRIM CLIP SET				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	Z				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018		03 Jul 2018 17:28 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN CHENG YU , ID: S75365808								
Main Claimant:	ISWANDY BIN SAMADI , ID: S74018608								
Vehicle Reg. No.:	SLH425Z	Date of Loss:	30/06/2018 18:00 - :59 [20 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03287C02	Policy/Cover Note No.:	DMPCSN3039661800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKS9240J	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (wcega Plaza) (HQ) 1 Bukit Batok Crescent, #05-23 WCEGA Plaza, 658064 Bukit Batok - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/07/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH425Z (SNM18D03287C02)
[SKS9240J]
TP
ISWANDY BIN SAMADI
Jun 30 2018 6:00PM
[TAN CHENG YU]
Vermogen Ace Pte Ltd (wcega Plaza)

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)					Thumbnail	Print	
1	02/07/18 18:22	Accident Statement						Load HTML	
Photos/Images							3 per page		☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)					Thumbnail	Print	
1	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
2	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
3	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
4	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
5	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
6	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
7	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
8	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
9	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
10	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
11	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
12	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
13	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
14	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
15	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
16	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
17	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
18	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
19	02/07/18 18:05	Accident Photo [Linked Accident Report Documents]						Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	08/11/18 15:15	Odometer Reading						Load JPG	☒
2	08/11/18 15:15	Chassis Number						Load JPG	☒
3	08/11/18 15:15	General View						Load JPG	☒
4	08/11/18 15:15	General View						Load JPG	☒
5	08/11/18 15:15	General View						Load JPG	☒
6	08/11/18 15:15	General View						Load JPG	☒
7	08/11/18 15:15	General View						Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
8	08/11/18 15:15	General View	 Load JPG	☒
9	08/11/18 15:15	General View	 Load JPG	☒
10	08/11/18 15:15	General View	 Load JPG	☒
11	08/11/18 15:15	General View	 Load JPG	☒
12	08/11/18 15:15	General View	 Load JPG	☒
13	08/11/18 15:15	General View	 Load JPG	☒
14	08/11/18 15:15	General View	 Load JPG	☒
15	08/11/18 15:15	General View	 Load JPG	☒
16	08/11/18 15:15	General View	 Load JPG	☒
17	08/11/18 15:15	General View	 Load JPG	☒
18	08/11/18 15:15	General View	 Load JPG	☒
19	08/11/18 15:15	General View	 Load JPG	☒
20	08/11/18 15:15	General View	 Load JPG	☒
21	08/11/18 15:15	General View	 Load JPG	☒
22	08/11/18 15:15	General View	 Load JPG	☒
23	08/11/18 15:15	General View	 Load JPG	☒
24	08/11/18 15:15	General View	 Load JPG	☒
25	08/11/18 15:15	General View	 Load JPG	☒
26	08/11/18 15:15	General View	 Load JPG	☒
27	08/11/18 15:15	General View	 Load JPG	☒
28	08/11/18 15:15	General View	 Load JPG	☒
29	08/11/18 15:15	General View	 Load JPG	☒
30	08/11/18 15:15	General View	 Load JPG	☒
31	08/11/18 15:15	General View	 Load JPG	☒
32	08/11/18 15:15	General View	 Load JPG	☒
33	08/11/18 15:15	General View	 Load JPG	☒
34	08/11/18 15:15	General View	 Load JPG	☒
35	08/11/18 15:15	General View	 Load JPG	☒
36	08/11/18 15:15	General View	 Load JPG	☒
37	08/11/18 15:15	General View	 Load JPG	☒
38	08/11/18 15:15	General View	 Load JPG	☒
39	08/11/18 15:15	General View	 Load JPG	☒
40	08/11/18 15:15	General View	 Load JPG	☒
41	08/11/18 15:15	General View	 Load JPG	☒
42	08/11/18 15:15	General View	 Load JPG	☒
43	08/11/18 15:15	General View	 Load JPG	☒
44	08/11/18 15:15	General View	 Load JPG	☒
45	08/11/18 15:15	General View	 Load JPG	☒
46	08/11/18 15:15	General View	 Load JPG	☒
47	08/11/18 15:15	General View	 Load JPG	☒
48	08/11/18 15:15	General View	 Load JPG	☒
49	08/11/18 15:15	General View	 Load JPG	☒
50	08/11/18 15:15	General View	 Load JPG	☒
51	08/11/18 15:15	General View	 Load JPG	☒
52	08/11/18 15:15	General View	 Load JPG	☒
53	08/11/18 15:15	General View	 Load JPG	☒
54	08/11/18 15:15	General View	 Load JPG	☒
55	08/11/18 15:15	General View	 Load JPG	☒
56	08/11/18 15:15	General View	 Load JPG	☒
57	08/11/18 15:15	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
58	08/11/18 15:15	General View	 Load JPG	☒
59	08/11/18 15:15	General View	 Load JPG	☒
60	08/11/18 15:15	General View	 Load JPG	☒
61	08/11/18 15:15	General View	 Load JPG	☒
62	08/11/18 15:15	General View	 Load JPG	☒
63	08/11/18 15:15	General View	 Load JPG	☒
64	08/11/18 15:15	General View	 Load JPG	☒
65	08/11/18 15:15	General View	 Load JPG	☒
66	08/11/18 15:15	General View	 Load JPG	☒
67	08/11/18 15:15	General View	 Load JPG	☒
68	08/11/18 15:15	General View	 Load JPG	☒
69	08/11/18 15:15	General View	 Load JPG	☒
70	08/11/18 15:15	General View	 Load JPG	☒
71	08/11/18 15:15	General View	 Load JPG	☒
72	08/11/18 15:15	General View	 Load JPG	☒
73	08/11/18 15:15	General View	 Load JPG	☒
74	08/11/18 15:15	General View	 Load JPG	☒
75	08/11/18 15:15	General View	 Load JPG	☒
76	08/11/18 15:15	General View	 Load JPG	☒
77	08/11/18 15:15	General View	 Load JPG	☒
78	08/11/18 15:15	General View	 Load JPG	☒
79	08/11/18 15:15	General View	 Load JPG	☒
80	08/11/18 15:15	General View	 Load JPG	☒
81	08/11/18 15:15	General View	 Load JPG	☒
82	08/11/18 15:15	General View	 Load JPG	☒
83	08/11/18 15:15	General View	 Load JPG	☒
84	08/11/18 15:15	General View	 Load JPG	☒
85	08/11/18 15:15	General View	 Load JPG	☒
86	08/11/18 15:15	General View	 Load JPG	☒
87	08/11/18 15:15	General View	 Load JPG	☒
88	08/11/18 15:15	General View	 Load JPG	☒
89	08/11/18 15:15	General View	 Load JPG	☒
90	08/11/18 15:15	General View	 Load JPG	☒
91	08/11/18 15:15	General View	 Load JPG	☒
92	08/11/18 15:15	General View	 Load JPG	☒
93	08/11/18 15:15	General View	 Load JPG	☒
94	08/11/18 15:15	General View	 Load JPG	☒
95	08/11/18 15:15	General View	 Load JPG	☒
96	08/11/18 15:15	General View	 Load JPG	☒
97	08/11/18 15:15	General View	 Load JPG	☒
98	08/11/18 15:15	General View	 Load JPG	☒
99	08/11/18 15:15	General View	 Load JPG	☒
100	08/11/18 15:15	General View	 Load JPG	☒
101	08/11/18 15:15	General View	 Load JPG	☒
102	08/11/18 15:15	General View	 Load JPG	☒
103	08/11/18 15:15	General View	 Load JPG	☒
104	08/11/18 15:15	General View	 Load JPG	☒
105	08/11/18 15:15	General View	 Load JPG	☒
106	08/11/18 15:15	General View	 Load JPG	☒
107	08/11/18 15:15	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
108	08/11/18 15:15	General View	 Load JPG	☒
109	08/11/18 15:15	General View	 Load JPG	☒
110	08/11/18 15:15	General View	 Load JPG	☒
111	08/11/18 15:15	General View	 Load JPG	☒
112	08/11/18 15:15	General View	 Load JPG	☒
113	08/11/18 15:15	General View	 Load JPG	☒
114	08/11/18 15:15	General View	 Load JPG	☒
115	08/11/18 15:15	General View	 Load JPG	☒
116	08/11/18 15:15	General View	 Load JPG	☒
117	08/11/18 15:15	General View	 Load JPG	☒
118	08/11/18 15:15	General View	 Load JPG	☒
119	08/11/18 15:15	General View	 Load JPG	☒
120	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
121	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
122	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
123	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
124	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
125	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
126	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
127	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
128	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
129	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
130	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
131	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
132	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
133	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
134	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
135	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
136	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
137	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
138	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
139	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
140	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
141	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
142	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
143	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
144	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
145	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
146	08/11/18 15:17	Dismantled Parts	 Load JPG	☒
147	08/11/18 15:17	Photo After Spray	 Load JPG	☒
148	08/11/18 15:17	Photo After Spray	 Load JPG	☒
149	08/11/18 15:17	Photo After Spray	 Load JPG	☒
150	08/11/18 15:17	Photo After Spray	 Load JPG	☒
151	08/11/18 15:17	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/07/18 17:27	OI GIA	 Load PDF	
2	03/07/18 17:27	PRS	 Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 18:02	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
2	02/07/18 18:21	IC,CI,DL [Linked Accident Report Documents]	 Load TIF	
3	02/07/18 18:21	POLICE REPROT [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 18:22	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 18:05	Accident Photo	 Load JPG	☒
2	02/07/18 18:05	Accident Photo	 Load JPG	☒
3	02/07/18 18:05	Accident Photo	 Load JPG	☒
4	02/07/18 18:05	Accident Photo	 Load JPG	☒
5	02/07/18 18:05	Accident Photo	 Load JPG	☒
6	02/07/18 18:05	Accident Photo	 Load JPG	☒
7	02/07/18 18:05	Accident Photo	 Load JPG	☒
8	02/07/18 18:05	Accident Photo	 Load JPG	☒
9	02/07/18 18:05	Accident Photo	 Load JPG	☒
10	02/07/18 18:05	Accident Photo	 Load JPG	☒
11	02/07/18 18:05	Accident Photo	 Load JPG	☒
12	02/07/18 18:05	Accident Photo	 Load JPG	☒
13	02/07/18 18:05	Accident Photo	 Load JPG	☒
14	02/07/18 18:05	Accident Photo	 Load JPG	☒
15	02/07/18 18:05	Accident Photo	 Load JPG	☒
16	02/07/18 18:05	Accident Photo	 Load JPG	☒
17	02/07/18 18:05	Accident Photo	 Load JPG	☒
18	02/07/18 18:05	Accident Photo	 Load JPG	☒
19	02/07/18 18:05	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	02/07/18 18:02	Sketch Plan	 Load TIF	
2	02/07/18 18:21	IC,CI,DL	 Load TIF	
3	02/07/18 18:21	POLICE REPROT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012125/T1SD3E2

Date: 14/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3039661800

Claimant Vehicle
No: SLH425ZInsured Vehicle
No: SKS9240J

Date of Loss: 30/06/2018

Nature of Claim: TP

Claim
No: SNM18D03287C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH425Z

Make & Model: TOYOTA SIENTA, 1.5 (A)

Reg. Date: 21/10/2016 (Man. Year: 2015)

Colour: White

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2NR8566921

Chassis No: NSP1707016603

Odometer: 114138 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Front Left Side: Achilles 6 mm

Front Right Side: Achilles 6 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

185/60 R15

Achilles 6 mm

Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,682.81	10,649.22	17,033.59	61.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,930.00	3,090.00	4,840.00	61.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,612.81	13,739.22	21,873.59	61.42
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	35,612.81	11,000.00	24,612.81	69.11
+ GST 7.00/7.00% (S\$)	2,492.90	770.00	1,722.90	69.11
Nett Amount (S\$)	38,105.71	11,770.00	26,335.71	69.11

INSPECTION

Date of Assignment: 03/07/2018

Date Inspected: 04/07/2018 Inspected At:

6 BENOI SECTOR

Repairer : Vermogen Ace Pte Ltd (wcega
Plaza) (HQ)

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2018)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH425Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,895.80 FL	*1,086.00 FL
2	2		*TAILGATE DAMPER	Repair	320.00 FL	*- FL
3	2		*TAILGATE HINGE	Repair	280.00 FL	*- FL
4	1		*TAILGATE INNER TRIM	Deformed	280.00 FL	*280.00 FL
5	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
6	1		*TAILGATE LOCK	Bent	790.70 FL	*235.60 FL
7	1		*TAILGATE LOCK CATCH	Bent	45.00 FL	*45.00 FL
8	1		*TAILGATE HANDLE SWITCH	Distorted	295.30 FL	*295.30 FL
9	1		*TAILGATE WINDSCREEN GLASS	Not Necessary	2,100.00 FL	*- FL
10	1		*SET TAILGATE WINDSCREEN GLASS MOULDING	Necessary	320.00 FL	*320.00 FL
11	1		*TAILGATE OUTER GARNISH	Deformed	287.60 FL	*287.60 FL
12	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	30.00 FL	*30.00 FL
13	1		*TAILGATE LOGO	Necessary	92.80 FL	*92.80 FL
14	2		*TAILGATE STOPPER	Necessary	100.00 FL	*100.00 FL
15	1		*TAILGATE WIPER MOTOR	Jammed	400.00 FL	*400.00 FL
16	1		*TAILGATE WIPER ARM	Not Necessary	200.00 FL	*- FL
17	1		*TAILGATE WIPER LINK	Not Necessary	240.00 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Twisted	495.70 FL	*285.50 FL
19	1		*TAILGATE INNER HANDLE	Deformed	89.60 FL	*89.60 FL
20	2		*TAILGATE LAMP	Cracked	991.58 FL	*991.58 FL
21	1		*TAILGATE ANTENNA SENSOR	Cracked	181.20 FL	*181.20 FL
22	1		*REAR BUMPER	Deformed	596.50 FL	*596.50 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
24	1		*REAR BUMPER GARNISH CENTER	Deformed	395.80 FL	*395.80 FL
25	2		*REAR BUMPER GARNISH	Cut	553.80 FL	*391.00 FL
26	2		*REAR BUMPER REFLECTOR	Not Necessary	195.40 FL	*- FL
27	2		*REAR BUMPER SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
28	1		*REAR BUMPER SMALL GARNISH	Not Necessary	24.00 FL	*- FL
29	1		*REAR BUMPER SPONGE	Deformed	45.00 FL	*45.00 FL
30	1		*REAR END PANEL INNER	Bent	697.70 FL	*498.20 FL
31	1		*REAR END PANEL OUTER	Bent	478.01 FL	*478.01 FL
32	1		*REAR END PANEL TOP GARNISH	Cracked	279.50 FL	*195.20 FL
33	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
34	2		*TAILLAMP	N/S Cracked / O/S Missing	1,359.00 FL	*1,020.60 FL
35	2		*TAILLAMP BRACKET	Necessary	390.54 FL	*390.54 FL
36	2		*TAILLAMP PANEL	Repair	2,790.00 FL	*- FL
37	2		*SET TAILLAMP CLIPS	Necessary	80.00 FL	*80.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*SPARE TYRE PANEL	Buckled	1,379.60 FL	*899.10 FL
39	1		*SPARE TYRE BRACKET	Repair	182.22 FL	*- FL
40	1		*SPARE TYRE INSULATOR	Deformed	279.90 FL	*279.90 FL
41	1		*SPARE TYRE TOOL TRAY	Deformed	757.90 FL	*429.00 FL
42	2		*SPRAY TYRE TOP BOARD	Deformed	512.00 FL	*512.00 FL
43	2		*REAR FENDER	Not Necessary	3,352.00 FL	*- FL
44	2		*REAR FENDER AIR DUCT	Deformed	129.60 FL	*129.60 FL
45	2		*REAR FENDER INNER TRIM	Deformed	1,941.00 FL	*1,941.00 FL
46	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FL	*100.00 FL
47	2		*REAR FENDER INNER SHIELD	Not Necessary	384.20 FL	*- FL
48	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	20.00 FL	*- FL
49	1		*EXHAUST MUFFLER	Repair	795.60 FL	*- FL
50	1		*EXHAUST HEATSHIELD	Not Necessary	89.90 FL	*- FL
51	2		*EXHAUST MOUNTING	Not Necessary	100.00 FL	*- FL
52	1		*REAR TOW HOOK	Not Necessary	61.30 FL	*- FL
53	1		*REAR NUMBER PLATE)	Cracked	35.00 FS	*45.00 FS
54	1		*REAR NUMBER PLATE CASING)		35.00 FS	*- FS
55	1		*REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
56	2		*REAR BUMPER EXTENSION GROMMET SCREW	Necessary	8.00 FS	*8.00 FS
57	1		*TAILGATE WINDSCREEN PRIMER	Necessary	40.00 FS	*40.00 FS
58	2		*TAILGATE WINDSCREEN SEALANT	Necessary	65.00 FS	*65.00 FS
59	1		*TAILGATE WINDSCREEN SUPPORT SPONGE	Necessary	60.00 FS	*60.00 FS
60	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
61	1		*SPARE TYRE SEALANT	Necessary	80.00 FS	*40.00 FS
62	1		*SET SPARE TYRE SOUND DAMPER	Necessary	250.00 FS	*120.00 FS
63	1		*TAILGATE SEALANT	Necessary	80.00 FS	*40.00 FS
64	2		*TAILLAMP PAD	Not Necessary	80.00 FS	*- FS
65	3		*EXHAUST RUBBER HOOK	Not Necessary	60.00 FS	*- FS
66	1		*EXHAUST GASKET	Not Necessary	45.00 FS	*- FS
67	2		*REAR CHASSIS MEMBER	Not Necessary	2,954.00 FL	*- FL
68	2		*REAR DOOR	Not Necessary	3,316.00 FL	*- FL
69	2		*REAR FENDER GARNISH LOWER LH/RH	Not Necessary	188.00 FL	*- FL
70	2		*REAR FENDER GARNISH UPPER LH/RH	Repair	360.00 FL	*- FL
71	2		*REAR FENDER UPPER INNER TRIM	Not Necessary	716.00 FL	*- FL
72	2		*SET REAR FENDER UPPER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
73	2		*REAR BUMPER EXTENSION FASTENER	Necessary	7.00 FS	*7.00 FS
74	2		*REAR BUMPER FASTENER	Necessary	8.00 FS	*8.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	36,472.75	13,974.63
- List Item Discount on L Items 25.00/25.00% (S\$)	8,789.94	3,325.41
Total Parts (S\$)	27,682.81	10,649.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING DAMAGED PANELS. TO REMOVE AND REPLACE DAMAGED PARTS. REAR PORTION	New	3,500.00	1,400.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS. REAR PORTION	New	2,800.00	1,200.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	150.00	40.00
4	TO REMOVE AND REPLACE REAR WINDSCREEN	New	180.00	120.00
5	TO REMOVE AND REFIT INTERIOR TRIM, SEATS AND UPHOLSTERY TO FACILITATE REPAIR	New	300.00	60.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	150.00	30.00
7	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
8	TO RUST PROOF REPAIRED AREAS	New	200.00	80.00
9	TO REMOVE AND REFIT EXHAUST PIPE AND ALIGN	New	150.00	100.00
10	TO MOUNT VEHICLE ON CELETTE BENCH FOR CHASSIS ALIGNMENT	New	350.00	0.00
Gross Labour Cost (S\$)			7,930.00	3,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >