

ASS. REC. BY:

REF: CS/CTI180121271 K+bnz Special Instruction:

SITUA. BY:

ASSIGNMENT (Office)

From (Person): Meamen Elaine Cheong of CTL Date/Time: 03/07/2018 5:10pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 6381Y Insured: SCN 838R

at Workshop m/s Cheng Hoe Tel: 6755 6142

of Bk 1019 Yishun Ind Park A #01-374

Policy No: DMP CSN3112361801 Claim No: SNM18D0312602

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21/06/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' Bk 10 AMK Ind Park 2A #01-04 H.O.D. Endorsement: _____

Date/Time: 04/07/2018 9:58am Person Contacted: Dorlyn Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJR 6381Y - CS/RSI14 010503 / Rgbdl</u> <u>DOA: 29/5/2014</u>
	<u>SCN 838R - X</u>
<u>15/11</u>	<u>L1 Lp @ 29501 Confirm Tune (ped. 1152) 287.2)</u>

ASS. REC. BY:

REF: 0721

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.


L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 15 NOV 2018

Date/Time, File Pass to?

1) Bill Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + R.S. SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TP

2950/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018 Sendback Est	03 Jul 2018 14:34 S\$4,102.00	03 Jul 2018 17:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LECCA CAR LEASING, Co. Reg. No.: 53247626C		
Main Claimant:	LIM BENG HWA, ID: S1317144J		
Vehicle Reg. No.:	SJR6381Y	Date of Loss:	21/06/2018 14:00 - :59 [107 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03126C02	Policy/Cover Note No.:	DMPCSN3112361801
Vehicle Reg. No. (Insured):	SCN838R	Policy No. (Claimant):	5076139953-02
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/07/2018]		
Driver/Custodian (Insured):	RAJA (/ Male), Tel: +6593896269		
Adj Asg. Remarks:	EST \$4389.14, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7144J
Vehicle Details	
Vehicle No.:	SJR6381Y
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 1.5 MT R
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	ZY519959
Chassis No.:	JMODE10Y190130626
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$15,796.00
Original Registration Date:	02 Jul 2009
First Registration Date:	02 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$15,796.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jul 2019
PARF Rebate Amount:	\$7,898.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$1,275.00
Total Rebate Amount:	\$9,173.00

The information contained herein is correct as at 05 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2018 14:10
Date Of Accident	21/06/2018 14:45
Exact Location Of Accident	UBI RD 2 (SLIP RD TO AIRPORT RD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR6381Y
Insured/Policyholder	
Name Of Registered Owner	LIM BENG HWA
NRIC No	S1317144J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96470193
Alternative Phone No	OTHERS-96470193

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA2 1.5 MT R
Exact Purpose for which vehicle was being used at time of accident	DRIVING TIUTION USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076139953-02
Cover Note Number	02/01/2018 - 01/01/2019

Driver

Name of Driver	ALEX TAN KIAN HYE
NRIC No	S9810385F
Date Of Birth	04/04/1998
Occupation	INDOOR
Date Of Driving Pass	21/06/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84844715
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 3 CROWHURST DRIVE
 Postcode 557882
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - STUDENT
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : LIM BENG HWA
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS GIVING DRIVING TUITION TO MY LEARNER (ALEX TAN KIAN HYE, S9810385F) ON 21/06/2018 AT 1445HR AND AT THE SLIP ROAD FROM UBI RD 2 TOWARDS AIRPORT ROAD, MY LEARNER STOPPED AT THE SLIP ROAD FOR TRAFFIC ON THE MAIN ROAD TO CLEAR. WHEN THERE WERE NO VEHICLES ON THE RIGHT AND BEFORE HE COULD MOVED OUT OF THE SLIP ROAD, WE FELT AN IMPACT FROM THE BACK AND REALISED MOTOR CAR SCN838R HAD CAME FROM BEHIND AND HIT ONTO OUR VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCN838R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver RAJA
 NRIC/Passport Number
 Contact Number 93896269
 Address
 Postcode
 Insurance Company Name

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SJR6381Y
INSURER : NTUC
DATE & TIME: 21/06/18 @ 1445

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Dorlyn (ANK) 22/06/18
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SJR6381Y (NTUC)
Date & Time: 21/06/2018 @ 1445 (clear day)

I was giving Driving Tuition to my learner (Alex Tan Kian Hye, S9810385F) on 21/06/2018 at 1445hr and at the slip road from Ubi road 2 towards Airport rd, my learner stopped at the slip road for traffic on the main road to clear. When there were no vehicles on the right and before he could moved out of the slip road, we felt an impact from the back and realised motor car SCN 838R had came from behind and hit onto our vehicle rear portion.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/FIN No.:

() Claim Own Policy ☒ Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
 Tel : 67556142 Fax : 67557719
 Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
LECCA CAR LEASING

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (SCN838R)
Policy No:		Date of Loss:	21/06/2018
Vehicle Reg. No.:	SJR6381Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ALEX TAN KIAN HYE	Driver (Insured):	RAJA
Make/Model:	MAZDA 2, 1.5 (A)	Vehicle Reg. Date:	02/07/2009
Vehicle Colour:	RED		
Engine No:	ZY519959	Chassis No:	JM0DE10Y190130626
Odometer:	0 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) 0

Not Withheld
61 Day 8? Repairing
Repair After Pain today

Description of Accident/Loss I WAS GIVING DRIVING TUITION TO MY LEARNER (ALEX TAN KIAN HYE, S9810385F) ON 21/06/2018 AT 1445HR AND AT THE SLIP ROAD FROM UBI RD 2 TOWARDS AIRPORT ROAD, MY LEARNER STOPPED AT THE SLIP ROAD FOR TRAFFIC ON THE MAIN ROAD TO CLEAR. WHEN THERE WERE NO VEHICLES ON THE RIGHT AND BEFORE HE COULD MOVED OUT OF THE SLIP ROAD, WE FELT AN IMPACT FROM THE BACK AND REALISED MOTOR CAR SCN838R HAD CAME FROM BEHIND AND HIT ONTO OUR VEHICLE REAR PORTION.

Present Location: CHENG HOE MOTOR PTE LTD (AMK)

COST OF CLAIMS	Amount
Parts	1,867.00
Miscellaneous Items	275.00
Labour	1,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,102.00
+ GST 7.00% (\$\$)	287.14
Nett Amount (\$\$)	4,389.14

This claim is handled by: DORLYN LI YAZHU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

SJR6381Y

TP/Chine

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jul 2018)
 Parts: 143 MAZDA 2 1.5 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SJR6381Y/03/07/2018 14:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc rear bumper	0.00	0.00	Bu *450.00F ✓
2	1		*1 pc rear bumper reinforcement	0.00	0.00	Bu *120.00F ✓
3	1		*1 pc rear bumper LH side retainer	0.00	0.00	P.V. *14.00F —
4	1		*5 pcs rear bumper clips @ \$2/pc	0.00	0.00	Me *10.00F —
5	1		*1 set rear bumper no. plate lamp	0.00	0.00	SM *140.00F —
6	1		*1 pc LH taillamp	0.00	0.00	SM *220.00F X
7	1		*1 pc tailgate	0.00	0.00	Bu *550.00F ✓
8	1		*1 pc tailgate logo	0.00	0.00	Me *28.00F —
9	1		*1 pc tailgate emblem MAZda	0.00	0.00	Me *18.00F —
10	1		*1 pc tailgate emblem 2	0.00	0.00	Me *14.00F —
11	1		*1 pc tailgate inner rubber	0.00	0.00	Me *68.00F —
12	1		*1 pc rear end panel	0.00	0.00	Bu *150.00F ✓
13	1		*1 pc rear end panel inner top garnish	0.00	0.00	Me *85.00F ✓
Total Parts (S\$)						1,867.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SJR6381Y/03/07/2018 14:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 pc rear no. plate	35.00 ✓
2	1	1 set reverse sensor	200.00 ✓
3	1	1 unit rear windscreen glass sealant	40.00 ✓
Sub Total (S\$)			275.00

Supp 1m tail gate inner lock

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Remove & refix rear windscreen glass	New	100.00 ✓
2	Remove & refix rear bumper, tailgate & attachments, taillamps; to cut, weld & renew rear end panel; knocking & repair rear fenders, rear compartment panel & realign the same	New	900.00 ✓
3	Putty & respray rear bumper, reinforcement, tailgate, rear end panel, rear fenders, rear compartment panel & all affected areas	New	900.00 ✓
4	Rustproofing	New	60.00 ✓
Gross Labour Cost (S\$)			1,960.00

Cheng Hoe Motor Pte Ltd/SJR6381Y/03/07/2018 14:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
 Tel : 67556142 Fax : 67557719
 Email: chmotor@singnet.com.sg

(SUPPLEMENTARY)

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
 LECCA CAR LEASING

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (SCN838R)
Policy No:	DMPCSN3112361801	Date of Loss:	21/06/2018
Vehicle Reg. No.:	SJR6381Y	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	RAJA
Driver (TP):	ALEX TAN KIAN HYE		
Make/Model:	MAZDA 2, 1.5 (A)	Vehicle Reg. Date:	02/07/2009
Vehicle Colour:	RED	Chassis No:	JM0DE10Y190130626
Engine No:	ZY519959		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	I WAS GIVING DRIVING TUITION TO MY LEARNER (ALEX TAN KIAN HYE, S9810385F) ON 21/06/2018 AT 1445HR AND AT THE SLIP ROAD FROM UBI RD 2 TOWARDS AIRPORT ROAD, MY LEARNER STOPPED AT THE SLIP ROAD FOR TRAFFIC ON THE MAIN ROAD TO CLEAR. WHEN THERE WERE NO VEHICLES ON THE RIGHT AND BEFORE HE COULD MOVED OUT OF THE SLIP ROAD, WE FELT AN IMPACT FROM THE BACK AND REALISED MOTOR CAR SCN838R HAD CAME FROM BEHIND AND HIT ONTO OUR VEHICLE REAR PORTION.		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

COST OF CLAIMS	Amount
Parts	95.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	95.00

+ GST 7.00% (S\$)	6.65
Nett Amount (S\$)	101.65
+ Previous Estimates (S\$)	4,389.14
Claim Total (S\$)	4,490.79

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jul 2018)

Parts: 143 MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SJR6381Y/07/07/2018 09:30

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT INNER LOCK	0.00	0.00	*95.00 F dd
Total Parts (S\$)						95.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SJR6381Y/07/07/2018 09:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SJR6381Y/07/07/2018 09:30. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012127/KTBN2

Date: 16/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3112361801
Claimant Vehicle No :	SJR6381Y	Insured Vehicle No :	SCN838R
Date of Loss:	21/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03126C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6381Y	Engine No:	ZY519959
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM0DE10Y190130626
Reg. Date:	02/07/2009 (Man. Year: 2008)	Odometer:	213229 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,962.00	1,742.00	220.00	11.21
Miscellaneous Items	275.00	275.00	0.00	0.00
Labour	1,960.00	1,660.00	300.00	15.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,197.00	3,677.00	520.00	12.39
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	4,197.00	2,950.00	1,247.00	29.71
+ GST 7.00/7.00% (S\$)	293.79	206.50	87.29	29.71
Nett Amount (S\$)	4,490.79	3,156.50	1,334.29	29.71

INSPECTION

Date of Assignment:	03/07/2018	
Date Inspected:	04/07/2018	Inspected At:
		Blk 10 AMK Ind Park 2A #01/04
		Repairer: Cheng Hoe Motor Pte Ltd
		Blk 1019 Yishun Ind. Park A
		#01-374/382
		Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2018)
 Parts: 143 MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJR6381Y)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc rear bumper	Buckled	450.00 F	*450.00 F
2	1		*1 pc rear bumper reinforcement	Bent	120.00 F	*120.00 F
3	1		*1 pc rear bumper LH side retainer	Distorted	14.00 F	*14.00 F
4	1		*5 pcs rear bumper clips @ \$2/pc	Necessary	10.00 F	*10.00 F
5	1		*1 set rear bumper no. plate lamp	Cracked	140.00 F	*140.00 F
6	1		*1 pc LH taillamp	Serviceable	220.00 F	*- F
7	1		*1 pc tailgate	Bent	550.00 F	*550.00 F
8	1		*1 pc tailgate logo	Necessary	28.00 F	*28.00 F
9	1		*1 pc tailgate emblem MAZda	Necessary	18.00 F	*18.00 F
10	1		*1 pc tailgate emblem 2	Necessary	14.00 F	*14.00 F
11	1		*1 pc tailgate inner rubber	Distorted/Dented	68.00 F	*68.00 F
12	1		*1 pc rear end panel	Bent	150.00 F	*150.00 F
13	1		*1 pc rear end panel inner top garnish	Mtg Distorted	85.00 F	*85.00 F
Supplementary #1						
14	1		*REAR BOOT INNER LOCK	Dented	95.00 F	*95.00 F
				Total Parts (S\$)	1,962.00	1,742.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc rear no. plate (CRACKED)	35.00	35.00
2	1	1 set reverse sensor (SHORTED)	200.00	200.00
3	1	1 unit rear wndscreen glass sealant (NECESSARY)	40.00	40.00
Sub Total (\$\$)			275.00	275.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove & refix rear windscreen glass	New	100.00	100.00
2	Remove & refix rear bumper,tailgate & attachments,tailamps;to cut,weld & renew rear end panel;knocking & repair rear fenders,rear compartment panel & realign the same	New	900.00	700.00
3	Putty & respray rear bumper,reinforcement,tailgate,rear end panel,rear fenders,rear compartment panel & all affected areas	New	900.00	800.00
4	Rustproofing	New	60.00	60.00
Gross Labour Cost (\$\$)			1,960.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >