

Surveyor

Kenneth

ASSIGNMENT (Office)

CWS

From (Person)

Leirene jaw

of

FCI

Date/Time

4/7/18 @ 10:51am

Estimated Cost

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 9749Z

Insured:

8HC 7039H

at Workshop n/s

Trans-cab

Tel:

6287 6666

of

No. 2 AMK St 63

Policy No:

Claim No:

D18005168MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Ds

H.O.D. Endorsement:

Date/Time: 10:53am @ 4/7/18

Person Contacted:

Candy

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 9749Z - CC 3 / AIG 15007002 / Kua 3q2

DOA: 19/04/2015

8HC 7039H - CS/FCI 16017673 / Ugh 3c2

DOA: 03/07/2016

5/7/18

Email preli revised to FCI

ASS. REC. BY:

REF: 1021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S110 97497 Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c. 1995

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

420624

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABC15AUC 276108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

215/60R16

R: Felix

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

11/7/18

D.O.I.

4/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/7 File pass to Catherine

5/7/18 L1 Exp 84800 (Red 48, 506.26, 9170)

RECEIVED 8 JUL 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

5/7 - typist

Report Format:

Lump Sum / I.B.I. (\$) :

CWS

4800/2

Days Of Repair:

4

Resurvey No. of Trip:

-

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Fixtures

Others

TOTAL

43X15 = 645

170 + 645

50

16

881



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005168MFSH

Our ref: CS/FCI18012138/Kvd3

Date : 5/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 9749Z


We thank for your instruction on 4/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/7/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$53,306.26
Revised Estimate Amount	: S\$4,800.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-07-2018	Our Ref No. D18005168MFSH
Accident Date	01-07-2018	Claim Type. Third Party
Insured Vehicle	SHC7039H	Third Party Vehicle. SHD9749Z
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242024)



PRI Documents



Close



PRI Header Details

Claim No	D18005168MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7039H	TP Vehicle No	SHD9749Z
PRI Recieved Date	03-07-2018 07:23:13 PM	Surveyor Appointed Date	04-07-2018 10:50:02 AM	Surveyor Accept Date	04-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 5 July 2018 1:46 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005168MFSH/1, SHD 9749Z
Attachments: SHD 9749Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 9749Z

Date of survey: 4/7/2018

Number of days :4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 4 July 2018 10:56 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005168MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 July 2018 10:50 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005168MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

[-> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9749Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000727
Chassis No.:	VF1ABL15AUC276168
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Dec 2013
First Registration Date:	04 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2021
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	03 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$26,816.00
Total Rebate Amount:	\$36,189.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jul 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9749Z**AAD1807-007**

Not Notarized
L1 Syg & 4800h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9749Z

VF1ABL15AUC276168

RENAULT

LATITUDE

1.7.2018

FCIL**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Per</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Dis/mt</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97	X
8	1 BUMPR RETAINER LH REAR	\$	<i>Sm</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>Bt</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>D, 1</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	} X
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36	
19	1 BOOT BADGE	\$	<i>na</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1807-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9749Z

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45		
32	1 FENDER PANEL REAR LH	\$	R	3,299.13		
33	1 WHEELARCH REAR LH	\$	Sn	543.47		
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45		
35	1 FENDER PANEL REAR RH	\$	R	3,299.13		
36	1 WHEELARCH REAR RH	\$	Sn	543.47		
37	1 TAILLAMP RH	\$	Sn	552.55		
38	1 TAILLAMP PANEL RH	\$	R	986.70		
39	1 TAILLAMP LH	\$	Sn	552.55		
40	1 TAILLAMP PANEL LH	\$	R	986.70		
41	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	}	X
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56		
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88		
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
45	1 EXHAUST REAR	\$	R	7,489.05		
46	1 EXHAUST CAP REAR	\$	R	230.49		
47	1 FUEL FLAP L70Y	\$	Sn	343.57		
48	1 CHASSIS PANEL REAR LH	\$	R	3,766.43		
TOTAL		\$		42,823.60		
10%		\$		4,282.36		
		\$		38,541.24		

Special Nett

1	1SET PARKING AID	\$	Shay	700.00	✓
2	1SET REAR BUMPER CLIP	\$	R	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	R	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	R	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	R	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	R	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	R	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	R	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	R	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	R	30.00	X
13	1 BOOT STICKER "6555-3333"	\$	R	30.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9749Z

14	1 BOOT INNER TRIM CLIP	\$	~ 45.00	}	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	~ 35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	~ 35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	~ 28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	~ 28.00		
19	1 TAILLAMP CLIP RH	\$	~ 5.00		
20	1 TAILLAMP CLIP LH	\$	~ 5.00		
21	2 REAR WINDSCREEN SELANT	\$	~ 80.00		
22	1 WINDSCREEN MOULDING	\$	~ 100.00		
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	~ 100.00		
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	~ 385.00	}	
25	1 SPARE TYRE	\$	~ 330.00		

TOTAL \$ 2,225.02**TOTAL PARTS \$ 40,766.26****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9749Z

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
TOTAL	\$	12,540.00	

Over All Total \$ 53,306.26

53686 24

(LUMP SUM)**Repair Days****20 DAYS**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012138/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7039H	Veh. Inspected	SHD 9749Z	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005168MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC276168	Colour	WHITE	
Odometer	420624	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	FALKEN	8 mm	
L/H Rear Tyre	215/60 R16	FALKEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2018	Inspection Date	04/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9749Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / CRACKED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	DISTORTED	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
	LESS 10% DISCOUNT		-4,282.36	-439.62
			38,541.22	3,956.53
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00

Report Ref No. CS/FCI18012138/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	865.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET RH REAR,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,DOOR PANEL REAR LH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR,EXHAUST CAP REAR AND CHASSIS PANEL REAR LH.		4,200.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANELINSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	1,190.00
	GRAND TOTAL		53,686.24	6,011.53
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CS/FCI18012138/Kvd3n2



Report Ref No. CS/FCI18012138/Kvd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.