

ASS. REC. BY:

REF: CS/FCI18012140/Kvd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Lurene jaw

of

FCI

Date/Time: 3/7/16 @ 6:55pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHF 559D

Insured:

SHC 0329S

at Workshop m/s

Trans-Cab

Tel:

6287 6666

of

No. 2 AMK st-63

Policy No:

Claim No:

D18005177 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

8:50am @ 4/7/16

Person Contacted:

Candy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHF 559D - CC3/FCI15014424/Kvbc2	DOA: 22/5/2015
	SHC 329S - CS/FCI16003111/Fgh3d1	DOA: 14/02/2016
5/7/16	Email preli revised to FCI	

(08/11/13) wef
ASS REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 4/7/2018
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SHF 559D
at Workshop m/s Trans-Cab
of No. 2 AMK st. 63
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 06 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 559D Yr Regn: 06, 14
Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /
Truck / Trailer or _____
Make: Renault Latitude G.C. 1995
Colour: M. White / R A/C: Insured / Std / NI / NA
Sp. Reading: 364273 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: VF1ABL15AUC 278122
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: ☒ Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti
Front _____ Rear _____
R/Bal. 8 mm R/Bal. 8 mm
L/Bal. 8 mm L/Bal. 8 mm
D.O.A. 28/6/18 D.O.I. 4/7/18
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/7 file pass to Carham

5/7/18 1/Lp 'B74501' (Red 31, 309.24, 81M)

RECEIVED 05 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) 5/7 - typist

Report Format : CWS

Lump Sum / I.B.I: (\$ 74501/2)

Days Of Repair: 6

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

28x15=420

170+420

50

22

662



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005177MFSH

Our ref: CS/FCI18012140/Kvd3

Date : 5/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHF 559D


We thank for your instruction on 3/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/7/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$38,759.24
Revised Estimate Amount	: S\$7,450.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-07-2018	Our Ref No. D18005177MFSH
Accident Date	28-06-2018	Claim Type. Third Party
Insured Vehicle	SHC0329S	Third Party Vehicle. SHF559D
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242036)



PRI Documents



Close X

PRI Header Details

Claim No	D18005177MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0329S	TP Vehicle No	SHF559D
PRI Recieved Date	03-07-2018 08:05:58 PM	Surveyor Appointed Date	03-07-2018 06:54:53 PM	Surveyor Accept Date	04-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 5 July 2018 2:04 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005177MFSH/2, SHF 559D
Attachments: SHF 559D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHF 559D
Date of survey: 4/7/2018
Number of days :6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 July 2018 4:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005177MFSH/2

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 July 2018 3:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005177MFSH/2

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHF559D
Vehicle to be Exported:	Yes
Intended De-registration Date:	29 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001454
Chassis No.:	VF1ABL15AUC278122
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Jun 2014
First Registration Date:	20 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	19 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$28,488.00
Total Rebate Amount:	\$37,861.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Jun 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 559D**AAD1806-285**

Not Authored
L1Pny 874301

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 559D

VF1ABL15AUC278122

RENAULT

LATITUDE

28.6.2018

FCIL

	PART		LIST
1	FENDER PANEL FRT RH	\$	R 783.83 ✓
1	WHEELARCH FRT RH	\$	Sn 278.84 X
1	FENDER BRACKET LOWER RH	\$	Sn 15.79 X
1	FENDER INSULATOR RH	\$	Sn 130.84 X
1	DOOR PANEL FRT RH	\$	R 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	R 261.28
1	DOOR HINGE LOWER RH	\$	R 300.55
1	DOOR CHECK FRT RH	\$	Sn 194.77
1	DOOR LOCK FRT RH	\$	R 908.75
1	DOOR CATCH FRT RH	\$	Sn 131.23
1	DOOR HANDLE OUTER FRT RH	\$	Sn 477.76
1	DOOR HANDLE COVER FRT RH	\$	Sn 13.22
1	DOOR HANDLE MODULE FRT RH	\$	Sn 133.60
1	DOOR REGULATOR FRT RH	\$	R 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	Sn 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	Sn 120.97
1	DOOR PANEL REAR RH	\$	R 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	Sn 176.82
1	DOOR HINGE UPPER RH	\$	R 274.50
1	DOOR HINGE LOWER RH	\$	R 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	Sn 203.06
1	DOOR LOCK REAR RH	\$	R 908.75
1	DOOR HANDLE OUTER REAR RH	\$	Sn 126.49
1	DOOR HANDLE CAP REAR RH	\$	Sn 35.52
1	DOOR HANDLE SEAL REAR RH	\$	Sn 7.89
1	DOOR HANDLE COVER REAR RH	\$	Sn 13.22
1	DOOR HANDLE MODULE REAR RH	\$	Sn 133.60
1	DOOR REGULATOR REAR RH	\$	R 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	Sn 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	Sn 12.43

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 559D

1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR RH	\$	423.10
1	DOOR MOULDING REAR RH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR RH	\$	1,509.06
1	DOOR WATER SHIELD REAR RH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR RH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	20.33
1	DOOR GRAB HANDLE REAR RH	\$	210.96
1	DOOR BLIND REAR RH	\$	741.80
1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
1	DOOR SEAL REAR RH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64
1	FENDER PANEL REAR RH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR RH	\$	543.47
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	ROCKER PANEL INNER GARNISH RH	\$	466.51 X
1	ROCKER PANEL INNER RH	\$	1,024.79 X
1	ROCKER PANEL CENTER RH	\$	990.25 X
1	BUMPER COVER REAR	\$	1,108.46 X

\$	29,407.90
10% \$	2,940.79
\$	26,467.11

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 559D

1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	605n
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	155n
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	605n
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT RH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

TOTAL	\$	462.13
--------------	-----------	---------------

TOTAL PARTS	\$	26,929.24
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	600l
Putty and spray painting of the affected portion.	\$	4,200.00	1100l
To rust-proofing of the affected areas.	\$	170.00	90l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To check steering geometry and computer wheel alignment	\$		220.00 60l
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To Check Electrical Lighting Concerned.	\$		170.00 20l

Trans-cab Auto Services Pte Ltd

AAD1806-285

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 559D

To transfer of front fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 601
Towing Fees.	\$	120.00 501
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X

TOTAL \$ 11,830.00

Over All Total \$ 38,759.24

LUMP SUM (REPAIR DAY)

15 DAYS

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012140/Kvd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 329S	Veh. Inspected	SHF 559D
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18005177MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278122	Colour	METALLIC WHITE / RED
Odometer	364273	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/06/2018	Inspection Date	04/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 559D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FENDER PANEL FRT RH	BENT	783.83	783.83 ✓
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66 ✓
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR +	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR +	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR +	908.75	-
1	DOOR CATCH FRT RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR +	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR +	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR +	300.55	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR +	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-

Report Ref No. CS/FCI18012140/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	SERVICEABLE	5.92	-
1	DOOR MOULDING SCREW L70Y	SERVICEABLE	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	NOT NECESSARY	48.74	-
1	DOOR FINISHER INNER REAR RH	NOT NECESSARY	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY RH	CRACKED	1,483.40	1,483.40

Report Ref No. CS/FCI18012140/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408033

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR ✓	1,024.79	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR ✓	990.25	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR ✓	1,108.46	-
	LESS 10% DISCOUNT		-2,940.79	-795.66
			26,467.11	7,160.89
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CHASSIS" (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER "6555 3333" (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
			462.11	135.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		4,500.00	600.00

Report Ref No. CS/FCI18012140/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR REGULATOR FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK REAR RH, DOOR REGULATOR REAR RH, DOOR FINISHER BRACKET INNER REAR RH, DOOR FINISHER BRACKET INNER REAR RH, DOOR FINISHER BRACKET INNER REAR RH, DOOR FINISHER BRACKET INNER REAR RH, FENDER PANEL REAR RH, ROCKER PANEL INNER RH, ROCKER PANEL CENTER RH AND BUMPER COVER REAR.)			-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.		120.00	50.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			11,830.00	2,040.00
	GRAND TOTAL		38,759.22	9,335.89
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,450.00

Report Ref No. CS/FCI18012140/Kvd3n2



Report Ref No. CS/FCI18012140/Kvd3n2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.