

ASS. REC. BY:

REF: CS/FCI18612143/Ard3ⁿ²

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

CWS

Lurene jaw

of

FCI

Date/Time: 3/7/2018 @ 5.38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 3914T

Insured:

SHA 9464K

at Workshop m/s

MA Solution

Tel:

67444165

of

23 kaki Bukit Ave 4 #02-03

Policy No:

Claim No:

DIE005066MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Ds'

H.O.D. Endorsement:

Date/Time:

9:03am @ 4/7/18

Person Contacted:

Ms. Hong

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 3914T - CS3/INC/6003640/Uqbd1-1 DOA: 22/2/2016
	SHA 9464K - CS/FCI15066427/Uvbg2 DOA: 14/04/2015
5/7/18	Revert to insurance pending estimate.
	Adrian confirm L/S \$4100 @ 6 days (net: \$11,736.78, 74%)

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJF3814T

Yr Regn:

2008 / MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Optrac.c 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

92574

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KLINA96E7H101367Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

04/07/18

Survey held at

M6 SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.COE Expiry: 27/05/23MV: 28KRV: 18.7KNett: 9.3K

RECEIVED 01 AUG 2018

MV: \$28,000, LTA: \$18,695.00 NV \$9,305.00

Date/Time, File Pass to?



Preli. Report

1)

typical

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

170 + 755x15: 75505046391

Report Format:

TPLump Sum / LB (\$) 4100



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012143/Ard3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9464K	Veh. Inspected	SJF 3914T
Policy No.		Coverage (\$)	0.00
Claim No.	D18005066MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	04/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/06/2018	Inspection Date	04/07/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	28-06-2018	Our Ref No. D18005066MFSH
Accident Date	26-06-2018	Claim Type. Third Party
Insured Vehicle	SHA9464K	Third Party Vehicle. SJF3914T
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	MS HONG	
Contact No.	67444165/ 0	Fax No. 67444604
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241879)



PRI Documents



Close

PRI Header Details

Claim No	D18005066MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & MG SOLU
Workshop Name	MG SOLUTION PTE LTD (Contact Person : MS HONG)	Survey Location & Contact Details	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03 Mobile: 0 , Phone: 67444165 , Fax: 67444604 EmailId: MG3SOLUTION@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9464K	TP Vehicle No	SJF3914T
PRI Recieved Date	03-07-2018 01:21:26 PM	Surveyor Appointed Date	03-07-2018 05:37:03 PM	Surveyor Accept Date	04-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-07-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, July 05, 2018 3:26 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005066MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle SJF 3914T on 04/07/2018.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, July 04, 2018 9:05 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005066MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 3 July 2018 5:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005066MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8885E
Vehicle Details	
Vehicle No.:	SJF3914T
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jul 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	OPTRA 1.6AT MY7.5 FACELIFT
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	F16D3721273K
Chassis No.:	KL1NA196E7H101367
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,169.00
Original Registration Date:	28 May 2008
First Registration Date:	28 May 2008
Transfer Count:	1
Actual ARF Paid:	\$13,169.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,096.00
COE Rebate Amount:	\$18,695.00
Total Rebate Amount:	\$18,695.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Jul 2018

OK

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: FIRST CAPITAL INSURANCE LIMITED	DATE	: 3-Jul-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJF 3914 T	KLINA196E7H101367	
MODEL	: CHEVROLET OPTRA 1.6AT	Janice	
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>		DATE	: 26-Jun-18
		TIME	: 17:45HRS
THIRD PARTY REQUESTOR / CONTACT : DEON			

CLAIM DETAIL : PARTS

S/ N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckled</i>	1	\$ 1,920.00	\$ 1,920.00 973
2	BOOTLID EMBLEM 'OPTRA'	1	\$ 52.00	\$ 52.00
3	BOOTLID EMBLEM 'CHEVROLET' <i>New</i>	1	\$ 65.00	\$ 65.00
4	BOOTLID EMBLEM 'MAGNUM'	1	\$ 63.80	\$ 63.80
5	BOOTLID LOGO <i>New</i>	1	\$ 58.00	\$ 58.00
6	BOOTLID LOCK <i>Replaced</i>	1	\$ 320.00	\$ 320.00 87.
7	BOOTLID LOCK CATCH <i>Replaced</i>	1	\$ 89.20	\$ 89.20
8	BOOTLID KEY LOCK	1	\$ 297.40	\$ 297.40
9	BOOTLID INNER TRIM <i>New</i>	1	\$ 466.30	\$ 466.30
10	BOOTLID WEATHERSTRIP <i>lt</i>	1	\$ 163.00	\$ 163.00
11	BOOTLID WINDSCREEN MOULDING <i>new</i>	1	\$ 155.20	\$ 155.20
12	REAR BUMPER <i>Distorted</i>	1	\$ 1,880.00	\$ 1,880.00 1250
13	REAR BUMPER LOWER LIP <i>Not New</i>	1	\$ 499.00	\$ 499.00
14	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.30	\$ 124.60
15	REAR BUMPER REINFORCEMENT BRACKET <i>New</i>	2	\$ 489.00	\$ 978.00
16	TAILLAMP <i>Not New L&L covered</i>	2	\$ 580.10	\$ 1,160.20 325
17	TAILLAMP PANEL <i>Not New</i>	2	\$ 188.90	\$ 377.80
18	END PANEL <i>Distorted</i>	1	\$ 830.00	\$ 830.00 530
19	END PANEL TOP GARNISH <i>Behind</i>	1	\$ 180.20	\$ 180.20 58
20	REAR FLOOR PANEL TOP BOARD <i>Not New</i>	1	\$ 515.00	\$ 515.00
21	TOOLS BOX COMPARTMENT <i>Not New</i>	1	\$ 280.70	\$ 280.70

Comes as
assy with
bumpers

22	EXHAUST PIPE <i>Nol Nee</i>	1	\$ 1,415.20	\$ 1,415.20	<i>x</i>
23	EXHAUST PIPE MOUNTING <i>Nol Nee</i>	4	\$ 55.90	\$ 223.60	<i>x</i>

3789.40

3410.46

TOTAL PRICE \$12,114.20

LESS 10% \$ 1,211.42

SUB TOTAL PRICE \$10,902.78

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00	<i>x</i>
2	TAILGATE INNER BOARD CLIPS	1	\$ 22.00	\$ 22.00	<i>✓</i>
3	TAILGATE WINDSCREEN SEALANT	1	\$ 120.00	\$ 120.00	<i>✓</i>
4	TAILGATE WINDSCREEN INNER SHIELD	1	\$ 100.00	\$ 100.00	<i>x</i>
5	REAR BUMPER CLIPS(SET) <i>Nec</i>	1	\$ 22.00	\$ 22.00	<i>✓</i>
6	TAILLAMP CLIPS(SET) <i>me</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
7	REAR END PANEL INSULATOR SEAL <i>me</i>	1	\$ 120.00	\$ 120.00	<i>60</i>
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>me</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
9	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

302 TOTAL

\$694.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING(REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,600.00	<i>800</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$1,600.00	<i>600</i>	
3	TUFF COAT	\$250.00	<i>40</i>	
4	WIRING AND BULB CHECK	\$80.00	<i>30</i>	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$120.00	<i>40</i>	
6	TRANSFER TAILGATE MECHANISM	\$120.00	<i>x</i>	
7	CONDUCT WATER LEAKAGE TEST	\$120.00	<i>x</i>	
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$350.00	<i>x</i>	

ESTIMATE REPORT
 I, KK Auto Consultants, hence notify the Repairer of the following:
 TOTAL PARTS COST \$11,596.78
 TOTAL LABOUR COST \$4,240.00
 TOTAL REPAIR COST \$15,836.78
 • Third party survey is on a "no win, no fee" basis.
 • Additional modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
APPROVED DETAILS
 EXCESS
 NO. OF WORKING DAYS :
 RE-SURVEY Acknowledged by Repairer
 Signature:
 Date:

\$4,240.00

Adrian King
1/s 04/07/18

total: \$18246

1/s: H.K.

15836.78

PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012143/Ard3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9464K	Veh. Inspected	SJF 3914T	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005066MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	03/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET OPTRA	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	KL1NA196E7H101367	Colour	SILVER	
Odometer	92574	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	ROADSTONE	6 mm	
L/H Front Tyre	195/60 R15	ROADSTONE	6 mm	
R/H Rear Tyre	195/60 R15	ROADSTONE	6 mm	
L/H Rear Tyre	195/60 R15	ROADSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2018	Inspection Date	04/07/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 3914T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BUCKLED	1,920.00	973.00
1	BOOTLID EMBLEM "OPTRA"	NECESSARY	52.00	52.00
1	BOOTLID EMBLEM "CHEVROLET"	NECESSARY	65.00	65.00
1	BOOTLID EMBLEM "MAGNUM"	NECESSARY	63.80	63.80
1	BOOTLID LOGO	NECESSARY	58.00	58.00
1	BOOTLID LOCK	DAMAGED	320.00	87.00
1	BOOTLID LOCK CATCH	NOT NECESSARY	89.20	-
1	BOOTLID KEY LOCK	NOT NECESSARY	297.40	-
1	BOOTLID INNER TRIM	NOT NECESSARY	466.30	-
1	BOOTLID WEATHERSTRIP	CUT	163.00	163.00
1	BOOTLID WINDSCREEN MOULDING	NOT NECESSARY	155.20	-
1	REAR BUMPER }	DISTORTED	1,880.00	1,290.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$489.00 }		978.00	-
1	REAR BUMPER LOWER LIP	NOT NECESSARY	499.00	-
2	REAR BUMPER SIDE RETAINER @\$62.30	NECESSARY	124.60	124.60
2	TAILLAMP @\$580.10	N/S CRACKED	1,160.20	325.00
2	TAILLAMP PANEL @\$188.90	NOT NECESSARY	377.80	-
1	END PANEL	DENTED	830.00	530.00
1	END PANEL TOP GARNISH	DEFORMED	180.20	58.00
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	515.00	-
1	TOOLS BOX COMPARTMENT	NOT NECESSARY	280.70	-
1	EXHAUST PIPE	NOT NECESSARY	1,415.20	-
4	EXHAUST PIPE MOUNTING @\$55.90	NOT NECESSARY	223.60	-
	LESS 10% DISCOUNT		-1,211.42	-378.94
			10,902.78	3,410.46
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	TAILGATE INNER BOARD CLIPS (SN)	NOT NECESSARY	22.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	TAILGATE WINDSCREEN INNER SHIELD (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/FCI18012143/Ard3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	22.00	22.00
1	SET TAILLAMP CLIPS (SN)	NECESSARY	20.00	10.00
1	REAR END PANEL INSULATOR SEAL (SN)	NECESSARY	120.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			694.00	302.00
	LABOUR			
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	350.00	-
	TO PANEL BEAT, REMOVE AND REPLACE PARTS.		1,600.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	600.00
	TUFF COAT.		250.00	40.00
	WIRING AND BULB CHECK.		80.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	40.00
	TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
			4,240.00	1,510.00
GRAND TOTAL			15,836.78	5,222.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/FC118012143/Ard3n2

MARKET VALUE: \$28,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$18,695.00=NETT VALUE: \$9,305.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.