

REPAIR ESTIMATE*

VEHICLE NO : SH 7989J

DATE 3/7/2018 9:36

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,480.00
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Grille (LH/RH)	\$	285.50	\$ 571.00
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Retainer Mounting	\$	9.20	\$ 18.40
	Headlamp (LH/RH)	\$	1,388.00	\$ 2,776.00
	SUB TOTAL			\$ 6,610.70
	LESS 20%			\$ 1,322.14
	DISCOUNTED TOTAL			\$ 5,288.56
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 5,988.56

NA2 LKK
2/7/18 1700
P/P
Before paint photo
2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.