

ASS. REC. BY:

REF: CS3/SM018012149/R124d302 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Irene James

of

SMO

Date/Time: 4/7/18 @ 11:25am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SBC 666 P

Insured: SLP 5939 H

at Workshop m/s: Cheong Auto

Tel: 9025 3248

of 262 Queensway

Policy No:

Claim No: CMTD1802813 / AGC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/07/2018

4/7/2018 @ 9/7/18 @ after 10am

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time: 11:41am @ 4/7/18

Person Contacted:

jason

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SBC 666 P - X
	SLP 5939 H - X
10/7/18	2 dismantled
	\$ 2800 h

(08/11/13) wef

ASS. REC. BY:

REF: SMO

87468

ASSIGNMENT

From: _____ Date: 9/7/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBC 666P

at Workshop m/s cheong Auto

of 262 Queensway

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) after 10am

Make of Veh: jason @ 90253248

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBC 666P Yr Regn: 2012 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ c.c 1796

Colour: GRN A/C: Insured / Std / NI / NA

Sp.Reading: 123624 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 21204724580935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/35 ZR18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 09/07/18 @ 1230pm

Survey held at 262, Queensway

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimate repair range \$4,000 - \$5,000. (Bryan)

RECEIVED 17 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 100

Transportation: 60

S + RS, SI

Photos

Others

TOTAL

160

Report Format: PRS.

Lump Sum / I.B.I: (\$)

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Wednesday, 4 July 2018 11:25 AM
To: assignments
Cc: Nivitha (LKK Auto)
Subject: FW: CMTD1802813/AGC - SUV(LKK)/ SLP5939H & SBC666P ACC ON 01.07.18
Attachments: 4367_001.pdf

Hi,

Kindly assign your surveyor to conduct the pre-repair inspection @ TP workshop, CHEONG AUTO PTE LTD (SBC 666P).

Please refer to the email attachment for location and person to contact.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Ye, Yong Kang Melvin
Sent: Wednesday, 4 July, 2018 11:22 AM
To: Henry, Irene James <irene.henry@sompo.com.sg>
Subject: FW: CMTD1802813/AGC - SUV(LKK)/ SLP5939H & SBC666P ACC ON 01.07.18

From: Teo, Grace
Sent: Tuesday, 3 July, 2018 4:26 PM
To: ct-admin@visionlawllc.com; yhlee@outlook.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1802813/AGC - SUV(LKK)/ SLP5939H & SBC666P ACC ON 01.07.18

Our Reference: CMTD1802813/AGC

Your Reference: AM.jt.Ins.C47. 107208.18 (sj)

Date: 3rd July 2018

Attention:
M/S VISION LAW LLC

Dear Anjali,

ACCIDENT INVOLVING SLP5939H & SBC666P ON 01.07.18

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

Kindly provide us the address of location and contact for our motor surveyor to conduct the pre-repair survey.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: ct-admin@visionlawllc.com [<mailto:ct-admin@visionlawllc.com>]

Sent: Tuesday, July 03, 2018 3:19 PM

To: yhlée@outlook.sg; Teo, Grace; Claims - Motor Survey
Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

Unique Entity Number :200721148H

✓ **HEAD OFFICE:** 133 New Bridge Road

#18-01/02 Chinatown Point

Singapore 059413

Branch: 490 Toa Payoh Lorong 6

#03-11 HDB Hub

Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)

FAX ✓ : (65) 65356802 (General)

: (65) 65355905 (Litigation)

E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703

FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.C47.107208.18 (sj)

Your Ref: CMTD1802813/AGC

4 July 2018

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attention: Motor Claims Department

BY FAX: 6221 3147

email: motorsurvey@sompo.com.sg

email: grace.teo@sompo.com.sg

Dear Sirs,

ACCIDENT INVOLVING SBC 666 P & SLP 5939 H ON 01 JULY 2018 ALONG BOON LAY WAY AT ABOUT 2055 HOURS

(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email dated 03 July 2018 informing that your wish to conduct a pre-repair survey on our client's vehicle SBC 666 P.

Please be informed that the said vehicle can be inspected at:

Cheong Auto Pte Ltd

Esso Petrol Station

262 Queensway

Singapore 149061

Contact Person:

Mr Jason Cheong (9025 3248)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Anjali M
(Head Office)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SBC 666 P – By Email: cheongauto@yahoo.com.sg only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8746B
Vehicle Details	
Vehicle No.:	SBC666P
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030416758
Chassis No.:	WDD2120472A580935
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,036.00
Original Registration Date:	18 Jul 2012
First Registration Date:	18 Jul 2012
Transfer Count:	0
Actual ARF Paid:	\$54,036.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2022
PARF Rebate Amount:	\$37,825.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$82,289.00
COE Rebate Amount:	\$32,937.00
Total Rebate Amount:	\$70,762.00

The information contained herein is correct as at 16 Jul 2018

OK



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18012149/R1z4d3e2		
50 RAFFLES PLACE #05-01/06		Date: 18-07-2018		
SINGAPORE LAND TOWERS SINGAPORE 048623				
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLP 5939H	Veh. Inspected	SBC 666P	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1802813/AGC	Excess (\$)	0.00	
Assign From	IRENE JAMES	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E 250	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2120472A580935	Colour	GREY	
Odometer	123624 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35Z R18	MICHELIN	6 mm	
L/H Front Tyre	265/35Z R18	MICHELIN	6 mm	
R/H Rear Tyre	265/35Z R18	MICHELIN	6 mm	
L/H Rear Tyre	265/35Z R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
5. General Information				
Accident Date	01/07/2018	Inspect Date / Time	09/07/2018 (12:30 PM)	
Survey held at	CHEONG AUTO PTE LTD 262 QUEENSWAY SINGAPORE 149061			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO18012149/R1z4d3e2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.