

REPAIR ESTIMATE*

DATE 28/6/2018 17:10

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,681.40
	Boot Lid Lock Upper			\$ 137.90
	Boot Lid Lock Lower			\$ 31.70
	Boot Lid 'H' Emblem			\$ 27.20
	Boot Lid CRDI Plate			\$ 41.00
	Boot Lid Lamp (LH/RH) LH-?, RH- mt		\$ 556.80	\$ 1,113.60
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 41.00
	Bootlid Lower Garnish			\$ 398.00
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket		\$ 49.00	\$ 98.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Rear Bumper Reflector Lamp (LH/RH) LH-?, RH- mt		\$ 32.00	\$ 64.00
	Tail Lamp (LH/RH)		\$ 565.60	\$ 1,131.20
	Rear Panel			\$ 592.30
	Rear Panel Garnish			\$ 57.70
	Rear Panel Lower Panel			\$ 495.50
	Spare Tyre Holder			\$ 28.80
	Spare Tyre Panel			\$ 900.50
	Spare Tyre Panel Cushion			\$ 209.05
	Exhaust Pipe Insulator		\$ 58.55	\$ 117.10
	Exhaust Silencer		\$ 954.00	\$ 1,908.00
	Exhaust Pipe Hanger		\$ 58.55	\$ 117.10
	Exhaust Pipe Centre			\$ 1,150.30
	Rear Fender (LH)			\$ 2,020.10
	Rear Windscreen Moulding			\$ 60.00
	SUB TOTAL			\$ 14,364.80
	LESS 20%			\$ 2,872.96
	DISCOUNTED TOTAL			\$ 11,491.84
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No.Plates			\$ 25.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Windscreen Sealant			\$ 46.00
				\$ 236.70

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,800.00 900
	Spray Painting Charge			\$ 1,000.00 800
	Wiring Charge			\$ 50.00 30
	Tuff Kote			\$ 50.00 30
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 60
	Remove/Refix Rear Windscreen Glass			\$ 120.00 X
	Remove/Refix Reverse Sensor			\$ 120.00 30
	Remove/Refix Exhaust Pipe			\$ 240.00 120?
	TOWING- KING BOLLY			\$ 150.00 120
	TOTAL LABOUR			\$ 3,530.00
	ESTIMATE TOTAL			\$ 15,258.54
Taufik 97495749 WP 29/6/18C 1720 Resurvey after repair 7 days. Sun @ 10am to 10m.				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				