



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKU2217M

Mdm Lim Mui Siam

25J Jalan Hock Chye
Singapore 534179

Mobile: 98163828

Vehicle & Document Information

WIP No **24834**
Reg No/Reg Date **SKU2217M / 15/06/2015**
Date In/Mileage **/ 0**
Chassis No **WDD2120342B143256**
Engine No **27492030355931**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212)**
Colour/Trim **021 197 Obsidian B1/ 042 215 Leather Sia**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	02/07/2018/ 09:36	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100416768-03 // 29/06/2018 DRIVE IN/EXCESS : 29/06/2018 // SHC5143C - AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960 1920.00
A BPIRES RESPRAY REAR BUMPER				600 960.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
M REAR BUMPER	1.00	1630.57	00.00	DE 1630.57
M REAR BUMPER LOWER TRIM	1.00	241.49	00.00	CA 241.49
M LH/ REAR BUMPER CHROME MOULDING	1.00	128.17	00.00	RE 128.17
M RH/ REAR BUMPER CHROME MOULDING	1.00	128.17	00.00	RE 128.17
M LH/ REAR BUMPER BOTTOM BRACKET	1.00	17.36	00.00	RE 17.36
M RH/ REAR BUMPER BOTTOM BRACKET	1.00	17.36	00.00	RE 17.36
M LH/ REAR BUMPER SIDE STABILITY	1.00	30.77	00.00	? 30.77
M RH/ REAR BUMPER SIDE STABILITY	1.00	30.77	00.00	? 30.77
M REAR DISTANCE SENSOR	2.00	172.07	00.00	? 344.14
M SPACER RING	2.00	6.42	00.00	? 12.84
M CTR/ BASIC MOUNTING FOR BUMPER	1.00	211.58	00.00	? 211.58
M REAR CROSS MEMBER	1.00	789.45	00.00	? 789.45

Rasul
Ap 90110068
3 days
17/07/18 @ 1235
Respray 64 point

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirmed & accepted by
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: _____
Authorized signatory and company stamp

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett **6,962.67**
7% GST on **6962.67** **487.39**
Total Payable 7,450.06

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg