

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

18/7/18
@
1600pm
Survey

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLE3983A
Chassis No : JHMRC1880GC205072
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : YAP KOK BOON
Ins Policy No. :
Date of Accident : 1/7/2018

Document No. : SQT18002715 Page 1
Date : 3. Jul 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : K24W72012260
Date | Time : 3. Jul 2018 9:53:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: YAP KOK BOON						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 01/07/18						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SLU6026J						

BO-WHEEL ALIGN X4	WHEEL ALIGNMENT	1	180.00		180.00	12.60	192.60
					Sum Ext. Service	180.00	192.60
60260-T6A-300ZZ	FENDER COMPL.FR.	1	537.80	25	403.35	28.23	431.58
74150-T6A-000	FENDER ASSYL.FR.INNER	1	118.30	25	88.72	6.21	94.93
91512-SX0-003	CLIPINNER FENDER	5	3.50	25	13.12	0.92	14.04
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
04711-T6A-000ZZ	FACE,FR.BUMPER	1	677.60	25	508.20	35.57	543.77
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	11.60	25	8.70	0.61	9.31
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	34.20	25	25.65	1.80	27.45
71109-T6A-003	GARNISHL.FR.BUMPER	1	40.90	25	30.67	2.15	32.82
33150-T6A-Q01	HEADLIGHT ASSY,L.	1	886.20	25	664.65	46.53	711.18
42700-T6A-Q81	DISKALUMINIUM WHEEL 17X7J	1	897.00	25	672.75	47.09	719.84
44300-T6A-J51	BEARING ASSYFR.HUB	1	135.50	25	101.62	7.11	108.73
51215-T6A-000	KNUCKLE COMPL.FR.	1	292.60	25	219.45	15.36	234.81
51360-T6A-N00	LOWER ARM ASSY,L.FR.	1	623.80	25	467.85	32.75	500.60
					Sum Item	3225.73	3451.53
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		80.00	5.60	85.60
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)	1	840.00		840.00	58.80	898.80

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLE3983A
Chassis No : JHMRC1880GC205072
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : YAP KOK BOON
Ins Policy No. :
Date of Accident : 1/7/2018

Document No. : SQT18002715
Date : 3. Jul 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : K24W72012260
Date | Time : 3. Jul 2018 9:53:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE11R	REMOVE & RENEW FR L FENDER & FRONT BUMPER.	1	1120.00	560	1120.00	78.40	1198.40
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1100.00	900	1100.00	77.00	1177.00
Sum Labor					3170.00	221.90	3,391.90

Survey By

Date & Time

Excess

Status

Signature

Total Amount 6,575.73 460.30 7,036.03

Total (Inclusive of GST) 7,036.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/7/2018 11:26:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)