

Ah Lim Motor Company
10 Ang Mo Kio Industrial
Park 2A
#01-09 AMK Autopoint
Singapore 568047

SURVEYOR COPY

Claim Reference:
Assessment Number: AH000851
Version: AHLIM001/1

Full Report - V1
Registration: SJX9519S
Printed: 03/07/2018 17:20

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Ahlim ahlim	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	Estimated Repair Time:
Policy Number:	Quote Due Date:
Other Reference:	Actual Repair Days:
Third Party:	Parts Ordered Date:
Insured Amount:	Hire Car Start:
Under Warranty:	Hire Car End:
Warranty Expired:	Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer:	LEXUS
Model:	GS 300/350/430/450h/460TWO COAT METALLIC
Sub Model:	300
Model Sheet Number:	2415 01
Registration:	SJX9519S
Registration Month:	July
Registration Year:	2010
VIN Number:	JTHBH96S505068309
Manufacture Year:	2010
Odometer:	Not Known
Colour:	
Engine Number:	3GR0281127
Fuel Level:	%


Model Specs

PARK PILOT SYSTEM	3.0 LTR 183 KW
	PAINTING OFF VEHICLE

Vehicle Condition

Vehicle Status


Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	03/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Ah Lim Motor Company

Claim Reference:
Assessment Number: AH000851
Version: AHLIM001/1

Full Report - V1
Registration: SJX9519S
Printed: 03/07/2018 17:20



Addresses

Cost Summary

Total Labour	\$1,233.00
Total Paint/Material	\$242.86
Total Parts	\$4,445.90
Total of Additional Costs	\$355.00
Excess:	TBA
Grand Total Exc GST:	\$6,276.76
7 % GST:	\$439.37
Grand Total Inc GST:	\$6,716.13

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B290	RENEW END PANEL (BUMPER REMOVED) INCLUDES: R + R BOOT FLOOR CARPET AND ALL TRIMS IN THE REPAIR SECTION	42.0	189.00
B350	R + R BOOTLID	5.0	22.50
B360)	RENEW BOOTLID (REMOVED) INCLUDES: CONVERT ATTACHED PARTS, RENEW IF NECESSARY	5.0	22.50
B410	R + R REAR BUMPER INCLUDES: R + R BOOT TRIMS	6.0	27.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	4.50
B420)	RENEW REAR BUMPER REINFORCEMENT	2.0	9.00
NO NUMBER	R + R LEFT REAR BUMPER BRACKET	1.0	4.50
NO NUMBER	R + R RIGHT REAR BUMPER BRACKET	1.0	4.50
B407)	RENEW LEFT TAILLAMP	1.0	4.50
B407)	RENEW RIGHT TAILLAMP	1.0	4.50
3481	REPAIR L/R SIDE PANEL	20.0*	90.00
3482	REPAIR R/R SIDE PANEL	20.0*	90.00
3901	REPAIR REAR FLOOR PANEL	20.0*	90.00

LABOUR COST


Total Work Units	125.0	
Sub Total	12.5HRS	\$562.50
Paint Labour	14.9HRS	670.50
Total Labour	27.4HRS	\$1,233.00

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

WU Cost Price (\$)



Printed: 03/07/2018 17:20

PAGE 3 OF 4

Ah Lim Motor Company

Claim Reference:
Assessment Number: AH000851
Version: AHLIM001/1

Full Report - V1
Registration: SJX9519S
Printed: 03/07/2018 17:20

Extras

Description		Betterment	Price
REVERSE SENSOR	SPECIALIST	0%	\$200.00
NUMBER PLATE	SPECIALIST		\$35.00
CHK WIRING	SPECIALIST	0%	\$40.00
REINSTALL	SPECIALIST		\$80.00
TRIM&GARN			
Total Extras			\$355.00

Final Calculation

Total Parts		\$4,445.90
Labour		
Total Panel/Mechanical	\$562.50	
Total Paintwork	\$670.50	
Total Labour		\$1,233.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$355.00	
Total of Additional Costs		\$355.00
Total Paint/Material Costs		\$242.86
Grand Total Excludes GST		\$6,276.76
GST @ 7 %		\$439.37
Grand Total Includes GST		\$6,716.13

Assessment Notes

